

# CATALOGO COMPRESSORI



	SEPARATOR OE BSB REF.	AIR PRIMARY OE BSB REF.	AIR SAFETY OE BSB REF.	OIL FILTER OE BSB REF.
<b>ABAC</b>	<i>10 HP</i>			
<b>ABAC</b>				
<b>10 HP</b>	9056011 <b>FD 3035</b>	9056018 <b>FA 2172</b>		9056110
<b>15 HP</b>	9056011 <b>FD 3035</b>	9056018 <b>FA 2172</b>		9056110
<b>20 HP</b>	9056012 <b>FD 3102</b>	9056010 <b>FA 2203</b>		9056110
<b>25 HP</b>	9056012 <b>FD 3102</b>	9056010 <b>FA 2203</b>		9056110
<b>30 HP</b>	9056012 <b>FD 3102</b>	9056010 <b>FA 2203</b>		9056110
<b>40 2S</b>	9056175 <b>FD 3355</b>			
<b>40 HP</b>	9056102 <b>FD 3047</b>	9056019 <b>FA 1752</b>		9056113 <b>FI 1268 V</b>
<b>50 HP</b>	9056102 <b>FD 3047</b>	9056019 <b>FA 1752</b>		9056113 <b>FI 1268 V</b>
<b>60 2S</b>	9056175 <b>FD 3355</b>			
<b>60 HP</b>	9056102 <b>FD 3047</b>	9056019 <b>FA 1752</b>		9056113 <b>FI 1268 V</b>
<b>FORMULA 11</b>	9056292 <b>FD 3096 V</b>	9056293 <b>FA 2843</b>		9056113 <b>FI 1268 V</b>
<b>FORMULA 15 BA 51</b>	9056292 <b>FD 3096 V</b>	9056293 <b>FA 2843</b>		9056113 <b>FI 1268 V</b>
<b>FORMULA 15 BA 69</b>	9056292 <b>FD 3096 V</b>	9056002 <b>FA 5003</b>		9056113 <b>FI 1268 V</b>
<b>FORMULA 22</b>	9056322 <b>FD 3373 V</b>	9056940 <b>FA 5001</b>		9056113 <b>FI 1268 V</b>
<b>FORMULA 5.5 10/13 BAR</b>	9056237 <b>FD 3034 V</b>	9056293 <b>FA 2843</b>		9056238 <b>FO 0029 V</b>
<b>FORMULA 7.5 10/13 BAR</b>	9056237 <b>FD 3034 V</b>	9056293 <b>FA 2843</b>		9056238 <b>FO 0029 V</b>
<b>GENESIS 10</b>	9056237 <b>FD 3034 V</b>	9056250 <b>FA 5507</b>		9056238 <b>FO 0029 V</b>
<b>GENESIS 11</b>	9056292 <b>FD 3096 V</b>	9056293 <b>FA 2843</b>		9056113 <b>FI 1268 V</b>
<b>GENESIS 15</b>	9056292 <b>FD 3096 V</b>	9056250 <b>FA 5507</b>		9056113 <b>FI 1268 V</b>
<b>GENESIS 15 BA 51</b>	9056292 <b>FD 3096 V</b>	9056293 <b>FA 2843</b>		9056113 <b>FI 1268 V</b>
<b>GENESIS 15 BA 69</b>	9056292 <b>FD 3096 V</b>	9056002 <b>FA 5003</b>		9056113 <b>FI 1268 V</b>
<b>GENESIS 5.5</b>	9056237 <b>FD 3034 V</b>	9056250 <b>FA 5507</b>		9056238 <b>FO 0029 V</b>
<b>GENESIS 5.5 10/13 BAR</b>	9056237 <b>FD 3034 V</b>	9056293 <b>FA 2843</b>		9056282 <b>FI 0906 V</b>
<b>GENESIS 7.5</b>	9056237 <b>FD 3034 V</b>	9056293 <b>FA 2843</b>		9056238 <b>FO 0029 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ABAC</b> <i>GENESIS 7.5 10/13 BAR</i>				
<i>GENESIS 7.5 10/13 BAR</i>	9056237 <b>FD 3034 V</b>	9056293 <b>FA 2843</b>		9056282 <b>FI 0906 V</b>
<i>RTC 10</i>	9056162 <b>FD 3006</b>	9056157 <b>FA 2110</b>		9056113 <b>FI 1268 V</b>
<i>RTC 15</i>	9056162 <b>FD 3006</b>	9056157 <b>FA 2110</b>		9056113 <b>FI 1268 V</b>
<i>RTC 25</i>	9056176 <b>FD 3007</b>	9056157 <b>FA 2110</b>		9056113 <b>FI 1268 V</b>
<i>RTC 40</i>	9056176 <b>FD 3007</b>	9618035 <b>FA 5001</b>		9056113 <b>FI 1268 V</b>
<i>RTC 50</i>	9056175 <b>FD 3355</b>			
<i>RTC 7.5</i>	9056162 <b>FD 3006</b>	9056157 <b>FA 2110</b>		9056113 <b>FI 1268 V</b>
<i>SCREW 1</i>	9056011 <b>FD 3035</b>	9056018 <b>FA 2172</b>		9056113 <b>FI 1268 V</b>
<i>SCREW 2</i>	9056012 <b>FD 3102</b>	9056010 <b>FA 2203</b>		9056113 <b>FI 1268 V</b>
<i>SCREW 20</i>	9056176 <b>FD 3007</b>	9056010 <b>FA 2203</b>		9056113 <b>FI 1268 V</b>
<i>SCREW 30</i>	9056176 <b>FD 3007</b>	9056010 <b>FA 2203</b>		9056113 <b>FI 1268 V</b>
<i>SCREW 40</i>	9056176 <b>FD 3007</b>	9056010 <b>FA 2203</b>		9056113 <b>FI 1268 V</b>
<i>SCREW 50</i>	9056175 <b>FD 3355</b>	9056019 <b>FA 1752</b>		9056103 <b>FI 1304 V</b>
<i>SCREW 60</i>	9056175 <b>FD 3355</b>	9056019 <b>FA 1752</b>		9056103 <b>FI 1304 V</b>
<i>SMART 10 (8-10-13 BAR)</i>	9056237 <b>FD 3034 V</b>	9056293 <b>FA 2843</b>		9056238 <b>FO 0029 V</b>
<i>SMART 15 (8-10-13 BAR)</i>	9056292 <b>FD 3096 V</b>	9056293 <b>FA 2843</b>		9056113 <b>FI 1268 V</b>
<i>SMART 20 (8-10-13 BAR)</i>	9056292 <b>FD 3096 V</b>	9056293 <b>FA 2843</b>		9056113 <b>FI 1268 V</b>
<i>SMART 25 (8-10-13 BAR)</i>	9056322 <b>FD 3373 V</b>	9056718 <b>FA 2067</b>		9056113 <b>FI 1268 V</b>
<i>SMART 30 (8-10-13 BAR)</i>	9056322 <b>FD 3373 V</b>	9056718 <b>FA 2067</b>		9056113 <b>FI 1268 V</b>
<i>SMART 7.5 (8-10-13 BAR)</i>	9056237 <b>FD 3034 V</b>	9056293 <b>FA 2843</b>		9056238 <b>FO 0029 V</b>
<i>SPINN 11</i>	9056292 <b>FD 3096 V</b>	9056293 <b>FA 2843</b>		9056113 <b>FI 1268 V</b>
<i>SPINN 5.5</i>	9056237 <b>FD 3034 V</b>	9056293 <b>FA 2843</b>		9056238 <b>FO 0029 V</b>
<i>SPINN 7.5</i>	9056237 <b>FD 3034 V</b>	9056293 <b>FA 2843</b>		9056238 <b>FO 0029 V</b>
<i>VT 10</i>	9056162 <b>FD 3006</b>	9056157 <b>FA 2110</b>		9056113 <b>FI 1268 V</b>
<i>VT 10 CMP</i>	9056237 <b>FD 3034 V</b>	9056250 <b>FA 5507</b>		9056238 <b>FO 0029 V</b>
<i>VT 100</i>	9056572 <b>FD 3445</b>	9618205 <b>FA 5854</b>		9618213
<i>VT 125</i>	9056572 <b>FD 3445</b>	9618205 <b>FA 5854</b>		9618213



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ABAC</b>	<b>VT 15</b>			
<b>VT 15</b>	9056162 <b>FD 3006</b>	9056157 <b>FA 2110</b>		9056113 <b>FI 1268 V</b>
<b>VT 15 CMP</b>	9056292 <b>FD 3096 V</b>	9056293 <b>FA 2843</b>		
<b>VT 150</b>	9056573 <b>FD 3037</b>	9618206 <b>FA 1404</b>		9618213
<b>VT 180 10 BAR</b>	9056573 <b>FD 3037</b>	9618206 <b>FA 1404</b>		9618213
<b>VT 180 8 BAR</b>	9056574 <b>FD 3444</b>	9618206 <b>FA 1404</b>		9618213
<b>VT 20</b>	9056162 <b>FD 3006</b>	9618034 <b>FA 5003</b>		9056113 <b>FI 1268 V</b>
<b>VT 20 CMP</b>	9056292 <b>FD 3096 V</b>	9056293 <b>FA 2843</b>		
<b>VT 220</b>	9056574 <b>FD 3444</b>	9618207 <b>FA 1302</b>		9618213
<b>VT 25</b>	9056176 <b>FD 3007</b>	9618035 <b>FA 5001</b>		9056113 <b>FI 1268 V</b>
<b>VT 270</b>	9056595 <b>FD 3290</b>	9618208 <b>FA 1556</b>		9618213
<b>VT 30</b>	9056176 <b>FD 3007</b>	9618035 <b>FA 5001</b>		9056113 <b>FI 1268 V</b>
<b>VT 40</b>	9056176 <b>FD 3007</b>	9618035 <b>FA 5001</b>		9056113 <b>FI 1268 V</b>
<b>VT 40 CMP</b>	9056322 <b>FD 3373 V</b>	9056718 <b>FA 2067</b>		
<b>VT 50</b>	9056025 <b>FD 3464</b>	9056019 <b>FA 1752</b>		9056103 <b>FI 1304 V</b>
<b>VT 50 NEW TYPE</b>	9056025 <b>FD 3464</b>	9056189 <b>FA 5002</b>		9056103 <b>FI 1304 V</b>
<b>VT 60</b>	9056025 <b>FD 3464</b>	9056019 <b>FA 1752</b>		9056103 <b>FI 1304 V</b>
<b>VT 60 NEW TYPE</b>	9056025 <b>FD 3464</b>	9056189 <b>FA 5002</b>		9056103 <b>FI 1304 V</b>
<b>VT 7.5</b>	9056162 <b>FD 3006</b>	9056157 <b>FA 2110</b>		9056113 <b>FI 1268 V</b>
<b>VT 7.5 CMP</b>	9056237 <b>FD 3034 V</b>	9056250 <b>FA 5507</b>		9056238 <b>FO 0029 V</b>
<b>VT 75</b>	9056025 <b>FD 3464</b>	9056189 <b>FA 5002</b>		9056103 <b>FI 1304 V</b>
<b>ZENITH 03-270</b>	9056237 <b>FD 3034 V</b>	9056780 <b>FA 5507</b>		9056238 <b>FO 0029 V</b>
<b>ZENITH 04-270</b>	9056237 <b>FD 3034 V</b>	9056780 <b>FA 5507</b>		9056238 <b>FO 0029 V</b>
<b>ZENITH 05-270</b>	9056237 <b>FD 3034 V</b>	9056780 <b>FA 5507</b>		9056238 <b>FO 0029 V</b>
<b>ZENITH 07-270</b>	9056237 <b>FD 3034 V</b>	9056780 <b>FA 5507</b>		9056238 <b>FO 0029 V</b>
<b>ZENITH 07-500</b>	9056237 <b>FD 3034 V</b>	9056780 <b>FA 5507</b>		9056238 <b>FO 0029 V</b>
<b>ZENITH 10-270</b>	9056237 <b>FD 3034 V</b>	9056780 <b>FA 5507</b>		9056238 <b>FO 0029 V</b>
<b>ZENITH 10-500</b>	9056237 <b>FD 3034 V</b>	9056780 <b>FA 5507</b>		9056238 <b>FO 0029 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ABAC</b>				
<i>ZENITH 15-270</i>				
<i>ZENITH 15-270</i>	9056292 <b>FD 3096 V</b>	9056780 <b>FA 5507</b>		9056113 <b>FI 1268 V</b>
<i>ZENITH 15-500</i>	9056292 <b>FD 3096 V</b>	9056780 <b>FA 5507</b>		9056113 <b>FI 1268 V</b>
<b>ADICOMP</b>				
<i>VE 11 A</i>	40100005 <b>FD 3096 V</b>	40300001 <b>FA 1959</b>		40200007 <b>FI 1268 V</b>
<i>VE 15 A</i>	40100005 <b>FD 3096 V</b>	40300001 <b>FA 1959</b>		40200007 <b>FI 1268 V</b>
<i>VE 15 B</i>	40100005 <b>FD 3096 V</b>	40300001 <b>FA 1959</b>		40200007 <b>FI 1268 V</b>
<i>VE 18 B</i>	40100033 <b>FD 3031 V</b>	40300001 <b>FA 1959</b>		40200007 <b>FI 1268 V</b>
<i>VE 22 B</i>	40100033 <b>FD 3031 V</b>	40300001 <b>FA 1959</b>		40200007 <b>FI 1268 V</b>
<i>VE 22 C</i>	40100033 <b>FD 3031 V</b>	40300004 <b>FA 2017</b>		40200007 <b>FI 1268 V</b>
<i>VE 2208 C</i>	40100036 <b>FD 3031 V</b>	40300004 <b>FA 2017</b>		40200007 <b>FI 1268 V</b>
<i>VE 30 C</i>	40100033 <b>FD 3031 V</b>	40300004 <b>FA 2017</b>		40200007 <b>FI 1268 V</b>
<i>VE 30 CS</i>	40100033 <b>FD 3031 V</b>	40300004 <b>FA 2017</b>		40200007 <b>FI 1268 V</b>
<i>VE 37 C</i>	40100033 <b>FD 3031 V</b>	40300004 <b>FA 2017</b>		40200007 <b>FI 1268 V</b>
<i>VE 37 H</i>	40100033 <b>FD 3031 V</b>	40300004 <b>FA 2017</b>		40200007 <b>FI 1268 V</b>
<i>VE 45 H</i>	40100033 <b>FD 3031 V</b>	40300004 <b>FA 2017</b>		40200007 <b>FI 1268 V</b>
<i>VE 5 A</i>	40100002 <b>FD 3034 V</b>	40300001 <b>FA 1959</b>		40200007 <b>FI 1268 V</b>
<i>VE 7 A</i>	40100002 <b>FD 3034 V</b>	40300001 <b>FA 1959</b>		40200007 <b>FI 1268 V</b>
<b>ALMIG</b>				
<i>BELT 11-15</i>	57251002 <b>FD 3597</b>	57208787 <b>FA 1981/1</b>		57200221 <b>FO 0418 V</b>
<i>BELT 132</i>	57258111 <b>FD 3031 V</b>	57208790 <b>FA 2035</b>		57211103 <b>FO 0030 V</b>
<i>BELT 133-160</i>	17203382 <b>FD 3635</b>	57307730 <b>FA 5573</b>		57213145 <b>FI 1099 V</b>
<i>BELT 16-18-22</i>	57211105 <b>FD 3611 V</b>	57208787 <b>FA 1981/1</b>		57200222 <b>FI 1288 V</b>
<i>BELT 200</i>	17203382 <b>FD 3635</b>	57307730 <b>FA 5573</b>		57213145 <b>FI 1099 V</b>
<i>BELT 30-37</i>	57258112 <b>FD 3031 V</b>	57208787 <b>FA 1981/1</b>		57200222 <b>FI 1288 V</b>
<i>BELT 38</i>	57258111 <b>FD 3031 V</b>	57208787 <b>FA 1981/1</b>		57203291 <b>FI 1286 V</b>
<i>BELT 45-55-75</i>	57258111 <b>FD 3031 V</b>	57208786 <b>FA 2030</b>		57211103 <b>FO 0030 V</b>
<i>BELT 4-5-7</i>	57251002 <b>FD 3597</b>	57208789 <b>FA 2034</b>		57200221 <b>FO 0418 V</b>
<i>BELT 76-90-110</i>	57258111 <b>FD 3031 V</b>	57208790 <b>FA 2035</b>		57211103 <b>FO 0030 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ALMIG</b>				
<i>DIRECT 11-15</i>				
<i>DIRECT 11-15</i>	57211105 <b>FD 3611 V</b>	57208787 <b>FA 1981/1</b>		57200222 <b>FI 1288 V</b>
<i>DIRECT 132-160</i>	17203382 <b>FD 3635</b>	57307730 <b>FA 5573</b>		57213145 <b>FI 1099 V</b>
<i>DIRECT 16-18-22</i>	57258112	57208787 <b>FA 1981/1</b>		57200222 <b>FI 1288 V</b>
<i>DIRECT 37</i>	57258111 <b>FD 3031 V</b>	57208786 <b>FA 2030</b>		57203291 <b>FI 1286 V</b>
<i>DIRECT 45-55</i>	57258111 <b>FD 3031 V</b>	57208786 <b>FA 2030</b>		57211103 <b>FO 0030 V</b>
<i>DIRECT 75-90</i>	57258111 <b>FD 3031 V</b>	57208790 <b>FA 2035</b>		57211103 <b>FO 0030 V</b>
<i>FLEX 16-18</i>	57211105 <b>FD 3611 V</b>	57208788 <b>FA 2033</b>		57200222 <b>FI 1288 V</b>
<i>FLEX 22-30</i>	57258112	57208787 <b>FA 1981/1</b>		57200222 <b>FI 1288 V</b>
<i>FLEX 6-7-11-15</i>	57251002 <b>FD 3597</b>	57208789 <b>FA 2034</b>		57200221 <b>FO 0418 V</b>
<i>GEAR 110</i>	57258111 <b>FD 3031 V</b>	57208790 <b>FA 2035</b>		57211103 <b>FO 0030 V</b>
<i>GEAR 132</i>	17203382 <b>FD 3635</b>	57307730 <b>FA 5573</b>		57213145 <b>FI 1099 V</b>
<i>GEAR 160</i>	17203382 <b>FD 3635</b>	57307730 <b>FA 5573</b>		57213145 <b>FI 1099 V</b>
<i>GEAR 200</i>	61203311	17230173		57213145 <b>FI 1099 V</b>
<i>GEAR 201</i>	61203311	17230173		57213145 <b>FI 1099 V</b>
<i>GEAR 30-47</i>	57258111 <b>FD 3031 V</b>	57208786 <b>FA 2030</b>		57203291 <b>FI 1286 V</b>
<i>GEAR 45-55</i>	57258111 <b>FD 3031 V</b>	57208786 <b>FA 2030</b>		57211103 <b>FO 0030 V</b>
<i>GEAR 75-90</i>	57258111 <b>FD 3031 V</b>	57208790 <b>FA 2035</b>		57211103 <b>FO 0030 V</b>
<i>VARIABLE 150</i>	17203382 <b>FD 3635</b>	57307730 <b>FA 5573</b>		57213145 <b>FI 1099 V</b>
<i>VARIABLE 16-20</i>	57211105 <b>FD 3611 V</b>	57208787 <b>FA 1981/1</b>		57200222 <b>FI 1288 V</b>
<i>VARIABLE 210</i>	17203382 <b>FD 3635</b>	57307730 <b>FA 5573</b>		57213145 <b>FI 1099 V</b>
<i>VARIABLE 24-28</i>	57258112	57208787 <b>FA 1981/1</b>		57200222 <b>FI 1288 V</b>
<i>VARIABLE 260</i>	17200111	17230173		57213145 <b>FI 1099 V</b>
<i>VARIABLE 32-34</i>	57258112	57208786 <b>FA 2030</b>		57200222 <b>FI 1288 V</b>
<i>VARIABLE 35</i>	57258111 <b>FD 3031 V</b>	57208787 <b>FA 1981/1</b>		57203291 <b>FI 1286 V</b>
<i>VARIABLE 37</i>	57258111 <b>FD 3031 V</b>	57208787 <b>FA 1981/1</b>		57203291 <b>FI 1286 V</b>
<i>VARIABLE 55-65</i>	57258111 <b>FD 3031 V</b>	57208786 <b>FA 2030</b>		57211103 <b>FO 0030 V</b>
<i>VARIABLE 70</i>	57258111 <b>FD 3031 V</b>	57208786 <b>FA 2030</b>		57203291 <b>FI 1286 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ALMIG</b> <i>VARIABLE 90-115-130</i>				
<i>VARIABLE 90-115-130</i>	57258111 <b>FD 3031 V</b>	57208790 <b>FA 2035</b>		57211103 <b>FO 0030 V</b>
<b>ALUP</b>				
<i>ALLEGRO 100</i>	17258111 <b>FD 3031 V</b>	17208790 <b>FA 2035</b>		17211103 <b>FO 0030 V</b>
<i>ALLEGRO 115</i>	17258111 <b>FD 3031 V</b>	17208790 <b>FA 2035</b>		17211103 <b>FO 0030 V</b>
<i>ALLEGRO 130</i>	17258111 <b>FD 3031 V</b>	17208790 <b>FA 2035</b>		17211103 <b>FO 0030 V</b>
<i>ALLEGRO 150 FROM SERIES No. 217763</i>	17203382 <b>FD 3635</b>	17307730 <b>FA 5573</b>		17213145 <b>FI 1099 V</b>
<i>ALLEGRO 150 UP TO SERIES No. 217762</i>	17203382 <b>FD 3635</b>	17208790 <b>FA 2035</b>		17213145 <b>FI 1099 V</b>
<i>ALLEGRO 16</i>	17211105 <b>FD 3611 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>ALLEGRO 20</i>	17211105 <b>FD 3611 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>ALLEGRO 210</i>	17203383 <b>FD 3635</b>	17201210 <b>FA 2049</b>		17213145 <b>FI 1099 V</b>
<i>ALLEGRO 210 FROM SERIES No. 217763</i>	17203382 <b>FD 3635</b>	17307730 <b>FA 5573</b>		17213145 <b>FI 1099 V</b>
<i>ALLEGRO 210 UP TO SERIES No. 217762</i>	17203382 <b>FD 3635</b>	17208790 <b>FA 2035</b>		17213145 <b>FI 1099 V</b>
<i>ALLEGRO 24</i>	17211105 <b>FD 3611 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>ALLEGRO 24 FROM SERIES No. F0500001</i>	17258112 <b>FD 3031 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>ALLEGRO 260</i>	17203388 <b>FD 3605</b>	17230173 <b>FA 2030</b>		17213145 <b>FI 1099 V</b>
<i>ALLEGRO 28</i>	17258112 <b>FD 3031 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>ALLEGRO 30 FROM SERIES No. 215000</i>	17258111 <b>FD 3031 V</b>	17208787 <b>FA 1981/1</b>		17203291 <b>FI 1286 V</b>
<i>ALLEGRO 30 FROM SERIES No. 217576</i>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17203291 <b>FI 1286 V</b>
<i>ALLEGRO 32</i>	17258112 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17200222 <b>FI 1288 V</b>
<i>ALLEGRO 38</i>	17258112 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17200222 <b>FI 1288 V</b>
<i>ALLEGRO 40 FROM SERIES No. 215000</i>	17258111 <b>FD 3031 V</b>	17208787 <b>FA 1981/1</b>		17203291 <b>FI 1286 V</b>
<i>ALLEGRO 40 FROM SERIES No. 217576</i>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17203291 <b>FI 1286 V</b>
<i>ALLEGRO 50</i>	17258111 <b>FD 3031 V</b>	17208787 <b>FA 1981/1</b>		17203291 <b>FI 1286 V</b>
<i>ALLEGRO 60 FROM SERIES No. F0502976</i>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17211103 <b>FO 0030 V</b>
<i>ALLEGRO 60 FROM SERIES No. F0600000</i>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17203291 <b>FI 1286 V</b>
<i>ALLEGRO 80 FROM SERIES No. F0502976</i>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17211103 <b>FO 0030 V</b>
<i>ALLEGRO 80 FROM SERIES No. F0600000</i>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17203291 <b>FI 1286 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ALUP</b>				
<i>LARGO 110</i>				
<b>LARGO 110</b>	17258111 <b>FD 3031 V</b>	17208790 <b>FA 2035</b>		17211103 <b>FO 0030 V</b>
<b>LARGO 132</b>	21203382 <b>FD 3635</b>	17307730 <b>FA 5573</b>		17213145 <b>FI 1099 V</b>
<b>LARGO 160</b>	21203382 <b>FD 3635</b>	17307730 <b>FA 5573</b>		17213145 <b>FI 1099 V</b>
<b>LARGO 201</b>	21203311	17230173		17213145 <b>FI 1099 V</b>
<b>OPUS 11</b>	17211105 <b>FD 3611 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<b>OPUS 110</b>	17258111 <b>FD 3031 V</b>	17208790 <b>FA 2035</b>		17211103 <b>FO 0030 V</b>
<b>OPUS 132 FROM SERIES No. 217764</b>	17203382 <b>FD 3635</b>	17307730 <b>FA 5573</b>		17211103 <b>FO 0030 V</b>
<b>OPUS 132 FROM SERIES No. F0500001</b>	17203382 <b>FD 3635</b>	17307730 <b>FA 5573</b>		17213145 <b>FI 1099 V</b>
<b>OPUS 132 UP TO SERIES No. 217763</b>	17203382 <b>FD 3635</b>	17208790 <b>FA 2035</b>		17211103 <b>FO 0030 V</b>
<b>OPUS 15</b>	17211105 <b>FD 3611 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<b>OPUS 16</b>	17211105 <b>FD 3611 V</b>	17208786 <b>FA 2030</b>		17200222 <b>FI 1288 V</b>
<b>OPUS 160 FROM SERIES No. 217763</b>	17203382 <b>FD 3635</b>	17307730 <b>FA 5573</b>		17213145 <b>FI 1099 V</b>
<b>OPUS 160 UP TO SERIES No. 217762</b>	17203382 <b>FD 3635</b>	17208790 <b>FA 2035</b>		17213145 <b>FI 1099 V</b>
<b>OPUS 22</b>	17211105 <b>FD 3611 V</b>	17208786 <b>FA 2030</b>		17200222 <b>FI 1288 V</b>
<b>OPUS 250</b>	17203388 <b>FD 3605</b>	17230173		17213145 <b>FI 1099 V</b>
<b>OPUS 250 FROM SERIES No. 218448</b>	17203382 <b>FD 3635</b>	17230173		17213145 <b>FI 1099 V</b>
<b>OPUS 30</b>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17203291 <b>FI 1286 V</b>
<b>OPUS 315</b>	17203388 <b>FD 3605</b>	17230173		17213145 <b>FI 1099 V</b>
<b>OPUS 37</b>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17203291 <b>FI 1286 V</b>
<b>OPUS 45</b>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17203291 <b>FI 1286 V</b>
<b>OPUS 45 FROM SERIES No. F0502976</b>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17211103 <b>FO 0030 V</b>
<b>OPUS 55</b>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17203291 <b>FI 1286 V</b>
<b>OPUS 55 FROM SERIES No. F0502976</b>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17211103 <b>FO 0030 V</b>
<b>OPUS 75</b>	17258111 <b>FD 3031 V</b>	17208790 <b>FA 2035</b>		17211103 <b>FO 0030 V</b>
<b>OPUS 90</b>	17258111 <b>FD 3031 V</b>	17208790 <b>FA 2035</b>		17211103 <b>FO 0030 V</b>
<b>SCD 10</b>	17251004 <b>FD 3034 V</b>	17200210		17200221 <b>FO 0845 V</b>
<b>SCD 15</b>	17251001 <b>FD 3096 V</b>	17200210		17200221 <b>FO 0845 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ALUP</b>				
<i>SCD 20</i>				
<i>SCD 20</i>	17211102 <b>FD 3373 V</b>	17200210		17200222 <b>FI 1288 V</b>
<i>SCD 25</i>	17211102 <b>FD 3373 V</b>	17200210		17200222 <b>FI 1288 V</b>
<i>SCD 30</i>	17211102 <b>FD 3373 V</b>	17200210		17200222 <b>FI 1288 V</b>
<i>SCD 5</i>	17251004 <b>FD 3034 V</b>	17200210		17200221 <b>FO 0845 V</b>
<i>SCD 8</i>	17251004 <b>FD 3034 V</b>	17200210		17200221 <b>FO 0845 V</b>
<i>SCG 100</i>	21203292 <b>FD 3042</b>	17203293 <b>FA 1252</b>		
<i>SCG 120</i>	21203292 <b>FD 3042</b>	17203293 <b>FA 1252</b>		
<i>SCG 150</i>	21203378	17203293 <b>FA 1252</b>		
<i>SCG 150 FROM SERIES No. 211172</i>	21203378	17203880 <b>FA 1302</b>		
<i>SCG 180</i>	21203292 <b>FD 3042</b>	17203293 <b>FA 1252</b>		
<i>SCG 181</i>	17203382 <b>FD 3635</b>	17203880 <b>FA 1302</b>		17213145 <b>FI 1099 V</b>
<i>SCG 220</i>	21203292 <b>FD 3042</b>	17203293 <b>FA 1252</b>		
<i>SCG 221</i>	17203382 <b>FD 3635</b>	17203880 <b>FA 1302</b>		17213145 <b>FI 1099 V</b>
<i>SCG 270</i>	21203292 <b>FD 3042</b>	17203294		
<i>SCG 271</i>		17233920 <b>FA 1556</b>		17213145 <b>FI 1099 V</b>
<i>SCG 550</i>	21203292 <b>FD 3042</b>	17203880 <b>FA 1302</b>		
<i>SCG 60</i>	21203391 <b>FD 3064</b>	17204120 <b>FA 1105</b>		
<i>SCG 75</i>	21203391 <b>FD 3064</b>	17204120 <b>FA 1105</b>		
<i>SCG 75/128</i>	21203292 <b>FD 3042</b>	17203293 <b>FA 1252</b>		
<i>SCK 10</i>	17251004 <b>FD 3034 V</b>	17207785 <b>FA 2056</b>		17200221 <b>FO 0845 V</b>
<i>SCK 10 FROM SERIES No. 260000</i>	17251004 <b>FD 3034 V</b>	17208788 <b>FA 2033</b>		17200221 <b>FO 0845 V</b>
<i>SCK 10 FROM SERIES No. 271800</i>	17251002 <b>FD 3597</b>	17208788 <b>FA 2033</b>		17200221 <b>FO 0845 V</b>
<i>SCK 10 UP TO SERIES No. 259999</i>	17251004 <b>FD 3034 V</b>	17207785 <b>FA 2056</b>		17200221 <b>FO 0845 V</b>
<i>SCK 101</i>	17258111 <b>FD 3031 V</b>	17201201 <b>FA 1783</b>		17211103 <b>FO 0030 V</b>
<i>SCK 102</i>	17258111 <b>FD 3031 V</b>	17207786 <b>FA 5504</b>		17203291 <b>FI 1286 V</b>
<i>SCK 102 FROM SERIES No. 215000</i>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17203291 <b>FI 1286 V</b>
<i>SCK 102 FROM SERIES No. F0502976</i>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17211103 <b>FO 0030 V</b>





	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ALUP</b> <i>SCK 102 UP TO SERIES No. 214999</i>				
<i>SCK 102 UP TO SERIES No. 214999</i>	17258111 <b>FD 3031 V</b>	17202550 <b>FA 1714</b>		17203291 <b>FI 1286 V</b>
<i>SCK 121</i>	17258111 <b>FD 3031 V</b>	17201201 <b>FA 1783</b>		17211103 <b>FO 0030 V</b>
<i>SCK 131</i>	17258111 <b>FD 3031 V</b>	17201201 <b>FA 1783</b>		17211103 <b>FO 0030 V</b>
<i>SCK 15</i>	17251001 <b>FD 3096 V</b>	17207785 <b>FA 2056</b>		17200221 <b>FO 0845 V</b>
<i>SCK 15 FROM SERIES No. 260000</i>	17251001 <b>FD 3096 V</b>	17208788 <b>FA 2033</b>		17200221 <b>FO 0845 V</b>
<i>SCK 15 FROM SERIES No. 271800</i>	17251002 <b>FD 3597</b>	17208788 <b>FA 2033</b>		17200221 <b>FO 0845 V</b>
<i>SCK 15 UP TO SERIES No. 259999</i>	17251001 <b>FD 3096 V</b>	17207785 <b>FA 2056</b>		17200221 <b>FO 0845 V</b>
<i>SCK 151</i>	17258111 <b>FD 3031 V</b>	17201210 <b>FA 2049</b>		17211103 <b>FO 0030 V</b>
<i>SCK 15-10</i>	17251001 <b>FD 3096 V</b>	17208785 <b>FA 2027</b>		17200221 <b>FO 0845 V</b>
<i>SCK 181</i>	17258111 <b>FD 3031 V</b>	17208790 <b>FA 2035</b>		17211103 <b>FO 0030 V</b>
<i>SCK 182</i>	17203382 <b>FD 3635</b>	17307730 <b>FA 5573</b>		17213145 <b>FI 1099 V</b>
<i>SCK 21</i>	17211102 <b>FD 3373 V</b>	17207787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>SCK 21 FROM SERIES No. 260000</i>	17211102 <b>FD 3373 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>SCK 21 FROM SERIES No. 281500</i>	17211105 <b>FD 3611 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>SCK 21 UP TO SERIES No. 259999</i>	17211102 <b>FD 3373 V</b>	17207797 <b>FA 5504</b>		17200222 <b>FI 1288 V</b>
<i>SCK 22</i>	17251001 <b>FD 3096 V</b>	17207785 <b>FA 2056</b>		17200221 <b>FO 0845 V</b>
<i>SCK 22 FROM SERIES No. 260000</i>	17251001 <b>FD 3096 V</b>	17208788 <b>FA 2033</b>		17200221 <b>FO 0845 V</b>
<i>SCK 22 FROM SERIES No. 280000</i>	17251002 <b>FD 3597</b>	17208787 <b>FA 1981/1</b>		17200221 <b>FO 0845 V</b>
<i>SCK 22 UP TO SERIES No. 259999</i>	17251001 <b>FD 3096 V</b>	17207785 <b>FA 2056</b>		17200221 <b>FO 0845 V</b>
<i>SCK 221 FROM 2003</i>	17203383 <b>FD 3635</b>	17208790 <b>FA 2035</b>		17213145 <b>FI 1099 V</b>
<i>SCK 221 UP TO SERIES No. 217762</i>	17203382 <b>FD 3635</b>	17208790 <b>FA 2035</b>		17213145 <b>FI 1099 V</b>
<i>SCK 25</i>	21200201 <b>FD 3032</b>	17202550 <b>FA 1714</b>		
<i>SCK 26</i>	17211102 <b>FD 3373 V</b>	17207787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>SCK 26 FROM SERIES No. 281500</i>	17211105 <b>FD 3611 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>SCK 26 UP TO SERIES No. 259999</i>	17211102 <b>FD 3373 V</b>	17207797 <b>FA 5504</b>		17200222 <b>FI 1288 V</b>
<i>SCK 271 FROM SERIES No. 217763</i>	17203382 <b>FD 3635</b>	17307730 <b>FA 5573</b>		17213145 <b>FI 1099 V</b>
<i>SCK 271 UP TO SERIES No. 217762</i>	17203382 <b>FD 3635</b>	17208790 <b>FA 2035</b>		17213145 <b>FI 1099 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ALUP</b>				
<i>SCK 272</i>				
<i>SCK 272</i>	17203382 <b>FD 3635</b>	17307730 <b>FA 5573</b>		17213145 <b>FI 1099 V</b>
<i>SCK 30</i>	21200201 <b>FD 3032</b>	17202550 <b>FA 1714</b>		17203291 <b>FI 1286 V</b>
<i>SCK 31</i>	17211102 <b>FD 3373 V</b>	17207787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>SCK 31 FROM SERIES No. 281500</i>	17211105 <b>FD 3611 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>SCK 31 UP TO SERIES No. 259999</i>	17211102 <b>FD 3373 V</b>	17207797 <b>FA 5504</b>		17200222 <b>FI 1288 V</b>
<i>SCK 40</i>	21203391 <b>FD 3064</b>	17202550 <b>FA 1714</b>		
<i>SCK 41</i>	17258111 <b>FD 3031 V</b>	17202550 <b>FA 1714</b>		17203291 <b>FI 1286 V</b>
<i>SCK 41 UP TO SERIES No. 214999</i>	17258111 <b>FD 3031 V</b>	17202550 <b>FA 1714</b>		17203291 <b>FI 1286 V</b>
<i>SCK 42</i>	17258111 <b>FD 3031 V</b>	17207787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>SCK 42 FROM SERIES No. 260000</i>	17258111 <b>FD 3031 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>SCK 42 FROM SERIES No. 281500</i>	17258112 <b>FD 3031 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>SCK 42 UP TO SERIES No. 259999</i>	17258111 <b>FD 3031 V</b>	17207797 <b>FA 5504</b>		17200222 <b>FI 1288 V</b>
<i>SCK 5</i>	17251004 <b>FD 3034 V</b>	17207785 <b>FA 2056</b>		17200221 <b>FO 0845 V</b>
<i>SCK 5 FROM SERIES No. 260000</i>	17251004 <b>FD 3034 V</b>	17208788 <b>FA 2033</b>		17200221 <b>FO 0845 V</b>
<i>SCK 5 FROM SERIES No. 271800</i>	17251002 <b>FD 3597</b>	17208788 <b>FA 2033</b>		17200221 <b>FO 0845 V</b>
<i>SCK 5 NEW</i>	17251001 <b>FD 3096 V</b>	17207788 <b>FA 5507</b>		17200221 <b>FO 0845 V</b>
<i>SCK 5 UP TO SERIES No. 259999</i>	17251004 <b>FD 3034 V</b>	17207785 <b>FA 2056</b>		17200221 <b>FO 0845 V</b>
<i>SCK 50</i>	21203391 <b>FD 3064</b>	17202550 <b>FA 1714</b>		
<i>SCK 51</i>	17258111 <b>FD 3031 V</b>	17202550 <b>FA 1714</b>		17203291 <b>FI 1286 V</b>
<i>SCK 51 FROM SERIES No. 215000</i>	17258111 <b>FD 3031 V</b>	17208787 <b>FA 1981/1</b>		17203291 <b>FI 1286 V</b>
<i>SCK 51 FROM SERIES No. 217576</i>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17203291 <b>FI 1286 V</b>
<i>SCK 51 UP TO SERIES No. 214999</i>	17258111 <b>FD 3031 V</b>	17202550 <b>FA 1714</b>		17203291 <b>FI 1286 V</b>
<i>SCK 52</i>	17258111 <b>FD 3031 V</b>	17207787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>SCK 52 FROM SERIES No. 218000</i>	17258112 <b>FD 3031 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>SCK 52 FROM SERIES No. 260000</i>	17258111 <b>FD 3031 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>SCK 52 UP TO SERIES No. 259999</i>	17258111 <b>FD 3031 V</b>	17207797 <b>FA 5504</b>		17200222 <b>FI 1288 V</b>
<i>SCK 61</i>	17211102 <b>FD 3373 V</b>	17202550 <b>FA 1714</b>		17203291 <b>FI 1286 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ALUP</b>				
<i>SCK 61 FROM SERIES No. 215000</i>				
<i>SCK 61 FROM SERIES No. 215000</i>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17203291 <b>FI 1286 V</b>
<i>SCK 61 FROM SERIES No. F0502976</i>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17211103 <b>FO 0030 V</b>
<i>SCK 61 UP TO SERIES No. 214999</i>	17258111 <b>FD 3031 V</b>	17202550 <b>FA 1714</b>		17203291 <b>FI 1286 V</b>
<i>SCK 75/128</i>	21203292 <b>FD 3042</b>	17203293 <b>FA 1252</b>		
<i>SCK 76</i>	17211102 <b>FD 3373 V</b>	17202550 <b>FA 1714</b>		17203291 <b>FI 1286 V</b>
<i>SCK 76 FROM SERIES No. 215000</i>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17203291 <b>FI 1286 V</b>
<i>SCK 76 FROM SERIES No. F0502976</i>	17258111 <b>FD 3031 V</b>	17208786 <b>FA 2030</b>		17211103 <b>FO 0030 V</b>
<i>SCK 76 UP TO SERIES No. 214999</i>	17258111 <b>FD 3031 V</b>	17202550 <b>FA 1714</b>		17203291 <b>FI 1286 V</b>
<i>SCK 8</i>	17251004 <b>FD 3034 V</b>	17200210		17200221 <b>FO 0845 V</b>
<i>SCK 8 FROM SERIES No. 260000</i>	17251002 <b>FD 3597</b>	17208788 <b>FA 2033</b>		17200221 <b>FO 0845 V</b>
<i>SCK 8 FROM SERIES No. F0606343</i>	17251002 <b>FD 3597</b>	17208789 <b>FA 2034</b>		17200221 <b>FO 0845 V</b>
<i>SCR 10</i>	21200531 <b>FD 3059</b>	17200210		
<i>SCR 100</i>	21203292 <b>FD 3042</b>	17203293 <b>FA 1252</b>		
<i>SCR 120</i>	21203292 <b>FD 3042</b>	17203293 <b>FA 1252</b>		
<i>SCR 15</i>	21200109 <b>FD 3432</b>	17200218		
<i>SCR 20 UP TO SERIES No. 210001</i>	21200110 <b>FD 3062</b>	17200218		
<i>SCR 25</i>	21200201 <b>FD 3032</b>	17202550 <b>FA 1714</b>		
<i>SCR 25 UP TO SERIES No. 210137</i>	21200110 <b>FD 3062</b>	17201530 <b>FA 1230</b>		
<i>SCR 30</i>	21200201 <b>FD 3032</b>	17202550 <b>FA 1714</b>		
<i>SCR 30 UP TO SERIES No. 210147</i>	21200110 <b>FD 3062</b>	17201530 <b>FA 1230</b>		
<i>SCR 40</i>	21203391 <b>FD 3064</b>	17202550 <b>FA 1714</b>		
<i>SCR 40 UP TO SERIES No. 187798</i>	21203391 <b>FD 3064</b>	17200001 <b>FA 1220</b>		
<i>SCR 40 UP TO SERIES No. 200267</i>	21203391 <b>FD 3064</b>	17204120 <b>FA 1105</b>		
<i>SCR 50</i>	21203391 <b>FD 3064</b>	17202550 <b>FA 1714</b>		
<i>SCR 50 UP TO SERIES No. 188011</i>	21203391 <b>FD 3064</b>	17200001 <b>FA 1220</b>		
<i>SCR 50 UP TO SERIES No. 200262</i>	21203391 <b>FD 3064</b>	17204120 <b>FA 1105</b>		
<i>SCR 60</i>	21203391 <b>FD 3064</b>	17204120 <b>FA 1105</b>		



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ALUP</b>				
<i>SCR 75</i>				
<i>SCR 75</i>	21203391 <b>FD 3064</b>	17204120 <b>FA 1105</b>		
<i>SCR 75/128</i>	21203292 <b>FD 3042</b>	17203293 <b>FA 1252</b>		
<i>SCR 8</i>	21200531 <b>FD 3059</b>	17200210		
<i>SOLO 11</i>	17251002 <b>FD 3597</b>	17208789 <b>FA 2034</b>		17200221 <b>FO 0845 V</b>
<i>SOLO 15</i>	17251002 <b>FD 3597</b>	17208789 <b>FA 2034</b>		17200221 <b>FO 0845 V</b>
<i>SOLO 16 FROM SERIES No. F0701435</i>	17211105 <b>FD 3611 V</b>	17208788 <b>FA 2033</b>		17200222 <b>FI 1288 V</b>
<i>SOLO 16 UP TO SERIES No. F0701434</i>	17211105 <b>FD 3611 V</b>	17208787 <b>FA 1981/1</b>		17200221 <b>FO 0845 V</b>
<i>SOLO 18 FROM SERIES No. F0701435</i>	17211105 <b>FD 3611 V</b>	17208788 <b>FA 2033</b>		17200222 <b>FI 1288 V</b>
<i>SOLO 18 UP TO SERIES No. F0701434</i>	17211105 <b>FD 3611 V</b>	17208787 <b>FA 1981/1</b>		17200221 <b>FO 0845 V</b>
<i>SOLO 22</i>	17258112 <b>FD 3611 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>SOLO 30</i>	17258112 <b>FD 3611 V</b>	17208787 <b>FA 1981/1</b>		17200222 <b>FI 1288 V</b>
<i>SOLO 6</i>	17251002 <b>FD 3597</b>	17208789 <b>FA 2034</b>		17200221 <b>FO 0845 V</b>
<i>SOLO 7</i>	17251002 <b>FD 3597</b>	17208789 <b>FA 2034</b>		17200221 <b>FO 0845 V</b>
<i>VARIO 15</i>	9057425 <b>FD 3096 V</b>	9057419 <b>FA 2843</b>		9057423 <b>FI 1268 V</b>
<i>VARIO 18</i>	9057426 <b>FD 3373 V</b>	9657421 <b>FA 5001</b>		9057423 <b>FI 1268 V</b>
<i>VARIO 22</i>	9057426 <b>FD 3373 V</b>	9657421 <b>FA 5001</b>		9057423 <b>FI 1268 V</b>
<b>ATLAS COPCO</b>				
<i>GA 10</i>	1513005800 <b>FD 3014</b>	1503019000 <b>FA 2003</b>		1513033700 <b>FO 0029 V</b>
<i>GA 10 FROM 1998 FROM SERIES No. 119500</i>	1613901400 <b>FD 3015</b>	1613900100 <b>FA 1933</b>		1613610500 <b>FO 0148 V</b>
<i>GA 10 FROM SERIES No. 145000</i>	2901052300 <b>FD 3015</b>	1613900100 <b>FA 1933</b>		2903033700 <b>FO 0029 V</b>
<i>GA 100</i>	1612386900 <b>FD 3016</b>	1619126900 <b>FA 1231</b>		1613610500 <b>FO 0148 V</b>
<i>GA 11</i>	1612386900 <b>FD 3016</b>	1619126900 <b>FA 1231</b>		1613610500 <b>FO 0148 V</b>
<i>GA 11 C</i>	1613750200 <b>FD 3353</b>	1613900100 <b>FA 1933</b>		1613610500 <b>FO 0148 V</b>
<i>GA 11 C FROM SERIES No. 119500</i>	1613901400 <b>FD 3015</b>	1613900100 <b>FA 1933</b>		1613610500 <b>FO 0148 V</b>
<i>GA 11 C FROM SERIES No. 145000</i>	2903087100 <b>FD 3096 V</b>	1613900100 <b>FA 1933</b>		1513033700 <b>FO 0029 V</b>
<i>GA 11 C FROM SERIES No. 255000</i>	1622007900 <b>FD 3562</b>	1613872000 <b>FA 2050</b>		1613610500 <b>FO 0148 V</b>
<i>GA 11 C FROM SERIES No. 268500</i>	1622051600 <b>FD 3593</b>	1613872000 <b>FA 2050</b>		1613610500 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATLAS COPCO</b>				
<i>GA 11 FROM 1993</i>				
<i>GA 11 FROM 1993</i>	1613692100 <b>FD 3017</b>	1619126900 <b>FA 1231</b>		1613610500 <b>FO 0148 V</b>
<i>GA 11 FROM 1995 FROM SERIES No. 217792</i>	1613750200 <b>FD 3353</b>	1619126900 <b>FA 1231</b>		1613610500 <b>FO 0148 V</b>
<i>GA 11 FROM 2000</i>	1622007900 <b>FD 3562</b>	1613872000 <b>FA 2050</b>		1613610500 <b>FO 0148 V</b>
<i>GA 11 FROM OCT. 1994 UP TO SERIES No. 217791</i>	1613692100 <b>FD 3017</b>	1619126900 <b>FA 1231</b>		1613610500 <b>FO 0148 V</b>
<i>GA 11 FROM SERIES No. 217792</i>		2903101200 <b>FA 1230</b>		
<i>GA 11 FROM SERIES No. 246349</i>	1613750200 <b>FD 3353</b>	1613872000 <b>FA 2050</b>		1613610500 <b>FO 0148 V</b>
<i>GA 110</i>	1614642300 <b>FD 3029</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<i>GA 110 FROM 1999</i>		1619378400 <b>FA 1758</b>		
<i>GA 110 FROM 1999 SERIES No. 056813</i>	1614905400 <b>FD 3609</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<i>GA 110 FROM SERIES No. 056813</i>		1621054700 <b>FA 1758</b>		
<i>GA 1107</i>	2252631300 <b>FD 3028</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<i>GA 1108</i>	2252631300 <b>FD 3028</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<i>GA 111</i>	1612386900 <b>FD 3016</b>	1619126900 <b>FA 1231</b>		1613610500 <b>FO 0148 V</b>
<i>GA 1110</i>	2252631300 <b>FD 3028</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<i>GA 115</i>	1612386900 <b>FD 3016</b>	1619126900 <b>FA 1231</b>		1613610500 <b>FO 0148 V</b>
<i>GA 118</i>	1612386900 <b>FD 3016</b>	1619126900 <b>FA 1231</b>		1613610500 <b>FO 0148 V</b>
<i>GA 1207</i>	2252631300 <b>FD 3028</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<i>GA 1208</i>	2252631300 <b>FD 3028</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<i>GA 1210</i>	2252631300 <b>FD 3028</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<i>GA 122</i>	1612386900 <b>FD 3016</b>	1619126900 <b>FA 1231</b>		1613610500 <b>FO 0148 V</b>
<i>GA 1308</i>	2252631300 <b>FD 3028</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<i>GA 132</i>	1614642300 <b>FD 3029</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<i>GA 132 from 07/2004</i>	1621938500 <b>FD 3681</b>	1621574200 <b>FA 1758</b>		1613610500 <b>FO 0148 V (X3 pcs.)</b>
<i>GA 132 FROM 1999</i>	1614905600 <b>FD 3639</b>			
<i>GA 132 FROM 1999 SERIES No. 056813</i>	1614905600 <b>FD 3639</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<i>GA 132 FROM 2006</i>	2906075200 <b>FD 3681</b>			
<i>GA 1407</i>	2252631300 <b>FD 3028</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATLAS COPCO</b>				
<i>GA 1408</i>				
<i>GA 1408</i>	2252631300	1030097900		1613610500
	<b>FD 3028</b>	<b>FA 1260</b>		<b>FO 0148 V</b>
<i>GA 1410</i>	2252631300	1030097900		1613610500
	<b>FD 3028</b>	<b>FA 1260</b>		<b>FO 0148 V</b>
<i>GA 15</i>	1612386900	1619126900		1613610500
	<b>FD 3016</b>	<b>FA 1231</b>		<b>FO 0148 V</b>
<i>GA 15 C FROM SERIES No. 255000</i>	1622007900	1613872000		1613610500
	<b>FD 3562</b>	<b>FA 2050</b>		<b>FO 0148 V</b>
<i>GA 15 C FROM SERIES No. 268500</i>	1622051600	1613872000		1613610500
	<b>FD 3593</b>	<b>FA 2050</b>		<b>FO 0148 V</b>
<i>GA 15 FROM 1993</i>	1613692100	1619126900		1613610500
	<b>FD 3017</b>	<b>FA 1231</b>		<b>FO 0148 V</b>
<i>GA 15 FROM 1995</i>	1613750200	1619126900		1613610500
	<b>FD 3353</b>	<b>FA 1231</b>		<b>FO 0148 V</b>
<i>GA 15 FROM 2000</i>	1622007900	1613872000		1613610500
	<b>FD 3562</b>	<b>FA 2050</b>		<b>FO 0148 V</b>
<i>GA 15 FROM OCT. 1994 UP TO SERIES No. 217791</i>	1613692100	1619126900		1613610500
	<b>FD 3017</b>	<b>FA 1231</b>		<b>FO 0148 V</b>
<i>GA 15 FROM SERIES No. 217792</i>	1613750200	1619126900		1613610500
	<b>FD 3353</b>	<b>FA 1231</b>		<b>FO 0148 V</b>
<i>GA 15 FROM SERIES No. 246349</i>	1613750200	1613872000		1613610500
	<b>FD 3353</b>	<b>FA 2050</b>		<b>FO 0148 V</b>
<i>GA 160</i>	1614642300	1030097900		1613610500
	<b>FD 3029</b>	<b>FA 1260</b>		<b>FO 0148 V</b>
<i>GA 160 from 07/2004</i>	1621938500	1621574200		1613610500
	<b>FD 3681</b>	<b>FA 1758</b>		<b>FO 0148 V (X3 pcs.)</b>
<i>GA 160 FROM 1999 SERIES No. 056813</i>	1614905600	1030097900		1613610500
	<b>FD 3639</b>	<b>FA 1260</b>		<b>FO 0148 V</b>
<i>GA 160 FROM 2006</i>	2906075200	1621574299		1613610500
	<b>FD 3681</b>	<b>FA 1758</b>		<b>FO 0148 V</b>
<i>GA 18</i>	1612386900	1619126900		1613610500
	<b>FD 3016</b>	<b>FA 1231</b>		<b>FO 0148 V</b>
<i>GA 18 C FROM SERIES No. 255000</i>	1622007900	1613872000		1613610500
	<b>FD 3562</b>	<b>FA 2050</b>		<b>FO 0148 V</b>
<i>GA 18 C FROM SERIES No. 268500</i>	1622051600	1613872000		1613610500
	<b>FD 3593</b>	<b>FA 2050</b>		<b>FO 0148 V</b>
<i>GA 18 FROM 1993</i>	1613692100	1619126900		1613610500
	<b>FD 3017</b>	<b>FA 1231</b>		<b>FO 0148 V</b>
<i>GA 18 FROM 1995</i>	1613750200	1619126900		1613610500
	<b>FD 3353</b>	<b>FA 1231</b>		<b>FO 0148 V</b>
<i>GA 18 FROM 1995 SERIES No. 217792</i>	1613750200	1619126900		1613610500
	<b>FD 3353</b>	<b>FA 1231</b>		<b>FO 0148 V</b>
<i>GA 18 FROM 2000</i>	1622007900	1613872000		1613610500
	<b>FD 3562</b>	<b>FA 2050</b>		<b>FO 0148 V</b>
<i>GA 18 FROM OCT. 1994 UP TO SERIES No. 217791</i>	1613692100	1619126900		1613610500
	<b>FD 3017</b>	<b>FA 1231</b>		<b>FO 0148 V</b>
<i>GA 18 FROM SERIES No. 246349</i>	1613750200	1613872000		1613610500
	<b>FD 3353</b>	<b>FA 2050</b>		<b>FO 0148 V</b>
<i>GA 18 VSD</i>	2901077901	1613872000		1613610500
	<b>FD 3593</b>	<b>FA 2050</b>		<b>FO 0148 V</b>
<i>GA 180 FROM 2006 VSD</i>	2906075200			
	<b>FD 3681</b>			
<i>GA 180 VSD</i>	1614905600	1030097900		1613610500
	<b>FD 3639</b>	<b>FA 1260</b>		<b>FO 0148 V</b>

	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATLAS COPCO</b>				
<i>GA 200</i>				
<i>GA 200</i>	1614704800 <b>FD 3362</b>	1030097900 <b>FA 1260</b>		1614727300 <b>FO 0030 V</b>
<i>GA 200 FROM 1999</i>	1614905600 <b>FD 3639</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<i>GA 200 FROM 2000</i>	1614952100 <b>FD 3573</b>	1621054700 <b>FA 1758</b>		1614727300 <b>FO 0030 V</b>
<i>GA 200 FROM 2006</i>	2906075300 <b>FD 3680</b>			
<i>GA 207</i>	1613243300 <b>FD 3527</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 208</i>	1613243300 <b>FD 3527</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 210</i>	1613243300 <b>FD 3527</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 22</i>	1612386900 <b>FD 3016</b>	1619126900 <b>FA 1231</b>		1613610500 <b>FO 0148 V</b>
<i>GA 22 C FROM SERIES No. 255000</i>	1622007900 <b>FD 3562</b>	1613872000 <b>FA 2050</b>		1613610500 <b>FO 0148 V</b>
<i>GA 22 C FROM SERIES No. 268500</i>	1622051600 <b>FD 3593</b>	1613872000 <b>FA 2050</b>		1613610500 <b>FO 0148 V</b>
<i>GA 22 FROM 1993</i>	1613692100 <b>FD 3017</b>	1619126900 <b>FA 1231</b>		1613610500 <b>FO 0148 V</b>
<i>GA 22 FROM 1995 SERIES No. 217792</i>	1613750200 <b>FD 3353</b>	1619126900 <b>FA 1231</b>		1613610500 <b>FO 0148 V</b>
<i>GA 22 FROM 2000</i>	1622007900 <b>FD 3562</b>	1613872000 <b>FA 2050</b>		1613610500 <b>FO 0148 V</b>
<i>GA 22 FROM OCT. 1994 UP TO SERIES No. 217791</i>	1613692100 <b>FD 3017</b>	1619126900 <b>FA 1231</b>		1613610500 <b>FO 0148 V</b>
<i>GA 22 FROM SERIES No. 246349</i>	1613750200 <b>FD 3353</b>	1613872000 <b>FA 2050</b>		1613610500 <b>FO 0148 V</b>
<i>GA 230</i>	1614532900 <b>FD 3019</b>	1619299700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>GA 237</i>	1614532900 <b>FD 3019</b>	1619299700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>GA 250</i>	1614704800 <b>FD 3362</b>	1030097900 <b>FA 1260</b>		1614727300 <b>FO 0030 V</b>
<i>GA 30</i>	1202641400 <b>FD 3020</b>	1619299700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>GA 30 C FROM 2000</i>	1622007900 <b>FD 3562</b>	1613872000 <b>FA 2050</b>		1613610500 <b>FO 0148 V</b>
<i>GA 30 C FROM SERIES No. 255000</i>	1622007900 <b>FD 3562</b>	1613872000 <b>FA 2050</b>		1613610500 <b>FO 0148 V</b>
<i>GA 30 C FROM SERIES No. 268500</i>	1622051600 <b>FD 3593</b>	1613872000 <b>FA 2050</b>		1613610500 <b>FO 0148 V</b>
<i>GA 30 FROM 1994</i>	1613688000 <b>FD 3021</b>	1613740700 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>GA 30 FROM 1994 UP TO SERIES No. 315329</i>	1613688000 <b>FD 3021</b>	1619299700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>GA 30 FROM 1998 SERIES No. AII 360000</i>	1613839700 <b>FD 3022</b>	1613740700 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>GA 30 FROM SERIES No. 315330</i>	1613688000 <b>FD 3021</b>	1613740700 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>GA 30 PLUS FROM SERIES No. API 507438</i>	1622314000 <b>FD 3580</b>	1613740800 <b>FA 5500</b>		1622314280



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATLAS COPCO</b>				
<i>GA 30 VSD</i>				
<i>GA 30 VSD</i>	1613750200 <b>FD 3353</b>	1613740700 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>GA 300</i>	1202834300 <b>FD 3031 V</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>GA 307</i>	1613243300 <b>FD 3527</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 308</i>	1613243300 <b>FD 3527</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 310</i>	1613243300 <b>FD 3527</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 315</i>	1614704800 <b>FD 3362</b>	1030097900 <b>FA 1260</b>		1614727300 <b>FO 0030 V</b>
<i>GA 315 FROM 2000</i>	1614952100 <b>FD 3573</b>	1621054700 <b>FA 1758</b>		1614727300 <b>FO 0030 V</b>
<i>GA 315 VSD</i>	1614952100 <b>FD 3573</b>			
<i>GA 315 VSD FROM 2006</i>	2906075300 <b>FD 3680</b>			
<i>GA 345</i>	1202834300 <b>FD 3031 V</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>GA 355</i>	1202834300 <b>FD 3031 V</b>	1619279800 <b>FA 1252</b>		1613610500 <b>FO 0148 V</b>
<i>GA 37</i>	1202641400 <b>FD 3020</b>	1619299700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>GA 37 FROM 1994</i>	1613688000 <b>FD 3021</b>	1613740700 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>GA 37 FROM 1994 UP TO SERIES No. 315329</i>	1613688000 <b>FD 3021</b>	1619299700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>GA 37 FROM 1998 SERIES No. All 360000</i>	1613839700 <b>FD 3022</b>	1613740700 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>GA 37 FROM SERIES No. 315330</i>	1613688000 <b>FD 3021</b>	1613740700 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>GA 37 PLUS FROM SERIES No. API 507438</i>	1622314000 <b>FD 3580</b>	1613740800 <b>FA 5500</b>		1622314280
<i>GA 37 VSD</i>	1613839701	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 37/7.5 BAR FROM SERIES No. 360000</i>	1613839700 <b>FD 3022</b>	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 37-10</i>	1613839701	1613740700 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>GA 37-13</i>	1613839701	1613740700 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>GA 375</i>	1202834300 <b>FD 3031 V</b>	1619279800 <b>FA 1252</b>		1613610500 <b>FO 0148 V</b>
<i>GA 407</i>	1613243300 <b>FD 3527</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 408</i>	1613243300 <b>FD 3527</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 410</i>	1613243300 <b>FD 3527</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 45</i>	1202741900 <b>FD 3023</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>GA 45 FROM 1994</i>	1613688000 <b>FD 3021</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>





	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATLAS COPCO</b>				
<i>GA 45 FROM 1994 UP TO SERIES No. 315329</i>				
<i>GA 45 FROM 1994 UP TO SERIES No. 315329</i>	1613688000 <b>FD 3021</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>GA 45 FROM 1995</i>	1613730600 <b>FD 3023</b>	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 45 FROM 1998 SERIES No. AII 360000</i>	1613839700 <b>FD 3022</b>	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 45 FROM SERIES No. 315330</i>	1613688000 <b>FD 3021</b>	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 45 FROM SERIES No. 360000</i>	2901056600 <b>FD 3022</b>	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 45 PLUS FROM SERIES No. API 507438</i>	1622314000 <b>FD 3580</b>	1613740800 <b>FA 5500</b>		1622314280
<i>GA 450</i>	1614952100 <b>FD 3573</b>			
<i>GA 450 FROM 2006</i>	2906075300 <b>FD 3680</b>			
<i>GA 45-10</i>	1613839701	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 45-13</i>	1613839701	1613740700 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>GA 45-7.5</i>	1613839701	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 5</i>	1513005800 <b>FD 3014</b>	1503019000 <b>FA 2003</b>		1513033700 <b>FO 0029 V</b>
<i>GA 5 C FROM SERIES No. 130000</i>	1613901400 <b>FD 3015</b>	1613900100 <b>FA 1933</b>		1613610500 <b>FO 0148 V</b>
<i>GA 5 C FROM SERIES No. 145000</i>	2903087100 <b>FD 3096 V</b>	1613900100 <b>FA 1933</b>		1513033700 <b>FO 0029 V</b>
<i>GA 5 FROM 1998</i>	1613901400 <b>FD 3015</b>	1613900100 <b>FA 1933</b>		1613610500 <b>FO 0148 V</b>
<i>GA 5 FROM 1998 SERIES No. 119500</i>	1613901400 <b>FD 3015</b>	1613900100 <b>FA 1933</b>		1613610500 <b>FO 0148 V</b>
<i>GA 5 FROM SERIES No. 119500</i>	2901052300 <b>FD 3015</b>	1613900100 <b>FA 1933</b>		1613610500 <b>FO 0148 V</b>
<i>GA 5 FROM SERIES No. 145000</i>	2901052300 <b>FD 3015</b>	1613900100 <b>FA 1933</b>		2903033700 <b>FO 0029 V</b>
<i>GA 50 FROM 1998 SERIES No. 350000</i>	2901056600 <b>FD 3022</b>	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 50 FROM 1998 SERIES No. AII 350000</i>	1613839700 <b>FD 3022</b>	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 50 VSD</i>	1613839700 <b>FD 3022</b>	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 507</i>	1613243300 <b>FD 3527</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 508</i>	1613243300 <b>FD 3527</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 510</i>	1613243300 <b>FD 3527</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 55</i>	1202741900 <b>FD 3023</b>	1619279800 <b>FA 1252</b>		1613610500 <b>FO 0148 V</b>
<i>GA 55 C</i>	1613800700 <b>FD 3025</b>	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 55 C FROM SERIES No. 471000</i>	1613955900 <b>FD 3643</b>	1613950100 <b>FA 5133</b>		1613610500 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATLAS COPCO</b>				
<i>GA 55 FROM 1995</i>				
<i>GA 55 FROM 1995</i>	1613730600 <b>FD 3023</b>	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 55 FROM 1996</i>	1613800700 <b>FD 3025</b>	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 55 FROM 1996 FROM SERIES No. 460001</i>	1613800700 <b>FD 3025</b>	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 55 FROM 2000</i>	1613955900 <b>FD 3643</b>			1613610500 <b>FO 0148 V</b>
<i>GA 55 FROM SERIES No. 460001</i>	2901043200 <b>FD 3025</b>	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 55 FROM SERIES No. API 507438</i>	1622314000 <b>FD 3580</b>	1622185501		1622314280
<i>GA 55 PLUS FROM 2005/05</i>	1622365600 <b>FD 3579</b>	1613950300 <b>FA 5134</b>		1622365200 <b>FO 0990</b>
<i>GA 607</i>	1616283600 <b>FD 3027</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 608</i>	1616283600 <b>FD 3027</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 610</i>	1616283600 <b>FD 3027</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 7</i>	1513005800 <b>FD 3014</b>	1503019000 <b>FA 2003</b>		1513033700 <b>FO 0029 V</b>
<i>GA 7 C FROM SERIES No. 130000</i>	1613901400 <b>FD 3015</b>	1613900100 <b>FA 1933</b>		1613610500 <b>FO 0148 V</b>
<i>GA 7 C FROM SERIES No. 145000</i>	2903087100 <b>FD 3096 V</b>	1613900100 <b>FA 1933</b>		1513033700 <b>FO 0029 V</b>
<i>GA 7 FROM SERIES No. 119500</i>	1613901400 <b>FD 3015</b>	1613900100 <b>FA 1933</b>		1613610500 <b>FO 0148 V</b>
<i>GA 7 FROM SERIES No. 145000</i>	2901052300 <b>FD 3015</b>	1613900100 <b>FA 1933</b>		2903033700 <b>FO 0029 V</b>
<i>GA 707</i>	1616283600 <b>FD 3027</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 708</i>	1616283600 <b>FD 3027</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 710</i>	1616283600 <b>FD 3027</b>	1030107000 <b>FA 1229</b>		1613610500 <b>FO 0148 V</b>
<i>GA 75</i>	1202741900 <b>FD 3023</b>	1613950100 <b>FA 5133</b>		1613610500 <b>FO 0148 V</b>
<i>GA 75 C FROM SERIES No. 474000</i>	1613984000 <b>FD 3576</b>	1613950300 <b>FA 5134</b>		1613610500 <b>FO 0148 V</b>
<i>GA 75 FROM 1995</i>	1613730600 <b>FD 3023</b>	1613740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>GA 75 FROM 1996</i>	1613800700 <b>FD 3025</b>	1613800400 <b>FA 5854</b>		1613610500 <b>FO 0148 V</b>
<i>GA 75 FROM 1996 SERIES No. 460001</i>	1613800700 <b>FD 3025</b>	1613800400 <b>FA 5854</b>		1613610500 <b>FO 0148 V</b>
<i>GA 75 FROM 2000</i>	1613984000 <b>FD 3576</b>	1613950300 <b>FA 5134</b>		1613610500 <b>FO 0148 V</b>
<i>GA 75 FROM SERIES No. 460001</i>	2901043200 <b>FD 3025</b>	1613800400 <b>FA 5854</b>		1613610500 <b>FO 0148 V</b>
<i>GA 75 FROM SERIES No. 471000</i>	2901085800 <b>FD 3576</b>	1613950300 <b>FA 5134</b>		1613610500 <b>FO 0148 V</b>
<i>GA 75 PLUS FROM 2005/05</i>	2901056622 <b>FD 3579</b>	1613950300 <b>FA 5134</b>		1622365200 <b>FO 0990</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATLAS COPCO</b>				
<i>GA 75 VSD</i>				
<b>GA 75 VSD</b>	1613955900 <b>FD 3643</b>	1613950100 <b>FA 5133</b>		1613610500 <b>FO 0148 V</b>
<b>GA 807</b>	2252631300 <b>FD 3028</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<b>GA 808</b>	2252631300 <b>FD 3028</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<b>GA 810</b>	2252631300 <b>FD 3028</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<b>GA 90</b>	1614642300 <b>FD 3029</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<b>GA 90 C</b>	1613800700 <b>FD 3025</b>	1613800400 <b>FA 5854</b>		1613610500 <b>FO 0148 V</b>
<b>GA 90 C FROM SERIES No. 474000</b>	1613984000 <b>FD 3576</b>	1613950300 <b>FA 5134</b>		1613610500 <b>FO 0148 V</b>
<b>GA 90 FROM 1999</b>	1614905400 <b>FD 3609</b>	1619378400 <b>FA 1758</b>		1613610500 <b>FO 0148 V</b>
<b>GA 90 FROM 1999 SERIES No. 056813</b>	1614905400 <b>FD 3609</b>	1030097900 <b>FA 1260</b>		1613610500 <b>FO 0148 V</b>
<b>GA 90 FROM 2005/05</b>	1622365600 <b>FD 3579</b>	1613950300 <b>FA 5134</b>		1622365200 <b>FO 0990</b>
<b>GA 90 FROM SERIES No. 056813</b>	1614905400 <b>FD 3609</b>	1621054700 <b>FA 1758</b>		1613610500 <b>FO 0148 V</b>
<b>GA 90 VSD</b>	1613955900 <b>FD 3643</b>	1613950300 <b>FA 5134</b>		1613610500 <b>FO 0148 V</b>
<b>GAH 115</b>	1612386900 <b>FD 3016</b>	1619126900 <b>FA 1231</b>		1613610500 <b>FO 0148 V</b>
<b>GAH 118</b>	1612386900 <b>FD 3016</b>	1619126900 <b>FA 1231</b>		1613610500 <b>FO 0148 V</b>
<b>GAH 122</b>	1612386900 <b>FD 3016</b>	1619126900 <b>FA 1231</b>		1613610500 <b>FO 0148 V</b>
<b>GN 7.2</b>	1622087100 <b>FD 3096 V</b>	1613900100 <b>FA 1933</b>		2903033700 <b>FO 0029 V</b>
<b>GR 110</b>	2906063800	1621057400 <b>FA 1758</b>		1202804090 <b>FI 1285 V</b>
<b>GR 110 FROM SERIES No. AIF 85972</b>	1621938700	1621057400 <b>FA 1758</b>		1202804090 <b>FI 1285 V</b>
<b>GR 1120</b>	2252631300 <b>FD 3028</b>	1030097900 <b>FA 1260</b>		
<b>GR 132</b>	2906063800	1621057400 <b>FA 1758</b>		1202804090 <b>FI 1285 V</b>
<b>GR 132 FROM SERIES No. AIF 85972</b>	1621938700	1621057400 <b>FA 1758</b>		1202804090 <b>FI 1285 V</b>
<b>GR 1520</b>	2252631300 <b>FD 3028</b>			
<b>GR 160</b>	2906063800	1621057400 <b>FA 1758</b>		1202804090 <b>FI 1285 V</b>
<b>GR 160 FROM SERIES No. AIF 85972</b>	1621938700	1621057400 <b>FA 1758</b>		1202804090 <b>FI 1285 V</b>
<b>GR 200</b>	2906063800	1621057400 <b>FA 1758</b>		1202804090 <b>FI 1285 V</b>
<b>GR 200 FROM SERIES No. AIF 85972</b>	1621938700	1621057400 <b>FA 1758</b>		1202804090 <b>FI 1285 V</b>
<b>GR 620</b>	1613243300 <b>FD 3527</b>	1030107000 <b>FA 1229</b>		



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATLAS COPCO</b> <span style="margin-left: 150px;"><i>GX 11</i></span>				
<b>GX 11</b>	1622024500 <b>FD 3096 V</b>	1613900100 <b>FA 1933</b>		1613610500 <b>FO 0148 V</b>
<b>GX 11 FROM SERIES No. 620000</b>	1622087100 <b>FD 3096 V</b>	1613900100 <b>FA 1933</b>		1613610500 <b>FO 0148 V</b>
<b>GX 11 UP TO SERIES No. 619999</b>	1622087100 <b>FD 3096 V</b>	1613900100 <b>FA 1933</b>		2903033700 <b>FO 0029 V</b>
<b>GX 15</b>	1622035101 <b>FD 3373 V</b>	1613872000 <b>FA 2050</b>		1613610500 <b>FO 0148 V</b>
<b>GX 18</b>	1622035101 <b>FD 3373 V</b>	1613872000 <b>FA 2050</b>		1613610500 <b>FO 0148 V</b>
<b>GX 2</b>	1622062300 <b>FD 3034 V</b>	1622065800 <b>FA 2982</b>		1513033700 <b>FO 0029 V</b>
<b>GX 22</b>	1622035101 <b>FD 3373 V</b>	1613872000 <b>FA 2050</b>		1613610500 <b>FO 0148 V</b>
<b>GX 3</b>	1622062300 <b>FD 3034 V</b>	1622065800 <b>FA 2982</b>		1513033700 <b>FO 0029 V</b>
<b>GX 4</b>	1622062300 <b>FD 3034 V</b>	1622065800 <b>FA 2982</b>		1513033700 <b>FO 0029 V</b>
<b>GX 5</b>	1622024500 <b>FD 3096 V</b>	1613900100 <b>FA 1933</b>		1613610500 <b>FO 0148 V</b>
<b>GX 5 FROM SERIES No. 620000</b>	1622087100 <b>FD 3096 V</b>	1613900100 <b>FA 1933</b>		1613610500 <b>FO 0148 V</b>
<b>GX 5 UP TO SERIES No. 619999</b>	1622087100 <b>FD 3096 V</b>	1613900100 <b>FA 1933</b>		2903033700 <b>FO 0029 V</b>
<b>GX 7</b>	1622024500 <b>FD 3096 V</b>	1613900100 <b>FA 1933</b>		1613610500 <b>FO 0148 V</b>
<b>GX 7 FROM SERIES No. 620000</b>	1622087100 <b>FD 3096 V</b>	1613900100 <b>FA 1933</b>		1613610500 <b>FO 0148 V</b>
<b>GX 7 UP TO SERIES No. 619999</b>	1622087100 <b>FD 3096 V</b>	1613900100 <b>FA 1933</b>		2903033700 <b>FO 0029 V</b>
<b>HRHS 350D</b>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1613610500 <b>FO 0148 V</b>
<b>HRS 210 D</b>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1613610500 <b>FO 0148 V</b>
<b>LE 11</b>		1503019000 <b>FA 2003</b>		
<b>LE 12</b>		1503019000 <b>FA 2003</b>		
<b>LE 9</b>		1503019000 <b>FA 2003</b>		
<b>LT 11</b>		1503019000 <b>FA 2003</b>		
<b>LT 12</b>		1503019000 <b>FA 2003</b>		
<b>LT 9</b>		1503019000 <b>FA 2003</b>		
<b>PTS 1500 D PORTABLE</b>	2252631300 <b>FD 3028</b>	1619279900 <b>FA 1217</b>		1613610500 <b>FO 0148 V</b>
<b>XA 120</b>	1616283600 <b>FD 3027</b>	1619279800 <b>FA 1252</b>		1613610500 <b>FO 0148 V</b>
<b>XA 125</b>	1616465600 <b>FD 3045</b>	1619279800 <b>FA 1252</b>		1613610500 <b>FO 0148 V</b>
<b>XA 125 D</b>	1616465600 <b>FD 3045</b>	1619279900 <b>FA 1217</b>		1613610500 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATLAS COPCO</b>				
<i>XA 160</i>				
<i>XA 160</i>	1616283600 <b>FD 3027</b>	1619279900 <b>FA 1217</b>		1613610500 <b>FO 0148 V</b>
<i>XA 175 D</i>	1616465600 <b>FD 3045</b>	1619279900 <b>FA 1217</b>		1613610500 <b>FO 0148 V</b>
<i>XA 210 D</i>	2252631301 <b>FD 3308</b>	1619279800 <b>FA 1252</b>		1613610500 <b>FO 0148 V</b>
<i>XA 250</i>	1616283600 <b>FD 3027</b>			
<i>XA 30</i>	1619624800 <b>FD 3083</b>	2900059300 <b>FA 1241</b>		1613610500 <b>FO 0148 V</b>
<i>XA 35</i>	1202872200 <b>FD 3010</b>	2900059300 <b>FA 1241</b>		1613610500 <b>FO 0148 V</b>
<i>XA 350</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>		1613610500 <b>FO 0148 V</b>
<i>XA 350 D</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>		1613610500 <b>FO 0148 V</b>
<i>XA 40</i>	1619549800 <b>FD 3084</b>	2900059300 <b>FA 1241</b>		1613610500 <b>FO 0148 V</b>
<i>XA 40 D</i>	1619549800 <b>FD 3084</b>	2900059300 <b>FA 1241</b>		1613610500 <b>FO 0148 V</b>
<i>XA 45</i>	1202872200 <b>FD 3010</b>	2900059300 <b>FA 1241</b>		1613610500 <b>FO 0148 V</b>
<i>XA 50</i>	1619549800 <b>FD 3084</b>	1619279700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>XA 50 D</i>	1619549800 <b>FD 3084</b>	1619279700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>XA 55</i>	1202872200 <b>FD 3010</b>	1619279700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>XA 60</i>	1619549800 <b>FD 3084</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XA 65</i>	1202872200 <b>FD 3010</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XA 70</i>	1202872200 <b>FD 3010</b>			
<i>XA 75</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XA 80</i>	1613243300 <b>FD 3527</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XA 85</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XA 85 D WITH DEUTZ F3L912 ENG.</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XA 85 DDA</i>	1614437300 <b>FD 3087</b>			
<i>XA 90</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XA 90 D WITH DEUTZ F3L912 ENG.</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XAHH 160</i>	1616283600 <b>FD 3027</b>			
<i>XAHS 125</i>	1616465600 <b>FD 3045</b>	1619279900 <b>FA 1217</b>		1613610500 <b>FO 0148 V</b>
<i>XAHS 125 D</i>	1616465600 <b>FD 3045</b>	1619279900 <b>FA 1217</b>		1613610500 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATLAS COPCO</b>				
<i>XAHS 160</i>				
<i>XAHS 160</i>	1616283600 <b>FD 3027</b>			
<i>XAHS 175</i>	1616465600 <b>FD 3045</b>	1619279800 <b>FA 1252</b>		1613610500 <b>FO 0148 V</b>
<i>XAHS 175 DD WITH DEUTZ ENG. MOBILE</i>	1616465600 <b>FD 3045</b>	1619279800 <b>FA 1252</b>		1613610500 <b>FO 0148 V</b>
<i>XAHS 236 MD</i>	2911011200 <b>FD 3586</b>	2914502300 <b>FA 5931</b>		1202804000 <b>FI 1285 V</b>
<i>XAHS 280 D</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	
<i>XAHS 306 MD</i>	2911011500 <b>FD 3586</b>	2914501700 <b>FA 5932/1</b>		1202804000 <b>FI 1285 V</b>
<i>XAHS 350</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	
<i>XAHS 365</i>	1615603800 <b>FD 3357</b>	1619279900 <b>FA 1217</b>	1619569800 <b>FA 1310</b>	1202804000 <b>FI 1285 V</b>
<i>XAHS 416 MD AIB ASL 01</i>	2911011600	2914501700 <b>FA 5932/1</b>		1613610500 <b>FO 0148 V</b>
<i>XAHS 416 MD ASL 03</i>	2911011500 <b>FD 3586</b>	2914501700 <b>FA 5932/1</b>		1202804000 <b>FI 1285 V</b>
<i>XAHS 416 MD ASL 04</i>	2911011500 <b>FD 3586</b>	2914501700 <b>FA 5932/1</b>		1202804000 <b>FI 1285 V</b>
<i>XAHS 546 MD AIB ASL 01</i>	2911011600	2914501700 <b>FA 5932/1</b>		1613610500 <b>FO 0148 V</b>
<i>XAHS 546 MD ASL 04</i>	2911011600	2914501700 <b>FA 5932/1</b>		1202804000 <b>FI 1285 V</b>
<i>XAM 445</i>	1615603800 <b>FD 3357</b>		1619569800 <b>FA 1310</b>	1613610500 <b>FO 0148 V</b>
<i>XAMS 286 MD AIB ASL 02</i>	2911011200 <b>FD 3586</b>	2914502300 <b>FA 5931</b>		1613610500 <b>FO 0148 V</b>
<i>XAMS 376 MD AIB ASL 01</i>	2911011500 <b>FD 3586</b>	2914501700 <b>FA 5932/1</b>		1613610500 <b>FO 0148 V</b>
<i>XAMS 486 MD ASL 04</i>	2911011600	2914501700 <b>FA 5932/1</b>		1613610500 <b>FO 0148 V</b>
<i>XAMS 586 MD</i>	2911011600	2914501700 <b>FA 5932/1</b>		1613610500 <b>FO 0148 V</b>
<i>XAMS 796 CD AIB 04</i>	2911011500 <b>FD 3586</b>	2914501700 <b>FA 5932/1</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 120</i>	1616283600 <b>FD 3027</b>	1619279800 <b>FA 1252</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 125</i>	1616465600 <b>FD 3045</b>	1619279800 <b>FA 1252</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 125 D FROM SERIES No. 209142</i>	1615654600 <b>FD 3094</b>	1619279800 <b>FA 1252</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 136</i>	1604038200 <b>FD 3572</b>	2914931000 <b>FA 5854</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 137 MOBILE COMPRESSOR</i>	1626016301	2914502300 <b>FA 5931</b>		
<i>XAS 146</i>	1604038200 <b>FD 3572</b>	2914931000 <b>FA 5854</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 146 WITH DEUTZ ENG. MOBILE</i>	1604038201 <b>FD 3572</b>	2914931000 <b>FA 5854</b>		
<i>XAS 160</i>	1616283600 <b>FD 3027</b>	1619279900 <b>FA 1217</b>		1613610500 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATLAS COPCO</b>				
<i>XAS 175</i>				
<i>XAS 175</i>	1616465600 <b>FD 3045</b>	1619279900 <b>FA 1217</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 175 D</i>	1616465600 <b>FD 3045</b>	1619279900 <b>FA 1217</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 186</i>	1604038200 <b>FD 3572</b>	2914931000 <b>FA 5854</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 186 WITH DEUTZ ENG. MOBILE</i>	1604038201 <b>FD 3572</b>	2914931000 <b>FA 5854</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 210 D</i>	2252631301 <b>FD 3308</b>	1619279800 <b>FA 1252</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 230</i>	1616465600 <b>FD 3045</b>	1619284700 <b>FA 1106</b>	1619532700 <b>FA 1346</b>	1613610500 <b>FO 0148 V</b>
<i>XAS 230 WITH DEUTZ ENG. MOBILE</i>	1616465600 <b>FD 3045</b>	1619284700 <b>FA 1106</b>	1619532700 <b>FA 1346</b>	1613610500 <b>FO 0148 V</b>
<i>XAS 25</i>	1615636600 <b>FD 3361</b>	2914802100 <b>FA 1240</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 26</i>	1615636600 <b>FD 3361</b>	2914802100 <b>FA 1240</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 280</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	
<i>XAS 30</i>	1619624800 <b>FD 3083</b>	2900059300 <b>FA 1241</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 32</i>	1615636600 <b>FD 3361</b>	2914802100 <b>FA 1240</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 32 WITH DEUTZ BF4M1008 ENG. MOBILE</i>	1615636601 <b>FD 3361</b>	2914802100 <b>FA 1240</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 32 WITH YANMAR 3TNE68E ENG. 1993</i>	1615636601 <b>FD 3361</b>	2914802100 <b>FA 1240</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 35</i>	1202872200 <b>FD 3010</b>	2900059300 <b>FA 1241</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 350 D</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1613610500 <b>FO 0148 V</b>
<i>XAS 36</i>	1615636600 <b>FD 3361</b>	2914802100 <b>FA 1240</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 36 FROM 2003</i>	1604182700 <b>FD 3621</b>	2914930200 <b>FA 5509</b>	2914930300 <b>FA 5609</b>	1613610500 <b>FO 0148 V</b>
<i>XAS 366 CD</i>	2911011200 <b>FD 3586</b>	2914501700 <b>FA 5932/1</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 37</i>	2911006800 <b>FD 3431</b>	2914930600 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 37 K</i>	2911010500 <b>FD 3621</b>	2914930600 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 37 KD WITH KUBOTA D905 ENG.</i>		2914930200 <b>FA 5509</b>	2914930300 <b>FA 5609</b>	1613610500 <b>FO 0148 V</b>
<i>XAS 40</i>	1619549800 <b>FD 3084</b>	1619279700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 40 D</i>	1619549800 <b>FD 3084</b>	1619279700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 426 MD</i>	2911011500 <b>FD 3586</b>	2914501700 <b>FA 5932/1</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 430</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1613610500 <b>FO 0148 V</b>
<i>XAS 430 D</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1613610500 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATLAS COPCO</b>				
<i>XAS 45</i>				
<i>XAS 45</i>	1202872200 <b>FD 3010</b>	2900059300 <b>FA 1241</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 46</i>	1615769400 <b>FD 3176</b>	2914930600 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 46 WITH DEUTZ ENG. MOBILE COMPRESSOR</i>	1615769401 <b>FD 3176</b>	2914930600 <b>FA 5502</b>		2914805800 <b>FO 0420 V</b>
<i>XAS 47</i>	2911006800 <b>FD 3431</b>	2914930600 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 47 K</i>	2911010500 <b>FD 3621</b>	2914930600 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 495 MD</i>	1615603800 <b>FD 3357</b>		1619569800 <b>FA 1310</b>	1613610500 <b>FO 0148 V</b>
<i>XAS 495 MD MOBILE COMPRESSOR</i>	1615603803 <b>FD 3357</b>	1619279900 <b>FA 1217</b>	1619569800 <b>FA 1310</b>	1613610500 <b>FO 0148 V</b>
<i>XAS 50</i>	1619549800 <b>FD 3084</b>	1619279700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 50 D</i>	1619549800 <b>FD 3084</b>	1619279700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 55</i>	1202872200 <b>FD 3010</b>	1619279700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 55 DD WITH DEUTZ F3L1011 ENG.</i>	1202872201 <b>FD 3010</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 56</i>	1615769400 <b>FD 3176</b>	2914930600 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 57</i>	2911006800 <b>FD 3431</b>	2914930600 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 57 DD WITH DEUTZ D2011L02 ENG.</i>	2911006800 <b>FD 3431</b>	1613740700 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 60</i>	1619549800 <b>FD 3084</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 65</i>	1202872200 <b>FD 3010</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 66</i>	1615769400 <b>FD 3176</b>	2914930800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 66 WITH DEUTZ ENG.</i>	1615769401 <b>FD 3176</b>	2914930600 <b>FA 5502</b>		2914805800 <b>FO 0420 V</b>
<i>XAS 66 WITH DEUTZ ENG. MOBILE COMPRESSOR</i>	1615943600 <b>FD 3431</b>	2914930800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 67</i>	2911006800 <b>FD 3431</b>	2914930800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 67 DD WITH DEUTZ D2011L03 ENG. MOBILE</i>	2911006800 <b>FD 3431</b>	1615740800 <b>FA 5500</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 75 D</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>	1619532700 <b>FA 1346</b>	1613610500 <b>FO 0148 V</b>
<i>XAS 75 DD WITH DEUTZ F3L1011 ENG.</i>	1202872201 <b>FD 3010</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 76</i>	1615769400 <b>FD 3176</b>	2914930600 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 76 WITH DEUTZ ENG. MOBILE COMPRESSOR</i>	1615769401 <b>FD 3176</b>	2914930600 <b>FA 5502</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 80</i>	1202872200 <b>FD 3010</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 80 WITH DEUTZ F3L912 ENG.</i>	1613243300 <b>FD 3527</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>





	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATLAS COPCO</b>				
<i>XAS 85 D</i>				
<i>XAS 85 D</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 85 D WITH DEUTZ F3L912 ENG.</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 85 DD/RR WITH DEUTZ F3L912 ENG.</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>	1619532700 <b>FA 1346</b>	1613610500 <b>FO 0148 V</b>
<i>XAS 90</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 90 D WITH DEUTZ F3L912 ENG.</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 90 DD</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>	1619532700 <b>FA 1346</b>	1613610500 <b>FO 0148 V</b>
<i>XAS 96</i>	1615943600 <b>FD 3431</b>	2914931000 <b>FA 5854</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 96 WITH DEUTZ ENG. MOBILE COMPRESSOR</i>	1615943600 <b>FD 3431</b>	2914931000 <b>FA 5854</b>		1613610500 <b>FO 0148 V</b>
<i>XAS 97</i>	2911006800 <b>FD 3431</b>	2914931000 <b>FA 5854</b>		1613610500 <b>FO 0148 V</b>
<i>XASS 120</i>	1616283600 <b>FD 3027</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1613610500 <b>FO 0148 V</b>
<i>XASS 125</i>	1616465600 <b>FD 3045</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1613610500 <b>FO 0148 V</b>
<i>XASS 160</i>	1616283600 <b>FD 3027</b>	1619279900 <b>FA 1217</b>		1613610500 <b>FO 0148 V</b>
<i>XASS 175</i>	1616465600 <b>FD 3045</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1613610500 <b>FO 0148 V</b>
<i>XASS 30</i>	1619624800 <b>FD 3083</b>	2900059300 <b>FA 1241</b>		1613610500 <b>FO 0148 V</b>
<i>XASS 35</i>	1202872200 <b>FD 3010</b>	2900059300 <b>FA 1241</b>		1613610500 <b>FO 0148 V</b>
<i>XASS 40</i>	1619549800 <b>FD 3084</b>	1619279700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>XASS 45</i>	1202872200 <b>FD 3010</b>	2900059300 <b>FA 1241</b>		1613610500 <b>FO 0148 V</b>
<i>XASS 50</i>	1619549800 <b>FD 3084</b>	1619279700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>XASS 55</i>	1202872200 <b>FD 3010</b>	1619279700 <b>FA 1105</b>		1613610500 <b>FO 0148 V</b>
<i>XASS 60</i>	1619549800 <b>FD 3084</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XASS 65</i>	1202872200 <b>FD 3010</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XASS 75</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XASS 80</i>	1613243300 <b>FD 3527</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XASS 80 DD WITH DEUTZ F3L912 ENG.</i>	1613243300 <b>FD 3527</b>	1619284700 <b>FA 1106</b>	1619532700 <b>FA 1346</b>	1613610500 <b>FO 0148 V</b>
<i>XASS 85</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XASS 85 D WITH DEUTZ F3L912 ENG.</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XASS 90</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATLAS COPCO</b>				
<i>XASS 90 D WITH DEUTZ F3L912 ENG.</i>				
<i>XASS 90 D WITH DEUTZ F3L912 ENG.</i>	1614437300 <b>FD 3087</b>	1619284700 <b>FA 1106</b>		1613610500 <b>FO 0148 V</b>
<i>XR 210</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1613610500 <b>FO 0148 V</b>
<i>XR 210 D</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1613610500 <b>FO 0148 V</b>
<i>XR 350</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1613610500 <b>FO 0148 V</b>
<i>XRF 350</i>	2252631300 <b>FD 3028</b>			
<i>XRH 350 D</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1202804000 <b>FI 1285 V</b>
<i>XRHS 350 D</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1202804000 <b>FI 1285 V</b>
<i>XRHS 396 MD</i>	2911011700 <b>FD 3586</b>	2914501700 <b>FA 5932/1</b>		1202804000 <b>FI 1285 V</b>
<i>XRHS 486 MD</i>	2911011700 <b>FD 3586</b>	2914501700 <b>FA 5932/1</b>		1202804000 <b>FI 1285 V</b>
<i>XRS 210</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1613610500 <b>FO 0148 V</b>
<i>XRS 350</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1613610500 <b>FO 0148 V</b>
<i>XRVS 346</i>	1604132800	2914501700 <b>FA 5932/1</b>		1202804000 <b>FI 1285 V</b>
<i>XRVS 450</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1613610500 <b>FO 0148 V</b>
<i>XRVS 450 D</i>	2252631300 <b>FD 3028</b>	1619279800 <b>FA 1252</b>	1619554500 <b>FA 1345</b>	1613610500 <b>FO 0148 V</b>
<i>XRVS 455 MD</i>	1615603800 <b>FD 3357</b>	1619279900 <b>FA 1217</b>	1619569800 <b>FA 1310</b>	1613610500 <b>FO 0148 V</b>
<i>XRVS 455 MD MOBILE COMPRESSOR</i>	1615603803 <b>FD 3357</b>	1619279900 <b>FA 1217</b>	1619569800 <b>FA 1310</b>	1613610500 <b>FO 0148 V</b>
<i>XRVS 466 MD</i>	2911011700 <b>FD 3586</b>	2914501700 <b>FA 5932/1</b>		1202804000 <b>FI 1285 V</b>
<i>ZR 160</i>		1621009400 <b>FA 1864</b>		1621027000 <b>FO 0077 V</b>
<i>ZR 160 VSD</i>		1030097900 <b>FA 1260</b>		1614874700 <b>FI 0083 V</b>
<i>ZR 200</i>		1621009400 <b>FA 1864</b>		1621027000 <b>FO 0077 V</b>
<i>ZR 250</i>		1621009400 <b>FA 1864</b>		1621027000 <b>FO 0077 V</b>
<i>ZR 275</i>		1621009400 <b>FA 1864</b>		1621027000 <b>FO 0077 V</b>
<i>ZR 3</i>		1030107000 <b>FA 1229</b>		1613610590 <b>FO 0148 V</b>
<i>ZR 300</i>		1030097900 <b>FA 1260</b>		1621027000 <b>FO 0077 V</b>
<i>ZR 315</i>		1030097900 <b>FA 1260</b>		1621027000 <b>FO 0077 V</b>
<i>ZR 315 VSD</i>		1621009400 <b>FA 1864</b>		1614874700 <b>FI 0083 V</b>
<i>ZR 350</i>		1621054799 <b>FA 1758</b>		1621027000 <b>FO 0077 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATLAS COPCO</b>				
<i>ZR 355</i>				
<b>ZR 355</b>		1030097900 <b>FA 1260</b>		1621027000 <b>FO 0077 V</b>
<b>ZR 4</b>		1621054799 <b>FA 1758</b>		1613610590 <b>FO 0148 V</b>
<b>ZR 400</b>		1030097900 <b>FA 1260</b>		1621027000 <b>FO 0077 V</b>
<b>ZR 425</b>		1030097900 <b>FA 1260</b>		1621027000 <b>FO 0077 V</b>
<b>ZR 45</b>		2900058200 <b>FA 1512</b>		1619622700 <b>FI 1306 V</b>
<b>ZR 450</b>		1621009400 <b>FA 1864</b>		1621027000 <b>FO 0077 V</b>
<b>ZR 5</b>		1621054799 <b>FA 1758</b>		1613610590 <b>FO 0148 V</b>
<b>ZR 500</b>		1621009400 <b>FA 1864</b>		1621027000 <b>FO 0077 V</b>
<b>ZR 55</b>		2900058200 <b>FA 1512</b>		1619622700 <b>FI 1306 V</b>
<b>ZR 630</b>		1621009400 <b>FA 1864</b>		1621027000 <b>FO 0077 V</b>
<b>ZR 75</b>		1619279900 <b>FA 1217</b>		1619622700 <b>FI 1306 V</b>
<b>ZR 750</b>		1621009400 <b>FA 1864</b>		1613610500 <b>FO 0148 V</b>
<b>ZR 90</b>		1619279900 <b>FA 1217</b>		1619622700 <b>FI 1306 V</b>
<b>ZT 18</b>		1613740800 <b>FA 5500</b>		1030088200 <b>FO 0918 V</b>
<b>ZT 22</b>		1613740800 <b>FA 5500</b>		1030088200 <b>FO 0918 V</b>
<b>ZT 30</b>		1613740800 <b>FA 5500</b>		1030088200 <b>FO 0918 V</b>
<b>ZT 37</b>		1613740800 <b>FA 5500</b>		1030088200 <b>FO 0918 V</b>
<b>ZT 37 VSD</b>		1613740800 <b>FA 5500</b>		1030088200 <b>FO 0918 V</b>
<b>ZT 45</b>		2900058200 <b>FA 1512</b>		1619622700 <b>FI 1306 V</b>
<b>ZT 55</b>		2900058200 <b>FA 1512</b>		1619622700 <b>FI 1306 V</b>
<b>ZT 75</b>		1619279900 <b>FA 1217</b>		1619622700 <b>FI 1306 V</b>
<b>ZT 90</b>		1619279900 <b>FA 1217</b>		1619622700 <b>FI 1306 V</b>
<b>ATMOS</b>				
<b>E 140</b>	627963100245 <b>FD 3372 V</b>	627963092920		627960930000 <b>FO 0339 V</b>
<b>E 170</b>	627963100245 <b>FD 3372 V</b>	627963092920		627960930000 <b>FO 0339 V</b>
<b>E 40</b>	627963100962 <b>FD 3096 V</b>	627963087998		627960094100 <b>FO 0015 V</b>
<b>E 50</b>	627963100962 <b>FD 3096 V</b>	627963077998		627960094100 <b>FO 0015 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATMOS</b>				
<i>E 60</i>				
<i>E 60</i>	627963100962 <b>FD 3096 V</b>			627960094100 <b>FO 0015 V</b>
<i>E 60 M</i>	627963100962 <b>FD 3096 V</b>	627963087998		627960930000 <b>FO 0339 V</b>
<i>E 60-12</i>	627963100962 <b>FD 3096 V</b>			627960094100 <b>FO 0015 V</b>
<i>E 70 Z</i>	627963100962 <b>FD 3096 V</b>	627963087998		627960930000 <b>FO 0339 V</b>
<i>E 95</i>	627963100962 <b>FD 3096 V</b>	627963087998		627960094100 <b>FO 0015 V</b>
<i>PD 127</i>	627963100127 <b>FD 3275</b>			627963062226 <b>FI 1099 V</b>
<i>PD 20 R</i>	627963100127 <b>FD 3275</b>			627963062226 <b>FI 1099 V</b>
<i>PD 200</i>	627963100240 <b>FD 3102</b>			627960950000 <b>FI 1295 V</b>
<i>PD 25 DEUTZ ENG. F2M1011</i>	627963100240 <b>FD 3102</b>	627963092910		627960950000 <b>FI 1295 V</b>
<i>PD 30 DEUTZ ENG. F3M1011F</i>	627963062101	627963092414		627963062436 <b>FI 1302 V</b>
<i>PD 40 DEUTZ ENG.</i>	627963100131 <b>FD 3224</b>	627963092414		627960950000 <b>FI 1295 V</b>
<i>PD 5 R</i>		627963072910 <b>FA 5501</b>		627960951000 <b>FO 0077 V</b>
<i>PD 85 DEUTZ ENG. UNTIL 2005</i>	627963100131 <b>FD 3224</b>	627963092404		627963062156
<i>PDI 15I</i>	627963050670 <b>FD 3647</b>	627963092910		627960941000 <b>FO 0194 V</b>
<i>PDI 20</i>	627963050670 <b>FD 3647</b>	627963092910		627960941000 <b>FO 0194 V</b>
<i>PDI 20I</i>	627963050670 <b>FD 3647</b>	627963092910		627960941000 <b>FO 0194 V</b>
<i>PDP 15 PERKINS ENG.</i>	627963050670 <b>FD 3647</b>	627963072920		627960941000 <b>FO 0194 V</b>
<i>PDP 20 PERKINS ENG.</i>	627963050670 <b>FD 3647</b>	627963072920		627960941000 <b>FO 0194 V</b>
<i>PDP 28</i>	627963100962 <b>FD 3096 V</b>	627963092310 <b>FA 5502</b>		627960951000 <b>FO 0077 V</b>
<i>PDP 28 PERKINS ENG.</i>	627963100131 <b>FD 3224</b>	627963092310 <b>FA 5502</b>		627960951000 <b>FO 0077 V</b>
<i>SE 100 LOK</i>	627963100245 <b>FD 3372 V</b>	427900101016 <b>FA 1797</b>		627960920000 <b>FI 1290 V</b>
<i>SE 1000 K</i>	427901000005	427901001015		627963062226 <b>FI 1099 V</b>
<i>SE 120 LOK</i>	627963100240 <b>FD 3102</b>	427900101016 <b>FA 1797</b>		627960920000 <b>FI 1290 V</b>
<i>SE 120.1 LOK</i>	627963100245 <b>FD 3372 V</b>	427900101016 <b>FA 1797</b>		627960920000 <b>FI 1290 V</b>
<i>SE 1250 N</i>	427901000005	627963092304 <b>FA 1217</b>		627963062226 <b>FI 1099 V</b>
<i>SE 180</i>	427900400004			627960950000 <b>FI 1295 V</b>
<i>SE 270</i>	427900400004			627960950000 <b>FI 1295 V</b>

	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ATMOS</b>				
<i>SE 440</i>				
<i>SE 440</i>	627963100131 <b>FD 3224</b>	627963085011		427900520007
<i>SE 520 (REPLACED BY SEC 550)</i>	627963100131 <b>FD 3224</b>	627963085011		427900520007
<i>SE 650 N</i>	427901000005	427901001015		627963062226 <b>FI 1099 V</b>
<i>SEC 370 (REPLACED BY SE 350)</i>	627963100970 <b>FD 3031 V</b>	627963092310 <b>FA 5502</b>		627963062130 <b>FO 0100 V</b>
<i>SEC 750</i>	4930354171 <b>FD 3574</b>			
<b>BALMA</b>				
<i>BRIO 11</i>	9056943 <b>FD 3096 V</b>	9056937 <b>FA 2843</b>		9056935 <b>FI 1268 V</b>
<i>BRIO 5.5</i>	9056942 <b>FD 3034 V</b>	9056937 <b>FA 2843</b>		9056933 <b>FO 0029 V</b>
<i>BRIO 7.5</i>	9056942 <b>FD 3034 V</b>	9056937 <b>FA 2843</b>		9056933 <b>FO 0029 V</b>
<i>GALAXY 03-270</i>	9056942 <b>FD 3034 V</b>	9056780 <b>FA 5507</b>		9056933 <b>FO 0029 V</b>
<i>GALAXY 04-270</i>	9056942 <b>FD 3034 V</b>	9056780 <b>FA 5507</b>		9056933 <b>FO 0029 V</b>
<i>GALAXY 05-270</i>	9056942 <b>FD 3034 V</b>	9056780 <b>FA 5507</b>		9056933 <b>FO 0029 V</b>
<i>GALAXY 07-270</i>	9056942 <b>FD 3034 V</b>	9056780 <b>FA 5507</b>		9056238 <b>FO 0029 V</b>
<i>GALAXY 07-500</i>	9056942 <b>FD 3034 V</b>	9056780 <b>FA 5507</b>		9056933 <b>FO 0029 V</b>
<i>GALAXY 10-270</i>	9056942 <b>FD 3034 V</b>	9056780 <b>FA 5507</b>		9056933 <b>FO 0029 V</b>
<i>GALAXY 10-500</i>	9056942 <b>FD 3034 V</b>	9056780 <b>FA 5507</b>		9056933 <b>FO 0029 V</b>
<i>GALAXY 15-270</i>	9056292 <b>FD 3096 V</b>	9056780 <b>FA 5507</b>		9056113 <b>FI 1268 V</b>
<i>GALAXY 15-500</i>	9056942 <b>FD 3034 V</b>	9056780 <b>FA 5507</b>		9056113 <b>FI 1268 V</b>
<i>MODULO 11</i>	9056943 <b>FD 3096 V</b>	9056937 <b>FA 2843</b>		9056935 <b>FI 1268 V</b>
<i>MODULO 15/51</i>	9056943 <b>FD 3096 V</b>	9056937 <b>FA 2843</b>		9056935 <b>FI 1268 V</b>
<i>MODULO 15/69</i>	9056943 <b>FD 3096 V</b>	9056939 <b>FA 5003</b>		9056935 <b>FI 1268 V</b>
<i>MODULO 16/69</i>	9056944 <b>FD 3373 V</b>	9056940 <b>FA 5001</b>		9056935 <b>FI 1268 V</b>
<i>MODULO 18.5</i>	9056944 <b>FD 3373 V</b>	9056940 <b>FA 5001</b>		9056935 <b>FI 1268 V</b>
<i>MODULO 22</i>	9056944 <b>FD 3373 V</b>	9056940 <b>FA 5001</b>		9056935 <b>FI 1268 V</b>
<i>MODULO 5.5</i>	9056942 <b>FD 3034 V</b>	9056937 <b>FA 2843</b>		9056933 <b>FO 0029 V</b>
<i>MODULO 5.5 13-15 BAR</i>	9056942 <b>FD 3034 V</b>	9056937 <b>FA 2843</b>		9056934 <b>FI 0906 V</b>
<i>MODULO 7.5</i>	9056942 <b>FD 3034 V</b>	9056937 <b>FA 2843</b>		9056933 <b>FO 0029 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>BALMA</b>				
<i>MODULO 7.5 13-15 BAR</i>				
<b>MODULO 7.5 13-15 BAR</b>	9056942 <b>FD 3034 V</b>	9056937 <b>FA 2843</b>		9056934 <b>FI 0906 V</b>
<b>VISS 10</b>	9056162 <b>FD 3006</b>	9056293 <b>FA 2843</b>		9056113 <b>FI 1268 V</b>
<b>VISS 15</b>	9056162 <b>FD 3006</b>	9056293 <b>FA 2843</b>		9056113 <b>FI 1268 V</b>
<b>VISS 20</b>	9056162 <b>FD 3006</b>	9056002 <b>FA 5003</b>		9056113 <b>FI 1268 V</b>
<b>VISS 25</b>	9056176 <b>FD 3007</b>	9056227 <b>FA 5001</b>		9056113 <b>FI 1268 V</b>
<b>VISS 30</b>	9056176 <b>FD 3007</b>	9056227 <b>FA 5001</b>		9056113 <b>FI 1268 V</b>
<b>VISS 40</b>	9056176 <b>FD 3007</b>	9056227 <b>FA 5001</b>		9056113 <b>FI 1268 V</b>
<b>VISS 50</b>	9056025 <b>FD 3464</b>	9056189 <b>FA 5002</b>		9056103 <b>FI 1304 V</b>
<b>VISS 60</b>	9056176 <b>FD 3007</b>	9056189 <b>FA 5002</b>		9056113 <b>FI 1268 V</b>
<b>VISS 7.5</b>	9056162 <b>FD 3006</b>	9056293 <b>FA 2843</b>		9056113 <b>FI 1268 V</b>
<b>VISS 75</b>	9056176 <b>FD 3007</b>	9056189 <b>FA 5002</b>		9056113 <b>FI 1268 V</b>
<b>BECKER</b>				
<b>DP 2.100</b>	965408 <b>FD 3403</b>	909545 <b>FA 2064</b>		
<b>DP 2.140</b>	965407 <b>FD 3402</b>	909545 <b>FA 2064</b>		
<b>DT 3.10</b>		909518 <b>FA 1775</b>		
<b>DT 3.16</b>		909519 <b>FA 1779</b>		
<b>DT 3.25</b>	965401 <b>FD 3124</b>	909505 <b>FA 1703</b>		
<b>DT 3.3</b>		909526 <b>FA 2081</b>		
<b>DT 3.40</b>		909505 <b>FA 1703</b>		
<b>DT 3.6</b>		909518 <b>FA 1775</b>		
<b>DT 3.6/08</b>		909527 <b>FA 2205</b>		
<b>DT 3.60</b>		909505 <b>FA 1703</b>		
<b>DT 4.10</b>		909518 <b>FA 1775</b>		
<b>DT 4.16</b>		909519 <b>FA 1779</b>		
<b>DT 4.16 (05-51)</b>		909519 <b>FA 1779</b>		
<b>DT 4.25</b>		909505 <b>FA 1703</b>		
<b>DT 4.25K</b>		909505 <b>FA 1703</b>		



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>BECKER</b>				
<i>DT 4.40</i>				
<b>DT 4.40</b>	965402 <b>FD 3113</b>	909518 <b>FA 1775</b>		
<b>DT 4.40K</b>		909505 <b>FA 1703</b>		
<b>DT 4.8</b>		909527 <b>FA 2205</b>		
<b>DTLF 200</b>		909534 <b>FA 1984</b>		
<b>DTLF 250</b>	549000222	909510 <b>FA 1688</b>		
<b>DTLF 360</b>	549000222	909510 <b>FA 1688</b>		
<b>DTLF 500</b>		909540 <b>FA 1838</b>		
<b>DTLF400</b>		909540 <b>FA 1838</b>		
<b>DTLF400/6-73</b>		909540 <b>FA 1838</b>		
<b>DVP 100</b>		909507 <b>FA 1655</b>		
<b>DVP 140</b>		909507 <b>FA 1655</b>		
<b>DVP 60</b>		909506 <b>FA 1654</b>		
<b>DVP 70</b>		909506 <b>FA 1654</b>		
<b>DVT 2.100</b>	549000101	909505 <b>FA 1703</b>		
<b>DVT 2.140</b>	549000104	909505 <b>FA 1703</b>		
<b>DVT 2.60</b>	549000101	909505 <b>FA 1703</b>		
<b>DVT 2.80</b>	549000101	909505 <b>FA 1703</b>		
<b>DVT 3.100</b>	549000213	909507 <b>FA 1655</b>		
<b>DVT 3.140</b>	549000213	909507 <b>FA 1655</b>		
<b>DVT 3.60</b>	549000211	909506 <b>FA 1654</b>		
<b>DVT 3.80</b>	549000211	909506 <b>FA 1654</b>		
<b>DVT 70</b>		909505 <b>FA 1703</b>		
<b>DVTLF 250 (0-72)</b>		909534 <b>FA 1984</b>		
<b>DVTLF 250 (KSK)</b>		909534 <b>FA 1984</b>		
<b>DVTLF 250 (SK)</b>		909510 <b>FA 1688</b>		
<b>E PV 40/P 40I</b>		909506 <b>FA 1654</b>		
<b>E V 40/P 40I</b>		909506 <b>FA 1654</b>		



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>BECKER</b>				
<i>E V 40/PV 40I</i>				
<i>E V 40/PV 40I</i>		909506 <b>FA 1654</b>		
<i>KDT 2.100</i>	549000101	909505 <b>FA 1703</b>		
<i>KDT 2.140</i>		909505 <b>FA 1703</b>		
<i>KDT 2.60</i>	549000101	909505 <b>FA 1703</b>		
<i>KDT 2.80</i>	549000101	909505 <b>FA 1703</b>		
<i>KDT 3.100</i>	549000213	909507 <b>FA 1655</b>		
<i>KDT 3.140</i>	549000213	909507 <b>FA 1655</b>		
<i>KDT 3.60</i>	549000211	909507 <b>FA 1655</b>		
<i>KDT 3.60/6</i>		909507 <b>FA 1655</b>		
<i>KDT 3.80</i>	549000211	909507 <b>FA 1655</b>		
<i>KDT 3.80/6</i>		909510 <b>FA 1688</b>		
<i>KVT 2.100</i>	549000101	909505 <b>FA 1703</b>		
<i>KVT 2.140</i>		909505 <b>FA 1703</b>		
<i>KVT 2.60</i>	549000101	909505 <b>FA 1703</b>		
<i>KVT 2.80</i>	549000101	909505 <b>FA 1703</b>		
<i>KVT 3.100</i>	549000213	909507 <b>FA 1655</b>		
<i>KVT 3.140</i>	549000213	909507 <b>FA 1655</b>		
<i>KVT 3.60</i>	549000211	909507 <b>FA 1655</b>		
<i>KVT 3.60 INDEX B. C. D</i>		909507 <b>FA 1655</b>		
<i>KVT 3.60/6</i>		909510 <b>FA 1688</b>		
<i>KVT 3.80</i>	549000211	909507 <b>FA 1655</b>		
<i>PICCHIO 2200</i>	549000211	909507 <b>FA 1655</b>		
<i>RV 33</i>		909512 <b>FA 1304</b>		
<i>SV 5.1050/1 BLOWER</i>		84040112 <b>FA 1783</b>		
<i>SV 5.250/2 BLOWER</i>		84040110 <b>FA 1628</b>		
<i>SV 5.300/1 BLOWER</i>		84040110 <b>FA 1628</b>		
<i>SV 5.490/1 BLOWER</i>		84040112 <b>FA 1783</b>		





	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>BECKER</b>				
<i>SV 5.690/1 BLOWER</i>				
<i>SV 5.690/1 BLOWER</i>		84040112 <b>FA 1783</b>		
<i>SV 5.90/2 BLOWER</i>		84040207 <b>FA 1657</b>		
<i>SV 7.330/1 BLOWER</i>		909548 <b>FA 2104</b>		
<i>SV 7.430/1 BLOWER</i>		909548 <b>FA 2104</b>		
<i>SV 8.130/1 BLOWER</i>		909568 <b>FA 2069</b>		
<i>SV 8.160/1 BLOWER</i>		909568 <b>FA 2069</b>		
<i>SV 8.190/1 BLOWER</i>		909568 <b>FA 2069</b>		
<i>T 10</i>		909508 <b>FA 1712</b>		
<i>T 16</i>		909508 <b>FA 1712</b>		
<i>T 25</i>		909509 <b>FA 1653</b>		
<i>T 3.16</i>		909518 <b>FA 1775</b>		
<i>T 3.16 DSK</i>		909518 <b>FA 1775</b>		
<i>T 3.25 DSK</i>		909505 <b>FA 1703</b>		
<i>T 3.3</i>		909526 <b>FA 2081</b>		
<i>T 3.40</i>		909505 <b>FA 1703</b>		
<i>T 3.40 DSK</i>		909505 <b>FA 1703</b>		
<i>T 3.60</i>		909505 <b>FA 1703</b>		
<i>T 3.60 DSK</i>		909505 <b>FA 1703</b>		
<i>T 4.10 DSK</i>		909505 <b>FA 1703</b>		
<i>T 4.10 DV</i>		909519 <b>FA 1779</b>		
<i>T 4.16</i>		909518 <b>FA 1775</b>		
<i>T 4.16 DV</i>		909519 <b>FA 1779</b>		
<i>T 4.25 DSK</i>		909505 <b>FA 1703</b>		
<i>T 4.40 DSK</i>		909505 <b>FA 1703</b>		
<i>T 40</i>		909508 <b>FA 1712</b>		
<i>T 40 DS</i>		909508 <b>FA 1712</b>		
<i>U 1.16</i>	965404 <b>FD 3396</b>			



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>BECKER</b>				
<i>U 2.100</i>				
<i>U 2.100</i>	549000107	84040207 <b>FA 1657</b>		
<i>U 2.165</i>	549000129	84040207 <b>FA 1657</b>		
<i>U 2.190</i>	549000129	84040110 <b>FA 1628</b>		
<i>U 2.250</i>	549000129	84040110 <b>FA 1628</b>		
<i>U 3.10</i>	65401 <b>FD 3124</b>			
<i>U 3.16</i>	965401 <b>FD 3124</b>	84040107		
<i>U 3.25 SA</i>	065401 <b>FD 3124</b>			
<i>U 3.40</i>	965401 <b>FD 3124</b>	84040107		
<i>U 3.40.33</i>	65401 <b>FD 3124</b>			
<i>U 3.6</i>	965406 <b>FD 3413</b>			
<i>U 3.6-09</i>	965406 <b>FD 3413</b>			
<i>U 3.6-46</i>	965406 <b>FD 3413</b>			
<i>U 4.100</i>	549000261	84040110 <b>FA 1628</b>		
<i>U 4.100 UNTIL INDEX C</i>	965409 <b>FD 3393</b>	84040207 <b>FA 1657</b>		
<i>U 4.100 UP TO INDEX D</i>	965416 <b>FD 3583</b>			
<i>U 4.165</i>	549000264	84040207 <b>FA 1657</b>		
<i>U 4.250</i>	549000264	84040110 <b>FA 1628</b>		
<i>U 4.250 INDEX E AND F</i>	965415 <b>FD 3582</b>			
<i>U 4.400</i>	965410 <b>FD 3406</b>			
<i>U 4.400 INDEX A AND D</i>	965410 <b>FD 3406</b>			
<i>U 4.40-09</i>	965414 <b>FD 3622</b>			
<i>U 4.630</i>	965411 <b>FD 3407</b>			
<i>U 4.630 INDEX C AND D</i>	965411 <b>FD 3407</b>			
<i>U 4.70 UNTIL INDEX C</i>	965409 <b>FD 3393</b>	84040107		
<i>U 4.70 UP TO INDEX D</i>	965416 <b>FD 3583</b>	84040107		
<i>VADS 650</i>		909540 <b>FA 1838</b>		909704312 <b>FO 0418 V</b>
<i>VFP 2.100</i>	965404 <b>FD 3396</b>			



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>BECKER</b>				
<i>VFP 2.80</i>				
<b>VFP 2.80</b>	965404 <b>FD 3396</b>			
<b>VT 25</b>		909509 <b>FA 1653</b>		
<b>VT 3.10</b>		909518 <b>FA 1775</b>		
<b>VT 3.16</b>		909519 <b>FA 1779</b>		
<b>VT 3.25</b>		909505 <b>FA 1703</b>		
<b>VT 3.3</b>		909526 <b>FA 2081</b>		
<b>VT 3.40</b>		909505 <b>FA 1703</b>		
<b>VT 3.6</b>		909518 <b>FA 1775</b>		
<b>VT 3.6/08</b>		909527 <b>FA 2205</b>		
<b>VT 3.60</b>		909505 <b>FA 1703</b>		
<b>VT 4.10</b>		909518 <b>FA 1775</b>		
<b>VT 4.10 DV</b>		909518 <b>FA 1775</b>		
<b>VT 4.16</b>		909519 <b>FA 1779</b>		
<b>VT 4.16 DV</b>		909519 <b>FA 1779</b>		
<b>VT 4.25</b>		909505 <b>FA 1703</b>		
<b>VT 4.25 DSK</b>		909505 <b>FA 1703</b>		
<b>VT 4.40 DSK</b>		909505 <b>FA 1703</b>		
<b>VT 4.8</b>		909527 <b>FA 2205</b>		
<b>VTLF 200</b>		909510 <b>FA 1688</b>		
<b>VTLF 250</b>	549000222	909510 <b>FA 1688</b>		
<b>VTLF 250 (0-72)</b>		909534 <b>FA 1984</b>		
<b>VTLF 250 (SK)</b>		909510 <b>FA 1688</b>		
<b>VTLF 360</b>	549000222	909510 <b>FA 1688</b>		
<b>VTLF 360 (0-72)</b>		909534 <b>FA 1984</b>		
<b>VTLF 360 (SK)</b>		909510 <b>FA 1688</b>		
<b>VTLF 500</b>		909540 <b>FA 1838</b>		
<b>VTLF 500 (SK)</b>		909510 <b>FA 1688</b>		



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>BECKER</b> <span style="float: right;"><i>VTLF400</i></span>				
<i>VTLF400</i>		909540 <b>FA 1838</b>		
<i>VTLF400 (SK)</i>		909510 <b>FA 1688</b>		
<i>VX 4.10</i>		909518 <b>FA 1775</b>		
<i>VX 4.16</i>		909519 <b>FA 1779</b>		
<i>VX 4.25</i>		909505 <b>FA 1703</b>		
<i>VX 4.40</i>		909505 <b>FA 1703</b>		
<b>BIGIESSE</b>				
<i>100 PBO-M</i>	35128			34204 <b>FO 0200 V</b>
<i>170 CBO-M</i>	40770			34204 <b>FO 0200 V</b>
<i>170 PBO-M</i>	40770			34204 <b>FO 0200 V</b>
<i>270 CBO-M</i>	40771			34204 <b>FO 0200 V</b>
<i>270 PBO-M</i>	40771			34204 <b>FO 0200 V</b>
<b>BOGE</b>				
<i>S 10</i>	575000103 <b>FD 3034 V</b>	569003301 <b>FA 1933</b>		558000307 <b>FI 1290 V</b>
<i>S 100</i>	575000101 <b>FD 3031 V</b>	569000726 <b>FA 1106</b>		558000301 <b>FO 0148 V</b>
<i>S 125</i>	575000101 <b>FD 3031 V</b>	569000729 <b>FA 1217</b>		558000308 <b>FI 1099 V</b>
<i>S 15</i>	575000102 <b>FD 3096 V</b>	569000901 <b>FA 3070</b>		558000309 <b>FO 0918 V</b>
<i>S 150</i>	575000101 <b>FD 3031 V</b>	569000729 <b>FA 1217</b>		558000308 <b>FI 1099 V</b>
<i>S 180/10</i>	575000101 <b>FD 3031 V</b>	569000730 <b>FA 1302</b>		558000308 <b>FI 1099 V</b>
<i>S 20</i>	575000103 <b>FD 3034 V</b>	569000901 <b>FA 3070</b>		558000307 <b>FI 1290 V</b>
<i>S 30</i>	575000105 <b>FD 3372 V</b>	569002811 <b>FA 5505</b>		558000303 <b>FO 0195 V</b>
<i>S 40</i>	575000101 <b>FD 3031 V</b>	143000303 <b>FA 1241</b>		558000303 <b>FO 0195 V</b>
<i>S 40/S 40-2</i>	575000101 <b>FD 3031 V</b>	143000303 <b>FA 1241</b>		558000303 <b>FO 0195 V</b>
<i>S 50</i>	575000101 <b>FD 3031 V</b>	143000303 <b>FA 1241</b>		558000303 <b>FO 0195 V</b>
<i>S 60</i>	575000101 <b>FD 3031 V</b>	143000303 <b>FA 1241</b>		558000303 <b>FO 0195 V</b>
<i>S 75</i>	575000101 <b>FD 3031 V</b>	569000726 <b>FA 1106</b>		558000301 <b>FO 0148 V</b>
<i>SD 40</i>	575000101 <b>FD 3031 V</b>	143000303 <b>FA 1241</b>		558000303 <b>FO 0195 V</b>
<i>SF 60-2/SDF 60-2</i>	575000101 <b>FD 3031 V</b>			558000301 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>BOGE</b>				
<i>SG 270</i>				
<b>SG 270</b>	5750002669 <b>FD 3236</b>			
<b>BOTTARINI</b>				
<b>DS 2-18</b>	221046 <b>FD 3096 V</b>	220918 <b>FA 2036</b>		220910C
<b>DS 25-30</b>	221090 <b>FD 3032</b>	220901 <b>FA 1266 AL</b>		220910C
<b>DS 32</b>	221090 <b>FD 3032</b>	220902 <b>FA 1004 AL</b>		220910C
<b>DS 40</b>	221090 <b>FD 3032</b>	220981 <b>FA 1212 AL</b>		220910C
<b>GBV 10</b>	221046 <b>FD 3096 V</b>	220913 <b>FA 1959</b>		220910C
<b>GBV 10 UNTIL 1992</b>	221056 <b>FD 3038</b>	220913 <b>FA 1959</b>		220910C
<b>GBV 100</b>	221000 <b>FD 3065</b>	220905 <b>FA 1293 AL</b>		220911 <b>FO 0148 V</b>
<b>GBV 100 10 BAR</b>	221100 <b>FD 3186</b>	220905 <b>FA 1293 AL</b>		220911 <b>FO 0148 V</b>
<b>GBV 100 7.5 BAR</b>	221043 <b>FD 3186</b>	220905 <b>FA 1293 AL</b>		220911 <b>FO 0148 V</b>
<b>GBV 125</b>	221065 <b>FD 3066</b>	220980 <b>FA 1217</b>		220912 <b>FO 0030 V</b>
<b>GBV 125 10 BAR</b>	221043 <b>FD 3186</b>	220905 <b>FA 1293 AL</b>		220911 <b>FO 0148 V</b>
<b>GBV 125 7.5 BAR</b>	221004 <b>FD 3642</b>	220980 <b>FA 1217</b>		220911 <b>FO 0148 V</b>
<b>GBV 125 SS</b>	221100 <b>FD 3186</b>	220905 <b>FA 1293 AL</b>		220911 <b>FO 0148 V</b>
<b>GBV 15</b>	221046 <b>FD 3096 V</b>	220913 <b>FA 1959</b>		220910C
<b>GBV 15 UNTIL 1992</b>	221056 <b>FD 3038</b>	220913 <b>FA 1959</b>		220910C
<b>GBV 150 10 BAR</b>	221065 <b>FD 3066</b>	220980 <b>FA 1217</b>		220912 <b>FO 0030 V</b>
<b>GBV 150 7.5 BAR</b>	221065 <b>FD 3066</b>	220905 <b>FA 1293 AL</b>		220912 <b>FO 0030 V</b>
<b>GBV 150 SS</b>	221004 <b>FD 3642</b>	220980 <b>FA 1217</b>		220912 <b>FO 0030 V</b>
<b>GBV 180 10 BAR</b>	221065 <b>FD 3066</b>	220980 <b>FA 1217</b>		220912 <b>FO 0030 V</b>
<b>GBV 180 7.5 BAR</b>	221050 <b>FD 3638</b>	220980 <b>FA 1217</b>		220912 <b>FO 0030 V</b>
<b>GBV 180 SS</b>	221065 <b>FD 3066</b>	220980 <b>FA 1217</b>		220912 <b>FO 0030 V</b>
<b>GBV 20</b>	221046 <b>FD 3096 V</b>	220913 <b>FA 1959</b>		220910C
<b>GBV 20 UNTIL 1992</b>	221056 <b>FD 3038</b>	220913 <b>FA 1959</b>		220910C
<b>GBV 25</b>	221090 <b>FD 3032</b>	220901 <b>FA 1266 AL</b>		220910C
<b>GBV 30</b>	221090 <b>FD 3032</b>	220901 <b>FA 1266 AL</b>		220910C



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>BOTTARINI</b> <i>GBV 40</i>				
<b>GBV 40</b>	221091 <b>FD 3062</b>	220902 <b>FA 1004 AL</b>		220911 <b>FO 0148 V</b>
<b>GBV 5</b>	221055 <b>FD 3034 V</b>	220913 <b>FA 1959</b>		220910C
<b>GBV 50</b>	221092 <b>FD 3064</b>	220902 <b>FA 1004 AL</b>		220911 <b>FO 0148 V</b>
<b>GBV 60</b>	221092 <b>FD 3064</b>	220902 <b>FA 1004 AL</b>		220911 <b>FO 0148 V</b>
<b>GBV 60 SS AR 7.5 BAR</b>	221093 <b>FD 3009</b>	220903 <b>FA 1280 AL</b>		
<b>GBV 7.5</b>	221029 <b>FD 3031 V</b>	220913 <b>FA 1959</b>		220910C
<b>GBV 75</b>	221092 <b>FD 3064</b>	220903 <b>FA 1280 AL</b>		220911 <b>FO 0148 V</b>
<b>GBV 95</b>	221042 <b>FD 3009</b>	220905 <b>FA 1293 AL</b>		220911 <b>FO 0148 V</b>
<b>KDV 30</b>	89848519 <b>FD 3145</b>	89874439		89559379 <b>FI 1268 V</b>
<b>KDV 37</b>	221022 <b>FD 3464</b>	223466		220910C
<b>KDV 50</b>		223466		223475 <b>FO 0100 V</b>
<b>KS 10</b>	221046 <b>FD 3096 V</b>	223452 <b>FA 2110</b>		220977 <b>FO 0339 V</b>
<b>KS 12</b>	221046 <b>FD 3096 V</b>	220913 <b>FA 1959</b>		220977 <b>FO 0339 V</b>
<b>KS 123</b>	223487 <b>FD 3078</b>	223491 <b>FA 5854</b>		223489
<b>KS 157</b>	223487 <b>FD 3078</b>	223491 <b>FA 5854</b>		223489
<b>KS 18</b>	221046 <b>FD 3096 V</b>	220913 <b>FA 1959</b>		220977 <b>FO 0339 V</b>
<b>KS 22</b>	221046 <b>FD 3096 V</b>	220913 <b>FA 1959</b>		220910C
<b>KS 28</b>	221029 <b>FD 3031 V</b>	220901 <b>FA 1266 AL</b>		220910C
<b>KS 35</b>	221029 <b>FD 3031 V</b>	220901 <b>FA 1266 AL</b>		220910C
<b>KS 4</b>	221055 <b>FD 3034 V</b>	223452 <b>FA 2110</b>		220977 <b>FO 0339 V</b>
<b>KS 44</b>	221022 <b>FD 3464</b>	220959 <b>FA 1418 AL</b>		220910C
<b>KS 5</b>	221055 <b>FD 3034 V</b>	223452 <b>FA 2110</b>		220977 <b>FO 0339 V</b>
<b>KS 58</b>	221022 <b>FD 3464</b>	220868 <b>FA 2117</b>		220910C
<b>KS 67</b>	221022 <b>FD 3464</b>	220868 <b>FA 2117</b>		220910C
<b>KS 7</b>	221055 <b>FD 3034 V</b>	223452 <b>FA 2110</b>		220977 <b>FO 0339 V</b>
<b>KS 9</b>	221046 <b>FD 3096 V</b>	220913 <b>FA 1959</b>		220977 <b>FO 0339 V</b>
<b>KS 96</b>	223456 <b>FD 3592</b>	223469 <b>FA 5500</b>		223475 <b>FO 0100 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>BOTTARINI</b>				
	<i>MK 7</i>			
<i>MK 7</i>	221055 <b>FD 3034 V</b>			220977 <b>FO 0339 V</b>
<i>MP 10</i>	221055 <b>FD 3034 V</b>	223452 <b>FA 2110</b>		240621
<i>MP 5</i>	240610	223452 <b>FA 2110</b>		240621
<i>MP 7</i>	221055 <b>FD 3034 V</b>	223452 <b>FA 2110</b>		240621
<i>MSC 43</i>		220981 <b>FA 1212 AL</b>		
<i>MSC 43 SS</i>	221029 <b>FD 3031 V</b>	220981 <b>FA 1212 AL</b>		220910C
<i>SP 10</i>		222731 <b>FA 2071</b>		
<i>SP 12</i>		222731 <b>FA 2071</b>		
<i>SP 7</i>		222731 <b>FA 2071</b>		
<i>SP 9</i>		222731 <b>FA 2071</b>		
<b>BUSCH</b>				
<i>EVA CB 0220</i>	532507 <b>FD 3055</b>			531001 <b>FI 1306 V</b>
<i>EVA CB 0250</i>	532507 <b>FD 3055</b>			531001 <b>FI 1306 V</b>
<i>KB 0010 D</i>	532105216 <b>FD 3420</b>			
<i>KB 0016 D</i>	532105216 <b>FD 3420</b>			
<i>R 5 004 B</i>	532000208 <b>FD 3413</b>			
<i>R 5 010</i>	532300 <b>FD 3394</b>	532000005 <b>FA 1665</b>		
<i>R 5 010 C</i>	532216 <b>FD 3420</b>	532000005 <b>FA 1665</b>		
<i>R 5 010 D</i>	532216 <b>FD 3420</b>	532000005 <b>FA 1665</b>		
<i>R 5 012 B</i>	532000510 <b>FD 3148</b>	532000005 <b>FA 1665</b>		
<i>R 5 016</i>	532300 <b>FD 3394</b>	532000005 <b>FA 1665</b>		
<i>R 5 016 C</i>	532216 <b>FD 3420</b>	532000005 <b>FA 1665</b>		
<i>R 5 016 D</i>	532216 <b>FD 3420</b>	532000005 <b>FA 1665</b>		
<i>R 5 0160 B</i>	532000508 <b>FD 3054</b>	530000001 <b>FA 2058</b>		531000001 <b>FI 1306 V</b>
<i>R 5 0160 C</i>	532000508 <b>FD 3054</b>	530000001 <b>FA 2058</b>		531000001 <b>FI 1306 V</b>
<i>R 5 0160-116</i>	532000303 <b>FD 3137</b>			531000001 <b>FI 1306 V</b>
<i>R 5 021 B</i>	532000510 <b>FD 3148</b>	532000005 <b>FA 1665</b>		



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>BUSCH</b>				
<i>R 5 025</i>				
<i>R 5 025</i>	532000302 <b>FD 3136</b>	532000005 <b>FA 1665</b>		531002 <b>FO 0022 V</b>
<i>R 5 025 B</i>	532000302 <b>FD 3136</b>	532000005 <b>FA 1665</b>		531002 <b>FO 0022 V</b>
<i>R 5 025 C</i>	532000512 <b>FD 3391</b>	532000005 <b>FA 1665</b>		531002 <b>FO 0022 V</b>
<i>R 5 025 E</i>	532000512 <b>FD 3391</b>	532000002		531002 <b>FO 0022 V</b>
<i>R 5 0250 B</i>	532000508 <b>FD 3054</b>	530000001 <b>FA 2058</b>		531000001 <b>FI 1306 V</b>
<i>R 5 0250 C</i>	532000508 <b>FD 3054</b>	530000001 <b>FA 2058</b>		531000001 <b>FI 1306 V</b>
<i>R 5 0250-116</i>	532000303 <b>FD 3137</b>			531000001 <b>FI 1306 V</b>
<i>R 5 0300 B</i>	532000508 <b>FD 3054</b>			531000001 <b>FI 1306 V</b>
<i>R 5 0300 C</i>	532000508 <b>FD 3054</b>			531000001 <b>FI 1306 V</b>
<i>R 5 0302 D</i>	532000508 <b>FD 3054</b>			
<i>R 5 040 B</i>	532000302 <b>FD 3136</b>	532000005 <b>FA 1665</b>		531002 <b>FO 0022 V</b>
<i>R 5 040 C</i>	532000512 <b>FD 3391</b>	532000005 <b>FA 1665</b>		531002 <b>FO 0022 V</b>
<i>R 5 040 E</i>	532000512 <b>FD 3391</b>	532000002		531002 <b>FO 0022 V</b>
<i>R 5 0400-212</i>	532000304 <b>FD 3138</b>	532000006 <b>FA 1108</b>		531005 <b>FO 0148 V</b>
<i>R 5 0502 B</i>	532000304 <b>FD 3138</b>			531005 <b>FO 0148 V</b>
<i>R 5 055 C</i>	532000512 <b>FD 3391</b>			531002 <b>FO 0022 V</b>
<i>R 5 055 E</i>	532000512 <b>FD 3391</b>			531002 <b>FO 0022 V</b>
<i>R 5 063 B</i>	532000302 <b>FD 3136</b>	532000002		531002 <b>FO 0022 V</b>
<i>R 5 063 C</i>	532000302 <b>FD 3136</b>	532000002		531002 <b>FO 0022 V</b>
<i>R 5 063 E</i>	532000302 <b>FD 3136</b>	532000002		531002 <b>FO 0022 V</b>
<i>R 5 0630-212</i>	532000304 <b>FD 3138</b>	532000006 <b>FA 1108</b>		531005 <b>FO 0148 V</b>
<i>R 5 100</i>	532000302 <b>FD 3136</b>	532000002		531002 <b>FO 0022 V</b>
<i>R 5 100 B</i>	532000302 <b>FD 3136</b>	532000003 <b>FA 1657</b>		531002 <b>FO 0022 V</b>
<i>R 5 100 C</i>	532000302 <b>FD 3136</b>	532000003 <b>FA 1657</b>		531002 <b>FO 0022 V</b>
<i>R 5 100 E</i>	532000302 <b>FD 3136</b>	532000003 <b>FA 1657</b>		531002 <b>FO 0022 V</b>
<i>R 5 1000 B</i>	532000304 <b>FD 3138</b>			531005 <b>FO 0148 V</b>
<i>R 5 160</i>	532000303 <b>FD 3137</b>	532004003 <b>FA 1628</b>		531000001 <b>FI 1306 V</b>





	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>BUSCH</b>				
<i>R 5 160 B</i>				
<i>R 5 160 B</i>	532000303 <b>FD 3137</b>	532004003 <b>FA 1628</b>		531000001 <b>FI 1306 V</b>
<i>R 5 160 C</i>	532000303 <b>FD 3137</b>	532004003 <b>FA 1628</b>		531000001 <b>FI 1306 V</b>
<i>R 5 160 D</i>	532000303 <b>FD 3137</b>	532004003 <b>FA 1628</b>		531000001 <b>FI 1306 V</b>
<i>R 5 1600 B</i>	532000304 <b>FD 3138</b>			531005 <b>FO 0148 V</b>
<i>R 5 165 D</i>	532000303 <b>FD 3137</b>			531000001 <b>FI 1306 V</b>
<i>R 5 202 D</i>	532000303 <b>FD 3137</b>			531000001 <b>FI 1306 V</b>
<i>R 5 205 D</i>	532000303 <b>FD 3137</b>			531000001 <b>FI 1306 V</b>
<i>R 5 250</i>	532000303 <b>FD 3137</b>	532004003 <b>FA 1628</b>		531000001 <b>FI 1306 V</b>
<i>R 5 250 B</i>	532000303 <b>FD 3137</b>	532004003 <b>FA 1628</b>		531000001 <b>FI 1306 V</b>
<i>R 5 250 C</i>	532000303 <b>FD 3137</b>	532004003 <b>FA 1628</b>		531000001 <b>FI 1306 V</b>
<i>R 5 250 D</i>	532000303 <b>FD 3137</b>	532004003 <b>FA 1628</b>		531000001 <b>FI 1306 V</b>
<i>R 5 255 D</i>	532000303 <b>FD 3137</b>	532004003 <b>FA 1628</b>		531000001 <b>FI 1306 V</b>
<i>R 5 302 D</i>	532000303 <b>FD 3137</b>			531000001 <b>FI 1306 V</b>
<i>R 5 305 D</i>	532000303 <b>FD 3137</b>			531000001 <b>FI 1306 V</b>
<i>R 5 400</i>	532000304 <b>FD 3138</b>	532000006 <b>FA 1108</b>		531005 <b>FO 0148 V</b>
<i>R 5 400 B</i>	532000304 <b>FD 3138</b>	532000006 <b>FA 1108</b>		531005 <b>FO 0148 V</b>
<i>R 5 630</i>	532000304 <b>FD 3138</b>	532000006 <b>FA 1108</b>		531005 <b>FO 0148 V</b>
<i>R 5 630 B</i>	532000304 <b>FD 3138</b>	532000006 <b>FA 1108</b>		531005 <b>FO 0148 V</b>
<i>R5/RA/RC 0004 B</i>	532208 <b>FD 3413</b>			
<i>R5/RA/RC 0006 B</i>	532208 <b>FD 3413</b>			
<i>R5/RA/RC 0010 B</i>	532300 <b>FD 3394</b>	532005 <b>FA 1665</b>		
<i>R5/RA/RC 0010 C</i>	532105216 <b>FD 3420</b>	532005 <b>FA 1665</b>		
<i>R5/RA/RC 0010 D</i>	532105216 <b>FD 3420</b>	532005 <b>FA 1665</b>		
<i>R5/RA/RC 0012</i>	532510 <b>FD 3148</b>	532005 <b>FA 1665</b>		
<i>R5/RA/RC 0012 B</i>	532510 <b>FD 3148</b>	532005 <b>FA 1665</b>		
<i>R5/RA/RC 0016 B</i>	532300 <b>FD 3394</b>	532005 <b>FA 1665</b>		
<i>R5/RA/RC 0016 C</i>	532105216 <b>FD 3420</b>	532005 <b>FA 1665</b>		



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>BUSCH</b>				
<i>R5/RA/RC 0016 D</i>				
<i>R5/RA/RC 0016 D</i>	532105216 <b>FD 3420</b>	532005 <b>FA 1665</b>		
<i>R5/RA/RC 0018 D</i>	532105216 <b>FD 3420</b>	532005 <b>FA 1665</b>		
<i>R5/RA/RC 0020 D</i>	532105216 <b>FD 3420</b>	532005 <b>FA 1665</b>		
<i>R5/RA/RC 0021</i>	532510 <b>FD 3148</b>	532005 <b>FA 1665</b>		
<i>R5/RA/RC 0021 B</i>	532510 <b>FD 3148</b>	532005 <b>FA 1665</b>		
<i>R5/RA/RC 0025</i>	532302 <b>FD 3136</b>	532005 <b>FA 1665</b>		531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0025 B</i>	532302 <b>FD 3136</b>	532005 <b>FA 1665</b>		531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0025 C</i>	532512 <b>FD 3391</b>	532005 <b>FA 1665</b>		531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0025 E</i>	532512 <b>FD 3391</b>	532002		531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0040</i>	532302 <b>FD 3136</b>	532005 <b>FA 1665</b>		531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0040 B</i>	532302 <b>FD 3136</b>	532005 <b>FA 1665</b>		531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0040 C</i>	532512 <b>FD 3391</b>	532005 <b>FA 1665</b>		531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0040 E</i>	532512 <b>FD 3391</b>	532005 <b>FA 1665</b>		531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0055 C</i>	532512 <b>FD 3391</b>			531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0055 E</i>	532512 <b>FD 3391</b>			531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0063</i>	532302 <b>FD 3136</b>	532002		531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0063 B</i>	532302 <b>FD 3136</b>	532002		531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0063 C</i>	532302 <b>FD 3136</b>	532002		531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0063 E</i>	532302 <b>FD 3136</b>	532002		531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0100 B</i>	532302 <b>FD 3136</b>	532003 <b>FA 1657</b>		531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0100 B5M1 (0100-131)</i>	532301 <b>FD 3424</b>			
<i>R5/RA/RC 0100 C</i>	532302 <b>FD 3136</b>	532003 <b>FA 1657</b>		531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0100 E</i>	532302 <b>FD 3136</b>	532003 <b>FA 1657</b>		531002 <b>FO 0022 V</b>
<i>R5/RA/RC 0160 B</i>	532303 <b>FD 3137</b>	532004 <b>FA 1628</b>		531001 <b>FI 1306 V</b>
<i>R5/RA/RC 0160 C</i>	532303 <b>FD 3137</b>	532004 <b>FA 1628</b>		531001 <b>FI 1306 V</b>
<i>R5/RA/RC 0160 D</i>	532303 <b>FD 3137</b>	532004 <b>FA 1628</b>		531001 <b>FI 1306 V</b>
<i>R5/RA/RC 0160-116</i>	532303 <b>FD 3137</b>			531001 <b>FI 1306 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>BUSCH</b>				
<i>R5/RA/RC 0165 D</i>				
<i>R5/RA/RC 0165 D</i>	532303 <b>FD 3137</b>			531001 <b>FI 1306 V</b>
<i>R5/RA/RC 0202 D</i>	532303 <b>FD 3137</b>			531001 <b>FI 1306 V</b>
<i>R5/RA/RC 0205 D</i>	532303 <b>FD 3137</b>			531001 <b>FI 1306 V</b>
<i>R5/RA/RC 0250</i>	532303 <b>FD 3137</b>	532004 <b>FA 1628</b>		531001 <b>FI 1306 V</b>
<i>R5/RA/RC 0250 B</i>	532303 <b>FD 3137</b>	532004 <b>FA 1628</b>		531001 <b>FI 1306 V</b>
<i>R5/RA/RC 0250 C</i>	532303 <b>FD 3137</b>	532004 <b>FA 1628</b>		531001 <b>FI 1306 V</b>
<i>R5/RA/RC 0250 D</i>	532303 <b>FD 3137</b>	532004 <b>FA 1628</b>		531001 <b>FI 1306 V</b>
<i>R5/RA/RC 0250-116</i>	532303 <b>FD 3137</b>			531001 <b>FI 1306 V</b>
<i>R5/RA/RC 0255 D</i>	532303 <b>FD 3137</b>			531001 <b>FI 1306 V</b>
<i>R5/RA/RC 0302 D</i>	532303 <b>FD 3137</b>			531001 <b>FI 1306 V</b>
<i>R5/RA/RC 0305 D</i>	532303 <b>FD 3137</b>			531001 <b>FI 1306 V</b>
<i>R5/RA/RC 0400 B</i>	532304 <b>FD 3138</b>	532006 <b>FA 1108</b>		531005 <b>FO 0148 V</b>
<i>R5/RA/RC 0400-212</i>	532304 <b>FD 3138</b>	532006 <b>FA 1108</b>		531005 <b>FO 0148 V</b>
<i>R5/RA/RC 0502 B</i>	532304 <b>FD 3138</b>			531005 <b>FO 0148 V</b>
<i>R5/RA/RC 0630 B</i>	532304 <b>FD 3138</b>	532006 <b>FA 1108</b>		531005 <b>FO 0148 V</b>
<i>R5/RA/RC 0630-212</i>	532304 <b>FD 3138</b>	532006 <b>FA 1108</b>		531005 <b>FO 0148 V</b>
<i>R5/RA/RC 0800</i>	532304 <b>FD 3138</b>			
<i>R5/RA/RC 1000 B</i>	532304 <b>FD 3138</b>	532007 <b>FA 1302</b>		531005 <b>FO 0148 V</b>
<i>R5/RA/RC 1600 B</i>	532304 <b>FD 3138</b>	532007 <b>FA 1302</b>		531005 <b>FO 0148 V</b>
<i>RE 0016 B</i>	532127413 <b>FD 3394</b>			
<i>RE 0040/0063 B</i>	532127413 <b>FD 3394</b>			
<b>CECCATO</b>				
<i>CRA 10 MOD. 7432</i>	640510 <b>FD 3133</b>	641115 <b>FA 0010</b>		640509 <b>FO 0029 V</b>
<i>CRA 100 MOD. 7546</i>	640511 <b>FD 3437</b>	641128 <b>FA 1106</b>		641130 <b>FO 0030 V</b>
<i>CRA 100 NEW TYPE</i>	640511 <b>FD 3437</b>	641128 <b>FA 1106</b>		641130 <b>FO 0030 V</b>
<i>CRA 125 MOD. 7564</i>	640511 <b>FD 3437</b>	641129 <b>FA 1252</b>		641130 <b>FO 0030 V</b>
<i>CRA 125 NEW TYPE</i>	640511 <b>FD 3437</b>	641129 <b>FA 1252</b>		641130 <b>FO 0030 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>CECCATO</b>				
<i>CRA 15 H</i>				
<i>CRA 15 H</i>	641125 <b>FD 3062</b>	641122 <b>FA 2014</b>		640211 <b>FI 1288 V</b>
<i>CRA 15 MK MOD. 7546</i>	640910 <b>FD 3036</b>	641121		641123 <b>FO 0029 V</b>
<i>CRA 15 MOD. 7540</i>	641125 <b>FD 3062</b>	640609 <b>FA 1442</b>		640211 <b>FI 1288 V</b>
<i>CRA 15 MOD. 7544</i>	641125 <b>FD 3062</b>	640609 <b>FA 1442</b>		640211 <b>FI 1288 V</b>
<i>CRA 150 MOD. 7566</i>	640511 <b>FD 3437</b>	641129 <b>FA 1252</b>		641130 <b>FO 0030 V</b>
<i>CRA 150 NEW TYPE</i>	640511 <b>FD 3437</b>	641129 <b>FA 1252</b>		641130 <b>FO 0030 V</b>
<i>CRA 20 MOD. 7541</i>	641125 <b>FD 3062</b>	640609 <b>FA 1442</b>		640211 <b>FI 1288 V</b>
<i>CRA 220</i>	640565 <b>FD 3012</b>	640095 <b>FA 1468</b>		640557 <b>FI 1045 V</b>
<i>CRA 25 MK MOD. 7547</i>	640911 <b>FD 3464</b>	641122 <b>FA 2014</b>		640211 <b>FI 1288 V</b>
<i>CRA 25 MOD. 7542</i>	641125 <b>FD 3062</b>	640609 <b>FA 1442</b>		640211 <b>FI 1288 V</b>
<i>CRA 25 MOD. 7545</i>	641125 <b>FD 3062</b>	640609 <b>FA 1442</b>		640211 <b>FI 1288 V</b>
<i>CRA 30 MOD. 7455</i>	641403 <b>FD 3009</b>	640610 <b>FA 1111</b>		640608 <b>FO 0148 V</b>
<i>CRA 30 MOD. 7548</i>	641125 <b>FD 3062</b>	640609 <b>FA 1442</b>		640211 <b>FI 1288 V</b>
<i>CRA 30 MOD. 7560</i>	641403 <b>FD 3009</b>			
<i>CRA 40 MOD. 7456</i>	641403 <b>FD 3009</b>	640610 <b>FA 1111</b>		640608 <b>FO 0148 V</b>
<i>CRA 40 MOD. 7561</i>	641403 <b>FD 3009</b>	641120 <b>FA 1219</b>		640608 <b>FO 0148 V</b>
<i>CRA 5.5 MOD. 7430</i>	640510 <b>FD 3133</b>	641115 <b>FA 0010</b>		640509 <b>FO 0029 V</b>
<i>CRA 50 MOD. 7457</i>	641403 <b>FD 3009</b>	640610 <b>FA 1111</b>		640608 <b>FO 0148 V</b>
<i>CRA 60 MOD. 7458</i>	640912 <b>FD 3081</b>	640613 <b>FA 1102</b>		640608 <b>FO 0148 V</b>
<i>CRA 60 MOD. 7562</i>	641104 <b>FD 3042</b>	930568 <b>FA 1105</b>		640608 <b>FO 0148 V</b>
<i>CRA 7.5 MOD. 7431</i>	640510 <b>FD 3133</b>	641115 <b>FA 0010</b>		640509 <b>FO 0029 V</b>
<i>CRA 75 MOD. 7459</i>	640912 <b>FD 3081</b>	640613 <b>FA 1102</b>		640608 <b>FO 0148 V</b>
<i>CRA 75 MOD. 7563</i>	641104 <b>FD 3042</b>	930568 <b>FA 1105</b>		640608 <b>FO 0148 V</b>
<i>CSA 10</i>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		640509 <b>FO 0029 V</b>
<i>CSA 15</i>	640593 <b>FD 3563 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>CSA 15 INVERTER</i>	640593 <b>FD 3563 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>CSA 20</i>	640593 <b>FD 3563 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>CECCATO</b>				
<i>CSA 20 INVERTER</i>				
<i>CSA 20 INVERTER</i>	640593 <b>FD 3563 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>CSA 5.5</i>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		640509 <b>FO 0029 V</b>
<i>CSA 7.5</i>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		640509 <b>FO 0029 V</b>
<i>CSB 15</i>	2200641140 <b>FD 3649</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>CSB 20</i>	2200641140 <b>FD 3649</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>CSB 25</i>	2200641141 <b>FD 3595 V</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<i>CSB 30</i>	2200641141 <b>FD 3595 V</b>	640551 <b>FA 0023</b>		
<i>CSB 30 INVERTER</i>	2200641141 <b>FD 3595 V</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<i>CSB 40</i>	2200641141 <b>FD 3595 V</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<i>CSB GENER. 2 15-20-25 HP</i>	6221372450 <b>FD 3373 V</b>	6211472300 <b>FA 2050</b>		6211472250 <b>FO 0148 V</b>
<i>CSB GENER. 2 30-40 HP</i>	6212372550 <b>FD 3031 V</b>	6211472300 <b>FA 2050</b>		6211472250 <b>FO 0148 V</b>
<i>CSC 30</i>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		2202260271 <b>FO 0148 V</b>
<i>CSC 40</i>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		2202260271 <b>FO 0148 V</b>
<i>CSC 50 FROM SERIES No. CAI088250</i>	640584 <b>FD 3560</b>	641128 <b>FA 1106</b>		2202260271 <b>FO 0148 V</b>
<i>CSC 50 INVERTER</i>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		2202260271 <b>FO 0148 V</b>
<i>CSC 50 UP TO SERIES No. CAI088249</i>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		2202260271 <b>FO 0148 V</b>
<i>CSC 60</i>	640584 <b>FD 3560</b>	641128 <b>FA 1106</b>		2202260271 <b>FO 0148 V</b>
<i>CSC 60 INVERTER</i>	640584 <b>FD 3560</b>	641128 <b>FA 1106</b>		2202260271 <b>FO 0148 V</b>
<i>CSC 75</i>	640584 <b>FD 3560</b>	641128 <b>FA 1106</b>		2202260271 <b>FO 0148 V</b>
<i>CSD 100 INVERTER</i>	640594 <b>FD 3462</b>	2202730600 <b>FA 5134</b>		2202260271 <b>FO 0148 V</b>
<i>CSD 125</i>	640594 <b>FD 3462</b>	2202730600 <b>FA 5134</b>		2202260271 <b>FO 0148 V</b>
<i>CSD 75 INVERTER</i>	640594 <b>FD 3462</b>	2202730600 <b>FA 5134</b>		2202260271 <b>FO 0148 V</b>
<i>CSM 10</i>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		2202726102 <b>FO 0029 V</b>
<i>CSM 15</i>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		2202726102 <b>FO 0029 V</b>
<i>CSM 20</i>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		2202726102 <b>FO 0029 V</b>
<i>CSM 3</i>	2200641142 <b>FD 3596</b>	2200640815 <b>FA 2982</b>		640509 <b>FO 0029 V</b>
<i>CSM 4</i>	2200641142 <b>FD 3596</b>	2200640815 <b>FA 2982</b>		640509 <b>FO 0029 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>CECCATO</b>				
<i>CSM 5.5</i>				
<i>CSM 5.5</i>	2200641142 <b>FD 3596</b>	2200640815 <b>FA 2982</b>		640509 <b>FO 0029 V</b>
<i>CSM 7.5</i>	2200641142 <b>FD 3596</b>	2200640815 <b>FA 2982</b>		640509 <b>FO 0029 V</b>
<i>DRA 100</i>	6221338300 <b>FD 3594</b>	6211459400 <b>FA 5854</b>		6211441200 <b>FO 0280 V</b>
<i>DRA 100 FROM SERIES No. 550099</i>	6221338300 <b>FD 3594</b>	6211459400 <b>FA 5854</b>		6211441250 <b>FI 1062 V</b>
<i>DRA 100 UP TO SERIES No. 550098</i>	6221338300 <b>FD 3594</b>	6211460500 <b>FA 1485 AL</b>		6211441250 <b>FI 1062 V</b>
<i>DRA 125</i>	6221338300 <b>FD 3594</b>	6211459400 <b>FA 5854</b>		6211441200 <b>FO 0280 V</b>
<i>DRA 125 FROM SERIES No. 550099</i>	6221338300 <b>FD 3594</b>	6211459400 <b>FA 5854</b>		6211441250 <b>FI 1062 V</b>
<i>DRA 125 UP TO SERIES No. 550098</i>	6221338300 <b>FD 3594</b>	6211460500 <b>FA 1485 AL</b>		6211441250 <b>FI 1062 V</b>
<i>DRA 150</i>	6221341600 <b>FD 3272</b>	6211460400 <b>FA 5932</b>		6211441200 <b>FO 0280 V</b>
<i>DRA 180</i>	6221341600 <b>FD 3272</b>	6211460400 <b>FA 5932</b>		6211441200 <b>FO 0280 V</b>
<i>DRA 220</i>	6221341600 <b>FD 3272</b>	6211460400 <b>FA 5932</b>		6211441200 <b>FO 0280 V</b>
<i>DRA 220 INVERTER</i>	6221341600 <b>FD 3272</b>	6211460400 <b>FA 5932</b>		6211441250 <b>FI 1062 V</b>
<i>DRA 75</i>	6221338300 <b>FD 3594</b>	6211459400 <b>FA 5854</b>		6211441200 <b>FO 0280 V</b>
<i>DRA 75 FROM SERIES No. 550099</i>	6221338300 <b>FD 3594</b>	6211459400 <b>FA 5854</b>		6211441250 <b>FI 1062 V</b>
<i>DRA 75 UP TO SERIES No. 550098</i>	6221338300 <b>FD 3594</b>	6211460500 <b>FA 1485 AL</b>		6211441250 <b>FI 1062 V</b>
<i>DRD 40</i>	2202773001 <b>FD 3665</b>	2202772901 <b>FA 5500</b>		6211441255 <b>FI 1062 V</b>
<i>DRD 50</i>	2202773001 <b>FD 3665</b>	2202772901 <b>FA 5500</b>		6211441255 <b>FI 1062 V</b>
<i>DRD 60</i>	2202773001 <b>FD 3665</b>	2202772901 <b>FA 5500</b>		6211441255 <b>FI 1062 V</b>
<i>DRD 75</i>	2202773001 <b>FD 3665</b>	2202772901 <b>FA 5500</b>		6211441255 <b>FI 1062 V</b>
<i>DRE 100 INVERTER</i>	6221338300 <b>FD 3594</b>	6211459450 <b>FA 5854</b>		6211441255 <b>FI 1062 V</b>
<i>DRE 125</i>	6221363500 <b>FD 3604</b>	6211466050 <b>FA 5134</b>		6211441255 <b>FI 1062 V</b>
<i>DRE 75 INVERTER</i>	6221338300 <b>FD 3594</b>	6211459450 <b>FA 5854</b>		6211441255 <b>FI 1062 V</b>
<i>DRF 150</i>	6219098400 <b>FD 3272</b>	6211460400 <b>FA 5932</b>		6211441255 <b>FI 1062 V</b>
<i>DRF 180</i>	6219098400 <b>FD 3272</b>	6211460400 <b>FA 5932</b>		6211441255 <b>FI 1062 V</b>
<i>DRF 220</i>	6219098400 <b>FD 3272</b>	6211460400 <b>FA 5932</b>		6211441255 <b>FI 1062 V</b>
<i>MSC 22</i>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		2202260271 <b>FO 0148 V</b>
<i>MSC 37</i>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		2202260271 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>CECCATO</b>				
<i>MSC 45</i>				
<i>MSC 45</i>	640584 <b>FD 3560</b>	641128 <b>FA 1106</b>		2202260271 <b>FO 0148 V</b>
<i>MSC 55</i>	640584 <b>FD 3560</b>	641128 <b>FA 1106</b>		2202260271 <b>FO 0148 V</b>
<i>MSM 11</i>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		2202726102 <b>FO 0029 V</b>
<i>MSM 15</i>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		2202726102 <b>FO 0029 V</b>
<i>MSM 2.2</i>	2200641142 <b>FD 3596</b>	2200640815 <b>FA 2982</b>		640509 <b>FO 0029 V</b>
<i>MSM 3</i>	2200641142 <b>FD 3596</b>	2200640815 <b>FA 2982</b>		640509 <b>FO 0029 V</b>
<i>MSM 4</i>	2200641142 <b>FD 3596</b>	2200640815 <b>FA 2982</b>		640509 <b>FO 0029 V</b>
<i>MSM 5.5</i>	2200641142 <b>FD 3596</b>	2200640815 <b>FA 2982</b>		640509 <b>FO 0029 V</b>
<i>MSM 7.5</i>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		2202726102 <b>FO 0029 V</b>
<i>RA 100</i>	930571 <b>FD 3192</b>	930570 <b>FA 1252</b>		640608 <b>FO 0148 V</b>
<i>RA 125</i>	930571 <b>FD 3192</b>	930570 <b>FA 1252</b>		640608 <b>FO 0148 V</b>
<i>RA 150</i>	930571 <b>FD 3192</b>	930570 <b>FA 1252</b>		640608 <b>FO 0148 V</b>
<i>RA 40</i>	930578 <b>FD 3061</b>	930568 <b>FA 1105</b>		640608 <b>FO 0148 V</b>
<i>RA 60</i>	930569 <b>FD 3005</b>	930577 <b>FA 1249</b>		930299
<i>RL 100</i>	641403 <b>FD 3009</b>	641128 <b>FA 1106</b>		640608 <b>FO 0148 V</b>
<i>RL 100 MOD. 717598</i>	640594 <b>FD 3462</b>	641128 <b>FA 1106</b>		640608 <b>FO 0148 V</b>
<i>RL 30</i>	641137 <b>FD 3031 V</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>
<i>RL 30 MOD. 7170/80/90</i>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>
<i>RL 30 MOD. 7270/80/90</i>	641137 <b>FD 3031 V</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>
<i>RL 30 MOD. 7273/83/93</i>	641137 <b>FD 3031 V</b>	640610 <b>FA 1111</b>		640608 <b>FO 0148 V</b>
<i>RL 40</i>	641137 <b>FD 3031 V</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>
<i>RL 40 MOD. 7171/81/91</i>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		
<i>RL 40 MOD. 7271/81/91</i>	641137 <b>FD 3031 V</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>
<i>RL 40 MOD. 7274/84/94</i>	641137 <b>FD 3031 V</b>	640610 <b>FA 1111</b>		640608 <b>FO 0148 V</b>
<i>RL 50</i>	641137 <b>FD 3031 V</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>
<i>RL 50 INVERTER</i>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		2202200271 <b>FO 0148 V</b>
<i>RL 50 MOD. 7172/82/92</i>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>CECCATO</b>				
<i>RL 50 MOD. 7272/82/92</i>				
<i>RL 50 MOD. 7272/82/92</i>	641137 <b>FD 3031 V</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>
<i>RL 50 MOD. 7275/85/95</i>	641137 <b>FD 3031 V</b>	640610 <b>FA 1111</b>		640608 <b>FO 0148 V</b>
<i>RL 60</i>	641137 <b>FD 3031 V</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>
<i>RL 60 MOD. 7173/83/93</i>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>
<i>RL 60 MOD. 7276/86/96</i>	641137 <b>FD 3031 V</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>
<i>RL 75</i>	641403 <b>FD 3009</b>	641128 <b>FA 1106</b>		640608 <b>FO 0148 V</b>
<i>RL 75 INVERTER</i>	640594 <b>FD 3462</b>	641128 <b>FA 1106</b>		2202260271 <b>FO 0148 V</b>
<i>RL 75 MOD. 717498</i>	640594 <b>FD 3462</b>	641128 <b>FA 1106</b>		640608 <b>FO 0148 V</b>
<i>RLC 10</i>	640510 <b>FD 3133</b>	641115 <b>FA 0010</b>		640509 <b>FO 0029 V</b>
<i>RLC 15</i>	640552 <b>FD 3373 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>RLC 20</i>	640552 <b>FD 3373 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>RLC 5.5</i>	640510 <b>FD 3133</b>	641115 <b>FA 0010</b>		640509 <b>FO 0029 V</b>
<i>RLC 7.5</i>	640510 <b>FD 3133</b>	641115 <b>FA 0010</b>		640509 <b>FO 0029 V</b>
<i>RLE 15</i>	640552 <b>FD 3373 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>RLE 20</i>	640552 <b>FD 3373 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>RLE 25</i>	640552 <b>FD 3373 V</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<i>RLE 30</i>	640552 <b>FD 3373 V</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<i>RLE 40</i>	641137 <b>FD 3031 V</b>	640550 <b>FA 1943</b>		640211 <b>FI 1288 V</b>
<i>RLI 10</i>	640510 <b>FD 3133</b>	641115 <b>FA 0010</b>		640509 <b>FO 0029 V</b>
<i>RLI 11</i>	640552 <b>FD 3373 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>RLI 20</i>	640552 <b>FD 3373 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>RLI 5.5</i>	640510 <b>FD 3133</b>	641115 <b>FA 0010</b>		640509 <b>FO 0029 V</b>
<i>RLI 7.5</i>	640510 <b>FD 3133</b>	641115 <b>FA 0010</b>		640509 <b>FO 0029 V</b>
<i>RLX 60</i>	641403 <b>FD 3009</b>	641128 <b>FA 1106</b>		640608 <b>FO 0148 V</b>
<i>RLX 75</i>	641403 <b>FD 3009</b>	641128 <b>FA 1106</b>		640608 <b>FO 0148 V</b>
<i>TLE 30</i>	640552 <b>FD 3373 V</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<b>CHINOOK</b>				





	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>CHINOOK</b> <i>SCI 6</i>				
<i>SCI 6</i>	11703330 <b>FD 3034 V</b>			11716230
<i>SCI 7</i>	11703330 <b>FD 3034 V</b>	15601450		11716230
<i>SCI 8</i>	11700720 <b>FD 3096 V</b>	15601450		11716230
<b>COMPAIR</b>				
<i>6000 E</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6007 EA</i>	98262120 <b>FD 3218</b>	9826290 <b>FA 1684</b>		98262135 <b>FO 0420 V</b>
<i>6010 E</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6010 EA</i>	98262120 <b>FD 3218</b>	9826290 <b>FA 1684</b>		98262135 <b>FO 0420 V</b>
<i>6012</i>	98262102 <b>FD 3038</b>			
<i>6015 E</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6015 EA</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6020 E</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6020 EA</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6025 E</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6025 EA</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6030</i>	98262108 <b>FD 3085</b>	98262109 <b>FA 1626</b>		98262220 <b>FO 0148 V</b>
<i>6030 AS</i>	9826277 <b>FD 3180</b>	C1601252 <b>FA 1241</b>		98262220 <b>FO 0148 V</b>
<i>6030 E</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6030 EA</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6040</i>	98262108 <b>FD 3085</b>	98262109 <b>FA 1626</b>		98262220 <b>FO 0148 V</b>
<i>6040 AS</i>	9826277 <b>FD 3180</b>	C1601252 <b>FA 1241</b>		98262220 <b>FO 0148 V</b>
<i>6040 EA</i>	98262121 <b>FD 3195</b>	9826286 <b>FA 2020</b>		98262220 <b>FO 0148 V</b>
<i>6040 EA NEW TYPE</i>	98262121 <b>FD 3195</b>	9826286 <b>FA 2020</b>		98262220 <b>FO 0148 V</b>
<i>6040 EL</i>	98262121 <b>FD 3195</b>	9826286 <b>FA 2020</b>		98262220 <b>FO 0148 V</b>
<i>6040 EL NEW TYPE</i>	98262121 <b>FD 3195</b>	9826286 <b>FA 2020</b>		98262220 <b>FO 0148 V</b>
<i>6040 N</i>	98262121 <b>FD 3195</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<i>6040 N NEW TYPE</i>	98262121 <b>FD 3195</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>COMPAIR</b>	<b>6050</b>			
<b>6050</b>	9826277 <b>FD 3180</b>	C1601252 <b>FA 1241</b>		98262220 <b>FO 0148 V</b>
<b>6050 AS</b>	9826277 <b>FD 3180</b>	C1601252 <b>FA 1241</b>		98262220 <b>FO 0148 V</b>
<b>6050 EL</b>	98262121 <b>FD 3195</b>	9826286 <b>FA 2020</b>		98262220 <b>FO 0148 V</b>
<b>6050 EL NEW TYPE</b>	98262121 <b>FD 3195</b>	9826286 <b>FA 2020</b>		98262220 <b>FO 0148 V</b>
<b>6050 N</b>	98262121 <b>FD 3195</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<b>6050 N NEW TYPE</b>	98262121 <b>FD 3195</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<b>6060</b>	9826223 <b>FD 3005</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<b>6060 N</b>	98262162 <b>FD 3072</b>	C16012189 <b>FA 1106</b>		98262220 <b>FO 0148 V</b>
<b>6075</b>	9826223 <b>FD 3005</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<b>6075 N</b>	98262162 <b>FD 3072</b>	C16012189 <b>FA 1106</b>		98262220 <b>FO 0148 V</b>
<b>6100</b>	9826226 <b>FD 3192</b>	C111581014 <b>FA 1105</b>		98262219 <b>FO 0030 V</b>
<b>6100 N</b>	9826226 <b>FD 3192</b>	C111581041 <b>FA 1252</b>		98262219 <b>FO 0030 V</b>
<b>6115</b>	9826226 <b>FD 3192</b>	C111581014 <b>FA 1105</b>		98262219 <b>FO 0030 V</b>
<b>6125</b>	9826226 <b>FD 3192</b>	C111581014 <b>FA 1105</b>		98262219 <b>FO 0030 V</b>
<b>6150</b>	9826278 <b>FD 3040</b>	C111581390 <b>FA 1217</b>		98262219 <b>FO 0030 V</b>
<b>6180</b>	98262119 <b>FD 3207</b>			
<b>6180 N</b>	98262173 <b>FD 3269</b>	98262192 <b>FA 1556</b>		98262219 <b>FO 0030 V</b>
<b>6200 N</b>	98262173 <b>FD 3269</b>			
<b>6220</b>	98262119 <b>FD 3207</b>	98262192 <b>FA 1556</b>		98262219 <b>FO 0030 V</b>
<b>6220 N</b>	98262174 <b>FD 3235</b>	98262192 <b>FA 1556</b>		98262219 <b>FO 0030 V</b>
<b>6250 N</b>	98262174 <b>FD 3235</b>	98262192 <b>FA 1556</b>		
<b>6340</b>	9826213 <b>FD 3338</b>			98262219 <b>FO 0030 V</b>
<b>C 100</b>	13088474 <b>FD 3441</b>			00587374 <b>FI 1286 V</b>
<b>C 101</b>	13088474 <b>FD 3441</b>			00587374 <b>FI 1286 V</b>
<b>C 102</b>	13088474 <b>FD 3441</b>			00587374 <b>FI 1286 V</b>
<b>C 104</b>	13088474 <b>FD 3441</b>			00587374 <b>FI 1286 V</b>
<b>C 110-9 WITH DEUTZ BF4M2012C MOBILE</b>		100005026 <b>FA 2286</b>	100005027 <b>FA 2287</b>	



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>COMPAIR</b> <i>C 130</i>				
<i>C 130</i>	13088474 <b>FD 3441</b>			04425274 <b>FI 1099 V</b>
<i>C 131</i>	13088474 <b>FD 3441</b>			04425274 <b>FI 1099 V</b>
<i>C 132</i>	13088474 <b>FD 3441</b>			04425274 <b>FI 1099 V</b>
<i>C 134</i>	13088474 <b>FD 3441</b>			04425274 <b>FI 1099 V</b>
<i>C 190 TS 12</i>	13363674			04425274 <b>FI 1099 V</b>
<i>C 20</i>	13010174 <b>FD 3372 V</b>			10654074 <b>FI 1290 V</b>
<i>C 20 WITH KUBOTA D 1105 ENG. MOBILE</i>		A13306974 <b>FA 5001</b>	A13308874 <b>FA 5101</b>	04819974 <b>FI 1306 V</b>
<i>C 200-10</i>	13363674			04425274 <b>FI 1099 V</b>
<i>C 210-9</i>	13363674			04425274 <b>FI 1099 V</b>
<i>C 25</i>	13046874 <b>FD 3545</b>			
<i>C 25 WITH KUBOTA V 1505 ENG. MOBILE</i>		A13306974 <b>FA 5001</b>	A13308874 <b>FA 5101</b>	04819974 <b>FI 1306 V</b>
<i>C 30</i>	10012674 <b>FD 3070</b>	13306974 <b>FA 5001</b>		04819974 <b>FI 1306 V</b>
<i>C 30 G WITH KUBOTA V 1505 ENG. MOBILE</i>		A13306974 <b>FA 5001</b>	A13308874 <b>FA 5101</b>	04819974 <b>FI 1306 V</b>
<i>C 38 (G/GS) WITH DEUTZ F3M2011 ENG. MOBILE</i>		A13306974 <b>FA 5001</b>	A13308874 <b>FA 5101</b>	04819974 <b>FI 1306 V</b>
<i>C 38 WITH CUMMINS A 2300 ENG. MOBILE</i>		4472874 <b>FA 1240</b>	100010551 <b>FA 1562</b>	04819974 <b>FI 1306 V</b>
<i>C 40</i>	10012674 <b>FD 3070</b>	13306974 <b>FA 5001</b>		04819974 <b>FI 1306 V</b>
<i>C 42</i>	10012674 <b>FD 3070</b>	13306974 <b>FA 5001</b>		04819974 <b>FI 1306 V</b>
<i>C 42 (GENERATOR) WITH CUMMINS A 2300 ENG.</i>	982628045 <b>FD 3003</b>			C160121032
<i>C 50</i>	10012674 <b>FD 3070</b>	13306974 <b>FA 5001</b>		00587374 <b>FI 1286 V</b>
<i>C 50 WITH CUMMINS A 2300 ENG. MOBILE</i>		04472874 <b>FA 1240</b>	100010551 <b>FA 1562</b>	04819974 <b>FI 1306 V</b>
<i>C 50 WITH DEUTZ F3M2011 ENG. MOBILE</i>		A13306974 <b>FA 5001</b>	A13308874 <b>FA 5101</b>	98262135 <b>FO 0420 V</b>
<i>C 57-14</i>	13138274 <b>FD 3460</b>	13316774 <b>FA 5002</b>		00587374 <b>FI 1286 V</b>
<i>C 58-10</i>	13138274 <b>FD 3460</b>	13316774 <b>FA 5002</b>		00587374 <b>FI 1286 V</b>
<i>C 59-10</i>	13138274 <b>FD 3460</b>	13316774 <b>FA 5002</b>		00587374 <b>FI 1286 V</b>
<i>C 62</i>	13138274 <b>FD 3460</b>	13316774 <b>FA 5002</b>		00587374 <b>FI 1286 V</b>
<i>C 62 (GENERATOR) WITH CUMMINS ENG. MOBILE</i>		A13316774 <b>FA 5002</b>	A13316874 <b>FA 5102</b>	
<i>C 62 (GENERATOR) WITH DEUTZ F4M2011 ENG.</i>		C13316774 <b>FA 5002</b>	C13316874 <b>FA 5102</b>	98262135 <b>FO 0420 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>COMPAIR</b> <i>C 65-10 WITH DEUTZ BF4M2011 ENG. 2004-&gt;2008 MOBILE COMP</i>				
<i>C 65-10 WITH DEUTZ BF4M2011 ENG. 2004-</i>		A13316774 <b>FA 5002</b>	A13316874 <b>FA 5102</b>	00587374 <b>FI 1286 V</b>
<i>C 76</i>	13138274 <b>FD 3460</b>	13316774 <b>FA 5002</b>		00587374 <b>FI 1286 V</b>
<i>C 76 (GENERATOR) WITH DEUTZ F4M2011 ENG.</i>		A13316774 <b>FA 5002</b>	A13316874 <b>FA 5102</b>	00587374 <b>FI 1286 V</b>
<i>CA 15</i>	C11469233 <b>FD 3048</b>			
<i>CA 15</i>	C11469233 <b>FD 3048</b>			
<i>CYCLONE 105</i>	98262214 <b>FD 3034 V</b>	98262201 <b>FA 5507</b>		98262135 <b>FO 0420 V</b>
<i>CYCLONE 107</i>	98262214 <b>FD 3034 V</b>	98262201 <b>FA 5507</b>		98262135 <b>FO 0420 V</b>
<i>CYCLONE 111</i>	98262215 <b>FD 3096 V</b>	98262201 <b>FA 5507</b>		98262135 <b>FO 0420 V</b>
<i>CYCLONE 215</i>	98262215 <b>FD 3096 V</b>	98262205 <b>FA 5506</b>		98262220 <b>FO 0148 V</b>
<i>CYCLONE 218</i>	98262216 <b>FD 3372 V</b>	98262205 <b>FA 5506</b>		98262220 <b>FO 0148 V</b>
<i>CYCLONE 222</i>	98262216 <b>FD 3372 V</b>	98262205 <b>FA 5506</b>		98262220 <b>FO 0148 V</b>
<i>CYCLONE 330</i>	98262223 <b>FD 3031 V</b>	98262198 <b>FA 5500</b>		98262220 <b>FO 0148 V</b>
<i>CYCLONE 337</i>	98262223 <b>FD 3031 V</b>	98262198 <b>FA 5500</b>		98262220 <b>FO 0148 V</b>
<i>CYCLONE 345</i>	98262223 <b>FD 3031 V</b>	98262198 <b>FA 5500</b>		98262220 <b>FO 0148 V</b>
<i>CYCLONE 475</i>	98262197 <b>FD 3464</b>	98262207 <b>FA 5500</b>		98262220 <b>FO 0148 V</b>
<i>DS 100 UP TO 104</i>	13088474 <b>FD 3441</b>	13249474 <b>FA 1104</b>		00587374 <b>FI 1286 V</b>
<i>DS 130 UP TO 134</i>	13088474 <b>FD 3441</b>	13249474 <b>FA 1104</b>		04425274 <b>FI 1099 V</b>
<i>DS 20</i>	13010174 <b>FD 3372 V</b>	29504036 <b>FA 3070</b>		10654074 <b>FI 1290 V</b>
<i>DS 70 UP TO 74</i>	13138274 <b>FD 3460</b>	13203674 <b>FA 1105</b>		00587374 <b>FI 1286 V</b>
<i>HOLMAN 20</i>	982625133 <b>FD 3502</b>	982625141	982625141	982625134 <b>FO 0077 V</b>
<i>HOLMAN 2110 S</i>	982625085 <b>FD 3339</b>	982625126	9826251260002 <b>FA 5601</b>	C16012303 <b>FI 1286 V</b>
<i>HOLMAN 2130 S</i>	982625085 <b>FD 3339</b>	9826251260001 <b>FA 5501</b>	9826251260002 <b>FA 5601</b>	C16012303 <b>FI 1286 V</b>
<i>HOLMAN 2130 S WITH DEUTZ ENG.</i>	982625085 <b>FD 3339</b>	982625126	9826251260002 <b>FA 5601</b>	00587374 <b>FI 1286 V</b>
<i>HOLMAN 2150 S</i>	982628045 <b>FD 3003</b>	982625126	9826251260002 <b>FA 5601</b>	C16012303 <b>FI 1286 V</b>
<i>HOLMAN 2180 S</i>	982628045 <b>FD 3003</b>	982625126	9826251260002 <b>FA 5601</b>	C16012303 <b>FI 1286 V</b>
<i>HOLMAN 2260 S</i>	982625117 <b>FD 3347</b>	9826251250001 <b>FA 5502</b>	93262512 <b>FA 5602</b>	C16012303 <b>FI 1286 V</b>
<i>JOCKEY 012 5.2/6.1 M3</i>	13010174 <b>FD 3372 V</b>	29504376 <b>FA 1106</b>		00587374 <b>FI 1286 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>COMPAIR</b> <i>JOCKEY 012 7.4/8.0 M3</i>				
<i>JOCKEY 012 7.4/8.0 M3</i>	10525274 <b>FD 3031 V</b>	29504376 <b>FA 1106</b>		00587374 <b>FI 1286 V</b>
<i>JOCKEY 016</i>	10525274 <b>FD 3031 V</b>	29504406 <b>FA 1252</b>		10884174
<i>JOCKEY 20 UP TO 16 M3</i>	10651774 <b>FD 3241</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>JOCKEY 20 UP TO 25 M3</i>	10882574 <b>FD 3247</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>L 04</i>	10533574 <b>FD 3096 V</b>	10004746		04819974 <b>FI 1306 V</b>
<i>L 05</i>	10533574 <b>FD 3096 V</b>	11207674 <b>FA 5507</b>		04819974 <b>FI 1306 V</b>
<i>L 07</i>	10533574 <b>FD 3096 V</b>	11207674 <b>FA 5507</b>		04819974 <b>FI 1306 V</b>
<i>L 11</i>	13010174 <b>FD 3372 V</b>	11224574 <b>FA 5504</b>		04819974 <b>FI 1306 V</b>
<i>L 110</i>	10882574 <b>FD 3247</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>L 120 SR</i>		98262251 <b>FA 5931</b>		
<i>L 132</i>	11427274 <b>FD 3251</b>	11516974 <b>FA 5932/1</b>		04425274 <b>FI 1099 V</b>
<i>L 132 C</i>	10882574 <b>FD 3247</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>L 15</i>	13010174 <b>FD 3372 V</b>	100001611 <b>FA 2050</b>		04819974 <b>FI 1306 V</b>
<i>L 160</i>	11427274 <b>FD 3251</b>	11516974 <b>FA 5932/1</b>		04425274 <b>FI 1099 V</b>
<i>L 18</i>	13010174 <b>FD 3372 V</b>	100001611 <b>FA 2050</b>		04819974 <b>FI 1306 V</b>
<i>L 200</i>	11427474 <b>FD 3459</b>	11516974 <b>FA 5932/1</b>		04425274 <b>FI 1099 V</b>
<i>L 22</i>	13010174 <b>FD 3372 V</b>	100001611 <b>FA 2050</b>		04819974 <b>FI 1306 V</b>
<i>L 22 S</i>	10525274 <b>FD 3031 V</b>	11380674 <b>FA 5508</b>		11381974 <b>FI 1067 V</b>
<i>L 250</i>	11427474 <b>FD 3459</b>	11516974 <b>FA 5932/1</b>		04425274 <b>FI 1099 V</b>
<i>L 30</i>	10525274 <b>FD 3031 V</b>	11380674 <b>FA 5508</b>		11381974 <b>FI 1067 V</b>
<i>L 37</i>	10525274 <b>FD 3031 V</b>	11380674 <b>FA 5508</b>		11381974 <b>FI 1067 V</b>
<i>L 37 S</i>	10525274 <b>FD 3031 V</b>	11323374 <b>FA 5500</b>		04425274 <b>FI 1099 V</b>
<i>L 45</i>	10525274 <b>FD 3031 V</b>	11323374 <b>FA 5500</b>		04425274 <b>FI 1099 V</b>
<i>L 45 SR</i>	10525274 <b>FD 3031 V</b>	11323374 <b>FA 5500</b>		04425274 <b>FI 1099 V</b>
<i>L 55</i>	10525274 <b>FD 3031 V</b>	11323374 <b>FA 5500</b>		04425274 <b>FI 1099 V</b>
<i>L 75</i>	10525274 <b>FD 3031 V</b>	11323374 <b>FA 5500</b>		04425274 <b>FI 1099 V</b>
<i>L 75 S</i>	10882574 <b>FD 3247</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>COMPAIR</b>				
<i>L 75 SR</i>				
<i>L 75 SR</i>	98262197 <b>FD 3464</b>	98262207 <b>FA 5500</b>		98262220 <b>FO 0148 V</b>
<i>L 90</i>	10882574 <b>FD 3247</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>MARATHON 220-222</i>	10494574 <b>FD 3251</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>MARATHON 252</i>	10494574 <b>FD 3251</b>	29504526 <b>FA 1302</b>		04425274 <b>FI 1099 V</b>
<i>MARATHON 300</i>	11427474 <b>FD 3459</b>	29504526 <b>FA 1302</b>		04425274 <b>FI 1099 V</b>
<i>MARATHON 301 A</i>	11427474 <b>FD 3459</b>	29504526 <b>FA 1302</b>		04425274 <b>FI 1099 V</b>
<i>MARATHON 350-422</i>	11427474 <b>FD 3459</b>	06296777 <b>FA 1556</b>		04425274 <b>FI 1099 V</b>
<i>RA 100</i>	9826226 <b>FD 3192</b>	C16012190 <b>FA 1252</b>		98262219 <b>FO 0030 V</b>
<i>RA 125</i>	9826226 <b>FD 3192</b>	C16012190 <b>FA 1252</b>		98262219 <b>FO 0030 V</b>
<i>RA 125 MK II</i>	9826226 <b>FD 3192</b>			98262220 <b>FO 0148 V</b>
<i>RA 125 MK III</i>	9826278 <b>FD 3040</b>	C111581041 <b>FA 1252</b>		98262220 <b>FO 0148 V</b>
<i>RA 150</i>	9826248 <b>FD 3193</b>			98262220 <b>FO 0148 V</b>
<i>RA 150 MK III</i>	9826278 <b>FD 3040</b>	C111581390 <b>FA 1217</b>		98262220 <b>FO 0148 V</b>
<i>RA 200</i>	9826248 <b>FD 3193</b>			
<i>RA 220 A</i>	9826248 <b>FD 3193</b>	C111581054 <b>FA 1302</b>		98262219 <b>FO 0030 V</b>
<i>RA 270</i>	9826213 <b>FD 3338</b>			
<i>RA 30</i>	9826233 <b>FD 3061</b>			98262220 <b>FO 0148 V</b>
<i>RA 30 MK II</i>	9826233 <b>FD 3061</b>			98262220 <b>FO 0148 V</b>
<i>RA 30 MK III</i>	9826277 <b>FD 3180</b>	C1601252 <b>FA 1241</b>		98262220 <b>FO 0148 V</b>
<i>RA 340</i>	9826213 <b>FD 3338</b>			
<i>RA 40</i>	9826233 <b>FD 3061</b>	C111581051 <b>FA 1249</b>		98262220 <b>FO 0148 V</b>
<i>RA 40 MK II</i>	9826233 <b>FD 3061</b>			98262220 <b>FO 0148 V</b>
<i>RA 40 MK III</i>	9826277 <b>FD 3180</b>	C1601252 <b>FA 1241</b>		
<i>RA 50</i>	9826223 <b>FD 3005</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<i>RA 50 MK III</i>	9826277 <b>FD 3180</b>	C1601252 <b>FA 1241</b>		98262220 <b>FO 0148 V</b>
<i>RA 60</i>	9826223 <b>FD 3005</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<i>RA 75</i>	9826223 <b>FD 3005</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>COMPAIR</b>				
<i>RA 75 MK II</i>				
<i>RA 75 MK II</i>	9826223 <b>FD 3005</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<i>RALLY 040-062</i>	10525274 <b>FD 3031 V</b>	11380674 <b>FA 5508</b>		11381974 <b>FI 1067 V</b>
<i>RALLY 070-112</i>	10525274 <b>FD 3031 V</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>RALLY 070-112 FROM SERIES No. 446</i>	10525274 <b>FD 3031 V</b>	11323374 <b>FA 5500</b>		04425274 <b>FI 1099 V</b>
<i>REGATTA 140-215</i>	10882574 <b>FD 3247</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>ROTAIR RA 40</i>	20047307 <b>FD 3306</b>			
<i>ROTAIR RA 60</i>	20047307 <b>FD 3306</b>			
<i>SC 10 D</i>	00652674 <b>FD 3186</b>	00927074 <b>FP 2445</b>		04425274 <b>FI 1099 V</b>
<i>SC 10 DS</i>	00652674 <b>FD 3186</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SC 10 ES</i>	00652674 <b>FD 3186</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SC 100 D</i>	00652674 <b>FD 3186</b>	05151274 <b>FA 1202 AL</b>		04425274 <b>FI 1099 V</b>
<i>SC 100 DW</i>	00652674 <b>FD 3186</b>	05151274 <b>FA 1202 AL</b>		04425274 <b>FI 1099 V</b>
<i>SC 101 D</i>	00652674 <b>FD 3186</b>	00927074 <b>FP 2445</b>		04425274 <b>FI 1099 V</b>
<i>SC 121 D</i>	00614874 <b>FD 3065</b>	00927074 <b>FP 2445</b>		04425274 <b>FI 1099 V</b>
<i>SC 14 D</i>	00614874 <b>FD 3065</b>	00927074 <b>FP 2445</b>		04425274 <b>FI 1099 V</b>
<i>SC 140 DS UP TO 142 DS</i>	00614874 <b>FD 3065</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SC 141 DS</i>	00614874 <b>FD 3065</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SC 17 DS</i>	00614874 <b>FD 3065</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SC 170 DS UP TO 174 DS</i>	00614874 <b>FD 3065</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SC 20 DS-1</i>	05482874 <b>FD 3073</b>	04472874 <b>FA 1240</b>		05773274 <b>FI 1295 V</b>
<i>SC 20 DS-2</i>	05482874 <b>FD 3073</b>	04472874 <b>FA 1240</b>		05773274 <b>FI 1295 V</b>
<i>SC 20 DS-3</i>	10533574 <b>FD 3096 V</b>	04472874 <b>FA 1240</b>		10654074 <b>FI 1290 V</b>
<i>SC 23 D</i>	04115374 <b>FD 3066</b>	00927074 <b>FP 2445</b>		04425274 <b>FI 1099 V</b>
<i>SC 230 DS UP TO 234 DS</i>	04115374 <b>FD 3066</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SC 28 DS</i>	04555974 <b>FD 3059</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SC 3 DS</i>	00542274 <b>FD 3064</b>	04005074 <b>FA 1105</b>		00587374 <b>FI 1286 V</b>
<i>SC 3 ES</i>	00542274 <b>FD 3064</b>	04005074 <b>FA 1105</b>		00587374 <b>FI 1286 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>COMPAIR</b> <i>SC 30 DS-1</i>				
<i>SC 30 DS-1</i>	05482874 <b>FD 3073</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SC 30 DS-2</i>	05482874 <b>FD 3073</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SC 38 DS</i>	00542274 <b>FD 3064</b>	04005074 <b>FA 1105</b>		00587374 <b>FI 1286 V</b>
<i>SC 40 DS</i>	00489174 <b>FD 3432</b>	04472874 <b>FA 1240</b>		00587374 <b>FI 1286 V</b>
<i>SC 40 DS-1</i>	10012674 <b>FD 3070</b>	04472874 <b>FA 1240</b>		00587374 <b>FI 1286 V</b>
<i>SC 40 DS-2</i>	10012674 <b>FD 3070</b>	04472874 <b>FA 1240</b>		00587374 <b>FI 1286 V</b>
<i>SC 5 DS</i>	00691674 <b>FD 3009</b>	29504376 <b>FA 1106</b>		00587374 <b>FI 1286 V</b>
<i>SC 5 ES</i>	00691674 <b>FD 3009</b>	04005074 <b>FA 1105</b>		00587374 <b>FI 1286 V</b>
<i>SC 50 D</i>	00542274 <b>FD 3064</b>	05150574 <b>FA 1005 AL</b>		00587374 <b>FI 1286 V</b>
<i>SC 50 DS</i>	00542274 <b>FD 3064</b>	29504476 <b>FA 1241</b>		00587374 <b>FI 1286 V</b>
<i>SC 50 DS-1</i>	10525274 <b>FD 3031 V</b>	29504476 <b>FA 1241</b>		00587374 <b>FI 1286 V</b>
<i>SC 50 DT-1</i>	10525274 <b>FD 3031 V</b>	29504476 <b>FA 1241</b>		00587374 <b>FI 1286 V</b>
<i>SC 7 D</i>	00691674 <b>FD 3009</b>			04425274 <b>FI 1099 V</b>
<i>SC 7 DS</i>	00691674 <b>FD 3009</b>	29504406 <b>FA 1252</b>		04425274 <b>FI 1099 V</b>
<i>SC 7 ES</i>	00652674 <b>FD 3186</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SC 70 D</i>	00542274 <b>FD 3064</b>	05150574 <b>FA 1005 AL</b>		00587374 <b>FI 1286 V</b>
<i>SC 70 DS UP TO 104 DS</i>	04179274 <b>FD 3069</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SC 70 DW</i>	00542274 <b>FD 3064</b>	05150574 <b>FA 1005 AL</b>		00587374 <b>FI 1286 V</b>
<i>SE 012</i>	04179274 <b>FD 3069</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SE 016</i>	00652674 <b>FD 3186</b>	29504406 <b>FA 1252</b>		04425274 <b>FI 1099 V</b>
<i>SE 020</i>	04115374 <b>FD 3066</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SE 10 S</i>	04555974 <b>FD 3059</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SE 11 P</i>	05482874 <b>FD 3073</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SE 11 P NORMAL TYPE</i>	04555974 <b>FD 3059</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SE 11 S</i>	04555974 <b>FD 3059</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SE 111 S</i>	00652674 <b>FD 3186</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SE 116 S-155 S</i>	10651774 <b>FD 3241</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>





	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>COMPAIR</b> <i>SE 116 S-155 S NORMAL TYPE</i>				
<i>SE 116 S-155 S NORMAL TYPE</i>	10882474 <b>FD 3272</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SE 116 S-155 S OLD TYPE</i>	00614874 <b>FD 3065</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SE 120 S</i>	00652674 <b>FD 3186</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SE 121 S</i>	00652674 <b>FD 3186</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SE 140 AS-170 AS</i>	00702274 <b>FD 3066</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SE 15 S</i>	04555974 <b>FD 3059</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SE 150 S</i>	00652674 <b>FD 3186</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SE 16 P</i>	05482874 <b>FD 3073</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SE 16 P NORMAL TYPE</i>	04555974 <b>FD 3059</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SE 16 S</i>	04555974 <b>FD 3059</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SE 180 AS/WS-255 AS/WS</i>	10882574 <b>FD 3247</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SE 191 WS-221 WS</i>	00702274 <b>FD 3066</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SE 20 EKS</i>	00348774 <b>FD 3032</b>	00338474 <b>FA 1219</b>		00587374 <b>FI 1286 V</b>
<i>SE 20 S</i>	04555974 <b>FD 3059</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SE 21 P</i>	05482874 <b>FD 3073</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SE 21 P NORMAL TYPE</i>	04555974 <b>FD 3059</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SE 21 S</i>	04555974 <b>FD 3059</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SE 25 P</i>	05482874 <b>FD 3073</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SE 25 P NORMAL TYPE</i>	04555974 <b>FD 3059</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SE 26 S-30 S</i>	04555974 <b>FD 3059</b>	04472874 <b>FA 1240</b>		00587374 <b>FI 1286 V</b>
<i>SE 30 EKS</i>	00348774 <b>FD 3032</b>	00338474 <b>FA 1219</b>		00587374 <b>FI 1286 V</b>
<i>SE 31 S-40 S</i>	05074574 <b>FD 3062</b>	29504476 <b>FA 1241</b>		00587374 <b>FI 1286 V</b>
<i>SE 350 WES</i>	03560777 <b>FD 3337</b>	03608077		04425274 <b>FI 1099 V</b>
<i>SE 41 S-50 S</i>	00542274 <b>FD 3064</b>	29504476 <b>FA 1241</b>		00587374 <b>FI 1286 V</b>
<i>SE 51 S-60 S</i>	00542274 <b>FD 3064</b>	29504476 <b>FA 1241</b>		04425274 <b>FI 1099 V</b>
<i>SE 61 S</i>	04179274 <b>FD 3069</b>	29504476 <b>FA 1241</b>		04425274 <b>FI 1099 V</b>
<i>SE 70 S</i>	04179274 <b>FD 3069</b>	29504476 <b>FA 1241</b>		04425274 <b>FI 1099 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>COMPAIR</b>				
<i>SE 71 S</i>				
<i>SE 71 S</i>	00652674 <b>FD 3186</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SE 76 S</i>	04179274 <b>FD 3069</b>	29504476 <b>FA 1241</b>		04425274 <b>FI 1099 V</b>
<i>SE 85 S</i>	00652674 <b>FD 3186</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SE 90 S</i>	04179274 <b>FD 3069</b>	29504476 <b>FA 1241</b>		04425274 <b>FI 1099 V</b>
<i>SIRIUS 132-160</i>	11427274 <b>FD 3251</b>	11516974 <b>FA 5932/1</b>		04425274 <b>FI 1099 V</b>
<i>SIRIUS 200-250</i>	11427474 <b>FD 3459</b>	11516974 <b>FA 5932/1</b>		04425274 <b>FI 1099 V</b>
<i>SPRINT 005-012</i>	13010074 <b>FD 3571 V</b>	29504036 <b>FA 3070</b>		10654074 <b>FI 1290 V</b>
<i>SPRINT 015-022</i>	10533574 <b>FD 3096 V</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SPRINT 025-032</i>	10596274 <b>FD 3372 V</b>	29504036 <b>FA 3070</b>		00587374 <b>FI 1286 V</b>
<i>SPRINT 040-047</i>	10525274 <b>FD 3031 V</b>	29504036 <b>FA 3070</b>		00587374 <b>FI 1286 V</b>
<i>SPRINT 050-057</i>	10525274 <b>FD 3031 V</b>	29504476 <b>FA 1241</b>		00587374 <b>FI 1286 V</b>
<i>START 005</i>	10533574 <b>FD 3096 V</b>	11207674 <b>FA 5507</b>		04819974 <b>FI 1306 V</b>
<i>START 007</i>	10533574 <b>FD 3096 V</b>	11207674 <b>FA 5507</b>		04819974 <b>FI 1306 V</b>
<i>START 010</i>	10533574 <b>FD 3096 V</b>	11207674 <b>FA 5507</b>		04819974 <b>FI 1306 V</b>
<i>START 015</i>	13010174 <b>FD 3372 V</b>	11224574 <b>FA 5504</b>		04819974 <b>FI 1306 V</b>
<i>START 017</i>	13010174 <b>FD 3372 V</b>	11224574 <b>FA 5504</b>		04819974 <b>FI 1306 V</b>
<i>START 025</i>	13010174 <b>FD 3372 V</b>	11224574 <b>FA 5504</b>		04819974 <b>FI 1306 V</b>
<i>START 026</i>	13010174 <b>FD 3372 V</b>	11224574 <b>FA 5504</b>		04819974 <b>FI 1306 V</b>
<i>START 037</i>	13010174 <b>FD 3372 V</b>	11224574 <b>FA 5504</b>		04819974 <b>FI 1306 V</b>
<i>SZ 350 WES UP TO 353 WES</i>	03560777 <b>FD 3337</b>	03608077		04425274 <b>FI 1099 V</b>
<i>SZ 400 HORIZONTAL TANK</i>	03560777 <b>FD 3337</b>	03608077		04425274 <b>FI 1099 V</b>
<i>SZ 400 VERTICAL TANK</i>	00702274 <b>FD 3066</b>	03608077		04425274 <b>FI 1099 V</b>
<i>TORNADO 45 SR</i>	10525274 <b>FD 3031 V</b>	98262207 <b>FA 5500</b>		98262220 <b>FO 0148 V</b>
<i>TORNADO 75 SR</i>	98262197 <b>FD 3464</b>	98262207 <b>FA 5500</b>		98262220 <b>FO 0148 V</b>
<i>ZITAIR 100 G</i>	982628020 <b>FD 3301</b>	C1601252 <b>FA 1241</b>		C16012302 <b>FI 1306 V</b>
<i>ZITAIR 100 WITH DEUTZ F2L511 ENG.</i>	982628020 <b>FD 3301</b>	C1601252 <b>FA 1241</b>		C16012302 <b>FI 1306 V</b>
<i>ZITAIR 125</i>	982628020 <b>FD 3301</b>	C16012180 <b>FA 1240</b>		



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>COMPAIR</b>				
<i>ZITAIR 125 MK II</i>				
<i>ZITAIR 125 MK II</i>	9826226 <b>FD 3192</b>	C1601252 <b>FA 1241</b>		00587374 <b>FI 1286 V</b>
<i>ZITAIR 125 WITH DEUTZ F2L511 ENG.</i>	982628020 <b>FD 3301</b>	C1601252 <b>FA 1241</b>		C16012302 <b>FI 1306 V</b>
<i>ZITAIR 130 D MKIV</i>	982625072 <b>FD 3333</b>			
<i>ZITAIR 150 D MKIV</i>	982625072 <b>FD 3333</b>			C16012303 <b>FI 1286 V</b>
<i>ZITAIR 150 MKII</i>	982625073 <b>FD 3332</b>	C11561724 <b>FA 1212 AL</b>		C16012303 <b>FI 1286 V</b>
<i>ZITAIR 150 MKII WITH PERKINS 504-2 ENG.</i>	982625073 <b>FD 3332</b>	C11561724 <b>FA 1212 AL</b>		00587374 <b>FI 1286 V</b>
<i>ZITAIR 175 D WITH DEUTZ ENG.</i>	982628026 <b>FD 3303</b>	C16012189 <b>FA 1106</b>		01182001 <b>FO 0052 V</b>
<i>ZITAIR 175 P WITH PERKINS 4.236/248 ENG.</i>	982628026 <b>FD 3303</b>	C16012189 <b>FA 1106</b>		9826220 <b>FO 0148 V</b>
<i>ZITAIR 175 WITH DEUTZ F3L912 ENG.</i>		C16012190 <b>FA 1252</b>		C16012012 <b>FI 1268 V</b>
<i>ZITAIR 175 WITH DEUTZ F4L1011 ENG.</i>				C16011251 <b>FO 0029 V</b>
<i>ZITAIR 180 MKII</i>	982625073 <b>FD 3332</b>	C1601252 <b>FA 1241</b>		C16012303 <b>FI 1286 V</b>
<i>ZITAIR 180 P WITH PERKINS ENG.</i>	982625073 <b>FD 3332</b>	C1601252 <b>FA 1241</b>		C16012303 <b>FI 1286 V</b>
<i>ZITAIR 250</i>	982628027 <b>FD 3304</b>	C16012190 <b>FA 1252</b>		C16012303 <b>FI 1286 V</b>
<i>ZITAIR 250 D WITH DEUTZ F4L912 ENG.</i>	982628020 <b>FD 3301</b>	C16012190 <b>FA 1252</b>		C16012012 <b>FI 1268 V</b>
<i>ZITAIR 250 P WITH PERKINS ENG.</i>	982628027 <b>FD 3304</b>	C16012190 <b>FA 1252</b>		9826220 <b>FO 0148 V</b>
<i>ZITAIR 380-145</i>	982625079 <b>FD 3328</b>	1078A30930 <b>FA 1242</b>		9826280400001 <b>FI 1099 V</b>
<i>ZITAIR 380-170</i>	982625079 <b>FD 3328</b>	1078A30930 <b>FA 1242</b>		9826280400001 <b>FI 1099 V</b>
<i>ZITAIR 400-125</i>	982625079 <b>FD 3328</b>	1078A30930 <b>FA 1242</b>		9826280400001 <b>FI 1099 V</b>
<i>ZITAIR 400-170</i>	982625079 <b>FD 3328</b>	1078A30930 <b>FA 1242</b>		9826280400001 <b>FI 1099 V</b>
<i>ZITAIR 550-170</i>	1311K08020 <b>FD 3237</b>			
<i>ZITAIR 600-125</i>	982628046 <b>FD 3350</b>			9826280400001 <b>FI 1099 V</b>
<i>ZITAIR 65</i>	982628023 <b>FD 3295</b>	C1601252 <b>FA 1241</b>		C16012012 <b>FI 1268 V</b>
<i>ZITAIR 65 WITH DEUTZ F1L511 ENG.</i>	982628023 <b>FD 3295</b>	C1601252 <b>FA 1241</b>		C16011251 <b>FO 0029 V</b>
<i>ZITAIR 70</i>	982625085 <b>FD 3339</b>	C1601252 <b>FA 1241</b>		C16012012 <b>FI 1268 V</b>
<i>ZITAIR 70 P WITH PERKINS 103-100 ENG.</i>	982625085 <b>FD 3339</b>	C1601252 <b>FA 1241</b>		13294274 <b>FO 8061 V/OR</b>
<i>ZITAIR 70 WITH PERKINS 103-100 ENG.</i>	982625085 <b>FD 3339</b>			13294274 <b>FO 8061 V/OR</b>
<i>ZITAIR 750-175</i>	1311K08020 <b>FD 3237</b>	982625026 <b>FA 1270</b>		9826280400001 <b>FI 1099 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>COMPAIR</b> <span style="float: right;"><i>ZITAIR 750-300</i></span>				
<i>ZITAIR 750-300</i>	1311K08020 <b>FD 3237</b>	982625026 <b>FA 1270</b>		9826280400001 <b>FI 1099 V</b>
<i>ZITAIR 85</i>	982628020 <b>FD 3301</b>	C1601252 <b>FA 1241</b>		C16012302 <b>FI 1306 V</b>
<i>ZITAIR 85 G</i>	982628020 <b>FD 3301</b>	C1601252 <b>FA 1241</b>		C16012302 <b>FI 1306 V</b>
<i>ZITAIR 85 P</i>	982625085 <b>FD 3339</b>	C1601252 <b>FA 1241</b>		C16012012 <b>FI 1268 V</b>
<i>ZITAIR 85 WITH DEUTZ F2L511 ENG.</i>	982628020 <b>FD 3301</b>	C1601252 <b>FA 1241</b>		C16012302 <b>FI 1306 V</b>
<i>ZITAIR 90 D MKIV</i>	982625072 <b>FD 3333</b>			C16012303 <b>FI 1286 V</b>
<b>DARI</b>				
<i>DRK 5</i>	048275000 <b>FD 3034 V</b>	017058001 <b>FA 2982</b>		048385000 <b>FO 0029 V</b>
<i>DRK SD 5</i>				048443000 <b>FO 0130 V</b>
<i>DRS 7</i>				048443000 <b>FO 0130 V</b>
<b>DEMAG</b>				
<i>6000 E</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6007 EA</i>	98262120 <b>FD 3218</b>	9826290 <b>FA 1684</b>		98262135 <b>FO 0420 V</b>
<i>6010 E</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6010 EA</i>	98262120 <b>FD 3218</b>	9826290 <b>FA 1684</b>		98262135 <b>FO 0420 V</b>
<i>6012</i>	98262102 <b>FD 3038</b>			
<i>6015 E</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6015 EA</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6020 E</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6020 EA</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6025 E</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6025 EA</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6030</i>	98262108 <b>FD 3085</b>	C1601252 <b>FA 1241</b>		98262220 <b>FO 0148 V</b>
<i>6030 AS</i>	9826277 <b>FD 3180</b>	C1601252 <b>FA 1241</b>		98262220 <b>FO 0148 V</b>
<i>6030 E</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6030 EA</i>	98262102 <b>FD 3038</b>	9826284 <b>FA 1627</b>		98262220 <b>FO 0148 V</b>
<i>6040</i>	98262108 <b>FD 3085</b>	C1601252 <b>FA 1241</b>		98262220 <b>FO 0148 V</b>
<i>6040 AS</i>	9826277 <b>FD 3180</b>	C1601252 <b>FA 1241</b>		98262220 <b>FO 0148 V</b>

	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>DEMAG</b>				
<i>6040 EA NEW TYPE</i>				
<i>6040 EA NEW TYPE</i>	98262121 <b>FD 3195</b>	9826286 <b>FA 2020</b>		98262220 <b>FO 0148 V</b>
<i>6040 EL NEW TYPE</i>	98262121 <b>FD 3195</b>	9826286 <b>FA 2020</b>		98262220 <b>FO 0148 V</b>
<i>6040 N NEW TYPE</i>	98262121 <b>FD 3195</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<i>6050</i>	9826277 <b>FD 3180</b>	C1601252 <b>FA 1241</b>		98262220 <b>FO 0148 V</b>
<i>6050 AS</i>	9826277 <b>FD 3180</b>	C1601252 <b>FA 1241</b>		98262220 <b>FO 0148 V</b>
<i>6050 EL NEW TYPE</i>	98262121 <b>FD 3195</b>	9826286 <b>FA 2020</b>		98262220 <b>FO 0148 V</b>
<i>6050 N NEW TYPE</i>	98262121 <b>FD 3195</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<i>6060</i>	9826223 <b>FD 3005</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<i>6060 N</i>	98262162 <b>FD 3072</b>	C16012189 <b>FA 1106</b>		98262220 <b>FO 0148 V</b>
<i>6075</i>	9826223 <b>FD 3005</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<i>6075 N</i>	98262162 <b>FD 3072</b>	C16012189 <b>FA 1106</b>		98262220 <b>FO 0148 V</b>
<i>6100</i>	9826226 <b>FD 3192</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<i>6115</i>	9826226 <b>FD 3192</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<i>6125</i>	9826226 <b>FD 3192</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<i>6150</i>	9826278 <b>FD 3040</b>	C111581390 <b>FA 1217</b>		98262219 <b>FO 0030 V</b>
<i>6180</i>	98262119 <b>FD 3207</b>			
<i>6200 N</i>	98262173 <b>FD 3269</b>			
<i>6220</i>	98262119 <b>FD 3207</b>	98262192 <b>FA 1556</b>		98262219 <b>FO 0030 V</b>
<i>6250 N</i>	98262174 <b>FD 3235</b>	98262192 <b>FA 1556</b>		
<i>6340</i>	9826213 <b>FD 3338</b>			98262219 <b>FO 0030 V</b>
<i>C 100</i>	13088474 <b>FD 3441</b>			00587374 <b>FI 1286 V</b>
<i>C 101</i>	13088474 <b>FD 3441</b>			00587374 <b>FI 1286 V</b>
<i>C 102</i>	13088474 <b>FD 3441</b>			00587374 <b>FI 1286 V</b>
<i>C 104</i>	13088474 <b>FD 3441</b>			00587374 <b>FI 1286 V</b>
<i>C 130</i>	13088474 <b>FD 3441</b>			04425274 <b>FI 1099 V</b>
<i>C 131</i>	13088474 <b>FD 3441</b>			04425274 <b>FI 1099 V</b>
<i>C 132</i>	13088474 <b>FD 3441</b>			04425274 <b>FI 1099 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>DEMAG C 134</b>				
<b>C 134</b>	13088474 <b>FD 3441</b>			04425274 <b>FI 1099 V</b>
<b>C 190 TS 12</b>	13363674			04425274 <b>FI 1099 V</b>
<b>C 20</b>	13010174 <b>FD 3372 V</b>			10654074 <b>FI 1290 V</b>
<b>C 200-10</b>	13363674			04425274 <b>FI 1099 V</b>
<b>C 210-9</b>	13363674			04425274 <b>FI 1099 V</b>
<b>C 25</b>	13046874 <b>FD 3545</b>			
<b>C 30</b>	10012674 <b>FD 3070</b>	13306974 <b>FA 5001</b>		04819974 <b>FI 1306 V</b>
<b>C 40</b>	10012674 <b>FD 3070</b>	13306974 <b>FA 5001</b>		04819974 <b>FI 1306 V</b>
<b>C 42</b>	10012674 <b>FD 3070</b>	13306974 <b>FA 5001</b>		04819974 <b>FI 1306 V</b>
<b>C 50</b>	10012674 <b>FD 3070</b>	13306974 <b>FA 5001</b>		00587374 <b>FI 1286 V</b>
<b>C 57-14</b>	13138274 <b>FD 3460</b>	13316774 <b>FA 5002</b>		00587374 <b>FI 1286 V</b>
<b>C 58-10</b>	13138274 <b>FD 3460</b>	13316774 <b>FA 5002</b>		00587374 <b>FI 1286 V</b>
<b>C 59-10</b>	13138274 <b>FD 3460</b>	13316774 <b>FA 5002</b>		00587374 <b>FI 1286 V</b>
<b>C 62</b>	13138274 <b>FD 3460</b>	13316774 <b>FA 5002</b>		00587374 <b>FI 1286 V</b>
<b>C 76</b>	13138274 <b>FD 3460</b>	13316774 <b>FA 5002</b>		00587374 <b>FI 1286 V</b>
<b>CA 15</b>	C11469233 <b>FD 3048</b>			
<b>CYCLONE 105</b>	98262214 <b>FD 3034 V</b>	98262201 <b>FA 5507</b>		98262135 <b>FO 0420 V</b>
<b>CYCLONE 107</b>	98262214 <b>FD 3034 V</b>	98262201 <b>FA 5507</b>		98262135 <b>FO 0420 V</b>
<b>CYCLONE 111</b>	98262215 <b>FD 3096 V</b>	98262201 <b>FA 5507</b>		98262135 <b>FO 0420 V</b>
<b>CYCLONE 215</b>	98262215 <b>FD 3096 V</b>	98262205 <b>FA 5506</b>		98262220 <b>FO 0148 V</b>
<b>CYCLONE 218</b>	98262216 <b>FD 3372 V</b>	98262205 <b>FA 5506</b>		98262220 <b>FO 0148 V</b>
<b>CYCLONE 222</b>	98262216 <b>FD 3372 V</b>	98262205 <b>FA 5506</b>		98262220 <b>FO 0148 V</b>
<b>CYCLONE 330</b>	98262223 <b>FD 3031 V</b>			98262220 <b>FO 0148 V</b>
<b>CYCLONE 337</b>	98262223 <b>FD 3031 V</b>			98262220 <b>FO 0148 V</b>
<b>CYCLONE 345</b>	98262223 <b>FD 3031 V</b>			98262220 <b>FO 0148 V</b>
<b>CYCLONE 475</b>	98262197 <b>FD 3464</b>	98262207 <b>FA 5500</b>		98262220 <b>FO 0148 V</b>
<b>D15/D16</b>	BK3842400 <b>FD 3146</b>	BN030329		BN09202 <b>FI 1288 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>DEMAG</b>				
<i>D16/D30</i>				
<i>D16/D30</i>	93568293 <b>FD 3214</b>	93578344		93568285 <b>FI 1288 V</b>
<i>D20/30</i>	F404041062 <b>FD 3244</b>	F404051032 <b>FA 0139</b>		BN09202 <b>FI 1288 V</b>
<i>DS 100 UP TO 104</i>	13088474 <b>FD 3441</b>	13249474 <b>FA 1104</b>		00587374 <b>FI 1286 V</b>
<i>DS 100 UP TO 104 WITH DAIMLER BENZ OM 364A</i>	13088474 <b>FD 3441</b>	13249474 <b>FA 1104</b>		00587374 <b>FI 1286 V</b>
<i>DS 130 UP TO 134</i>	13088474 <b>FD 3441</b>	13249474 <b>FA 1104</b>		04425274 <b>FI 1099 V</b>
<i>DS 130 UP TO 134 WITH DAIMLER BENZ OM 366A</i>	13088474 <b>FD 3441</b>	13249474 <b>FA 1104</b>		04425274 <b>FI 1099 V</b>
<i>DS 20</i>	13010174 <b>FD 3372 V</b>	29504036 <b>FA 3070</b>		10654074 <b>FI 1290 V</b>
<i>DS 70 UP TO 74</i>	13138274 <b>FD 3460</b>	13203674 <b>FA 1105</b>		00587374 <b>FI 1286 V</b>
<i>DS 70 UP TO 74 WITH DEUTZ BF4L1011 ENG.</i>	13138274 <b>FD 3460</b>	13203674 <b>FA 1105</b>		00587374 <b>FI 1286 V</b>
<i>HOLMAN 20</i>	982625133 <b>FD 3502</b>		982625141	982625134 <b>FO 0077 V</b>
<i>HOLMAN 2110 S</i>	982625085 <b>FD 3339</b>	9826251260001 <b>FA 5501</b>	9826251260002 <b>FA 5601</b>	C16012303 <b>FI 1286 V</b>
<i>HOLMAN 2130 S</i>	982625085 <b>FD 3339</b>	9826251260001 <b>FA 5501</b>	9826251260002 <b>FA 5601</b>	C16012303 <b>FI 1286 V</b>
<i>HOLMAN 2150 S</i>	982628045 <b>FD 3003</b>	9826251260001 <b>FA 5501</b>	9826251260002 <b>FA 5601</b>	C16012303 <b>FI 1286 V</b>
<i>HOLMAN 2180 S</i>	982628045 <b>FD 3003</b>	9826251260001 <b>FA 5501</b>	9826251260002 <b>FA 5601</b>	C16012303 <b>FI 1286 V</b>
<i>HOLMAN 2260 S</i>	982625117 <b>FD 3347</b>	9826251250001 <b>FA 5502</b>	9826251250002 <b>FA 5602</b>	C16012303 <b>FI 1286 V</b>
<i>JOCKEY 012 5.2/6.1 M3</i>	13010174 <b>FD 3372 V</b>	29504376 <b>FA 1106</b>		00587374 <b>FI 1286 V</b>
<i>JOCKEY 012 7.4/8.0 M3</i>	10525274 <b>FD 3031 V</b>	29504376 <b>FA 1106</b>		00587374 <b>FI 1286 V</b>
<i>JOCKEY 016</i>	10525274 <b>FD 3031 V</b>	29504406 <b>FA 1252</b>		10884174
<i>JOCKEY 20 UP TO 16 M3</i>	10651774 <b>FD 3241</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>JOCKEY 20 UP TO 25 M3</i>	10882574 <b>FD 3247</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>L 04</i>	10533574 <b>FD 3096 V</b>	11207674 <b>FA 5507</b>		04819974 <b>FI 1306 V</b>
<i>L 05</i>	10533574 <b>FD 3096 V</b>	11207674 <b>FA 5507</b>		04819974 <b>FI 1306 V</b>
<i>L 07</i>	10533574 <b>FD 3096 V</b>	11207674 <b>FA 5507</b>		04819974 <b>FI 1306 V</b>
<i>L 11</i>	13010174 <b>FD 3372 V</b>	11224574 <b>FA 5504</b>		04819974 <b>FI 1306 V</b>
<i>L 110</i>	10882574 <b>FD 3247</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>L 120 SR</i>		98262251 <b>FA 5931</b>		
<i>L 132</i>	11427274 <b>FD 3251</b>	11516974 <b>FA 5932/1</b>		04425274 <b>FI 1099 V</b>

	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>DEMAG</b>				
<i>L 132 C</i>				
<i>L 132 C</i>	10882574 <b>FD 3247</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>L 15</i>	13010174 <b>FD 3372 V</b>	100001611 <b>FA 2050</b>		04819974 <b>FI 1306 V</b>
<i>L 160</i>	11427274 <b>FD 3251</b>	11516974 <b>FA 5932/1</b>		04425274 <b>FI 1099 V</b>
<i>L 18</i>	13010174 <b>FD 3372 V</b>	100001611 <b>FA 2050</b>		04819974 <b>FI 1306 V</b>
<i>L 200</i>	11427474 <b>FD 3459</b>	11516974 <b>FA 5932/1</b>		04425274 <b>FI 1099 V</b>
<i>L 22</i>	13010174 <b>FD 3372 V</b>	100001611 <b>FA 2050</b>		04819974 <b>FI 1306 V</b>
<i>L 22 S</i>	10525274 <b>FD 3031 V</b>	11380674 <b>FA 5508</b>		11381974 <b>FI 1067 V</b>
<i>L 250</i>	11427474 <b>FD 3459</b>	11516974 <b>FA 5932/1</b>		04425274 <b>FI 1099 V</b>
<i>L 30</i>	10525274 <b>FD 3031 V</b>	11380674 <b>FA 5508</b>		11381974 <b>FI 1067 V</b>
<i>L 37</i>	10525274 <b>FD 3031 V</b>	11380674 <b>FA 5508</b>		11381974 <b>FI 1067 V</b>
<i>L 37 S</i>	10525274 <b>FD 3031 V</b>	11323374 <b>FA 5500</b>		04425274 <b>FI 1099 V</b>
<i>L 45</i>	10525274 <b>FD 3031 V</b>	11323374 <b>FA 5500</b>		04425274 <b>FI 1099 V</b>
<i>L 45 SR</i>	10525274 <b>FD 3031 V</b>	11323374 <b>FA 5500</b>		04425274 <b>FI 1099 V</b>
<i>L 55</i>	10525274 <b>FD 3031 V</b>	11323374 <b>FA 5500</b>		04425274 <b>FI 1099 V</b>
<i>L 75</i>	10525274 <b>FD 3031 V</b>	11323374 <b>FA 5500</b>		04425274 <b>FI 1099 V</b>
<i>L 75 S</i>	10882574 <b>FD 3247</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>L 75 SR</i>	98262197 <b>FD 3464</b>	98262207 <b>FA 5500</b>		98262220 <b>FO 0148 V</b>
<i>L 90</i>	10882574 <b>FD 3247</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>MARATHON</i>	11427274 <b>FD 3251</b>	06296777 <b>FA 1556</b>		04425274 <b>FI 1099 V</b>
<i>MARATHON 220 UP TO 222</i>	10494574 <b>FD 3251</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>MARATHON 250 UP TO 302</i>	10494574 <b>FD 3251</b>	29504526 <b>FA 1302</b>	29504526 <b>FA 1302</b>	04425274 <b>FI 1099 V</b>
<i>MARATHON 300</i>	11427474 <b>FD 3459</b>	29504526 <b>FA 1302</b>		04425274 <b>FI 1099 V</b>
<i>MARATHON 301 A</i>	11427474 <b>FD 3459</b>	29504526 <b>FA 1302</b>		04425274 <b>FI 1099 V</b>
<i>MARATHON 350 UP TO 422</i>	10494474 <b>FD 3240</b>	06296777 <b>FA 1556</b>		04425274 <b>FI 1099 V</b>
<i>RA 100</i>	9826226 <b>FD 3192</b>	C16012190 <b>FA 1252</b>		98262219 <b>FO 0030 V</b>
<i>RA 125</i>	9826226 <b>FD 3192</b>	C16012190 <b>FA 1252</b>		98262219 <b>FO 0030 V</b>
<i>RA 125 MK II</i>	9826226 <b>FD 3192</b>			





	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>DEMAG</b>				
<i>RA 125 MK III</i>				
<i>RA 125 MK III</i>	9826278 <b>FD 3040</b>	C16012190 <b>FA 1252</b>		
<i>RA 150</i>	9826248 <b>FD 3193</b>			
<i>RA 150 MK III</i>	9826278 <b>FD 3040</b>	C111581390 <b>FA 1217</b>		
<i>RA 200</i>	9826248 <b>FD 3193</b>			
<i>RA 220 A</i>	9826248 <b>FD 3193</b>	C11581054 <b>FA 1302</b>		98262219 <b>FO 0030 V</b>
<i>RA 270</i>	9826213 <b>FD 3338</b>			
<i>RA 30</i>	9826233 <b>FD 3061</b>			98262220 <b>FO 0148 V</b>
<i>RA 30 MK II</i>	9826233 <b>FD 3061</b>			
<i>RA 30 MK III</i>	9826277 <b>FD 3180</b>	C1601252 <b>FA 1241</b>		
<i>RA 340</i>	9826213 <b>FD 3338</b>			
<i>RA 40</i>	9826233 <b>FD 3061</b>	C111581051 <b>FA 1249</b>		98262220 <b>FO 0148 V</b>
<i>RA 40 MK II</i>	9826233 <b>FD 3061</b>			
<i>RA 40 MK III</i>	9826277 <b>FD 3180</b>	C1601252 <b>FA 1241</b>		
<i>RA 50</i>	9826223 <b>FD 3005</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<i>RA 50 MK III</i>	9826277 <b>FD 3180</b>	C1601252 <b>FA 1241</b>		
<i>RA 60</i>	9826223 <b>FD 3005</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<i>RA 75</i>	9826223 <b>FD 3005</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<i>RA 75 MK II</i>	9826223 <b>FD 3005</b>	C111581014 <b>FA 1105</b>		98262220 <b>FO 0148 V</b>
<i>RALLY 040 UP TO 062</i>	10525274 <b>FD 3031 V</b>	11380674 <b>FA 5508</b>		04425274 <b>FI 1099 V</b>
<i>RALLY 070 UP TO 112</i>	10525274 <b>FD 3031 V</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>RALLY 070 UP TO 112 FROM SERIES No. 446</i>	10525274 <b>FD 3031 V</b>	11323374 <b>FA 5500</b>		04425274 <b>FI 1099 V</b>
<i>RALLY 1</i>	10525274 <b>FD 3031 V</b>	11380674 <b>FA 5508</b>		11381974 <b>FI 1067 V</b>
<i>RALLY 2</i>	10525274 <b>FD 3031 V</b>	11323374 <b>FA 5500</b>		04425274 <b>FI 1099 V</b>
<i>REGATTA 140 UP TO 200</i>	10882574 <b>FD 3247</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>ROTAIR RA 40</i>	20047307 <b>FD 3306</b>			
<i>ROTAIR RA 60</i>	20047307 <b>FD 3306</b>			
<i>SC 10 D</i>	00652674 <b>FD 3186</b>	00927074 <b>FP 2445</b>		04425274 <b>FI 1099 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>DEMAG</b>				
<i>SC 10 DS</i>				
<i>SC 10 DS</i>	00652674 <b>FD 3186</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SC 10 ES</i>	00652674 <b>FD 3186</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SC 100 D</i>	00652674 <b>FD 3186</b>	05151274 <b>FA 1202 AL</b>		04425274 <b>FI 1099 V</b>
<i>SC 100 DW</i>	00652674 <b>FD 3186</b>	05151274 <b>FA 1202 AL</b>		04425274 <b>FI 1099 V</b>
<i>SC 101 D</i>	00652674 <b>FD 3186</b>	00927074 <b>FP 2445</b>		04425274 <b>FI 1099 V</b>
<i>SC 121 D</i>	00614874 <b>FD 3065</b>	00927074 <b>FP 2445</b>		04425274 <b>FI 1099 V</b>
<i>SC 14 D</i>	00614874 <b>FD 3065</b>	00927074 <b>FP 2445</b>		04425274 <b>FI 1099 V</b>
<i>SC 140 DS UP TO 142 DS WITH DEUTZ BF6L913</i>	00614874 <b>FD 3065</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SC 141 DS WITH DEUTZ F6L413F ENG.</i>	00614874 <b>FD 3065</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SC 17 DS WITH DEUTZ F6L413F ENG.</i>	00614874 <b>FD 3065</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SC 170 DS UP TO 174 DS WITH DEUTZ BF6L913C</i>	00614874 <b>FD 3065</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SC 20 DS WITH DEUTZ F2L208F ENG.</i>	05482874 <b>FD 3073</b>	04472874 <b>FA 1240</b>		05773274 <b>FI 1295 V</b>
<i>SC 20 DS-1</i>	05482874 <b>FD 3073</b>	04472874 <b>FA 1240</b>		05773274 <b>FI 1295 V</b>
<i>SC 20 DS-2 WITH DEUTZ F2L208F ENG.</i>	05482874 <b>FD 3073</b>	04472874 <b>FA 1240</b>		05773274 <b>FI 1295 V</b>
<i>SC 20 DS-3</i>	10533574 <b>FD 3096 V</b>	04472874 <b>FA 1240</b>		10654074 <b>FI 1290 V</b>
<i>SC 20 DS-3 H WITH HATZ 2G30 ENG.</i>				05773274 <b>FI 1295 V</b>
<i>SC 20 DS-3 WITH DEUTZ F2L208F ENG.</i>	10533574 <b>FD 3096 V</b>	10458274 <b>FA 0053</b>		05773274 <b>FI 1295 V</b>
<i>SC 23 D WITH DEUTZ F8L413 ENG.</i>	04115374 <b>FD 3066</b>	00927074 <b>FP 2445</b>		04425274 <b>FI 1099 V</b>
<i>SC 23 DH WITH DEUTZ F8L413 ENG.</i>	04115374 <b>FD 3066</b>			0309944 <b>FO 0077 V</b>
<i>SC 230 DS UP TO 234 DS WITH DEUTZ F8L513 ENG.</i>	04115374 <b>FD 3066</b>	29504356 <b>FA 1217</b>	29504356 <b>FA 1217</b>	04425274 <b>FI 1099 V</b>
<i>SC 25 DS WITH DEUTZ F2L1011 ENG.</i>				04819974 <b>FI 1306 V</b>
<i>SC 28 DS WITH DEUTZ F2L511 ENG.</i>	04555974 <b>FD 3059</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SC 3 DS</i>	00542274 <b>FD 3064</b>	04005074 <b>FA 1105</b>		00587374 <b>FI 1286 V</b>
<i>SC 3 ES</i>	00542274 <b>FD 3064</b>	04005074 <b>FA 1105</b>		00587374 <b>FI 1286 V</b>
<i>SC 30 DS</i>	05482874 <b>FD 3073</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SC 30 DS-1 WITH DEUTZ F2L511D ENG.</i>	05482874 <b>FD 3073</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SC 30 DS-2 WITH DEUTZ F2L1011 ENG.</i>	05482874 <b>FD 3073</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>DEMAG</b>				
<i>SC 38 DS WITH DEUTZ F2L912 ENG.</i>				
<i>SC 38 DS WITH DEUTZ F2L912 ENG.</i>	00542274 <b>FD 3064</b>	04005074 <b>FA 1105</b>		00587374 <b>FI 1286 V</b>
<i>SC 40 DS</i>	00489174 <b>FD 3432</b>	04472874 <b>FA 1240</b>		00587374 <b>FI 1286 V</b>
<i>SC 40 DS-1 WITH DEUTZ F2L511D ENG.</i>	10012674 <b>FD 3070</b>	04472874 <b>FA 1240</b>		00587374 <b>FI 1286 V</b>
<i>SC 40 DS-2 WITH DEUTZ F2L511D ENG.</i>	10012674 <b>FD 3070</b>	04472874 <b>FA 1240</b>		00587374 <b>FI 1286 V</b>
<i>SC 40 DS-21 WITH DEUTZ F3L1011 ENG.</i>		04472874 <b>FA 1240</b>		00587374 <b>FI 1286 V</b>
<i>SC 5 DS</i>	00691674 <b>FD 3009</b>	29504376 <b>FA 1106</b>		00587374 <b>FI 1286 V</b>
<i>SC 5 ES</i>	00691674 <b>FD 3009</b>	04005074 <b>FA 1105</b>		00587374 <b>FI 1286 V</b>
<i>SC 5 WITH DEUTZ F3L912 ENG.</i>	00542274 <b>FD 3064</b>	29504376 <b>FA 1106</b>	13106374 <b>FA 1346</b>	00587374 <b>FI 1286 V</b>
<i>SC 50 D WITH DEUTZ F3L912 ENG.</i>	00542274 <b>FD 3064</b>	05150574 <b>FA 1005 AL</b>		00587374 <b>FI 1286 V</b>
<i>SC 50 DS WITH DEUTZ F3L912 ENG.</i>	00542274 <b>FD 3064</b>	29504476 <b>FA 1241</b>		00587374 <b>FI 1286 V</b>
<i>SC 50 DS-1 WITH DEUTZ F4L1011 ENG.</i>	10525274 <b>FD 3031 V</b>	29504476 <b>FA 1241</b>		00587374 <b>FI 1286 V</b>
<i>SC 50 DT-1</i>	10525274 <b>FD 3031 V</b>	29504476 <b>FA 1241</b>		00587374 <b>FI 1286 V</b>
<i>SC 7 D WITH DEUTZ F4L912 ENG.</i>	00652674 <b>FD 3186</b>	00927074 <b>FP 2445</b>		01160024 <b>FO 0083 V</b>
<i>SC 7 DS WITH DEUTZ F4L912 ENG.</i>	00691674 <b>FD 3009</b>	29504406 <b>FA 1252</b>		01160024 <b>FO 0083 V</b>
<i>SC 7 ES</i>	00652674 <b>FD 3186</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SC 70 D WITH DEUTZ F4L912 ENG.</i>	00542274 <b>FD 3064</b>	05150574 <b>FA 1005 AL</b>		00587374 <b>FI 1286 V</b>
<i>SC 70 DS UP TO 104 DS</i>	04179274 <b>FD 3069</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SC 70 DW WITH PERKINS 4.236 ENG.</i>	00542274 <b>FD 3064</b>	05150574 <b>FA 1005 AL</b>		00587374 <b>FI 1286 V</b>
<i>SE 012</i>	04179274 <b>FD 3069</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SE 016</i>	00652674 <b>FD 3186</b>	29504406 <b>FA 1252</b>		04425274 <b>FI 1099 V</b>
<i>SE 020</i>	04115374 <b>FD 3066</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SE 10 S</i>	04555974 <b>FD 3059</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SE 11 P</i>	05482874 <b>FD 3073</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SE 11 P NORMAL TYPE</i>	04555974 <b>FD 3059</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SE 11 S</i>	04555974 <b>FD 3059</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SE 111 S</i>	00652674 <b>FD 3186</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SE 116 S UP TO 155 S</i>	10651774 <b>FD 3241</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>DEMAG</b>				
<i>SE 116 S UP TO 155 S NORMAL TYPE</i>				
<i>SE 116 S UP TO 155 S NORMAL TYPE</i>	10882474 <b>FD 3272</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SE 116 S UP TO 155 S OLD TYPE</i>	00614874 <b>FD 3065</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SE 120 S</i>	00652674 <b>FD 3186</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SE 121 S</i>	00652674 <b>FD 3186</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SE 140 AS UP TO 170 AS</i>	00702274 <b>FD 3066</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SE 15 S</i>	04555974 <b>FD 3059</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SE 150 S</i>	00652674 <b>FD 3186</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SE 155 S</i>	10651774 <b>FD 3241</b>			
<i>SE 16 P</i>	05482874 <b>FD 3073</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SE 16 P NORMAL TYPE</i>	04555974 <b>FD 3059</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SE 16 S</i>	04555974 <b>FD 3059</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SE 180 AS/WS UP TO 255 AS/WS</i>	10882574 <b>FD 3247</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SE 191 WS UP TO 221 WS</i>	00702274 <b>FD 3066</b>	29504356 <b>FA 1217</b>		04425274 <b>FI 1099 V</b>
<i>SE 20 EKS</i>	00348774 <b>FD 3032</b>	00338474 <b>FA 1219</b>		00587374 <b>FI 1286 V</b>
<i>SE 20 S</i>	04555974 <b>FD 3059</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SE 21 P</i>	05482874 <b>FD 3073</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SE 21 P NORMAL TYPE</i>	04555974 <b>FD 3059</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SE 21 S</i>	04555974 <b>FD 3059</b>	04472874 <b>FA 1240</b>		04819974 <b>FI 1306 V</b>
<i>SE 25 P</i>	05482874 <b>FD 3073</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SE 25 P NORMAL TYPE</i>	04555974 <b>FD 3059</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SE 26 S UP TO 30 S</i>	04555974 <b>FD 3059</b>	04472874 <b>FA 1240</b>		00587374 <b>FI 1286 V</b>
<i>SE 30 EKS</i>	00348774 <b>FD 3032</b>	00338474 <b>FA 1219</b>		00587374 <b>FI 1286 V</b>
<i>SE 31 S UP TO 40 S</i>	05074574 <b>FD 3062</b>	29504476 <b>FA 1241</b>		00587374 <b>FI 1286 V</b>
<i>SE 350 WES</i>	03560777 <b>FD 3337</b>	03608077		04425274 <b>FI 1099 V</b>
<i>SE 41 S UP TO 50 S</i>	00542274 <b>FD 3064</b>	29504476 <b>FA 1241</b>		00587374 <b>FI 1286 V</b>
<i>SE 51 S UP TO 60 S</i>	00542274 <b>FD 3064</b>	29504476 <b>FA 1241</b>		04425274 <b>FI 1099 V</b>
<i>SE 61 S</i>	04179274 <b>FD 3069</b>	29504476 <b>FA 1241</b>		04425274 <b>FI 1099 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>DEMAG</b>				
<i>SE 70 S</i>				
<i>SE 70 S</i>	04179274 <b>FD 3069</b>	29504476 <b>FA 1241</b>		04425274 <b>FI 1099 V</b>
<i>SE 71 S</i>	00652674 <b>FD 3186</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SE 76 S</i>	04179274 <b>FD 3069</b>	29504476 <b>FA 1241</b>		04425274 <b>FI 1099 V</b>
<i>SE 85 S</i>	00652674 <b>FD 3186</b>	29504376 <b>FA 1106</b>		04425274 <b>FI 1099 V</b>
<i>SE 90 S</i>	04179274 <b>FD 3069</b>	29504476 <b>FA 1241</b>		04425274 <b>FI 1099 V</b>
<i>SIRIUS 132 UP TO 160</i>	11427274 <b>FD 3251</b>	06296777 <b>FA 1556</b>		04425274 <b>FI 1099 V</b>
<i>SIRIUS 160 O</i>	11427374 <b>FD 3240</b>	11516974 <b>FA 5932/1</b>		04425274 <b>FI 1099 V</b>
<i>SIRIUS 200 UP TO 250</i>	11427474 <b>FD 3459</b>	06296777 <b>FA 1556</b>		04425274 <b>FI 1099 V</b>
<i>SIRIUS 250 N</i>	11427474 <b>FD 3459</b>	11516974 <b>FA 5932/1</b>		04425274 <b>FI 1099 V</b>
<i>SIRIUS 250 O</i>	11427274 <b>FD 3251</b>	06296777 <b>FA 1556</b>		04425274 <b>FI 1099 V</b>
<i>SPRINT 005 UP TO 012</i>	13010074 <b>FD 3571 V</b>	29504036 <b>FA 3070</b>		10654074 <b>FI 1290 V</b>
<i>SPRINT 005 UP TO 017</i>	10533574 <b>FD 3096 V</b>	29504036 <b>FA 3070</b>		10654074 <b>FI 1290 V</b>
<i>SPRINT 015 UP TO 022</i>	10533574 <b>FD 3096 V</b>	29504036 <b>FA 3070</b>		04819974 <b>FI 1306 V</b>
<i>SPRINT 020 UP TO 022</i>	10533574 <b>FD 3096 V</b>	29504036 <b>FA 3070</b>		10654074 <b>FI 1290 V</b>
<i>SPRINT 025 UP TO 032</i>	10596274 <b>FD 3372 V</b>	29504036 <b>FA 3070</b>		00587374 <b>FI 1286 V</b>
<i>SPRINT 025 UP TO 047</i>	10596274 <b>FD 3372 V</b>	29504036 <b>FA 3070</b>		00587374 <b>FI 1286 V</b>
<i>SPRINT 040 UP TO 047</i>	10525274 <b>FD 3031 V</b>	29504036 <b>FA 3070</b>		00587374 <b>FI 1286 V</b>
<i>SPRINT 050 UP TO 057</i>	10525274 <b>FD 3031 V</b>	29504476 <b>FA 1241</b>		00587374 <b>FI 1286 V</b>
<i>SPRINT 1 020 UP TO 022</i>	10533574 <b>FD 3096 V</b>	29504036 <b>FA 3070</b>		10654074 <b>FI 1290 V</b>
<i>SPRINT 2 025 UP TO 047</i>	10596274 <b>FD 3372 V</b>	29504036 <b>FA 3070</b>		00587374 <b>FI 1286 V</b>
<i>SPRINT 3 050 UP TO 057</i>	10525274 <b>FD 3031 V</b>	29504476 <b>FA 1241</b>		00587374 <b>FI 1286 V</b>
<i>START 005</i>	10533574 <b>FD 3096 V</b>	11207674 <b>FA 5507</b>		04819974 <b>FI 1306 V</b>
<i>START 007</i>	10533574 <b>FD 3096 V</b>	11207674 <b>FA 5507</b>		04819974 <b>FI 1306 V</b>
<i>START 010</i>	10533574 <b>FD 3096 V</b>	11207674 <b>FA 5507</b>		04819974 <b>FI 1306 V</b>
<i>START 015</i>	13010174 <b>FD 3372 V</b>	11224574 <b>FA 5504</b>		04819974 <b>FI 1306 V</b>
<i>START 017</i>	13010174 <b>FD 3372 V</b>	11224574 <b>FA 5504</b>		04819974 <b>FI 1306 V</b>
<i>START 025</i>	13010174 <b>FD 3372 V</b>	11224574 <b>FA 5504</b>		04819974 <b>FI 1306 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>DEMAG</b>				
<i>START 026</i>				
<i>START 026</i>	13010174 <b>FD 3372 V</b>	11224574 <b>FA 5504</b>		04819974 <b>FI 1306 V</b>
<i>START 032</i>	13010174 <b>FD 3372 V</b>	11224574 <b>FA 5504</b>		04819974 <b>FI 1306 V</b>
<i>START 037</i>	13010174 <b>FD 3372 V</b>	11224574 <b>FA 5504</b>		04819974 <b>FI 1306 V</b>
<i>SZ 350 WES UP TO 353 WES</i>	03560777 <b>FD 3337</b>	03608077		04425274 <b>FI 1099 V</b>
<i>SZ 400 HORIZONTAL TANK</i>	03560777 <b>FD 3337</b>	03608077		04425274 <b>FI 1099 V</b>
<i>SZ 400 VERTICAL TANK</i>	00702274 <b>FD 3066</b>	03608077		04425274 <b>FI 1099 V</b>
<i>TORNADO 45 SR</i>	10525274 <b>FD 3031 V</b>	98262207 <b>FA 5500</b>		98262220 <b>FO 0148 V</b>
<i>TORNADO 75 SR</i>	98262197 <b>FD 3464</b>	98262207 <b>FA 5500</b>		98262220 <b>FO 0148 V</b>
<i>ZITAIR 100</i>	982628020 <b>FD 3301</b>	C1601252 <b>FA 1241</b>		C16012302 <b>FI 1306 V</b>
<i>ZITAIR 100 G</i>	982628020 <b>FD 3301</b>	C1601252 <b>FA 1241</b>		C16012302 <b>FI 1306 V</b>
<i>ZITAIR 125</i>	982628020 <b>FD 3301</b>	C16012180 <b>FA 1240</b>		
<i>ZITAIR 130 D MKIV</i>	982625072 <b>FD 3333</b>			
<i>ZITAIR 150 D MKIV</i>	982625072 <b>FD 3333</b>			C16012303 <b>FI 1286 V</b>
<i>ZITAIR 150 MKII</i>	982625073 <b>FD 3332</b>	C11561724 <b>FA 1212 AL</b>		C16012303 <b>FI 1286 V</b>
<i>ZITAIR 175 D</i>	982628026 <b>FD 3303</b>	C16012189 <b>FA 1106</b>		C16012303 <b>FI 1286 V</b>
<i>ZITAIR 175 P</i>	982628026 <b>FD 3303</b>	C16012189 <b>FA 1106</b>		C16012303 <b>FI 1286 V</b>
<i>ZITAIR 180 MKII</i>	982625073 <b>FD 3332</b>	C1601252 <b>FA 1241</b>		C16012303 <b>FI 1286 V</b>
<i>ZITAIR 180 P</i>	982625073 <b>FD 3332</b>	C1601252 <b>FA 1241</b>		C16012303 <b>FI 1286 V</b>
<i>ZITAIR 250</i>	982628027 <b>FD 3304</b>	C16012190 <b>FA 1252</b>		C16012303 <b>FI 1286 V</b>
<i>ZITAIR 250 D</i>	982628020 <b>FD 3301</b>	C16012190 <b>FA 1252</b>		C16012303 <b>FI 1286 V</b>
<i>ZITAIR 250 P</i>	982628027 <b>FD 3304</b>	C16012190 <b>FA 1252</b>		C16012303 <b>FI 1286 V</b>
<i>ZITAIR 380-145</i>	982625079 <b>FD 3328</b>	1078A30930 <b>FA 1242</b>		9826280400001 <b>FI 1099 V</b>
<i>ZITAIR 380-170</i>	982625079 <b>FD 3328</b>	1078A30930 <b>FA 1242</b>		9826280400001 <b>FI 1099 V</b>
<i>ZITAIR 400-125</i>	982625079 <b>FD 3328</b>	1078A30930 <b>FA 1242</b>		9826280400001 <b>FI 1099 V</b>
<i>ZITAIR 400-170</i>	982625079 <b>FD 3328</b>	1078A30930 <b>FA 1242</b>		9826280400001 <b>FI 1099 V</b>
<i>ZITAIR 550-170</i>	1311K08020 <b>FD 3237</b>			
<i>ZITAIR 600-125</i>	982628046 <b>FD 3350</b>			9826280400001 <b>FI 1099 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>DEMAG</b> <i>ZITAIR 65</i>				
<i>ZITAIR 65</i>	982628023 <b>FD 3295</b>	C1601252 <b>FA 1241</b>		C16012012 <b>FI 1268 V</b>
<i>ZITAIR 70</i>	982625085 <b>FD 3339</b>	C1601252 <b>FA 1241</b>		C16012012 <b>FI 1268 V</b>
<i>ZITAIR 70 P</i>	982625085 <b>FD 3339</b>	C1601252 <b>FA 1241</b>		C16012012 <b>FI 1268 V</b>
<i>ZITAIR 750-175</i>	1311K08020 <b>FD 3237</b>	982625026 <b>FA 1270</b>		9826280400001 <b>FI 1099 V</b>
<i>ZITAIR 750-300</i>	1311K08020 <b>FD 3237</b>	982625026 <b>FA 1270</b>		9826280400001 <b>FI 1099 V</b>
<i>ZITAIR 85</i>	982628020 <b>FD 3301</b>	C1601252 <b>FA 1241</b>		C16012302 <b>FI 1306 V</b>
<i>ZITAIR 85 G</i>	982628020 <b>FD 3301</b>	C1601252 <b>FA 1241</b>		C16012302 <b>FI 1306 V</b>
<i>ZITAIR 85 P</i>	982625085 <b>FD 3339</b>	C1601252 <b>FA 1241</b>		C16012012 <b>FI 1268 V</b>
<i>ZITAIR 90 D MKIV</i>	982625072 <b>FD 3333</b>			C16012303 <b>FI 1286 V</b>
<b>DVP</b>				
<i>LB 100</i>	1801033 <b>FD 3137</b>			1809001 <b>FO 0420 V</b>
<i>LB 180</i>	1801033 <b>FD 3137</b>			1809002 <b>FI 1306 V</b>
<i>LB 250</i>	1801033 <b>FD 3137</b>			1809002 <b>FI 1306 V</b>
<i>LB 40</i>	1801032 <b>FD 3136</b>			1809001 <b>FO 0420 V</b>
<i>LB 60</i>	1801032 <b>FD 3136</b>			1809001 <b>FO 0420 V</b>
<i>LC 105</i>	1801033 <b>FD 3137</b>			1809001 <b>FO 0420 V</b>
<i>LC 150</i>	1801063 <b>FD 3138</b>			1809001 <b>FO 0420 V</b>
<i>LC 205</i>	1801033 <b>FD 3137</b>			1809002 <b>FI 1306 V</b>
<i>LC 305</i>	1801033 <b>FD 3137</b>			1809002 <b>FI 1306 V</b>
<b>ECOAIR</b>				
<i>A20/A25</i>	88200357 <b>FD 3013</b>	88281829 <b>FA 5504</b>		93568236 <b>FO 0148 V</b>
<i>A21/A26</i>	88226238 <b>FD 3564</b>	88226220 <b>FA 2050</b>		93568236 <b>FO 0148 V</b>
<i>A30/A40</i>	88200753 <b>FD 3257</b>	88281829 <b>FA 5504</b>		93568236 <b>FO 0148 V</b>
<i>A31</i>	88226238 <b>FD 3564</b>	88226220 <b>FA 2050</b>		93568236 <b>FO 0148 V</b>
<i>A40 VARIANT</i>	88200357 <b>FD 3013</b>	88281829 <b>FA 5504</b>		93568236 <b>FO 0148 V</b>
<i>A5/A7/A10/A15</i>	88204318 <b>FD 3556</b>	88210620 <b>FA 1933</b>		93568258
<i>D02/D03/D04/D06</i>	93578292	93578300		93578284 <b>FO 0029 V</b>
<i>D05/D07</i>	93568277 <b>FD 3323</b>	93504678		93580884



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ECOAIR</b>				
<i>D10/D15</i>				
<i>D10/D15</i>	93568244 <b>FD 3146</b>	93580876 <b>FA 0028</b>		93568285 <b>FI 1288 V</b>
<i>D101</i>	93568269 <b>FD 3065</b>	93578375 <b>FA 2219</b>		93578367 <b>FI 1099 V</b>
<i>D125</i>	93568269 <b>FD 3065</b>	93578375 <b>FA 2219</b>		93578367 <b>FI 1099 V</b>
<i>D126Z/D152Z/D183Z/D22 2Z</i>	88181755 <b>FD 3001</b>	93585123 <b>FA 2066</b>		93585297 <b>FO 0030 V</b>
<i>D150/D180/D182</i>	93585958 <b>FD 3066</b>	93578375 <b>FA 2219</b>		93578367 <b>FI 1099 V</b>
<i>D151/D182 VARIANT/D221 VARIANT</i>	93585966	93578391		93578367 <b>FI 1099 V</b>
<i>D16</i>	93568293 <b>FD 3214</b>	93578334 <b>FA 0139</b>		93568285 <b>FI 1288 V</b>
<i>D20 UNTIL 1990</i>	93568293 <b>FD 3214</b>	93578334 <b>FA 0139</b>		
<i>D20/D30</i>	93568293 <b>FD 3214</b>	93578334 <b>FA 0139</b>		93568285 <b>FI 1288 V</b>
<i>D221</i>	93585958 <b>FD 3066</b>	93578375 <b>FA 2219</b>		93578367 <b>FI 1099 V</b>
<i>D31/50</i>	F403351022 <b>FD 3197</b>	F404051022 <b>FA 1229</b>		F402351082 <b>FI 1288 V</b>
<i>D31/D40/D50</i>	93568301 <b>FD 3197</b>	93578342 <b>FA 1229</b>		93568285 <b>FI 1288 V</b>
<i>D60/102</i>	N2785000 <b>FD 3352</b>	F406051022 <b>FA 2220</b>		F400651042 <b>FO 0148 V</b>
<i>D60/D75/D100/D102 UNTIL 09.1993</i>	93568319 <b>FD 3352</b>	93578359 <b>FA 2220</b>		93568236 <b>FO 0148 V</b>
<i>F 30</i>	F410251012 <b>FD 3372 V</b>			
<i>F 58</i>	F410351022 <b>FD 3031 V</b>			
<i>F42</i>	F410351022 <b>FD 3031 V</b>			
<i>F47</i>	F410351022 <b>FD 3031 V</b>			
<i>SDA 75</i>	F406051012 <b>FD 3114</b>			
<i>SVA 22</i>	404051062 <b>FD 3214</b>			
<b>FIAC</b>				
<i>AIRBLOCK 10 8-10-13 BAR</i>	7211960000 <b>FD 3096 V</b>	7212160010 <b>FA 1933</b>		7211141150 <b>FO 0029 V</b>
<i>AIRBLOCK 100 DR 8-10- 13 BAR</i>		7212240010 <b>FA 5500</b>		7211430000 <b>FI 1067 V</b>
<i>AIRBLOCK 100 DR/SD</i>	7212170000 <b>FD 3441</b>	7212240010 <b>FA 5500</b>		7211430000 <b>FI 1067 V</b>
<i>AIRBLOCK 100 SD 8-10-13 BAR</i>		7212240010 <b>FA 5500</b>		7211430000 <b>FI 1067 V</b>
<i>AIRBLOCK 15 8-10-13 BAR</i>	7211960000 <b>FD 3096 V</b>	7212160010 <b>FA 1933</b>		7211141150 <b>FO 0029 V</b>
<i>AIRBLOCK 20 8-10-13 BAR</i>	7212300000 <b>FD 3372 V</b>	7212160010 <b>FA 1933</b>		7211131200 <b>FI 1306 V</b>





	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>FIAC</b>				
<i>AIRBLOCK 25 8-10-13 BAR</i>				
<i>AIRBLOCK 25 8-10-13 BAR</i>	7212300000 <b>FD 3372 V</b>	7212160010 <b>FA 1933</b>		7211131200 <b>FI 1306 V</b>
<i>AIRBLOCK 30 8-10-13 BAR</i>	7212300000 <b>FD 3372 V</b>	7212160010 <b>FA 1933</b>		7211141300 <b>FO 0148 V</b>
<i>AIRBLOCK 40 8-10-13 BAR</i>	7212210000 <b>FD 3460</b>	7212360010 <b>FA 5501</b>		7211141300 <b>FO 0148 V</b>
<i>AIRBLOCK 50 8-10-13 BAR</i>	7212210000 <b>FD 3460</b>	7211690010 <b>FA 5501</b>		7211131500 <b>FO 0100 V</b>
<i>AIRBLOCK 60 8-10-13 BAR</i>	7211410000 <b>FD 3464</b>	7211690010 <b>FA 5501</b>		7211131500 <b>FO 0100 V</b>
<i>AIRBLOCK 75 DR 8-10-13 BAR</i>	7211410000 <b>FD 3464</b>	7212050010 <b>FA 5502</b>		7211430000 <b>FI 1067 V</b>
<i>AIRBLOCK 75 SD 8-10-13 BAR</i>	7211410000 <b>FD 3464</b>	7212050010 <b>FA 5502</b>		7211430000 <b>FI 1067 V</b>
<i>CRS 10</i>	7211960000 <b>FD 3096 V</b>	7211360000 <b>FA 0093</b>		7212250000 <b>FO 0845 V</b>
<i>CRS 15</i>	7211960000 <b>FD 3096 V</b>	7212320010 <b>FA 0028</b>		7211121100 <b>FI 0906 V</b>
<i>CRS 20</i>	7211960000 <b>FD 3096 V</b>	7212320010 <b>FA 0028</b>		7211121100 <b>FI 0906 V</b>
<i>CRS 30</i>				7211141300 <b>FO 0148 V</b>
<i>CRS 40</i>				7211141300 <b>FO 0148 V</b>
<i>CRS 5.5</i>	7211960000 <b>FD 3096 V</b>	7211360000 <b>FA 0093</b>		7212250000 <b>FO 0845 V</b>
<i>CRS 7.5</i>	7211960000 <b>FD 3096 V</b>	7211360000 <b>FA 0093</b>		7212250000 <b>FO 0845 V</b>
<i>CRS D 10</i>	7211960000 <b>FD 3096 V</b>	7211360000 <b>FA 0093</b>		7212250000 <b>FO 0845 V</b>
<i>CRS D 5.5</i>	7211960000 <b>FD 3096 V</b>	7211360000 <b>FA 0093</b>		7212250000 <b>FO 0845 V</b>
<i>CRS D 7.5</i>	7211960000 <b>FD 3096 V</b>	7211360000 <b>FA 0093</b>		7212250000 <b>FO 0845 V</b>
<i>SILVER 10</i>	7211960000 <b>FD 3096 V</b>	7211360000 <b>FA 0093</b>		7211121100 <b>FI 0906 V</b>
<i>SILVER 15</i>	7211960000 <b>FD 3096 V</b>	7211360000 <b>FA 0093</b>		7211121100 <b>FI 0906 V</b>
<i>SILVER 5.5</i>	7211960000 <b>FD 3096 V</b>	7211360000 <b>FA 0093</b>		7211121100 <b>FI 0906 V</b>
<i>SILVER 7.5</i>	7211960000 <b>FD 3096 V</b>	7211360000 <b>FA 0093</b>		7211121100 <b>FI 0906 V</b>
<i>TK 10</i>	7211960000 <b>FD 3096 V</b>	7211260000 <b>FA 1731</b>		7211121100 <b>FI 0906 V</b>
<i>TK 10 OLD</i>	7211960000 <b>FD 3096 V</b>	7211260000 <b>FA 1731</b>		7211141150 <b>FO 0029 V</b>
<i>TK 15 NEW</i>	7211960000 <b>FD 3096 V</b>	7211260000 <b>FA 1731</b>		7211121100 <b>FI 0906 V</b>
<i>TK 15 OLD</i>	7211960000 <b>FD 3096 V</b>	7211260000 <b>FA 1731</b>		7211141150 <b>FO 0029 V</b>
<i>TK 5.5</i>	7211960000 <b>FD 3096 V</b>	7211360000 <b>FA 0093</b>		7212250000 <b>FO 0845 V</b>
<i>TK 7 OLD</i>	7211960000 <b>FD 3096 V</b>	7211260000 <b>FA 1731</b>		7211141150 <b>FO 0029 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>FIAC</b>				
<i>TK 7.5</i>				
<i>TK 7.5</i>	7211960000 <b>FD 3096 V</b>	7211360000 <b>FA 0093</b>		7212250000 <b>FO 0845 V</b>
<i>V 10 NEW</i>	4088070000 <b>FD 3587</b>	7212160010 <b>FA 1933</b>		7211121100 <b>FI 0906 V</b>
<i>V 10 OLD</i>	4088070000 <b>FD 3587</b>	7211170000 <b>FA 1959</b>		7211141150 <b>FO 0029 V</b>
<i>V 100 NEW</i>	7212170000 <b>FD 3441</b>	7212240010 <b>FA 5500</b>		7120400000 <b>FI 1099 V</b>
<i>V 15 NEW</i>	4088070000 <b>FD 3587</b>	7212160010 <b>FA 1933</b>		7211121100 <b>FI 0906 V</b>
<i>V 15 OLD</i>	4088070000 <b>FD 3587</b>	7211170000 <b>FA 1959</b>		7211141150 <b>FO 0029 V</b>
<i>V 20 NEW</i>	4088070000 <b>FD 3587</b>	7212160010 <b>FA 1933</b>		7211121100 <b>FI 0906 V</b>
<i>V 20 OLD</i>	4088070000 <b>FD 3587</b>	7211170000 <b>FA 1959</b>		7211131200 <b>FI 1306 V</b>
<i>V 25 NEW</i>	4088070000 <b>FD 3587</b>	7212160010 <b>FA 1933</b>		7211121100 <b>FI 0906 V</b>
<i>V 25 OLD</i>	4088070000 <b>FD 3587</b>	7211260000 <b>FA 1731</b>		7211131200 <b>FI 1306 V</b>
<i>V 30 NEW</i>	4088080000 <b>FD 3102</b>	7211450010 <b>FA 2050</b>		7211141300 <b>FO 0148 V</b>
<i>V 30 OLD</i>	4088080000 <b>FD 3102</b>	7211180000 <b>FA 2117</b>		7211141300 <b>FO 0148 V</b>
<i>V 40 NEW</i>	4088090000 <b>FD 3047</b>	7211140000 <b>FA 1229</b>		7211141300 <b>FO 0148 V</b>
<i>V 40 OLD</i>	4088090000 <b>FD 3047</b>	7211140000 <b>FA 1229</b>		7211141300 <b>FO 0148 V</b>
<i>V 50</i>	4088090000 <b>FD 3047</b>	7211140000 <b>FA 1229</b>		7211141300 <b>FO 0148 V</b>
<i>V 50 NEW</i>	4088090000 <b>FD 3047</b>	7211140000 <b>FA 1229</b>		7211141300 <b>FO 0148 V</b>
<i>V 60 NEW</i>	7211410000 <b>FD 3464</b>	7212050010 <b>FA 5502</b>		7211141300 <b>FO 0148 V</b>
<i>V 7 OLD</i>	4088070000 <b>FD 3587</b>	7211170000 <b>FA 1959</b>		7211141150 <b>FO 0029 V</b>
<i>V 75 NEW</i>	7211410000 <b>FD 3464</b>	7212050010 <b>FA 5502</b>		7211141300 <b>FO 0148 V</b>
<b>FINI</b>				
<i>BS 15</i>	048287000 <b>FD 3096 V</b>	017066001 <b>FA 1933</b>		048033000 <b>FO 0077 V</b>
<i>BS 20</i>	048287000 <b>FD 3096 V</b>	017066001 <b>FA 1933</b>		048033000 <b>FO 0077 V</b>
<i>BUILDAIR 1500</i>	048287000 <b>FD 3096 V</b>			
<i>BUILDAIR 500</i>	048275000 <b>FD 3034 V</b>			048385000 <b>FO 0029 V</b>
<i>CUBE</i>	048275000 <b>FD 3034 V</b>	017058001 <b>FA 2982</b>		048385000 <b>FO 0029 V</b>
<i>KSC 10</i>	048287000 <b>FD 3096 V</b>	017002000 <b>FA 2202</b>		048033000 <b>FO 0077 V</b>
<i>KSC 10 COD. 260LK0050</i>	048287000 <b>FD 3096 V</b>	017002000 <b>FA 2202</b>		048033000 <b>FO 0077 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>FINI</b>	<b>KSC 15</b>			
<b>KSC 15</b>	048287000 <b>FD 3096 V</b>	017002000 <b>FA 2202</b>		048033000 <b>FO 0077 V</b>
<b>KSC 5 COD. 260LK0050</b>	048287000 <b>FD 3096 V</b>	017002000 <b>FA 2202</b>		048033000 <b>FO 0077 V</b>
<b>KSC 5 COD. 260LK0051</b>	048287000 <b>FD 3096 V</b>	017058001 <b>FA 2982</b>		048033000 <b>FO 0077 V</b>
<b>KSC 7 COD. 260LK0050</b>	048287000 <b>FD 3096 V</b>	017002000 <b>FA 2202</b>		048033000 <b>FO 0077 V</b>
<b>KSC 7.5</b>	048287000 <b>FD 3096 V</b>	017002000 <b>FA 2202</b>		048033000 <b>FO 0077 V</b>
<b>ROTAR 10 C COD. 260EA0050</b>	048041000 <b>FD 3035</b>	017027000 <b>FA 0047</b>		048129000 <b>FO 0339 V</b>
<b>ROTAR 15 C COD. 260LF0050</b>	048041000 <b>FD 3035</b>	017025000 <b>FA 2110</b>		048033000 <b>FO 0077 V</b>
<b>ROTAR 20 C COD. 260LB0050</b>	048132000 <b>FD 3051</b>	017025000 <b>FA 2110</b>		048033000 <b>FO 0077 V</b>
<b>ROTAR 25 C COD. 260LB0050</b>	048132000 <b>FD 3051</b>	017025000 <b>FA 2110</b>		048033000 <b>FO 0077 V</b>
<b>ROTAR 30 C COD. 260LR0050</b>	048150000 <b>FD 3134</b>	017026000 <b>FA 2794</b>		048033000 <b>FO 0077 V</b>
<b>ROTAR 40 C COD. 260EF0060</b>	048032000 <b>FD 3102</b>	017026000 <b>FA 2794</b>		048033000 <b>FO 0077 V</b>
<b>ROTAR 50 C</b>	048138000 <b>FD 3112</b>	017026000 <b>FA 2794</b>		048033000 <b>FO 0077 V</b>
<b>ROTAR 50 E</b>	048138000 <b>FD 3112</b>	017026000 <b>FA 2794</b>		048033000 <b>FO 0077 V</b>
<b>ROTAR 50 MEGA</b>	048273000 <b>FD 3650</b>	017026000 <b>FA 2794</b>		048221000 <b>FO 0148 V</b>
<b>ROTAR 60 C</b>	048138000 <b>FD 3112</b>	017023000 <b>FA 1105</b>		048033000 <b>FO 0077 V</b>
<b>ROTAR 60 E 10</b>	048273000 <b>FD 3650</b>	017026000 <b>FA 2794</b>		048033000 <b>FO 0077 V</b>
<b>ROTAR 60 MEGA</b>	048273000 <b>FD 3650</b>	017026000 <b>FA 2794</b>		048221000 <b>FO 0148 V</b>
<b>ROTAR 7 C COD. 260EA0050</b>	048041000 <b>FD 3035</b>	017027000 <b>FA 0047</b>		048129000 <b>FO 0339 V</b>
<b>ROTAR BSC 10 COD. 260LJ0050</b>	048287000 <b>FD 3096 V</b>	017025000 <b>FA 2110</b>		048033000 <b>FO 0077 V</b>
<b>ROTAR BSC 15 COD. 260LJ0050</b>	048287000 <b>FD 3096 V</b>	017025000 <b>FA 2110</b>		048033000 <b>FO 0077 V</b>
<b>ROTAR BSC 20 COD. 260LJ0050</b>	048287000 <b>FD 3096 V</b>	017025000 <b>FA 2110</b>		048033000 <b>FO 0077 V</b>
<b>ROTAR BSC COD. 260LZ0050</b>	048287000 <b>FD 3096 V</b>	017025000 <b>FA 2110</b>		048033000 <b>FO 0077 V</b>
<b>ROTAR CUBE 10</b>	048275000 <b>FD 3034 V</b>	017058001 <b>FA 2982</b>		048385000 <b>FO 0029 V</b>
<b>ROTAR CUBE 5</b>	048275000 <b>FD 3034 V</b>	017058001 <b>FA 2982</b>		048443000 <b>FO 0130 V</b>
<b>ROTAR CUBE 7</b>	048275000 <b>FD 3034 V</b>	017058001 <b>FA 2982</b>		048385000 <b>FO 0029 V</b>
<b>ROTAR GIGA 100</b>	048311000 <b>FD 3042</b>	017067001 <b>FA 1103 AL</b>		048313000 <b>FI 1099 V</b>
<b>ROTAR GIGA 75</b>	048311000 <b>FD 3042</b>	017067001 <b>FA 1103 AL</b>		048313000 <b>FI 1099 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>FINI</b>				
<i>ROTAR MC 308</i>				
<i>ROTAR MC 308</i>	048450000 <b>FD 3034 V</b>	017078000		048449000 <b>FO 0015 V</b>
<i>ROTAR MC 310</i>	048450000 <b>FD 3034 V</b>	017078000		048449000 <b>FO 0015 V</b>
<i>ROTAR MC 408</i>	048450000 <b>FD 3034 V</b>	017078000		048449000 <b>FO 0015 V</b>
<i>ROTAR MC 410</i>	048450000 <b>FD 3034 V</b>	017078000		048449000 <b>FO 0015 V</b>
<i>ROTAR MC 508</i>	048450000 <b>FD 3034 V</b>	017078000		048449000 <b>FO 0015 V</b>
<i>ROTAR MC 510</i>	048450000 <b>FD 3034 V</b>	017078000		048449000 <b>FO 0015 V</b>
<i>ROTAR MCI 4008</i>	048461000 <b>FD 3031 V</b>	017083000 <b>FA 5002</b>		048460000
<i>ROTAR MCI 4010</i>	048461000 <b>FD 3031 V</b>	017083000 <b>FA 5002</b>		048460000
<i>ROTAR MCI 5008</i>	048461000 <b>FD 3031 V</b>	017083000 <b>FA 5002</b>		048460000
<i>ROTAR MCI 5008 STC</i>	048461000 <b>FD 3031 V</b>	017083000 <b>FA 5002</b>		048460000
<i>ROTAR MCI 5010</i>	048461000 <b>FD 3031 V</b>	017083000 <b>FA 5002</b>		048460000
<i>ROTAR MCI 5010 STC</i>	048461000 <b>FD 3031 V</b>	017083000 <b>FA 5002</b>		048460000
<i>ROTAR PLUS 20</i>	048353000 <b>FD 3372 V</b>	017026000 <b>FA 2794</b>		048033000 <b>FO 0077 V</b>
<i>ROTAR PLUS 25</i>	048353000 <b>FD 3372 V</b>	017026000 <b>FA 2794</b>		048033000 <b>FO 0077 V</b>
<i>ROTAR PLUS 30</i>	048353000 <b>FD 3372 V</b>	017026000 <b>FA 2794</b>		048033000 <b>FO 0077 V</b>
<i>ROTAR PLUS 40</i>	048428000 <b>FD 3031 V</b>	017026000 <b>FA 2794</b>		048444000 <b>FO 0148 V</b>
<i>ROTAR R 10 1 SERIES</i>	048041000 <b>FD 3035</b>	017027000 <b>FA 0047</b>		048129000 <b>FO 0339 V</b>
<i>ROTAR R 10 2 SERIES</i>	048041000 <b>FD 3035</b>	017017000 <b>FA 1231</b>		048033000 <b>FO 0077 V</b>
<i>ROTAR R 100</i>	048046000 <b>FD 3005</b>	017023000 <b>FA 1105</b>		048035000 <b>FO 0195 V</b>
<i>ROTAR R 15 1 SERIES</i>	048041000 <b>FD 3035</b>	017027000 <b>FA 0047</b>		048129000 <b>FO 0339 V</b>
<i>ROTAR R 15 2 SERIES</i>	048041000 <b>FD 3035</b>	017020000 <b>FA 1231</b>		048033000 <b>FO 0077 V</b>
<i>ROTAR R 20</i>	048032000 <b>FD 3102</b>	017020000 <b>FA 1231</b>		048033000 <b>FO 0077 V</b>
<i>ROTAR R 25</i>	048032000 <b>FD 3102</b>	017002100		048033000 <b>FO 0077 V</b>
<i>ROTAR R 30</i>	048032000 <b>FD 3102</b>	017010100		048033000 <b>FO 0077 V</b>
<i>ROTAR R 40 1 SERIES</i>	048037000 <b>FD 3432</b>	048027000 <b>FA 1240</b>		048033000 <b>FO 0077 V</b>
<i>ROTAR R 40 2 SERIES</i>	048044000 <b>FD 3059</b>	017014000 <b>FA 1241</b>		048033000 <b>FO 0077 V</b>
<i>ROTAR R 40 3 SERIES</i>	048032000 <b>FD 3102</b>	017010000 <b>FA 1671</b>		048033000 <b>FO 0077 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>FINI</b>				
<i>ROTAR R 50</i>				
<i>ROTAR R 50</i>	048044000 <b>FD 3059</b>	017014000 <b>FA 1241</b>		048033000 <b>FO 0077 V</b>
<i>ROTAR R 60</i>	048135000 <b>FD 3111</b>	017023000 <b>FA 1105</b>		048033000 <b>FO 0077 V</b>
<i>ROTAR R 60 08 ELETT.</i>	048273000 <b>FD 3650</b>	017026000 <b>FA 2794</b>		048033000 <b>FO 0077 V</b>
<i>ROTAR R 60 ELETT.</i>	048273000 <b>FD 3650</b>			
<i>ROTAR R 75</i>	048046000 <b>FD 3005</b>	017023000 <b>FA 1105</b>		048035000 <b>FO 0195 V</b>
<i>ROTAR SC 308-270 TP</i>	048450000 <b>FD 3034 V</b>	017078000		048449000 <b>FO 0015 V</b>
<i>ROTAR SC 310-270 TP</i>	048450000 <b>FD 3034 V</b>	017078000		048449000 <b>FO 0015 V</b>
<i>ROTAR SC 408-270 TP</i>	048450000 <b>FD 3034 V</b>	017078000		048449000 <b>FO 0015 V</b>
<i>ROTAR SC 410-270 TP</i>	048450000 <b>FD 3034 V</b>	017078000		048449000 <b>FO 0015 V</b>
<i>ROTAR SC 508-270 TP</i>	048450000 <b>FD 3034 V</b>	017078000		048449000 <b>FO 0015 V</b>
<i>ROTAR SC 510-270 TP</i>	048450000 <b>FD 3034 V</b>	017078000		048449000 <b>FO 0015 V</b>
<i>ROTAR T 60 10 BAR</i>	048135000 <b>FD 3111</b>	017023000 <b>FA 1105</b>		048444000 <b>FO 0148 V</b>
<i>ROTAR T 60 8 BAR</i>	048135000 <b>FD 3111</b>	017023000 <b>FA 1105</b>		048444000 <b>FO 0148 V</b>
<i>ROTOR PLUS 25</i>	048353000 <b>FD 3372 V</b>	017025000 <b>FA 2110</b>		048033000 <b>FO 0077 V</b>
<i>UNIPAC B 100</i>	048032000 <b>FD 3102</b>			
<i>UNIPAC B 50</i>	048041000 <b>FD 3035</b>			
<b>FLUIDAIR</b>				
<i>ROTAPACK 45</i>	RP2SCK005 <b>FD 3397</b>			
<i>RPK 185</i>	RP2SCK025 <b>FD 3412</b>			
<i>RPK 235</i>	RP2SCK025 <b>FD 3412</b>			
<i>RPK 290</i>	RP2SCK030 <b>FD 3390</b>			
<i>RPK 330</i>	RP2SCK030 <b>FD 3390</b>			
<i>SR 100 L 23</i>	1150022901 <b>FD 3105</b>			
<i>SR 177</i>	RP2SCK025 <b>FD 3412</b>			
<i>SR 185</i>	RP2SCK025 <b>FD 3412</b>			
<i>SR 250 W</i>	RP2SCK030 <b>FD 3390</b>			
<i>SR 290 W</i>	RP2SCK030 <b>FD 3390</b>			



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>FLUIDAIR</b> <span style="float: right;"><i>SR 30</i></span>				
<i>SR 30</i>	RP2SCK005 <b>FD 3397</b>			
<i>SR 330 W</i>	RP2SCK030 <b>FD 3390</b>			
<i>SR 40</i>	RP2SCK005 <b>FD 3397</b>			
<b>FUSHENG</b>				
<i>250-350</i>	91101300 <b>FD 3271</b>			
<i>SA10</i>	91111003 <b>FD 3275</b>	7118266010		91107012 <b>FI 1286 V</b>
<i>SA100</i>	91101150 <b>FD 3066</b>	7118266010		91107082 <b>FO 0148 V</b>
<i>SA10W.4</i>	91111003 <b>FD 3275</b>	7118166010		91107012 <b>FI 1286 V</b>
<i>SA120W</i>	91101150 <b>FD 3066</b>	7118266010		91107082 <b>FO 0148 V</b>
<i>SA132</i>	91111001 <b>FD 3247</b>	7118266010		91107032 <b>FI 1099 V</b>
<i>SA132A/W</i>	91101175 <b>FD 3211</b>	7118266010		91107032 <b>FI 1099 V</b>
<i>SA185</i>	91111002 <b>FD 3448</b>	711882117151		91107032 <b>FI 1099 V</b>
<i>SA185W</i>	91101200 <b>FD 3285</b>	7118266010		91107032 <b>FI 1099 V</b>
<i>SA2</i>	91108022 <b>FD 3373 V</b>	7115166010 <b>FA 5509</b>		91107012 <b>FI 1286 V</b>
<i>SA20A</i>	91108022 <b>FD 3373 V</b>	94203210 <b>FA 5509</b>		91107012 <b>FI 1286 V</b>
<i>SA20W</i>	91111001 <b>FD 3247</b>	7118266010		91107082 <b>FO 0148 V</b>
<i>SA220A</i>	200950121 <b>FD 3063</b>	7115166011		91107012 <b>FI 1286 V</b>
<i>SA230A</i>	200950121 <b>FD 3063</b>	7115166011		91107012 <b>FI 1286 V</b>
<i>SA250W</i>	91101300 <b>FD 3271</b>	711882117151		71188300ETY369
<i>SA3</i>	91108042 <b>FD 3031 V</b>	7115166010 <b>FA 5509</b>		91107012 <b>FI 1286 V</b>
<i>SA30/37</i>	91108042 <b>FD 3031 V</b>	94203410 <b>FA 5502</b>		91107012 <b>FI 1286 V</b>
<i>SA350A</i>	201250111 <b>FD 3064</b>	7006166170		91107012 <b>FI 1286 V</b>
<i>SA4</i>	91101075 <b>FD 3066</b>	7115166010 <b>FA 5509</b>		91107012 <b>FI 1286 V</b>
<i>SA4100</i>	201250181 <b>FD 3040</b>	7113166010		91107012 <b>FI 1286 V</b>
<i>SA4125</i>	201250221 <b>FD 3066</b>	7113166010		91107012 <b>FI 1286 V</b>
<i>SA475</i>	201250181 <b>FD 3040</b>	7113166010		91107012 <b>FI 1286 V</b>
<i>SA5125A</i>	91111006 <b>FD 3069</b>			



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>FUSHENG</b>				
<i>SA5150W</i>				
<i>SA5150W</i>	91101150 <b>FD 3066</b>	7118266010		91107032 <b>FI 1099 V</b>
<i>SA5175W</i>	91101175 <b>FD 3211</b>	7118266010		91107032 <b>FI 1099 V</b>
<i>SA5200/5250W</i>	91111006 <b>FD 3069</b>	711882117151		91107032 <b>FI 1099 V</b>
<i>SA5200W</i>	91101200 <b>FD 3285</b>	7118266010		91107032 <b>FI 1099 V</b>
<i>SA5250W</i>	91111008 <b>FD 3236</b>	7118266101		91107032 <b>FI 1099 V</b>
<i>SA5300/5350W</i>	91101300 <b>FD 3271</b>	7118166010		91107032 <b>FI 1099 V</b>
<i>SA5300W</i>	91101175 <b>FD 3211</b>	7118266010		91107032 <b>FI 1099 V</b>
<i>SA5350W</i>	91101175 <b>FD 3211</b>	7118266010		91107032 <b>FI 1099 V</b>
<i>SA55</i>	91101075 <b>FD 3066</b>	7118266010		91107012 <b>FI 1286 V</b>
<i>SA75</i>	91111005 <b>FD 3464</b>	7118266010		91107012 <b>FI 1286 V</b>
<b>GARDNER DENVER</b>				
<i>ES 10</i>	03498328 <b>FD 3409</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>ES 11</i>	03498328 <b>FD 3409</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>ES 15</i>	03498328 <b>FD 3409</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>ES 18</i>	03267728 <b>FD 3122</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>ES 22</i>	03267728 <b>FD 3122</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>ES 30</i>	03267728 <b>FD 3122</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>ES 37</i>	03267728 <b>FD 3122</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>ES 45</i>	03340028 <b>FD 3408</b>	03400158 <b>FA 2922</b>		89515869 <b>FI 1300</b>
<i>ES 5</i>	03582228 <b>FD 3135</b>	85644309		81649209 <b>FO 0339 V</b>
<i>ES 55</i>	03340028 <b>FD 3408</b>	03400158 <b>FA 2922</b>		89515869 <b>FI 1300</b>
<i>ES 7</i>	03582228 <b>FD 3135</b>	85644309		81649209 <b>FO 0339 V</b>
<i>ES 75</i>	03340028 <b>FD 3408</b>	03400158 <b>FA 2922</b>		89515869 <b>FI 1300</b>
<i>ESB 4</i>	87286889 <b>FD 3546</b>	89559659 <b>FA 1449</b>		81649209 <b>FO 0339 V</b>
<i>ESB 5</i>	87286889 <b>FD 3546</b>	89559659 <b>FA 1449</b>		81649209 <b>FO 0339 V</b>
<i>ESD 110</i>	03340028 <b>FD 3408</b>	85067179 <b>FA 1758</b>		85062259 <b>FI 1301</b>
<i>ESD 132</i>	03340028 <b>FD 3408</b>	85067179 <b>FA 1758</b>		85062259 <b>FI 1301</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>GARDNER DENVER</b>				
<i>ESD 160</i>				
<i>ESD 160</i>	03340028 <b>FD 3408</b>	85067179 <b>FA 1758</b>		85062259 <b>FI 1301</b>
<i>ESD 75</i>	03340028 <b>FD 3408</b>	85067179 <b>FA 1758</b>		85062259 <b>FI 1301</b>
<i>ESD 90</i>	03340028 <b>FD 3408</b>	85067179 <b>FA 1758</b>		85062259 <b>FI 1301</b>
<i>ESG 250</i>	03340028 <b>FD 3408</b>	85067179 <b>FA 1758</b>		85062259 <b>FI 1301</b>
<i>ESR 4</i>	03582228 <b>FD 3135</b>	85644309		81649209 <b>FO 0339 V</b>
<i>ESR 5</i>	03582228 <b>FD 3135</b>	85644309		81649209 <b>FO 0339 V</b>
<i>ESS 11</i>	03582228 <b>FD 3135</b>	85644309		81649209 <b>FO 0339 V</b>
<i>ESS 18</i>	03498328 <b>FD 3409</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>MP 10</i>	221055 <b>FD 3034 V</b>	223452 <b>FA 2110</b>		240621
<i>MP 7</i>	221055 <b>FD 3034 V</b>	223452 <b>FA 2110</b>		240621
<i>ROL 100 LH</i>	43257100 <b>FD 3031 V</b>			
<i>VS 130</i>	03340028 <b>FD 3408</b>	85067179 <b>FA 1758</b>		85062259 <b>FI 1301</b>
<i>VS 155</i>	03340028 <b>FD 3408</b>	85067179 <b>FA 1758</b>		85062259 <b>FI 1301</b>
<i>VS 20</i>	03498328 <b>FD 3409</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>VS 25</i>	89848519 <b>FD 3145</b>	89874439		89559379 <b>FI 1268 V</b>
<i>VS 40</i>	03267728 <b>FD 3122</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>VS 60</i>	03340028 <b>FD 3408</b>	03400158 <b>FA 2922</b>		89515869 <b>FI 1300</b>
<i>VS 60 NEW TYPE</i>	03340028 <b>FD 3408</b>	89756519		89755919 <b>FO 0030 V</b>
<i>VS 80</i>	03340028 <b>FD 3408</b>	03400158 <b>FA 2922</b>		89515869 <b>FI 1300</b>
<i>VS 80 NEW TYPE</i>	03340028 <b>FD 3408</b>	89756519		89755919 <b>FO 0030 V</b>
<b>GEV</b>				
<i>100 GP/M</i>	35100			73017 <b>FO 0200 V</b>
<i>200 GP/M</i>	35180			73017 <b>FO 0200 V</b>
<i>300 GP/M</i>	35280			73017 <b>FO 0200 V</b>
<i>65 GP/M</i>	35065			73017 <b>FO 0200 V</b>
<b>GNUTTI</b>				
<i>HP 10</i>	95050130522 <b>FD 3143</b>	95040230321 <b>FA 1720 AL</b>		95040131222 <b>FI 1268 V</b>
<i>HP 15</i>	95150130230	95040230321 <b>FA 1720 AL</b>		95040131222 <b>FI 1268 V</b>





	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>GNUTTI</b>				
<i>HP 20</i>				
<b>HP 20</b>	95150130230 <b>FD 3395</b>	95040230321 <b>FA 1720 AL</b>		95040131222 <b>FI 1268 V</b>
<b>HP 5</b>	95040130322 <b>FD 3395</b>	95040230321 <b>FA 1720 AL</b>		95040131222 <b>FI 1268 V</b>
<b>HP 7.5</b>	95050130522 <b>FD 3143</b>	95040230321 <b>FA 1720 AL</b>		95040131222 <b>FI 1268 V</b>
<b>HPC</b>				
<b>CSV 125</b>	635490 <b>FD 3640</b>	620460		619811/A1 <b>FO 0148 V</b>
<b>CSV 150</b>	635490 <b>FD 3640</b>	620460		619811/A1 <b>FO 0148 V</b>
<b>HYDROVANE</b>				
<b>12</b>	52022 <b>FD 3174</b>	0878 <b>FA 2149</b>		0941/1
<b>120</b>	3415 <b>FD 3109</b>	1000089 <b>FA 2117</b>		6000284
<b>128</b>	3407 <b>FD 3050</b>	50332 <b>FA 2147</b>		50065
<b>128 NEW TYPE</b>	59180 <b>FD 3173</b>	50332 <b>FA 2147</b>		57562 <b>FI 1288 V</b>
<b>13</b>	3415 <b>FD 3109</b>	119 <b>FA 0066</b>		0941/1
<b>148</b>	3407 <b>FD 3050</b>	50332 <b>FA 2147</b>		50065
<b>148 NEW TYPE</b>	59180 <b>FD 3173</b>	50332 <b>FA 2147</b>		57562 <b>FI 1288 V</b>
<b>15</b>	57029 <b>FD 3170</b>	56296		
<b>170</b>	52471 <b>FD 3108</b>	PE605 <b>FA 2571</b>		6000284
<b>178</b>	3407 <b>FD 3050</b>	52438 <b>FA 2145</b>		50065
<b>178 NEW TYPE</b>	59180 <b>FD 3173</b>	52438 <b>FA 2145</b>		57562 <b>FI 1288 V</b>
<b>218</b>	3407 <b>FD 3050</b>	52438 <b>FA 2145</b>		57562 <b>FI 1288 V</b>
<b>218 NEW TYPE</b>	59180 <b>FD 3173</b>	52438 <b>FA 2145</b>		59946 <b>FO 0100 V</b>
<b>23</b>	3415 <b>FD 3109</b>	119 <b>FA 0066</b>		0941/1
<b>25</b>	57029 <b>FD 3170</b>	57019		
<b>258</b>	3407 <b>FD 3050</b>	52438 <b>FA 2145</b>		57562 <b>FI 1288 V</b>
<b>258 NEW TYPE</b>	59180 <b>FD 3173</b>	52438 <b>FA 2145</b>		59946 <b>FO 0100 V</b>
<b>33</b>	3415 <b>FD 3109</b>	119 <b>FA 0066</b>		0941/1
<b>37</b>	59177 <b>FD 3171</b>	50273 <b>FA 2152</b>		0941/1
<b>43</b>	3407 <b>FD 3050</b>	1000089 <b>FA 2117</b>		0941/1
<b>45 WITH PERKINS 4.107 ENG.</b>		PE322 <b>FA 0017</b>		

	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>HYDROVANE</b>				
	<i>47</i>			
<b>47</b>	59177 <b>FD 3171</b>	50273 <b>FA 2152</b>		O941/1
<b>5</b>	57029 <b>FD 3170</b>	56296		
<b>502</b>	57029 <b>FD 3170</b>	74015		
<b>6</b>	52022 <b>FD 3174</b>	0878 <b>FA 2149</b>		O941/1
<b>66</b>	52471 <b>FD 3108</b>	PE322 <b>FA 0017</b>		6000284
<b>66 WITH PERKINS 4.107 ENG.</b>	52471 <b>FD 3108</b>	PE322 <b>FA 0017</b>		6000284
<b>67</b>	70539 <b>FD 3172</b>	50273 <b>FA 2152</b>		56457 <b>FI 1290 V</b>
<b>68</b>	70539 <b>FD 3172</b>	50273 <b>FA 2152</b>		56457 <b>FI 1290 V</b>
<b>707</b>	59177 <b>FD 3171</b>	50273 <b>FA 2152</b>		O941/1
<b>715</b>	70539 <b>FD 3172</b>	50273 <b>FA 2152</b>		56457 <b>FI 1290 V</b>
<b>715 PUAS</b>	70539 <b>FD 3172</b>	50273 <b>FA 2152</b>		56457 <b>FI 1290 V</b>
<b>74D WITH PERKINS 4.107 ENG.</b>	52471 <b>FD 3108</b>	PE322 <b>FA 0017</b>		26540132 <b>FO 0117/1</b>
<b>822</b>	59180 <b>FD 3173</b>	50332 <b>FA 2147</b>		57562 <b>FI 1288 V</b>
<b>830</b>	59180 <b>FD 3173</b>	52438 <b>FA 2145</b>		57562 <b>FI 1288 V</b>
<b>837</b>	50190	52438 <b>FA 2145</b>		59946 <b>FO 0100 V</b>
<b>845</b>	59180 <b>FD 3173</b>	52438 <b>FA 2145</b>		59946 <b>FO 0100 V</b>
<b>87</b>	70539 <b>FD 3172</b>	50273 <b>FA 2152</b>		56457 <b>FI 1290 V</b>
<b>88</b>	70539 <b>FD 3172</b>	50273 <b>FA 2152</b>		56457 <b>FI 1290 V</b>
<b>H 150D</b>		PE322 <b>FA 0017</b>		101606
<b>H 90D</b>		PE322 <b>FA 0017</b>		101606
<b>INGERSOLL RAND</b>				
<b>ECM 350</b>				51302214 <b>FI 1294 V</b>
<b>ECM 490</b>	36723666 <b>FD 3495</b>	35355353 <b>FA 1325</b>		35378546 <b>FO 0074 V</b>
<b>ECM 590 WITH CUMMINS 6C8.3 ENG.</b>	36723666 <b>FD 3495</b>	35355353 <b>FA 1325</b>		35378546 <b>FO 0074 V</b>
<b>EMU HP</b>	89202022 <b>FD 3574</b>	89288971 <b>FA 5932/1</b>	89288989 <b>FA 5128</b>	35310556 <b>FO 0300 V</b>
<b>EMU LP</b>	89285761 <b>FD 3636</b>	89288971 <b>FA 5932/1</b>	89288989 <b>FA 5128</b>	35310556 <b>FO 0300 V</b>
<b>HP 10</b>	42410530 <b>FD 3615</b>	32170979 <b>FA 2072</b>		39856836 <b>FI 1307 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>INGERSOLL RAND</b>				
<i>HP 100</i>				
<i>HP 100</i>	39863857 <b>FD 3478</b>	39708466 <b>FA 2066</b>		39313317
<i>HP 25</i>	39863857 <b>FD 3478</b>	39588470 <b>FA 5506</b>		39123211 <b>FO 0148 V</b>
<i>HP 525</i>	35299577 <b>FD 3259</b>	92266519 <b>FA 1104</b>	91672683 <b>FA 1243</b>	
<i>HP 525 S</i>	92062132 <b>FD 3002</b>	92266519 <b>FA 1104</b>	91672683 <b>FA 1243</b>	
<i>HP 525 W</i>	92062132 <b>FD 3002</b>	92266519 <b>FA 1104</b>	91672683 <b>FA 1243</b>	
<i>HP 750 S</i>	92062132 <b>FD 3002</b>	92035948 <b>FA 1302</b>	92035955 <b>FA 1543</b>	
<i>HP 750 W</i>	92062132 <b>FD 3002</b>	92035948 <b>FA 1302</b>	92035955 <b>FA 1543</b>	
<i>NIRVANA IRN100H-2S FROM SERIES No.</i>	42542787	22130223		39911631 <b>FI 1307 V</b>
<i>NIRVANA IRN100H-CC FROM SERIES No. NV6100</i>	38008587	54672530 <b>FA 5133</b>		54672654 <b>FO 0148 V</b>
<i>NIRVANA IRN110K-2S FROM SERIES No.</i>	42542787	22130223		39911631 <b>FI 1307 V</b>
<i>NIRVANA IRN110K-CC FROM SERIES No.</i>	42542787	22130223		39911631 <b>FI 1307 V</b>
<i>NIRVANA IRN125H-CC FROM SERIES No.</i>	42542787	22130223		39911631 <b>FI 1307 V</b>
<i>NIRVANA IRN132K-2S FROM SERIES No.</i>	42542787	22130223		39911631 <b>FI 1307 V</b>
<i>NIRVANA IRN132K-CC FROM SERIES No.</i>	42542787	22130223		39911631 <b>FI 1307 V</b>
<i>NIRVANA IRN160K-2S FROM SERIES No.</i>	42542787	22130223		39911631 <b>FI 1307 V</b>
<i>NIRVANA IRN160K-CC FROM SERIES No.</i>	42542787	22130223		39911631 <b>FI 1307 V</b>
<i>NIRVANA IRN200H-2S FROM SERIES No.</i>	42542787	22130223		39911631 <b>FI 1307 V</b>
<i>NIRVANA IRN200H-CC FROM SERIES No.</i>	42542787	22130223		39911631 <b>FI 1307 V</b>
<i>NIRVANA IRN37K-CC FROM SERIES No.</i>	38008579 <b>FD 3648</b>	54672522 <b>FA 5500</b>		54672654 <b>FO 0148 V</b>
<i>NIRVANA IRN45K-CC FROM SERIES No.</i>	38008579 <b>FD 3648</b>	54672522 <b>FA 5500</b>		54672654 <b>FO 0148 V</b>
<i>NIRVANA IRN50H-CC FROM SERIES No. NV2100</i>	38008579 <b>FD 3648</b>	54672522 <b>FA 5500</b>		54672654 <b>FO 0148 V</b>
<i>NIRVANA IRN55K-CC FROM SERIES No.</i>	38008587	54672530 <b>FA 5133</b>		54672654 <b>FO 0148 V</b>
<i>NIRVANA IRN60H-CC FROM SERIES No. NV2100</i>	38008579 <b>FD 3648</b>	54672522 <b>FA 5500</b>		54672654 <b>FO 0148 V</b>
<i>NIRVANA IRN75H-CC FROM SERIES No. NV6100</i>	38008587	54672530 <b>FA 5133</b>		54672654 <b>FO 0148 V</b>
<i>NIRVANA IRN75K-2S FROM SERIES No.</i>	42542787	22130223		39911631 <b>FI 1307 V</b>
<i>NIRVANA IRN75K-CC FROM SERIES No.</i>	38008587	54672530 <b>FA 5133</b>		54672654 <b>FO 0148 V</b>
<i>NIRVANA IRN90K-2S FROM SERIES No.</i>	42542787	22130223		39911631 <b>FI 1307 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>INGERSOLL RAND</b>				
<i>NIRVANA IRN90K-CC FROM SERIES No. 2790010</i>				
<i>NIRVANA IRN90K-CC FROM SERIES No.</i>	42542787	22130223		39911631 <b>FI 1307 V</b>
<i>P 100</i>	92042506 <b>FD 3068</b>	92147353 <b>FA 1349 AL</b>	93603637 <b>FA 1215</b>	92128859 <b>FI 1306 V</b>
<i>P 100 ASD</i>	92128883 <b>FD 3013</b>	92124213 <b>FA 1241</b>	93603637 <b>FA 1215</b>	92128859 <b>FI 1306 V</b>
<i>P 100 AWD</i>	92128883 <b>FD 3013</b>	92124213 <b>FA 1241</b>	93603637 <b>FA 1215</b>	92128859 <b>FI 1306 V</b>
<i>P 100 DWD WITH DEUTZ F3L1011 ENG. 1987-2001</i>		36876423 <b>FA 1349 AL</b>		36897353
<i>P 100 DWD WITH DEUTZ F3M1011F ENG. 1987-</i>		36876423 <b>FA 1349 AL</b>		36897353
<i>P 100 WD</i>	92128883 <b>FD 3013</b>	92124213 <b>FA 1241</b>	93603637 <b>FA 1215</b>	92128859 <b>FI 1306 V</b>
<i>P 101</i>	92522135 <b>FD 3008</b>	92793025 <b>FA 5002</b>		92793223 <b>FO 0029 V</b>
<i>P 1050 E</i>	92062132 <b>FD 3002</b>	92035948 <b>FA 1302</b>	92035955 <b>FA 1543</b>	42851758
<i>P 110</i>	92522135 <b>FD 3008</b>	92793025 <b>FA 5002</b>		92793223 <b>FO 0029 V</b>
<i>P 125</i>	92042506 <b>FD 3068</b>			
<i>P 125 AWJD WITH JOHN DEERE ENG. 1987-2001</i>		35291509 <b>FA 1418 AL</b>		35308030 <b>FO 0178 V</b>
<i>P 125 DWD WITH DEUTZ F3L1011 ENG. 1987-2001</i>		36876423 <b>FA 1349 AL</b>		36897353
<i>P 125 DWD WITH DEUTZ F3M1011F ENG. 1987-</i>		36876423 <b>FA 1349 AL</b>		36897353
<i>P 125 EWD WITH DEUTZ F3M1011F ENG. 1987-</i>		36876423 <b>FA 1349 AL</b>		36897353
<i>P 125 FWD WITH DEUTZ F3L1011 ENG. 1987-2001</i>		36876423 <b>FA 1349 AL</b>		36897353
<i>P 125 SW</i>	92522135 <b>FD 3008</b>			
<i>P 125 WD</i>	92522135 <b>FD 3008</b>			
<i>P 125 WJD WITH JOHN DEERE ENG. 1987-2001</i>		35291509 <b>FA 1418 AL</b>		35308030 <b>FO 0178 V</b>
<i>P 130</i>	92522135 <b>FD 3008</b>	92793025 <b>FA 5002</b>		92793223 <b>FO 0029 V</b>
<i>P 130 AWJD WITH JOHN DEERE ENG. 1987-2001</i>		35291509 <b>FA 1418 AL</b>		35308030 <b>FO 0178 V</b>
<i>P 130 SD WITH DEUTZ F3L1011 ENG.</i>	92522135 <b>FD 3008</b>			35296920
<i>P 130 WD WITH DEUTZ F3L1011 ENG.</i>	92522135 <b>FD 3008</b>			35296920
<i>P 130 WD WITH DEUTZ F3M1011F ENG.</i>		36876423 <b>FA 1349 AL</b>		36897353
<i>P 130 WJD WITH JOHN DEERE ENG. 1987-2001</i>		35291509 <b>FA 1418 AL</b>		35308030 <b>FO 0178 V</b>
<i>P 140 SP</i>	92042506 <b>FD 3068</b>	92147353 <b>FA 1349 AL</b>	93603637 <b>FA 1215</b>	92118678 <b>FO 0148 V</b>
<i>P 140 WP</i>	92077601 <b>FD 3004</b>	92147353 <b>FA 1349 AL</b>	93603637 <b>FA 1215</b>	92118678 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>INGERSOLL RAND</b>				
<i>P 150</i>				
<i>P 150</i>	92042506 <b>FD 3068</b>	92147353 <b>FA 1349 AL</b>	93603637 <b>FA 1215</b>	92118678 <b>FO 0148 V</b>
<i>P 150 WD</i>	92077601 <b>FD 3004</b>	92147353 <b>FA 1349 AL</b>	93603637 <b>FA 1215</b>	92118678 <b>FO 0148 V</b>
<i>P 160 BWJD WITH JOHN DEERE ENG.</i>		36876423 <b>FA 1349 AL</b>		35308030 <b>FO 0178 V</b>
<i>P 175</i>	92042506 <b>FD 3068</b>	92124213 <b>FA 1241</b>	93603637 <b>FA 1215</b>	92118678 <b>FO 0148 V</b>
<i>P 175 BWJD WITH JOHN DEERE ENG.</i>		36876423 <b>FA 1349 AL</b>		35308030 <b>FO 0178 V</b>
<i>P 175 CWD</i>		36876423 <b>FA 1349 AL</b>		36897353
<i>P 175 WD</i>	92077601 <b>FD 3004</b>	92124213 <b>FA 1241</b>	93603637 <b>FA 1215</b>	92118678 <b>FO 0148 V</b>
<i>P 175 WD WITH DEUTZ F3L912 ENG.</i>	92077601 <b>FD 3004</b>	92124213 <b>FA 1241</b>		35296920
<i>P 180</i>	92808286 <b>FD 3277</b>	92867357 <b>FA 2015</b>		35296920
<i>P 180 WD</i>		92867357 <b>FA 2015</b>		35296920
<i>P 185</i>	35813187 <b>FD 3068</b>			
<i>P 250</i>	35579184 <b>FD 3198</b>	92117431 <b>FA 1212 AL</b>	35328442 <b>FA 1214</b>	92118678 <b>FO 0148 V</b>
<i>P 250 SD</i>	35579184 <b>FD 3198</b>			35292358 <b>FI 1288 V</b>
<i>P 250 WD</i>	35579184 <b>FD 3198</b>	35318252 <b>FA 1212 AL</b>	35328442 <b>FA 1214</b>	35292358 <b>FI 1288 V</b>
<i>P 250 WITH DEUTZ F4L912 ENG.</i>	35579184 <b>FD 3198</b>	92117431 <b>FA 1212 AL</b>		91605204 <b>FO 0083 V</b>
<i>P 260</i>	92866508 <b>FD 3282</b>	92117431 <b>FA 1212 AL</b>	35328442 <b>FA 1214</b>	92118678 <b>FO 0148 V</b>
<i>P 260 7/71</i>	54625942 <b>FD 3632</b>	39334784 <b>FA 5502</b>		92740950 <b>FO 0148 V</b>
<i>P 260 WD WITH DEUTZ BF4L1011 ENG. 1993</i>	92866508 <b>FD 3282</b>	92867357 <b>FA 2015</b>		92118678 <b>FO 0148 V</b>
<i>P 300 SGM</i>	35579184 <b>FD 3198</b>	35277078 <b>FA 1294</b>		35290642
<i>P 335</i>	35579184 <b>FD 3198</b>	35812437 <b>FA 1294</b>		92118678 <b>FO 0148 V</b>
<i>P 335 SD</i>	35579184 <b>FD 3198</b>	35277078 <b>FA 1294</b>		35328509
<i>P 335 WD</i>	35579184 <b>FD 3198</b>	35277078 <b>FA 1294</b>		35328509
<i>P 355</i>	35579184 <b>FD 3198</b>	35812437 <b>FA 1294</b>		92118678 <b>FO 0148 V</b>
<i>P 375</i>	36876472 <b>FD 3634</b>	35326230 <b>FA 1202 AL</b>	35328442 <b>FA 1214</b>	42843797
<i>P 375 WD</i>	92087881 <b>FD 3005</b>	92117431 <b>FA 1212 AL</b>	35328442 <b>FA 1214</b>	92118678 <b>FO 0148 V</b>
<i>P 375 WD LAST VERSION</i>	92719434 <b>FD 3071</b>	92117431 <b>FA 1212 AL</b>	35328442 <b>FA 1214</b>	92118678 <b>FO 0148 V</b>
<i>P 425 E ZENITH</i>	22111975 <b>FD 3581</b>	54717145		36897346



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>INGERSOLL RAND</b>				
<i>P 600</i>				
<i>P 600</i>	35299577 <b>FD 3259</b>			
<i>P 600 SCU</i>	92699198 <b>FD 3076</b>	92686922 <b>FA 1252</b>	92686930 <b>FA 1345</b>	
<i>P 600 SD 2T</i>	92699198 <b>FD 3076</b>	92686948 <b>FA 1217</b>	92686955 <b>FA 1310</b>	92118678 <b>FO 0148 V</b>
<i>P 600 WD 2T</i>	92699198 <b>FD 3076</b>	92686948 <b>FA 1217</b>	92686955 <b>FA 1310</b>	92118678 <b>FO 0148 V</b>
<i>P 65</i>	92128883 <b>FD 3013</b>			
<i>P 650 E</i>	92062132 <b>FD 3002</b>	92035948 <b>FA 1302</b>	92035955 <b>FA 1543</b>	99274060
<i>P 68</i>	92128883 <b>FD 3013</b>			
<i>P 700 E</i>	92062132 <b>FD 3002</b>	92035948 <b>FA 1302</b>	92035955 <b>FA 1543</b>	99274060
<i>P 75</i>	92128883 <b>FD 3013</b>			92128859 <b>FI 1306 V</b>
<i>P 750 S</i>	92062132 <b>FD 3002</b>	92035948 <b>FA 1302</b>	92035955 <b>FA 1543</b>	51302214 <b>FI 1294 V</b>
<i>P 750 W</i>	92062132 <b>FD 3002</b>	92035948 <b>FA 1302</b>	92035955 <b>FA 1543</b>	51302214 <b>FI 1294 V</b>
<i>P 80 WD WITH DEUTZ F4L1011 ENG.</i>				92118660 <b>FO 0022 V</b>
<i>P 85 S WITH DEUTZ F2L912 ENG.</i>	92128883 <b>FD 3013</b>	92124213 <b>FA 1241</b>		92118660 <b>FO 0022 V</b>
<i>P 85 SD</i>	92128883 <b>FD 3013</b>	92124213 <b>FA 1241</b>		92128859 <b>FI 1306 V</b>
<i>P 85 WD</i>	92128883 <b>FD 3013</b>	92124213 <b>FA 1241</b>		92128859 <b>FI 1306 V</b>
<i>P 85 WD WITH DEUTZ F2L511D ENG.</i>	92128883 <b>FD 3013</b>	92124213 <b>FA 1241</b>		92118660 <b>FO 0022 V</b>
<i>P 85 WD WITH DEUTZ F2L912 ENG.</i>	92128883 <b>FD 3013</b>	92124213 <b>FA 1241</b>		92118660 <b>FO 0022 V</b>
<i>P 900</i>	92062132 <b>FD 3002</b>	89288971 <b>FA 5932/1</b>	89288969 <b>FA 5128</b>	
<i>PA 50</i>	35577220 <b>FD 3204</b>	37802840		92118678 <b>FO 0148 V</b>
<i>PA 60</i>	35577220 <b>FD 3204</b>	37802840		92118678 <b>FO 0148 V</b>
<i>PA 75</i>	35577220 <b>FD 3204</b>	35262336		35262336
<i>PORTABLE 7/20 ENG. 3IRL2N</i>	54517776 <b>FD 3585</b>	54516075 <b>FA 5505</b>		
<i>PORTABLE 7/20 KUBOTA ENG. 3IRJ5N</i>	22305577 <b>FD 3648</b>	22295794 <b>FA 5509</b>		22355481
<i>PORTABLE 7/21 ENG. 3IRL2N</i>	54517776 <b>FD 3585</b>	54516075 <b>FA 5505</b>		
<i>PORTABLE 7/26 ENG. 3IRH2N</i>	54517776 <b>FD 3585</b>	54516075 <b>FA 5505</b>		22226351
<i>PORTABLE 7/26 E- REPLACES 7/26 ENG.</i>	54517776 <b>FD 3585</b>	54516075 <b>FA 5505</b>		22226351
<i>PORTABLE 7/31 ENG. 3IRH8N</i>	54596705 <b>FD 3637</b>	89232474 <b>FA 5501</b>		22226351



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>INGERSOLL RAND</b> <i>PORTABLE 7/31 E-REPLACES 7/31 ENG. 4IRH8N</i>				
<i>PORTABLE 7/31 E- REPLACES 7/31 ENG.</i>	54596705 <b>FD 3637</b>			22226351
<i>PORTABLE 7/41 ENG. 3IRL5N</i>	54596705 <b>FD 3637</b>	89232474 <b>FA 5501</b>		22226351
<i>PORTABLE 7/41 ENG. 4IRH8N</i>	54596705 <b>FD 3637</b>	89232474 <b>FA 5501</b>		22226351
<i>PORTABLE 7/41 Y</i>		54626452 <b>FA 5502</b>	54751532 <b>FA 5602</b>	22226351
<i>PORTABLE 7/51 ENG. 4IRI8N</i>	54625942 <b>FD 3632</b>	54773346 <b>FA 5500</b>	88110564 <b>FA 5600</b>	22226351
<i>PORTABLE 7/71 ENG. 4IRI8N</i>	54625942 <b>FD 3632</b>			
<i>SS 60</i>	39863840 <b>FD 3244</b>	39708466 <b>FA 2066</b>		39123211 <b>FO 0148 V</b>
<i>SSR 10 HORIZONTAL</i>	35299577 <b>FD 3259</b>	39708466 <b>FA 2066</b>		
<i>SSR 10 VERTICAL</i>	39863857 <b>FD 3478</b>	39708466 <b>FA 2066</b>		
<i>SSR 1000</i>	39726286 <b>FD 3199</b>	39125547 <b>FA 1629</b>		39125828 <b>FI 1305 V</b>
<i>SSR 12 HORIZONTAL</i>	35299577 <b>FD 3259</b>	39708466 <b>FA 2066</b>		
<i>SSR 12 VERTICAL</i>	39863857 <b>FD 3478</b>	39708466 <b>FA 2066</b>		
<i>SSR 15 HORIZONTAL</i>	35299577 <b>FD 3259</b>	39708466 <b>FA 2066</b>		
<i>SSR 15 VERTICAL</i>	39863857 <b>FD 3478</b>	39708466 <b>FA 2066</b>		
<i>SSR 18 HORIZONTAL</i>	39504147 <b>FD 3260</b>	39708466 <b>FA 2066</b>		
<i>SSR 18 VERTICAL</i>	39863865 <b>FD 3476</b>	39708466 <b>FA 2066</b>		
<i>SSR 20 HP FROM SERIES No. 2182000</i>	89264774 <b>FD 3564</b>	89295976 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>SSR 2000 10 L HORIZONTAL</i>	39705728 <b>FD 3226</b>	39708466 <b>FA 2066</b>		
<i>SSR 2000 10 L VERTICAL</i>	92871326 <b>FD 3074</b>	39708466 <b>FA 2066</b>		
<i>SSR 2000 6 L HORIZONTAL</i>	39705728 <b>FD 3226</b>	39708466 <b>FA 2066</b>		
<i>SSR 2000 6 L VERTICAL</i>	92871326 <b>FD 3074</b>	39708466 <b>FA 2066</b>		
<i>SSR 2000 7 L HORIZONTAL</i>	39705728 <b>FD 3226</b>	39708466 <b>FA 2066</b>		
<i>SSR 2000 7 L VERTICAL</i>	92871326 <b>FD 3074</b>	39708466 <b>FA 2066</b>		
<i>SSR 2000 8 L HORIZONTAL</i>	39705728 <b>FD 3226</b>	39708466 <b>FA 2066</b>		
<i>SSR 2000 8 L VERTICAL</i>	92871326 <b>FD 3074</b>	39708466 <b>FA 2066</b>		
<i>SSR 22 HORIZONTAL</i>	39504147 <b>FD 3260</b>	39708466 <b>FA 2066</b>		
<i>SSR 22 VERTICAL</i>	39863865 <b>FD 3476</b>	39708466 <b>FA 2066</b>		



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>INGERSOLL RAND</b>				
<i>SSR 25 HP FROM SERIES No. 2202000</i>				
<i>SSR 25 HP FROM SERIES No. 2202000</i>	89264774 <b>FD 3564</b>	89295976 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>SSR 28 HORIZONTAL</i>	39712070 <b>FD 3492</b>	39711726 <b>FA 2088</b>		39123237 <b>FI 1299</b>
<i>SSR 28 VERTICAL</i>	39863873 <b>FD 3471</b>	39711726 <b>FA 2088</b>		39123237 <b>FI 1299</b>
<i>SSR 30</i>	39726286 <b>FD 3199</b>	39125547 <b>FA 1629</b>		39138433 <b>FI 1305 V</b>
<i>SSR 30 HP FROM SERIES No. 2225000</i>	89264774 <b>FD 3564</b>	89295976 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>SSR 34 HORIZONTAL</i>	39712070 <b>FD 3492</b>	39711726 <b>FA 2088</b>		39123237 <b>FI 1299</b>
<i>SSR 34 VERTICAL</i>	39863873 <b>FD 3471</b>	39711726 <b>FA 2088</b>		39123237 <b>FI 1299</b>
<i>SSR 41 HORIZONTAL</i>	39712070 <b>FD 3492</b>	39711726 <b>FA 2088</b>		39123237 <b>FI 1299</b>
<i>SSR 41 VERTICAL</i>	39863873 <b>FD 3471</b>	39711726 <b>FA 2088</b>		39123237 <b>FI 1299</b>
<i>SSR EP 260</i>	54509500 <b>FD 3629</b>	39711726 <b>FA 2088</b>		39123237 <b>FI 1299</b>
<i>SSR EP 30</i>	39726286 <b>FD 3199</b>	39125547 <b>FA 1629</b>		39138433 <b>FI 1305 V</b>
<i>SSR EP 40</i>	39726286 <b>FD 3199</b>	39125547 <b>FA 1629</b>		39138433 <b>FI 1305 V</b>
<i>SSR EP 50 SE</i>	39831888 <b>FD 3484</b>	39708466 <b>FA 2066</b>		39138433 <b>FI 1305 V</b>
<i>SSR EP 75</i>	39737473 <b>FD 3074</b>	39708466 <b>FA 2066</b>		39123211 <b>FO 0148 V</b>
<i>SSR H 40 SE</i>	39726286 <b>FD 3199</b>	39125547 <b>FA 1629</b>		39138433 <b>FI 1305 V</b>
<i>SSR HP 75</i>	39737473 <b>FD 3074</b>	39708466 <b>FA 2066</b>		39123211 <b>FO 0148 V</b>
<i>SSR M 11</i>	92735547 <b>FD 3013</b>	92058825 <b>FA 1731</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 11 FROM SERIES No. 15002</i>	92735547 <b>FD 3013</b>	92889534 <b>FA 5506</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 11 FROM SERIES No. 16400</i>	92735547 <b>FD 3013</b>	93191542 <b>FA 5504</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 11 FROM SERIES No. 2161200</i>	39900923 <b>FD 3556</b>	88171913 <b>FA 1933</b>		39329602 <b>FI 1288 V</b>
<i>SSR M 110 FROM SERIES No. 2380444</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 110 FROM SERIES No. 62274 TO 62928</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 110 FROM SERIES No. 62954 TO 2380443</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 110 UP TO SERIES No. 62953</i>	92062132 <b>FD 3002</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 110-2S FROM SERIES No. 2520001 TO</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 110-2S FROM SERIES No. 2520153</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 132 FROM SERIES No. 2400244</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>





	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>INGERSOLL RAND</b>				
<i>SSR M 132 FROM SERIES No. 64166 TO 65053</i>				
<i>SSR M 132 FROM SERIES No. 64166 TO 65053</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 132 FROM SERIES No. 64903 TO 2400243</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 132 UP TO SERIES No. 64165</i>	92062132 <b>FD 3002</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 132-2S FROM SERIES No. 2530001 TO</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 132-2S FROM SERIES No. 2530174</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 15 C FROM SERIES No. 2182000</i>	89264774 <b>FD 3564</b>	89295976 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>SSR M 15 FROM SERIES No. 23002</i>	92735547 <b>FD 3013</b>	92889534 <b>FA 5506</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 15 FROM SERIES No. 24300 TO 2180384</i>	92735547 <b>FD 3013</b>	93191542 <b>FA 5504</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 150 2S</i>	93188019 <b>FD 3457</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 150 FROM SERIES No. 66274 TO 67059</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 150 UP TO SERIES No. 66273</i>	92062132 <b>FD 3002</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 150-2S FROM SERIES No. 2540001 TO</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 160 FROM SERIES No. 2420400</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 160-2S FROM SERIES No. 2540240</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 18.5</i>	92735547 <b>FD 3013</b>	93191542 <b>FA 5504</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 18.5 C FROM SERIES No. 2202000</i>	89264774 <b>FD 3564</b>	89295976 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>SSR M 18.5 FROM SERIES No. 27504</i>	92735547 <b>FD 3013</b>	92889534 <b>FA 5506</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 200 2S</i>	39863873 <b>FD 3471</b>	39750732 <b>FA 2204</b>		92888262 <b>FI 1099 V</b>
<i>SSR M 200 BISTADIO (2 STAGE)</i>	89213011 <b>FD 3463</b>	39903265 <b>FA 2876</b>		92755230
<i>SSR M 200 FROM SERIES No. 2440050</i>	54509500 <b>FD 3629</b>	39903265 <b>FA 2876</b>		92888262 <b>FI 1099 V</b>
<i>SSR M 200-2S FROM SERIES No. 2450180</i>	39890660	39903265 <b>FA 2876</b>		92888262 <b>FI 1099 V</b>
<i>SSR M 200-2S FROM SERIES No. 2550100</i>	39890660	39903265 <b>FA 2876</b>		92888262 <b>FI 1099 V</b>
<i>SSR M 200-2S LV FROM SERIES No. 2450180</i>	39890660	39903265 <b>FA 2876</b>		92888262 <b>FI 1099 V</b>
<i>SSR M 22</i>	39751391 <b>FD 3203</b>	39125547 <b>FA 1629</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 22 C FROM SERIES No. 2225000</i>	89264774 <b>FD 3564</b>	89295976 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>SSR M 22 FROM SERIES No. 2221800</i>	92890334 <b>FD 3257</b>	93191542 <b>FA 5504</b>		54672654 <b>FO 0148 V</b>
<i>SSR M 22 FROM SERIES No. 38840</i>	92890334 <b>FD 3257</b>	93191542 <b>FA 5504</b>		92740950 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>INGERSOLL RAND</b>				
<i>SSR M 22 WITH BELT-DRIVEN</i>				
<i>SSR M 22 WITH BELT-DRIVEN</i>	92890334 <b>FD 3257</b>	93191542 <b>FA 5504</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 22 WITH GEAR-DRIVEN</i>	92754688 <b>FD 3222</b>	93191542 <b>FA 5504</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 250 2S</i>	39863873 <b>FD 3471</b>	39750732 <b>FA 2204</b>		92888262 <b>FI 1099 V</b>
<i>SSR M 250 FROM SERIES No. 2450014</i>	54509500 <b>FD 3629</b>	39903265 <b>FA 2876</b>		92888262 <b>FI 1099 V</b>
<i>SSR M 250-2S FROM SERIES No. 2560030</i>	39890660 <b>FD 3629</b>	39903265 <b>FA 2876</b>		92888262 <b>FI 1099 V</b>
<i>SSR M 250-2S FROM SERIES No. 2560170</i>	39890660 <b>FD 3629</b>	39903265 <b>FA 2876</b>		92888262 <b>FI 1099 V</b>
<i>SSR M 250-2S LV FROM SERIES No. 2560170</i>	39890660 <b>FD 3629</b>	39903265 <b>FA 2876</b>		92888262 <b>FI 1099 V</b>
<i>SSR M 30</i>	39751391 <b>FD 3203</b>	39125547 <b>FA 1629</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 30 FROM SERIES No. 2241650</i>	92890334 <b>FD 3257</b>	93191542 <b>FA 5504</b>		54672654 <b>FO 0148 V</b>
<i>SSR M 30 FROM SERIES No. 43280</i>	92890334 <b>FD 3257</b>	93191542 <b>FA 5504</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 30 NEW TYPE BELT-DRIVEN</i>	92890334 <b>FD 3257</b>	93191542 <b>FA 5504</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 30 NEW TYPE GEAR-DRIVEN</i>	92754688 <b>FD 3222</b>	93191542 <b>FA 5504</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 300-2S FROM SERIES No. 2570014</i>	89213011 <b>FD 3463</b>	39903265 <b>FA 2876</b>		92888262 <b>FI 1099 V</b>
<i>SSR M 350-2S FROM SERIES No. 2580027</i>	89213011 <b>FD 3463</b>	39903265 <b>FA 2876</b>		92888262 <b>FI 1099 V</b>
<i>SSR M 37 B FROM SERIES No. 2260600</i>	92754696 <b>FD 3244</b>	88111901 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 37 FROM SERIES No. 2272000</i>	92754696 <b>FD 3244</b>	88111901 <b>FA 2066</b>		54672654 <b>FO 0148 V</b>
<i>SSR M 37 FROM SERIES No. 68548</i>	92754688 <b>FD 3222</b>	39708466 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 37 PE FROM SERIES No. 2275000</i>	54749247 <b>FD 3625</b>	22203095 <b>FA 1933</b>		54672654 <b>FO 0148 V</b>
<i>SSR M 37 UP TO SERIES No. 68547</i>	39751391 <b>FD 3203</b>	39708466 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 4</i>	92824473 <b>FD 3276</b>	92888718 <b>FA 5507</b>		92824598 <b>FO 0420 V</b>
<i>SSR M 4 FROM SERIES No. 2101200</i>	39900923 <b>FD 3556</b>	88171913 <b>FA 1933</b>		39329602 <b>FI 1288 V</b>
<i>SSR M 45</i>	92754696 <b>FD 3244</b>	39708466 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 45 FROM SERIES No. 2280250</i>	92754696 <b>FD 3244</b>	88111901 <b>FA 2066</b>		54672654 <b>FO 0148 V</b>
<i>SSR M 5.5</i>	92824473 <b>FD 3276</b>	92888718 <b>FA 5507</b>		92824598 <b>FO 0420 V</b>
<i>SSR M 5.5 FROM SERIES No. 2121300</i>	39900923 <b>FD 3556</b>	88171913 <b>FA 1933</b>		39329602 <b>FI 1288 V</b>
<i>SSR M 50</i>	92754696 <b>FD 3244</b>	39708466 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 55 FROM SERIES No. 2320700</i>	54601513 <b>FD 3244</b>	89266761 <b>FA 5854</b>		54672654 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>INGERSOLL RAND</b>				
<i>SSR M 55 FROM SERIES No. 78550</i>				
<i>SSR M 55 FROM SERIES No. 78550</i>	92871326 <b>FD 3074</b>	39708466 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 55 FROM SERIES No. 78692</i>	92871326 <b>FD 3074</b>	39708466 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 55-M 75 OLD MODEL</i>	92871326 <b>FD 3074</b>	39708466 <b>FA 2066</b>		54672654 <b>FO 0148 V</b>
<i>SSR M 7.5</i>	92824473 <b>FD 3276</b>	92888718 <b>FA 5507</b>		92824598 <b>FO 0420 V</b>
<i>SSR M 7.5 FROM SERIES No. 2141800</i>	39900923 <b>FD 3556</b>	88171913 <b>FA 1933</b>		39329602 <b>FI 1288 V</b>
<i>SSR M 75 FROM SERIES No. 2340700</i>	54601513 <b>FD 3001</b>	89266761 <b>FA 5854</b>		54672654 <b>FO 0148 V</b>
<i>SSR M 75 FROM SERIES No. 82000</i>	92722750 <b>FD 3232</b>	39708466 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 75 FROM SERIES No. 82108</i>	92722750 <b>FD 3232</b>	39708466 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>
<i>SSR M 75-2S FROM SERIES No. 2500001 TO</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		54672654 <b>FO 0148 V</b>
<i>SSR M 75-2S FROM SERIES No. 2500102</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		54672654 <b>FO 0148 V</b>
<i>SSR M 90 FROM SERIES No. 2360446</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 90 FROM SERIES No. 60227 TO 60788</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 90 FROM SERIES No. 60804 TO 2360445</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 90 UP TO SERIES No. 60226</i>	92062132 <b>FD 3002</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 90-2S FROM SERIES No. 2510001 TO</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR M 90-2S FROM SERIES No. 2510101</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSR MH 22 C</i>	89264774 <b>FD 3564</b>	89265976 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>SSR MH 5</i>	39900923 <b>FD 3556</b>	88171913 <b>FA 1933</b>		39329602 <b>FI 1288 V</b>
<i>SSR UP5 11 FROM SERIES No. 2170000</i>	54749247 <b>FD 3625</b>	89295976 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>SSR UP5 15 FROM SERIES No. 2190000</i>	54749247 <b>FD 3625</b>	89295976 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>SSR UP5 18 FROM SERIES No. 2210000</i>	54749247 <b>FD 3625</b>	89295976 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>SSR UP5 22 E FROM SERIES No. 2235000</i>	54749247 <b>FD 3625</b>	22203095 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>SSR UP5 22 FROM SERIES No. 2230000</i>	54749247 <b>FD 3625</b>	89295976 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>SSR UP5 30 FROM SERIES No. 2245000</i>	54749247 <b>FD 3625</b>	22203095 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>SSR UP6 15</i>	54749247 <b>FD 3625</b>	89295976 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>SSR UP6 20</i>	54749247 <b>FD 3625</b>	89295976 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>SSR UP6 25</i>	54749247 <b>FD 3625</b>	89295976 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>INGERSOLL RAND</b>				
<i>SSR UP6 30</i>				
<i>SSR UP6 30</i>	54749247 <b>FD 3625</b>	89295976 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>SSRM 11</i>	92735547 <b>FD 3013</b>	92058825 <b>FA 1731</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 11 NEW TYPE</i>	92735547 <b>FD 3013</b>	93191542 <b>FA 5504</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 110 FROM SERIES No. 62274</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSRM 110 UP TO SERIES No. 62273</i>	92062132 <b>FD 3002</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSRM 132 2S</i>	93188019 <b>FD 3457</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSRM 132 FROM SERIES No. 64166</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSRM 132 UP TO SERIES No. 64165</i>	92062132 <b>FD 3002</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSRM 15</i>	92735547 <b>FD 3013</b>	93191542 <b>FA 5504</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 150 2S</i>	93188019 <b>FD 3457</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSRM 150 FROM SERIES No. 66274</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSRM 150 FROM SERIES No. 67060 TO 2420399</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSRM 150 UP TO SERIES No. 66273</i>	92062132 <b>FD 3002</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSRM 18.5</i>	92735547 <b>FD 3013</b>	93191542 <b>FA 5504</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 200 2S</i>	39863873 <b>FD 3471</b>	39750732 <b>FA 2204</b>		92888262 <b>FI 1099 V</b>
<i>SSRM 22</i>	39751391 <b>FD 3203</b>	39125547 <b>FA 1629</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 22 NEW TYPE BELT- DRIVEN</i>	92890334 <b>FD 3257</b>	93191542 <b>FA 5504</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 22 NEW TYPE GEAR-DRIVEN</i>	92754688 <b>FD 3222</b>	93191542 <b>FA 5504</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 250 2S</i>	39863873 <b>FD 3471</b>	39750732 <b>FA 2204</b>		92888262 <b>FI 1099 V</b>
<i>SSRM 30</i>	39751391 <b>FD 3203</b>	39125547 <b>FA 1629</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 30 NEW TYPE BELT- DRIVEN</i>	92890334 <b>FD 3257</b>	93191542 <b>FA 5504</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 30 NEW TYPE GEAR-DRIVEN</i>	92754688 <b>FD 3222</b>	93191542 <b>FA 5504</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 300 2S</i>	92785328 <b>FD 3463</b>	39750732 <b>FA 2204</b>		92755230
<i>SSRM 350 2S</i>	92785328 <b>FD 3463</b>	39750732 <b>FA 2204</b>		92755230
<i>SSRM 37 FROM SERIES No. 68548</i>	92754688 <b>FD 3222</b>	39708466 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 37 FROM SERIES No. 68549</i>	92754688 <b>FD 3222</b>			
<i>SSRM 37 UP TO SERIES No. 68547</i>	39751391 <b>FD 3203</b>	39708466 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>INGERSOLL RAND</b>				
<i>SSRM 4</i>				
<i>SSRM 4</i>	92824473 <b>FD 3276</b>	92888718 <b>FA 5507</b>		92824598 <b>FO 0420 V</b>
<i>SSRM 45</i>	92754696 <b>FD 3244</b>	39708466 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 5.5</i>	92824473 <b>FD 3276</b>	92888718 <b>FA 5507</b>		92824598 <b>FO 0420 V</b>
<i>SSRM 50</i>	92754696 <b>FD 3244</b>	39708466 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 55 FROM SERIES No. 77001</i>	92722750 <b>FD 3232</b>	39708466 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 55 UP TO SERIES No. 77000</i>	39737473 <b>FD 3074</b>	39708466 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 7.5</i>	92824473 <b>FD 3276</b>	92888718 <b>FA 5507</b>		92824598 <b>FO 0420 V</b>
<i>SSRM 75 FROM SERIES No. 80001</i>	92722750 <b>FD 3232</b>	39708466 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 75 UP TO SERIES No. 80000</i>	39863857 <b>FD 3478</b>	39708466 <b>FA 2066</b>		92740950 <b>FO 0148 V</b>
<i>SSRM 90 FROM SERIES No. 60227</i>	92765783 <b>FD 3001</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSRM 90 UP TO SERIES No. 60226</i>	92062132 <b>FD 3002</b>	39708466 <b>FA 2066</b>		92740943 <b>FO 0030 V</b>
<i>SSRMH 22 C</i>	89264774 <b>FD 3564</b>	89265976 <b>FA 2050</b>		
<i>SSRMH 22 SERIES 68549</i>	92754688 <b>FD 3222</b>			
<i>SSRMH 30 SERIES 68549</i>	92754688 <b>FD 3222</b>			
<i>SSRMH 37 SERIES 68549</i>	92754688 <b>FD 3222</b>			
<i>SSRMH 5</i>	39900923 <b>FD 3556</b>			
<i>SSRML 22 SERIES 68549</i>	92754688 <b>FD 3222</b>			
<i>SSRML 30 SERIES 68549</i>	92754688 <b>FD 3222</b>			
<i>SSRMM 22 SERIES 68549</i>	92754688 <b>FD 3222</b>			
<i>SSRMM 30 SERIES 68549</i>	92754688 <b>FD 3222</b>			
<i>SSRMM 37 SERIES 68549</i>	92754688 <b>FD 3222</b>			
<i>SSRUP 5 15</i>	54749247 <b>FD 3625</b>	89295976 <b>FA 2050</b>		54672654 <b>FO 0148 V</b>
<i>U 10 HE-SP</i>	42361196 <b>FD 3613</b>	39763156 <b>FA 1629</b>		39446489 <b>FI 1288 V</b>
<i>U 25 HE-SP</i>	42361204 <b>FD 3613</b>	39449293 <b>FA 1629</b>		39460456 <b>FI 1305 V</b>
<i>U 30 HH-SP</i>	39726286 <b>FD 3199</b>	39125547 <b>FA 1933</b>		39138433 <b>FI 1288 V</b>
<i>UNI 11-10</i>	22388045 <b>FA 1933</b>	88171913 <b>FA 1933</b>		39329602 <b>FI 1288 V</b>
<i>UNI 7-10</i>	22388045 <b>FA 1933</b>	88171913 <b>FA 1933</b>		39329602 <b>FI 1288 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>INGERSOLL RAND</b>				
<i>VHP 400 SCU</i>				
<i>VHP 400 SCU</i>	92699198 <b>FD 3076</b>	92686948 <b>FA 1217</b>	92686955 <b>FA 1310</b>	99270134
<i>VHP 400 SD</i>	92699198 <b>FD 3076</b>	92686922 <b>FA 1252</b>	92686930 <b>FA 1345</b>	92740950 <b>FO 0148 V</b>
<i>VHP 400 SD 2T</i>	92699198 <b>FD 3076</b>	92686922 <b>FA 1252</b>	92686930 <b>FA 1345</b>	92740950 <b>FO 0148 V</b>
<i>VHP 400 WD</i>	92699198 <b>FD 3076</b>	92686948 <b>FA 1217</b>	92686955 <b>FA 1310</b>	92740950 <b>FO 0148 V</b>
<i>VHP 400 WD 2T</i>	92699198 <b>FD 3076</b>	92686948 <b>FA 1217</b>	92686955 <b>FA 1310</b>	92740950 <b>FO 0148 V</b>
<i>VHP 700</i>	92062132 <b>FD 3002</b>	92035948 <b>FA 1302</b>	92035955 <b>FA 1543</b>	
<i>VHP 700 S</i>	92062132 <b>FD 3002</b>	92055530 <b>FA 1302</b>	92035955 <b>FA 1543</b>	92740943 <b>FO 0030 V</b>
<i>VHP 700 W</i>	92062132 <b>FD 3002</b>	92055530 <b>FA 1302</b>	92035955 <b>FA 1543</b>	92740943 <b>FO 0030 V</b>
<i>WP 375 WIP</i>	22111975 <b>FD 3581</b>			
<i>XHP 650</i>	36762250 <b>FD 3452</b>			
<i>XHP 750</i>	36762250 <b>FD 3452</b>			
<i>XHP 900</i>	36762250 <b>FD 3452</b>			
<i>XP 600</i>	39705736 <b>FD 3259</b>			
<i>XP 600 S</i>	92062132 <b>FD 3002</b>	92055530 <b>FA 1302</b>	92035955 <b>FA 1543</b>	
<i>XP 600 W</i>	92062132 <b>FD 3002</b>	92055530 <b>FA 1302</b>	92035955 <b>FA 1543</b>	
<i>XP 750</i>	92062132 <b>FD 3002</b>			92740943 <b>FO 0030 V</b>
<i>XP 750 WCU WITH CUMMINS LT10 ENG.</i>	92725514 <b>FD 3229</b>	92035948 <b>FA 1302</b>	92035955 <b>FA 1543</b>	92048925 <b>FO 0073 V</b>
<i>XP 900</i>	92725514 <b>FD 3229</b>	92035948 <b>FA 1302</b>	92035955 <b>FA 1543</b>	92071182 <b>FO 0030 V</b>
<i>XP 900 S</i>	92062132 <b>FD 3002</b>	92055530 <b>FA 1302</b>	92035955 <b>FA 1543</b>	
<i>XP 900 W</i>	92062132 <b>FD 3002</b>	92055530 <b>FA 1302</b>	92035955 <b>FA 1543</b>	
<b>IRMER &amp; ELZE</b>				
<i>D 341 SL WITH DEUTZ F3L912 ENG.</i>				003681 <b>FI 1288 V</b>
<i>D 451 SL WITH DEUTZ F3L912 ENG.</i>				003681 <b>FI 1288 V</b>
<i>D 681 SL WITH DEUTZ F6L912 ENG.</i>				003681 <b>FI 1288 V</b>
<i>IRMAIR 1.5 ENG. B&amp;S 20 HP</i>	754501 <b>FD 3096 V</b>			003681 <b>FI 1288 V</b>
<i>IRMAIR 11 WITH DEUTZ BF4M1013E/EC ENG.</i>				650041 <b>FO 0148 V</b>
<i>IRMAIR 11 WITH JOHN DEERE 4032T ENG.</i>			593542 <b>FA 1217</b>	



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>IRMER &amp; ELZE</b> <i>IRMAIR 2 W WITH DEUTZ F4M1008 ENG.</i>				
<i>IRMAIR 2 W WITH DEUTZ F4M1008 ENG.</i>	754558 <b>FD 3373 V</b>		593790 <b>FA 0901</b>	003681 <b>FI 1288 V</b>
<i>IRMAIR 2 WITH DEUTZ F2L208F ENG.</i>	754558 <b>FD 3373 V</b>			
<i>IRMAIR 2 WITH YANMAR 3TNE68 ENG.</i>			4003156 <b>FA 5509</b>	003681 <b>FI 1288 V</b>
<i>IRMAIR 2.5 W WITH DEUTZ F4M1008 ENG.</i>			593790 <b>FA 0901</b>	752418 <b>FO 0379 V</b>
<i>IRMAIR 3 WITH DEUTZ F2L1011 ENG.</i>	754558 <b>FD 3373 V</b>			003681 <b>FI 1288 V</b>
<i>IRMAIR 4 WITH DEUTZ F3L1011 ENG.</i>	754558 <b>FD 3373 V</b>			003681 <b>FI 1288 V</b>
<i>IRMAIR 4 WITH DEUTZ F3M1011F ENG.</i>	754558 <b>FD 3373 V</b>		4003156 <b>FA 5509</b>	003681 <b>FI 1288 V</b>
<i>IRMAIR 5 WITH DEUTZ F4L1011 ENG.</i>			593514 <b>FA 1241</b>	650041 <b>FO 0148 V</b>
<i>IRMAIR 8 WITH DEUTZ BF4M1011F ENG.</i>	754558 <b>FD 3373 V</b>			
<i>S 1051 WITH DEUTZ F6L912 ENG.</i>			593542 <b>FA 1217</b>	650041 <b>FO 0148 V</b>
<i>S 1131-7 SL WITH DEUTZ F6L912 ENG.</i>			593542 <b>FA 1217</b>	
<i>S 1801 WITH DEUTZ F6L413F ENG.</i>			593542 <b>FA 1217</b>	650022 <b>FI 1099 V</b>
<i>S 2301 WITH DEUTZ F8L413F ENG.</i>				650022 <b>FI 1099 V</b>
<i>S 351SLS WITH DEUTZ F2L912 ENG.</i>				003681 <b>FI 1288 V</b>
<i>S 351SLS WITH DEUTZ F3L912 ENG.</i>				003681 <b>FI 1288 V</b>
<i>S 501SLS WITH DEUTZ F2L912 ENG.</i>				003681 <b>FI 1288 V</b>
<i>S 501SLS WITH DEUTZ F3L912 ENG.</i>				003681 <b>FI 1288 V</b>
<i>S 551-7 WITH DEUTZ F3L912 ENG.</i>				003681 <b>FI 1288 V</b>
<i>S 701 WITH DEUTZ F4L912 ENG.</i>				003681 <b>FI 1288 V</b>
<i>S 721-7 WITH DEUTZ F4L912 ENG.</i>				003681 <b>FI 1288 V</b>
<b>JCB GENERATOR</b>				
<i>G 55</i>		32/917804 <b>FA 5502</b>	32/917805 <b>FA 5602</b>	320/04133
<b>JENBACHER WERKE</b>				
<i>JW 1000 WITH DEUTZ F5L912 ENG.</i>		10002000 <b>FA 1217</b>		
<i>JW 220</i>		220222 <b>FA 1101</b>		
<i>JW 222</i>		220222 <b>FA 1101</b>		
<i>JW 223 WITH JANBACHER ENG.</i>		260302 <b>FA 1102</b>		
<i>JW 260</i>		260302 <b>FA 1102</b>		

	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>JENBACHER WERKE</b> <i>JW 277</i>				
<i>JW 277</i>		260302 <b>FA 1102</b>		
<i>JW 278 WITH JANBACHER ENG.</i>		260302 <b>FA 1102</b>		
<i>JW 300 WITH DEUTZ F2L511 ENG.</i>		260302 <b>FA 1102</b>		
<i>JW 302 WITH JANBACHER ENG.</i>		260302 <b>FA 1102</b>		
<i>JW 612 KS</i>				224404 <b>FI 1099 V</b>
<i>JW 616 KS</i>				224404 <b>FI 1099 V</b>
<b>JOSVAL</b>				
<i>MISTRAL 20B</i>	5632174 <b>FD 3372 V</b>	55707231130		5632182 <b>FI 1295 V</b>
<b>KAESER</b>				
<i>AIRTOWER 19</i>	620080 <b>FD 3098</b>	620030 <b>FA 1685</b>		619850 <b>FI 1306 V</b>
<i>AIRTOWER 26</i>	620080 <b>FD 3098</b>	620030 <b>FA 1685</b>		619850 <b>FI 1306 V</b>
<i>AIRTOWER 3 WITH SIGMA CONTROL</i>	620240 <b>FD 3041</b>	602150/A1 <b>FA 2172</b>		619010 <b>FO 0022 V</b>
<i>AIRTOWER 31</i>	620110 <b>FD 3043</b>	620550 <b>FA 2024</b>		619850 <b>FI 1306 V</b>
<i>AIRTOWER 31 NEW AIR FILTER</i>	620110 <b>FD 3043</b>	635400/A1 <b>FA 5501</b>		619850 <b>FI 1306 V</b>
<i>AIRTOWER 36</i>	620110 <b>FD 3043</b>	620550 <b>FA 2024</b>		619850 <b>FI 1306 V</b>
<i>AIRTOWER 36 NEW AIR FILTER</i>	620110 <b>FD 3043</b>	635400/A1 <b>FA 5501</b>		619850 <b>FI 1306 V</b>
<i>AIRTOWER 4 WITH SIGMA CONTROL</i>	620240 <b>FD 3041</b>	602150/A1 <b>FA 2172</b>		619010 <b>FO 0022 V</b>
<i>AIRTOWER 47</i>	620110 <b>FD 3043</b>	620550 <b>FA 2024</b>		619850 <b>FI 1306 V</b>
<i>AIRTOWER 47 NEW AIR FILTER</i>	620110 <b>FD 3043</b>	635400/A1 <b>FA 5501</b>		619850 <b>FI 1306 V</b>
<i>AIRTOWER 6 WITH SIGMA CONTROL</i>	620240 <b>FD 3041</b>	602150/A1 <b>FA 2172</b>		619010 <b>FO 0022 V</b>
<i>AIRTOWER 8</i>	620240 <b>FD 3041</b>	602150 <b>FA 2172</b>		
<i>AIRTOWER 8 WITH SIGMA CONTROL</i>	620240/A1 <b>FD 3041</b>	602150/A1 <b>FA 2172</b>		618761/A1
<i>AS 25</i>	620110 <b>FD 3043</b>	620000 <b>FA 1442</b>		619850 <b>FI 1306 V</b>
<i>AS 26</i>	620110 <b>FD 3043</b>	620000 <b>FA 1442</b>		619850 <b>FI 1306 V</b>
<i>AS 30</i>	620110 <b>FD 3043</b>	620000 <b>FA 1442</b>		619850 <b>FI 1306 V</b>
<i>AS 31</i>	620110 <b>FD 3043</b>	620550 <b>FA 2024</b>		619850 <b>FI 1306 V</b>
<i>AS 31 NEW AIR FILTER</i>	620110 <b>FD 3043</b>	635400/A1 <b>FA 5501</b>		619850 <b>FI 1306 V</b>
<i>AS 31 NEW TYPE</i>	620110 <b>FD 3043</b>	635400/A1 <b>FA 5501</b>		619850/A1 <b>FI 1306 V</b>





	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>KAESER AS 35</b>				
<b>AS 35</b>	620110 <b>FD 3043</b>	620000 <b>FA 1442</b>		619850 <b>FI 1306 V</b>
<b>AS 35 SIGMA 1</b>	620110 <b>FD 3043</b>	620000 <b>FA 1442</b>		619850 <b>FI 1306 V</b>
<b>AS 36</b>	620110 <b>FD 3043</b>	620550 <b>FA 2024</b>		619850 <b>FI 1306 V</b>
<b>AS 36 NEW AIR FILTER</b>	620110 <b>FD 3043</b>	635400/A1 <b>FA 5501</b>		619850 <b>FI 1306 V</b>
<b>AS 36 NEW TYPE</b>	620110 <b>FD 3043</b>	635400/A1 <b>FA 5501</b>		619850/A1 <b>FI 1306 V</b>
<b>AS 44</b>	620110 <b>FD 3043</b>	620550 <b>FA 2024</b>		619850 <b>FI 1306 V</b>
<b>AS 44 NEW AIR FILTER</b>	620110 <b>FD 3043</b>	635400/A1 <b>FA 5501</b>		619850 <b>FI 1306 V</b>
<b>AS 44 NEW TYPE</b>	620110 <b>FD 3043</b>	635400/A1 <b>FA 5501</b>		619850/A1 <b>FI 1306 V</b>
<b>AS 47</b>	620110 <b>FD 3043</b>	620550 <b>FA 2024</b>		619850 <b>FI 1306 V</b>
<b>AS 47 NEW AIR FILTER</b>	620110 <b>FD 3043</b>	635400/A1 <b>FA 5501</b>		619850 <b>FI 1306 V</b>
<b>AS 47 NEW TYPE</b>	620110 <b>FD 3043</b>	635400/A1 <b>FA 5501</b>		619850/A1 <b>FI 1306 V</b>
<b>ASD 32</b>	636690 <b>FD 3602</b>	641430 <b>FA 2045</b>		634630
<b>ASD 37</b>	636690 <b>FD 3602</b>	641430 <b>FA 2045</b>		634630
<b>ASD 47</b>	636690 <b>FD 3602</b>	641430 <b>FA 2045</b>		634630
<b>ASD 57</b>	636690 <b>FD 3602</b>	641430 <b>FA 2045</b>		634630
<b>ASV 40</b>	635480	620460		619011 <b>FO 0022 V</b>
<b>ASV 60</b>	635480	620460		619011 <b>FO 0022 V</b>
<b>BS 44</b>	620120 <b>FD 3064</b>	619960 <b>FA 1105</b>		619810 <b>FO 0148 V</b>
<b>BS 50</b>	620120 <b>FD 3064</b>	619960 <b>FA 1105</b>		619810 <b>FO 0148 V</b>
<b>BS 51</b>	620120 <b>FD 3064</b>	619960 <b>FA 1105</b>		619810 <b>FO 0148 V</b>
<b>BS 51 FROM 410750</b>	620120 <b>FD 3064</b>			
<b>BS 51 FROM SERIES No. 410750</b>	620120 <b>FD 3064</b>	620840 <b>FA 5502</b>		619810 <b>FO 0148 V</b>
<b>BS 51 UNTIL SERIES No. 410749</b>	620120 <b>FD 3064</b>	619960 <b>FA 1105</b>		619810 <b>FO 0148 V</b>
<b>BS 60</b>	620120 <b>FD 3064</b>	619960 <b>FA 1105</b>		619810 <b>FO 0148 V</b>
<b>BS 60 NEW TYPE</b>	620120 <b>FD 3064</b>	620840 <b>FA 5502</b>		619810 <b>FO 0148 V</b>
<b>BS 61</b>	620120 <b>FD 3064</b>	619960 <b>FA 1105</b>		619810 <b>FO 0148 V</b>
<b>BS 61 FROM 5101150</b>	620120 <b>FD 3064</b>			



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>KAESER</b>				
<i>BS 61 FROM SERIES No. 5101150</i>				
<i>BS 61 FROM SERIES No. 5101150</i>	620120 <b>FD 3064</b>	620840 <b>FA 5502</b>		619810 <b>FO 0148 V</b>
<i>BS 61 UNTIL SERIES No. 510149</i>	620120 <b>FD 3064</b>	619960 <b>FA 1105</b>		619810 <b>FO 0148 V</b>
<i>BSD 62</i>	635690 <b>FD 3601</b>	620850 <b>FA 5500</b>		634640/A1
<i>BSD 62 NEW AIR FILTER FROM 06/2004</i>	635690 <b>FD 3601</b>	641390 <b>FA 2048</b>		634641/A1
<i>BSD 72</i>	635690 <b>FD 3601</b>	620850 <b>FA 5500</b>		634640/A1
<i>BSD 72 NEW AIR FILTER FROM 06/2004</i>	635690 <b>FD 3601</b>	641390 <b>FA 2048</b>		634641/A1
<i>BSD 81</i>	635690 <b>FD 3601</b>	620850 <b>FA 5500</b>		634640/A1
<i>BSD 81 NEW AIR FILTER FROM 06/2004</i>	635690 <b>FD 3601</b>	641390 <b>FA 2048</b>		634641/A1
<i>BSV 100</i>	620420	620450/A1 <b>FA 1783</b>		619851 <b>FI 1306 V</b>
<i>BSV 80</i>	620420	620450/A1 <b>FA 1783</b>		619851 <b>FI 1306 V</b>
<i>CS 120</i>	620130 <b>FD 3042</b>	619970 <b>FA 1106</b>		619810 <b>FO 0148 V</b>
<i>CS 121</i>	620130 <b>FD 3042</b>	619970 <b>FA 1106</b>		619810 <b>FO 0148 V</b>
<i>CS 121 FROM SERIES No. 1210300</i>	620130 <b>FD 3042</b>	620850 <b>FA 5500</b>		619810 <b>FO 0148 V</b>
<i>CS 75</i>	620130 <b>FD 3042</b>	619970 <b>FA 1106</b>		619810 <b>FO 0148 V</b>
<i>CS 76</i>	620130 <b>FD 3042</b>	619970 <b>FA 1106</b>		619810 <b>FO 0148 V</b>
<i>CS 76 FROM SERIES No. 6100250</i>	620130 <b>FD 3042</b>	620850 <b>FA 5500</b>		619810 <b>FO 0148 V</b>
<i>CS 90</i>	620130 <b>FD 3042</b>	619970 <b>FA 1106</b>		619810 <b>FO 0148 V</b>
<i>CS 91</i>	620130 <b>FD 3042</b>	619970 <b>FA 1106</b>		619810 <b>FO 0148 V</b>
<i>CS 91 FROM SERIES No. 7600400</i>	620130 <b>FD 3042</b>	620850 <b>FA 5500</b>		619810 <b>FO 0148 V</b>
<i>CSD 102</i>	635710 <b>FD 3600</b>	635640 <b>FA 5854</b>		634640/A1
<i>CSD 102 NEW AIR FILTER FROM 06/2004</i>	635710 <b>FD 3600</b>	641490 <b>FA 2080</b>		634641/A1
<i>CSD 122</i>	635710 <b>FD 3600</b>	635640 <b>FA 5854</b>		634640/A1
<i>CSD 122 NEW AIR FILTER FROM 06/2004</i>	635710 <b>FD 3600</b>	641490 <b>FA 2080</b>		634641/A1
<i>CSD 82</i>	635710 <b>FD 3600</b>	635640 <b>FA 5854</b>		634640/A1
<i>CSD 82 NEW AIR FILTER FROM 06/2004</i>	635710 <b>FD 3600</b>	641490 <b>FA 2080</b>		634641/A1
<i>CSDX 137</i>	636230 <b>FD 3656</b>	641480 <b>FA 2038</b>		634650
<i>CSDX 162</i>	636230 <b>FD 3656</b>	641480 <b>FA 2038</b>		634650



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>KAESER</b>				
<i>CSV 125</i>				
<i>CSV 125</i>	635490 <b>FD 3640</b>	620460		619810 <b>FO 0148 V</b>
<i>CSV 150</i>	635490 <b>FD 3640</b>	620460		619810 <b>FO 0148 V</b>
<i>D 120</i>	620140 <b>FD 3030</b>	619930 <b>FA 1218</b>		619790 <b>FI 1099 V</b>
<i>D 150</i>	620140 <b>FD 3030</b>	619930 <b>FA 1218</b>		619790 <b>FI 1099 V</b>
<i>D 170</i>	635110/A2	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>D 180</i>	620140 <b>FD 3030</b>	619930 <b>FA 1218</b>		619790 <b>FI 1099 V</b>
<i>D 200</i>	635110/A2	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DS 140</i>	620140 <b>FD 3030</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DS 141</i>	621320 <b>FD 3640</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DS 170</i>	620140 <b>FD 3030</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DS 171</i>	621320 <b>FD 3640</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DS 200</i>	620140 <b>FD 3030</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DS 201</i>	621320 <b>FD 3640</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DS 220</i>	620140 <b>FD 3030</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DS 241</i>	621320 <b>FD 3640</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DSB 140</i>	620140 <b>FD 3030</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DSB 141</i>	620140 <b>FD 3030</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DSB 170</i>	620140 <b>FD 3030</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DSB 200</i>	620140 <b>FD 3030</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DSB 220</i>	620140 <b>FD 3030</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DSD 122 SFC</i>	636710	6356401/A1 <b>FA 5854</b>		634640/A1
<i>DSD 140</i>	621320 <b>FD 3640</b>	621820 <b>FA 2025</b>		
<i>DSD 141</i>	621320 <b>FD 3640</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DSD 141 NEW TYPE</i>	621320 <b>FD 3640</b>	621850/A1 <b>FA 5932</b>		619792
<i>DSD 142</i>	642720 <b>FD 3655</b>	641480 <b>FA 2038</b>		634650
<i>DSD 171</i>	621320 <b>FD 3640</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DSD 171 NEW TYPE</i>	621320 <b>FD 3640</b>	621850/A1 <b>FA 5932</b>		619792

	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>KAESER</b>				
<i>DSD 172</i>				
<i>DSD 172</i>	642720 <b>FD 3655</b>	641480 <b>FA 2038</b>		634650
<i>DSD 201</i>	621320 <b>FD 3640</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DSD 201 NEW TYPE</i>	621320 <b>FD 3640</b>	621850/A1 <b>FA 5932</b>		619792
<i>DSD 202</i>	642720 <b>FD 3655</b>	641480 <b>FA 2038</b>		634650
<i>DSD 238</i>	642720 <b>FD 3655</b>	641480 <b>FA 2038</b>		634650
<i>DSD 241</i>	621320 <b>FD 3640</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DSD 241 NEW TYPE</i>	621320 <b>FD 3640</b>	621850/A1 <b>FA 5932</b>		619792
<i>DSD 281</i>	621320 <b>FD 3640</b>	619890 <b>FA 1217</b>		619792
<i>DSD 281 NEW TYPE</i>	621320 <b>FD 3640</b>	621850/A1 <b>FA 5932</b>		619792
<i>DSD 281 SFC</i>	621320 <b>FD 3640</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DSDX 243</i>	642730 <b>FD 3651</b>	642480		634650
<i>DSDX 302</i>	642730 <b>FD 3651</b>	642480		634650
<i>DSG 140</i>	620140 <b>FD 3030</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DSG 170</i>	620140 <b>FD 3030</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DSG 200</i>	620140 <b>FD 3030</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>DSG 220</i>	620140 <b>FD 3030</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>ES 240</i>	620150 <b>FD 3191</b>	619950 <b>FA 1302</b>		619790 <b>FI 1099 V</b>
<i>ES 250</i>	620150 <b>FD 3191</b>	619950 <b>FA 1302</b>		619790 <b>FI 1099 V</b>
<i>ES 280</i>	620150 <b>FD 3191</b>	619950 <b>FA 1302</b>		619790 <b>FI 1099 V</b>
<i>ES 300</i>	620150 <b>FD 3191</b>	619950 <b>FA 1302</b>		619790 <b>FI 1099 V</b>
<i>ESB 250</i>	620150 <b>FD 3191</b>	619950 <b>FA 1302</b>		619790 <b>FI 1099 V</b>
<i>ESB 300</i>	620150 <b>FD 3191</b>	619950 <b>FA 1302</b>		619790 <b>FI 1099 V</b>
<i>ESD 251</i>	635590	621820/A1 <b>FA 5931</b>		619792
<i>ESD 251 UNTIL END 2005</i>		621820/A1 <b>FA 5931</b>		
<i>ESD 301</i>	635590	621820/A1 <b>FA 5931</b>		619792
<i>ESD 301 UNTIL END 2005</i>		621820/A1 <b>FA 5931</b>		
<i>ESD 351</i>	635590	621820/A1 <b>FA 5931</b>		619792



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>KAESER</b>				
<i>ESD 351 UNTIL END 2005</i>				
<i>ESD 351 UNTIL END 2005</i>		621820/A1 <b>FA 5931</b>		
<i>ESD 361</i>	635590	621820/A1 <b>FA 5931</b>		619792
<i>ESD 361 UNTIL END 2005</i>		621820/A1 <b>FA 5931</b>		
<i>ESD 441</i>	635590	621820/A1 <b>FA 5931</b>		619792
<i>ESD 441 UNTIL END 2005</i>		621820/A1 <b>FA 5931</b>		
<i>ESG 240</i>	620150 <b>FD 3191</b>	619950 <b>FA 1302</b>		619790 <b>FI 1099 V</b>
<i>ESG 250</i>	620150 <b>FD 3191</b>	619950 <b>FA 1302</b>		619790 <b>FI 1099 V</b>
<i>ESG 280</i>	620150 <b>FD 3191</b>	619950 <b>FA 1302</b>		619790 <b>FI 1099 V</b>
<i>ESG 300</i>	620150 <b>FD 3191</b>	619950 <b>FA 1302</b>		619790 <b>FI 1099 V</b>
<i>FS 360</i>	620170 <b>FD 3466</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>FS 440</i>	620170 <b>FD 3466</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>FSD 360</i>	620150 <b>FD 3191</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>FSD 440</i>	620150 <b>FD 3191</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>FSG 360</i>	620150 <b>FD 3191</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>FSG 440</i>	620150 <b>FD 3191</b>	619890 <b>FA 1217</b>		619790 <b>FI 1099 V</b>
<i>FSG 560</i>	620150 <b>FD 3191</b>	619950 <b>FA 1302</b>		619790 <b>FI 1099 V</b>
<i>FSG 620</i>	620150 <b>FD 3191</b>	619950 <b>FA 1302</b>		619790 <b>FI 1099 V</b>
<i>GS 590 FROM SERIES No. 591010</i>	620250 <b>FD 3466</b>	619950 <b>FA 1302</b>		619790 <b>FI 1099 V</b>
<i>GS 590 FROM SERIES No. 592001</i>	621340 <b>FD 3641</b>	619950 <b>FA 1302</b>		619790 <b>FI 1099 V</b>
<i>GS 650 FROM SERIES No. 651020</i>	620250 <b>FD 3466</b>	619950 <b>FA 1302</b>		619790 <b>FI 1099 V</b>
<i>GS 650 FROM SERIES No. 652001</i>	621340 <b>FD 3641</b>	619950 <b>FA 1302</b>		619790 <b>FI 1099 V</b>
<i>HS 690</i>	621340 <b>FD 3641</b>	635140		619790 <b>FI 1099 V</b>
<i>HS 760</i>	621340 <b>FD 3641</b>	635140		619790 <b>FI 1099 V</b>
<i>M 100</i>	6366800010 <b>FD 3462</b>	620850/A1 <b>FA 5500</b>	620840 <b>FA 5502</b>	634640/A1
<i>M 100 KUBOTA ENG. V3800DIT</i>	620320 <b>FD 3005</b>			
<i>M 12</i>	620240 <b>FD 3041</b>	602150 <b>FA 2172</b>		619011 <b>FO 0022 V</b>
<i>M 12 E</i>	620240 <b>FD 3041</b>	602150 <b>FA 2172</b>		619011 <b>FO 0022 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>KAESER</b>				
<i>M 12 ENG. B&amp;S VANGUARD 18 HP</i>				
<i>M 12 ENG. B&amp;S VANGUARD 18 HP</i>	620240 <b>FD 3041</b>	602150/A1 <b>FA 2172</b>	894530	619011 <b>FO 0022 V</b>
<i>M 120</i>	620320 <b>FD 3005</b>			
<i>M 120 T</i>	620331	620850 <b>FA 5500</b>		619810 <b>FO 0148 V</b>
<i>M 120 T DEUTZ ENG. BF4L1013C</i>	620331	620850/A1 <b>FA 5500</b>	620840/A1 <b>FA 5502</b>	619811/A1 <b>FO 0148 V</b>
<i>M 121</i>	636680 <b>FD 3462</b>	635640 <b>FA 5854</b>		634641 <b>FO 0148 V</b>
<i>M 121 DEUTZ ENG. BF4M2012C</i>	636680 <b>FD 3462</b>	6356401/A1 <b>FA 5854</b>		877690
<i>M 122</i>	6366800010 <b>FD 3462</b>	6356401/A1 <b>FA 5854</b>		634640/A1
<i>M 122 DEUTZ ENG. BF TCD 2012 L4</i>		6356401/A1 <b>FA 5854</b>		631611B
<i>M 123</i>	6366800010 <b>FD 3462</b>	6356401/A1 <b>FA 5854</b>		634640/A1
<i>M 12E ENG. ABM 4D112M-2</i>	620240 <b>FD 3041</b>	602150/A1 <b>FA 2172</b>		619011 <b>FO 0022 V</b>
<i>M 13 ENG. HONDA GX 620</i>	637950 <b>FD 3606</b>	64212P0/A1	890020	634620/H1
<i>M 15</i>	620240 <b>FD 3041</b>			
<i>M 15 ENG. HONDA GX 620</i>	620240 <b>FD 3041</b>			
<i>M 15 ENG. RUGGERINI</i>	620240 <b>FD 3041</b>	635070/A		618761/A1
<i>M 15 L</i>	620240 <b>FD 3041</b>	635070		618761 <b>FO 0418 V</b>
<i>M 15 LOMBARDINI ENG.</i>	620240 <b>FD 3041</b>	635070/A	635280/A1 <b>FA 5505</b>	618761/A1
<i>M 15 R</i>	620240 <b>FD 3041</b>	635070		618761 <b>FO 0418 V</b>
<i>M 17 ENG. HONDA GX 670</i>	637950 <b>FD 3606</b>	64212P0/A1	890020	634620/H1
<i>M 20 KUBOTA ENG. D 722</i>	645220	620030 <b>FA 1685</b>	635280/A1 <b>FA 5505</b>	634620/H1
<i>M 21</i>	620100 <b>FD 3097</b>	620030 <b>FA 1685</b>		619850 <b>FI 1306 V</b>
<i>M 21 HATZ ENG. 2G 40</i>	620100 <b>FD 3097</b>	620030 <b>FA 1685</b>	635280/A1 <b>FA 5505</b>	619851 <b>FI 1306 V</b>
<i>M 21 LOMBARDINI ENG. 9LD561 2G</i>	620100 <b>FD 3097</b>	620030 <b>FA 1685</b>	635280/A1 <b>FA 5505</b>	619850/A1 <b>FI 1306 V</b>
<i>M 21 NEW AIR FILTER</i>	620100 <b>FD 3097</b>	635280/A1 <b>FA 5505</b>		619850 <b>FI 1306 V</b>
<i>M 21/24 H</i>	620101 <b>FD 3097</b>	620030 <b>FA 1685</b>		619851 <b>FI 1306 V</b>
<i>M 21/24 L</i>	620101 <b>FD 3097</b>	620030 <b>FA 1685</b>		619851 <b>FI 1306 V</b>
<i>M 22</i>	620101 <b>FD 3097</b>	620030 <b>FA 1685</b>		619851 <b>FI 1306 V</b>
<i>M 22 KUBOTA ENG. D 90</i>	620100 <b>FD 3097</b>	620030 <b>FA 1685</b>	635280/A1 <b>FA 5505</b>	619850/A1 <b>FI 1306 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>KAESER</b>				
<i>M 220</i>				
<i>M 220</i>	621320 <b>FD 3640</b>	619890 <b>FA 1217</b>		619791 <b>FI 1099 V</b>
<i>M 24</i>	620100 <b>FD 3097</b>	620030 <b>FA 1685</b>		619850 <b>FI 1306 V</b>
<i>M 24 HATZ ENG. 2G 40</i>	620100 <b>FD 3097</b>	620030 <b>FA 1685</b>	635280/A1 <b>FA 5505</b>	619851 <b>FI 1306 V</b>
<i>M 24 LOMBARDINI ENG. 9LD561 2G</i>	620100 <b>FD 3097</b>	620030 <b>FA 1685</b>	635280/A1 <b>FA 5505</b>	619850/A1 <b>FI 1306 V</b>
<i>M 24 NEW AIR FILTER</i>	620100 <b>FD 3097</b>	635280/A1 <b>FA 5505</b>		619850 <b>FI 1306 V</b>
<i>M 25</i>	620100 <b>FD 3097</b>	620030 <b>FA 1685</b>	635280/A1 <b>FA 5505</b>	619850/A1 <b>FI 1306 V</b>
<i>M 26</i>	645220 <b>FD 3097</b>	620030 <b>FA 1685</b>	635280/A1 <b>FA 5505</b>	634620 <b>FI 1306 V</b>
<i>M 26 KUBOTA ENG. D 1105-B</i>		635280/A1 <b>FA 5505</b>		634620/H1 <b>FI 1306 V</b>
<i>M 260</i>	621320 <b>FD 3640</b>	619890 <b>FA 1217</b>		619791 <b>FI 1099 V</b>
<i>M 260 ENG. MB OM441A</i>	621320 <b>FD 3640</b>	619890 <b>FA 1217</b>		619792 <b>FI 1099 V</b>
<i>M 28</i>		602210 <b>FA 1240</b>		
<i>M 30</i>	620110 <b>FD 3043</b>	602210 <b>FA 1240</b>	635280/A1 <b>FA 5505</b>	619851 <b>FI 1306 V</b>
<i>M 30 DEUTZ ENG. F2L511D</i>	620110 <b>FD 3043</b>	602210 <b>FA 1240</b>		619850/A1 <b>FI 1306 V</b>
<i>M 31</i>	620360 <b>FD 3043</b>	635160 <b>FA 1240</b>		619851 <b>FI 1306 V</b>
<i>M 31 DEUTZ ENG. F2L1011</i>	620360 <b>FD 3043</b>	635160/A <b>FA 1240</b>	635280/A1 <b>FA 5505</b>	619851 <b>FI 1306 V</b>
<i>M 31 DEUTZ ENG. F2M1011F</i>	635250 <b>FD 3043</b>	602210 <b>FA 1240</b>	635280/A1 <b>FA 5505</b>	619850/A1 <b>FI 1306 V</b>
<i>M 31 DEUTZ ENG. F3M1011F</i>	635250 <b>FD 3043</b>	635160/A <b>FA 1240</b>	635320/A1 <b>FA 5509</b>	619850/A1 <b>FI 1306 V</b>
<i>M 32</i>	620350 <b>FD 3043</b>	635160 <b>FA 1240</b>		619851 <b>FI 1306 V</b>
<i>M 32 LOMBARDINI ENG. 11LD 626-3</i>	620360 <b>FD 3043</b>	635160/A <b>FA 1240</b>	635320/A1 <b>FA 5509</b>	619850/A1 <b>FI 1306 V</b>
<i>M 34 E</i>	620360 <b>FD 3043</b>	635160 <b>FA 1240</b>		619851 <b>FI 1306 V</b>
<i>M 34E ENG. ATB A160L/- 21</i>	635250 <b>FD 3043</b>	635160/A <b>FA 1240</b>		619851 <b>FI 1306 V</b>
<i>M 35</i>	619630 <b>FD 3043</b>	602210 <b>FA 1240</b>		619850/A1 <b>FI 1306 V</b>
<i>M 35 DEUTZ F2L511D ENG.</i>	619631/A1 <b>FD 3043</b>			619850/A1 <b>FI 1306 V</b>
<i>M 37</i>	620111 <b>FD 3043</b>	602210 <b>FA 1240</b>		619851 <b>FI 1306 V</b>
<i>M 37 DEUTZ ENG. F2L511D</i>	620110 <b>FD 3043</b>	602210 <b>FA 1240</b>		619850/A1 <b>FI 1306 V</b>
<i>M 38</i>	620360 <b>FD 3043</b>	635160 <b>FA 1240</b>		619851 <b>FI 1306 V</b>
<i>M 38 DEUTZ ENG. F3L1011F</i>	620360 <b>FD 3043</b>	635160/A <b>FA 1240</b>	635320/A1 <b>FA 5509</b>	619850/A1 <b>FI 1306 V</b>

	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>KAESER</b>				
<i>M 42</i>				
<i>M 42</i>	635250	635160		619851 <b>FI 1306 V</b>
<i>M 42 DEUTZ ENG. F3M1011F</i>	635250	635160/A	635320/A1 <b>FA 5509</b>	619850/A1 <b>FI 1306 V</b>
<i>M 43 KUBOTA ENG. D 1505 T</i>	635250	645660	635280/A1 <b>FA 5505</b>	634630
<i>M 46 E</i>	635250	620440 <b>FA 1473</b>		619851 <b>FI 1306 V</b>
<i>M 46E SIEMENS ENG. 1LA9 183-2</i>	635250	620440 <b>FA 1473</b>		619851 <b>FI 1306 V</b>
<i>M 50</i>	620311 <b>FD 3097</b>	433521/A1 <b>FA 1626</b>	602190/A <b>FA 1241</b>	619850/A1 <b>FI 1306 V</b>
<i>M 50 DEUTZ ENG. F3L912</i>	635250	645660	635280/A1 <b>FA 5505</b>	634630
<i>M 50 KUBOTA ENG. V1505-T</i>	619470 <b>FD 3097</b>	602190/A <b>FA 1241</b>		619850/A1 <b>FI 1306 V</b>
<i>M 51</i>	635250	620440 <b>FA 1473</b>	635320/A1 <b>FA 5509</b>	619811 <b>FO 0148 V</b>
<i>M 51 (51-10) DEUTZ ENG. F4L1011F UNTIL 1999</i>		602210 <b>FA 1240</b>	635320/A1 <b>FA 5509</b>	619010 <b>FO 0022 V</b>
<i>M 51 DEUTZ ENG. F4L1011F UP TO 1999</i>			635320/A1 <b>FA 5509</b>	619010 <b>FO 0022 V</b>
<i>M 52 KUBOTA ENG. V2203</i>	645790	645660		634641 <b>FO 0148 V</b>
<i>M 56</i>	620790	433521 <b>FA 1626</b>		619811 <b>FO 0148 V</b>
<i>M 56 DEUTZ ENG. F4L1011</i>	620790	433521/A1 <b>FA 1626</b>	635320/A1 <b>FA 5509</b>	619810 <b>FO 0148 V</b>
<i>M 57 KUBOTA ENG. V2403 M</i>	645790	645660		634641 <b>FO 0148 V</b>
<i>M 64 KUBOTA ENG. V2003T</i>	645790	645660		634641 <b>FO 0148 V</b>
<i>M 70 KUBOTA ENG. V2003T</i>	645790	645660		634641 <b>FO 0148 V</b>
<i>M 75</i>	620121 <b>FD 3044</b>	433521/A1 <b>FA 1626</b>	602190/A <b>FA 1241</b>	619810 <b>FO 0148 V</b>
<i>M 75 DEUTZ ENG. F4L912D</i>	620120 <b>FD 3064</b>	602190/A <b>FA 1241</b>		619810 <b>FO 0148 V</b>
<i>M 76</i>	620790	433520		619811 <b>FO 0148 V</b>
<i>M 76 DEUTZ ENG. BF4L1011F</i>	620790	433521/A1 <b>FA 1626</b>		619810 <b>FO 0148 V</b>
<i>M 80 KUBOTA ENG. V3300DIT</i>	6366800010 <b>FD 3462</b>	620850/A1 <b>FA 5500</b>		634640/A1
<i>MM 220 DEUTZ ENG. BF6M 1013 FC</i>	621320 <b>FD 3640</b>	621820/A1 <b>FA 5931</b>	621820/A1 <b>FA 5931</b>	619792
<i>MM 270 ENG. OM 501 LA</i>	621320 <b>FD 3640</b>	621850/A1 <b>FA 5932</b>	621820/A1 <b>FA 5931</b>	619792
<i>N 753 G</i>				619010 <b>FO 0022 V</b>
<i>SK 11</i>	620100 <b>FD 3097</b>	619940 <b>FA 1441</b>		619850 <b>FI 1306 V</b>
<i>SK 18</i>	620100 <b>FD 3097</b>	619940 <b>FA 1441</b>		619850 <b>FI 1306 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>KAESER</b>				
<i>SK 19</i>				
<i>SK 19</i>	619311/A1 <b>FD 3098</b>	620030 <b>FA 1685</b>		619850 <b>FI 1306 V</b>
<i>SK 21</i>	637920 <b>FD 3603</b>	641610		634620
<i>SK 24</i>	637920 <b>FD 3603</b>	641610		634620
<i>SK 25</i>	620100 <b>FD 3097</b>	619940 <b>FA 1441</b>		619850 <b>FI 1306 V</b>
<i>SK 26</i>	619311 <b>FD 3098</b>	620030 <b>FA 1685</b>		619850 <b>FI 1306 V</b>
<i>SM 11 WITH 12 LITERS TANK</i>	620090	602150 <b>FA 2172</b>		619850 <b>FI 1306 V</b>
<i>SM 11 WITH 9 LITERS TANK</i>	620240 <b>FD 3041</b>	602150 <b>FA 2172</b>		618760 <b>FO 0161 V</b>
<i>SM 12</i>	637950 <b>FD 3606</b>	642120		634620
<i>SM 15</i>	637950 <b>FD 3606</b>	642120		634620
<i>SM 6 WITH 12 LITERS TANK</i>	620090	602150 <b>FA 2172</b>		619850 <b>FI 1306 V</b>
<i>SM 6 WITH 9 LITERS TANK</i>	620240 <b>FD 3041</b>	602150 <b>FA 2172</b>		618760 <b>FO 0161 V</b>
<i>SM 8 WITH 12 LITERS TANK</i>	620090	602150 <b>FA 2172</b>		619850 <b>FI 1306 V</b>
<i>SM 8 WITH 9 LITERS TANK</i>	620240 <b>FD 3041</b>	602150 <b>FA 2172</b>		618760 <b>FO 0161 V</b>
<i>SM 9</i>	637950 <b>FD 3606</b>	642120		634620
<i>SU 11 WITH 12 LITERS TANK</i>	620090	602150 <b>FA 2172</b>		
<i>SU 11 WITH 9 LITERS TANK</i>	620240 <b>FD 3041</b>	602150 <b>FA 2172</b>		
<i>SU 6 WITH 12 LITERS TANK</i>	620090	602150 <b>FA 2172</b>		
<i>SU 6 WITH 9 LITERS TANK</i>	620240 <b>FD 3041</b>	602150 <b>FA 2172</b>		
<i>SU 8 WITH 12 LITERS TANK</i>	620090	602150 <b>FA 2172</b>		
<i>SU 8 WITH 9 LITERS TANK</i>	620240 <b>FD 3041</b>	602150 <b>FA 2172</b>		
<i>SX 3</i>	620180 <b>FD 3386</b>	602150 <b>FA 2172</b>		619010 <b>FO 0022 V</b>
<i>SX 3 SIGMA CONTROL</i>	620240 <b>FD 3041</b>	602150 <b>FA 2172</b>		619010 <b>FO 0022 V</b>
<i>SX 4</i>	620180 <b>FD 3386</b>	602150 <b>FA 2172</b>		619010 <b>FO 0022 V</b>
<i>SX 4 SIGMA CONTROL</i>	620240 <b>FD 3041</b>	602150 <b>FA 2172</b>		619010 <b>FO 0022 V</b>
<i>SX 6</i>	620180 <b>FD 3386</b>	602150 <b>FA 2172</b>		619010 <b>FO 0022 V</b>
<i>SX 6 SIGMA CONTROL</i>	620240 <b>FD 3041</b>	602150 <b>FA 2172</b>		619010 <b>FO 0022 V</b>
<b>LEYBOLD</b>				



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>LEYBOLD</b>				
<i>S 100 C</i>				
<i>S 100 C</i>	20011155 <b>FD 3620</b>			
<i>S 100 F</i>	20011155 <b>FD 3620</b>			
<i>S 160 C</i>	20011156 <b>FD 3400</b>			
<i>S 160 F</i>	20011156 <b>FD 3400</b>			
<i>S 250 C</i>	20011156 <b>FD 3400</b>			
<i>S 250 F</i>	20011156 <b>FD 3400</b>			
<i>S 400 F</i>	20011381 <b>FD 3614</b>			
<i>S 400 FL</i>	20011381 <b>FD 3614</b>			
<i>S 630 F</i>	20011365 <b>FD 3425</b>			
<i>S 630 FL</i>	20011365 <b>FD 3425</b>			
<i>SV 100</i>	71064763 <b>FD 3160</b>	71213283 <b>FA 1657</b>		39026151 <b>FO 0418 V</b>
<i>SV 1200</i>	71064773 <b>FD 3161</b>	71035242 <b>FA 1783</b>		71214598 <b>FO 0100 V</b>
<i>SV 16</i>	71064753 <b>FD 3418</b>	71040762 <b>FA 1665</b>		
<i>SV 180</i>	71064763 <b>FD 3160</b>			71018858 <b>FI 1306 V</b>
<i>SV 200</i>	71064763 <b>FD 3160</b>	71213293 <b>FA 1628</b>		71018858 <b>FI 1306 V</b>
<i>SV 25</i>	71064753 <b>FD 3418</b>	71040762 <b>FA 1665</b>		
<i>SV 280</i>	71064773 <b>FD 3161</b>			71018858 <b>FI 1306 V</b>
<i>SV 300</i>	71064773 <b>FD 3161</b>	71213293 <b>FA 1628</b>		71018858 <b>FI 1306 V</b>
<i>SV 40</i>	71064763 <b>FD 3160</b>	71046112		70408903
<i>SV 500</i>	71064773 <b>FD 3161</b>			71405318 <b>FO 0077 V</b>
<i>SV 500 B</i>	71431120 <b>FD 3657</b>			
<i>SV 580</i>	71064773 <b>FD 3161</b>			
<i>SV 585</i>	71064773 <b>FD 3161</b>			71077918
<i>SV 630</i>	71064773 <b>FD 3161</b>	71035242 <b>FA 1783</b>		71405318 <b>FO 0077 V</b>
<i>SV 630 B</i>	71431120 <b>FD 3657</b>			71405310
<i>SV 630 F</i>	71064773 <b>FD 3161</b>	71035242 <b>FA 1783</b>		71405318 <b>FO 0077 V</b>
<i>SV 65</i>	71064763 <b>FD 3160</b>	71046112		70408903



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>LEYBOLD</b>				
<i>SV 750</i>				
<i>SV 750</i>	71064773 <b>FD 3161</b>	71035242 <b>FA 1783</b>		71405318 <b>FO 0077 V</b>
<i>SV 750 B</i>	71431120 <b>FD 3657</b>			
<i>VAROVAC S 100 C</i>	20011155 <b>FD 3620</b>			39026151 <b>FO 0418 V</b>
<i>VAROVAC S 100 F</i>	20011155 <b>FD 3620</b>			39026151 <b>FO 0418 V</b>
<i>VAROVAC S 160 C</i>	20011156 <b>FD 3400</b>			39026151 <b>FO 0418 V</b>
<i>VAROVAC S 160 F</i>	20011156 <b>FD 3400</b>			39026151 <b>FO 0418 V</b>
<i>VAROVAC S 250 C</i>	20011156 <b>FD 3400</b>			39026151 <b>FO 0418 V</b>
<i>VAROVAC S 250 F</i>	20011156 <b>FD 3400</b>			39026151 <b>FO 0418 V</b>
<i>VAROVAC S 400 F</i>	20011381 <b>FD 3614</b>			18934
<i>VAROVAC S 400 FL</i>	20011381 <b>FD 3614</b>			18934
<i>VAROVAC S 630 F</i>	20011365 <b>FD 3425</b>			18934
<i>VAROVAC S 630 FL</i>	20011365 <b>FD 3425</b>			18934
<b>MACO-MEUDON</b>				
<i>BATIC 22 WITH LOMBARDINI LDA672</i>				400062 <b>FO 0064 V</b>
<i>MAP 21 WITH LOMBARDINI LDA672</i>				400062 <b>FO 0064 V</b>
<i>MAP 30 WITH DEUTZ F2L912 ENG.</i>		521884 <b>FA 1241</b>		
<i>MS 21 WITH HATZ 2G30 ENG.</i>				430000 <b>FO 0078 V</b>
<i>MS 31 WITH DEUTZ F3L1011 ENG.</i>	527645 <b>FD 3062</b>			
<i>MS 35 WITH DEUTZ F3L1011 ENG.</i>	527645 <b>FD 3062</b>			
<i>MS 70 WITH HATZ 4M40 ENG.</i>		529028 <b>FA 1952</b>		430001 <b>FO 0194 V</b>
<i>MV 131 WITH HATZ 4M40 ENG.</i>		529028 <b>FA 1952</b>		430001 <b>FO 0194 V</b>
<i>MV 185 WITH DEUTZ F3L912 ENG.</i>		520730 <b>FA 1212 AL</b>	520731 <b>FA 1214</b>	
<i>MV 21 WITH HATZ 2G30 ENG.</i>				430000 <b>FO 0078 V</b>
<i>MV 250 WITH DEUTZ F4L912 ENG.</i>		520730 <b>FA 1212 AL</b>	520731 <b>FA 1214</b>	
<i>MV 40 WITH LOMBARDINI LDA914</i>		521884 <b>FA 1241</b>		
<i>MV 450 WITH DEUTZ BF6L913 ENG.</i>			521475 <b>FA 1107</b>	
<i>MV 460 WITH DEUTZ BF6L913 ENG.</i>			521475 <b>FA 1107</b>	



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>MACO-MEUDON</b> <i>MV 50 WITH DEUTZ F2L511D ENG.</i>				
<i>MV 50 WITH DEUTZ F2L511D ENG.</i>		521884 <b>FA 1241</b>		
<i>MV 51 WITH DEUTZ F3L1011 ENG.</i>	520801 <b>FD 3063</b>			
<i>MV 60 WITH DEUTZ F2L511 ENG.</i>		521884 <b>FA 1241</b>		
<i>MV 91 WITH DEUTZ F4L1011 ENG.</i>	520801 <b>FD 3063</b>			
<b>MAHLE</b>				
<i>MSK 50</i>	5073655 <b>FD 3543</b>	5040118 <b>FA 1106</b>		5081732 <b>FO 0148 V</b>
<i>MSK 90</i>	5073465 <b>FD 3066</b>	5040126 <b>FA 1252</b>		5081916
<i>MSKD 15</i>	5073689 <b>FD 3231</b>	5024575 <b>FA 1752</b>		5081724 <b>FI 1289 V</b>
<i>MSKD 30</i>	5073689 <b>FD 3231</b>	5024575 <b>FA 1752</b>		5081732 <b>FO 0148 V</b>
<i>MSKD 37</i>	5073689 <b>FD 3231</b>	5024575 <b>FA 1752</b>		5081732 <b>FO 0148 V</b>
<i>MSKD 45</i>	5073655 <b>FD 3543</b>			5081732 <b>FO 0148 V</b>
<i>MSKD 55</i>	5073655 <b>FD 3543</b>			5081732 <b>FO 0148 V</b>
<i>MSKF 75</i>	5073457 <b>FD 3065</b>	5040118 <b>FA 1106</b>		5081916
<i>MSKF 90</i>	5073457 <b>FD 3065</b>	5040126 <b>FA 1252</b>		
<i>MSKG 05</i>	5073630 <b>FD 3509</b>	5024567 <b>FA 0028</b>		
<i>MSKG 11</i>	5073630 <b>FD 3509</b>	5024567 <b>FA 0028</b>		
<i>MSKG 15</i>	5073630 <b>FD 3509</b>	5024567 <b>FA 0028</b>		
<i>MSKG 18</i>	5073630 <b>FD 3509</b>	5024567 <b>FA 0028</b>		
<i>MSKG 22</i>	5161393 <b>FD 3423</b>			
<i>MSKG 30</i>	5737424 <b>FD 3031 V</b>			
<i>MSKG 45</i>	5737424 <b>FD 3031 V</b>	5024567 <b>FA 0028</b>		5081732 <b>FO 0148 V</b>
<i>MSKG 55</i>	5737424 <b>FD 3031 V</b>			
<i>MSKG 75</i>	5737424 <b>FD 3031 V</b>			
<i>MSKI 04-07</i>	5126636 <b>FD 3422</b>			5081724 <b>FI 1289 V</b>
<i>MSKIG 11-22</i>	5161393 <b>FD 3423</b>	5024583 <b>FA 1231</b>		
<i>MSKR 55</i>		5024575 <b>FA 1752</b>		
<i>MSKR2 30-45</i>		8116365 <b>FA 5501</b>		5081732 <b>FO 0148 V</b>
<b>MARK</b>				



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>MARK</b>	<b>CSC 30</b>			
<b>CSC 30</b>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		2202260271 <b>FO 0148 V</b>
<b>CSC 50</b>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		2202260271 <b>FO 0148 V</b>
<b>CSC 50 INVERTER</b>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		2202260271 <b>FO 0148 V</b>
<b>CSC 60</b>	640584 <b>FD 3560</b>	641128 <b>FA 1106</b>		2202260271 <b>FO 0148 V</b>
<b>CSC 60 INVERTER</b>	640584 <b>FD 3560</b>	641128 <b>FA 1106</b>		2202260271 <b>FO 0148 V</b>
<b>CSC 75</b>	640584 <b>FD 3560</b>	641128 <b>FA 1106</b>		2202260271 <b>FO 0148 V</b>
<b>CSD 100</b>	640594 <b>FD 3462</b>	2202730600 <b>FA 5134</b>		2202260271 <b>FO 0148 V</b>
<b>CSD 100 INVERTER</b>	640594 <b>FD 3462</b>	2202730600 <b>FA 5134</b>		2202260271 <b>FO 0148 V</b>
<b>CSD 125</b>	640594 <b>FD 3462</b>	2202730600 <b>FA 5134</b>		2202260271 <b>FO 0148 V</b>
<b>CSD 75</b>	640594 <b>FD 3462</b>	2202730600 <b>FA 5134</b>		2202260271 <b>FO 0148 V</b>
<b>CSD 75 INVERTER</b>	640594 <b>FD 3462</b>	2202730600 <b>FA 5134</b>		2202260271 <b>FO 0148 V</b>
<b>CSM 10</b>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		2202726102 <b>FO 0029 V</b>
<b>CSM 15</b>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		2202726102 <b>FO 0029 V</b>
<b>CSM 20</b>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		2202726102 <b>FO 0029 V</b>
<b>CSM 3</b>	2200641142 <b>FD 3596</b>	2200640815 <b>FA 2982</b>		640509 <b>FO 0029 V</b>
<b>CSM 4</b>	2200641142 <b>FD 3596</b>	2200640815 <b>FA 2982</b>		640509 <b>FO 0029 V</b>
<b>CSM 5.5</b>	2200641142 <b>FD 3596</b>	2200640815 <b>FA 2982</b>		640509 <b>FO 0029 V</b>
<b>CSM 7.5</b>	2200641142 <b>FD 3596</b>	2200640815 <b>FA 2982</b>		640509 <b>FO 0029 V</b>
<b>DRE 100</b>	6221338300 <b>FD 3594</b>	6211459450 <b>FA 5854</b>		6211441255 <b>FI 1062 V</b>
<b>DRE 100 INVERTER</b>	6221338300 <b>FD 3594</b>	6211459450 <b>FA 5854</b>		6211441255 <b>FI 1062 V</b>
<b>DRE 75</b>	6221338300 <b>FD 3594</b>	6211459450 <b>FA 5854</b>		6211441255 <b>FI 1062 V</b>
<b>DRE 75 INVERTER</b>	6221338300 <b>FD 3594</b>	6211459450 <b>FA 5854</b>		6211441255 <b>FI 1062 V</b>
<b>GDI 110</b>	640196 <b>FD 3080</b>	640095 <b>FA 1468</b>		640557 <b>FI 1045 V</b>
<b>GDI 132</b>	640181 <b>FD 3012</b>	640095 <b>FA 1468</b>		640557 <b>FI 1045 V</b>
<b>GDI 160</b>	640181 <b>FD 3012</b>	640095 <b>FA 1468</b>		640557 <b>FI 1045 V</b>
<b>GDI 45</b>	640067 <b>FD 3078</b>	640068 <b>FA 1704</b>		640557 <b>FI 1045 V</b>
<b>GDI 55</b>	640067 <b>FD 3078</b>	640068 <b>FA 1704</b>		640557 <b>FI 1045 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>MARK</b>	<i>GDI 75</i>			
<b>GDI 75</b>	640067 <b>FD 3078</b>	640068 <b>FA 1704</b>		640557 <b>FI 1045 V</b>
<b>GDI 90</b>	640196 <b>FD 3080</b>	640095 <b>FA 1468</b>		640557 <b>FI 1045 V</b>
<b>GDT 110</b>	640196 <b>FD 3080</b>	640095 <b>FA 1468</b>		640557 <b>FI 1045 V</b>
<b>GDT 132</b>	640181 <b>FD 3012</b>	640095 <b>FA 1468</b>		640557 <b>FI 1045 V</b>
<b>GDT 200</b>	640197 <b>FD 3268</b>	640095 <b>FA 1468</b>		640557 <b>FI 1045 V</b>
<b>MSA 11</b>	640593 <b>FD 3563 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<b>MSA 11 INVERTER</b>	640593 <b>FD 3563 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<b>MSA 15</b>	640593 <b>FD 3563 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<b>MSA 15 INVERTER</b>	640593 <b>FD 3563 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<b>MSA 4</b>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		640509 <b>FO 0029 V</b>
<b>MSA 5.5</b>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		640509 <b>FO 0029 V</b>
<b>MSA 7.5</b>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		640509 <b>FO 0029 V</b>
<b>MSB 11</b>	2200641140 <b>FD 3649</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<b>MSB 15</b>	2200641140 <b>FD 3649</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<b>MSB 18.5</b>	2200641141 <b>FD 3595 V</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<b>MSB 22</b>	2200641141 <b>FD 3595 V</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<b>MSB 30</b>	2200641141 <b>FD 3595 V</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<b>MSC 22</b>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		2202260271 <b>FO 0148 V</b>
<b>MSC 37</b>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		2202260271 <b>FO 0148 V</b>
<b>MSC 45</b>	640584 <b>FD 3560</b>	641128 <b>FA 1106</b>		2202260271 <b>FO 0148 V</b>
<b>MSC 55</b>	640584 <b>FD 3560</b>	641128 <b>FA 1106</b>		2202260271 <b>FO 0148 V</b>
<b>MSM 11</b>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		2202726102 <b>FO 0029 V</b>
<b>MSM 15</b>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		2202726102 <b>FO 0029 V</b>
<b>MSM 2.2</b>	2200641142 <b>FD 3596</b>	2200640815 <b>FA 2982</b>		640509 <b>FO 0029 V</b>
<b>MSM 3</b>	2200641142 <b>FD 3596</b>	2200640815 <b>FA 2982</b>		640509 <b>FO 0029 V</b>
<b>MSM 4</b>	2200641142 <b>FD 3596</b>	2200640815 <b>FA 2982</b>		640509 <b>FO 0029 V</b>
<b>MSM 5.5</b>	2200641142 <b>FD 3596</b>	2200640815 <b>FA 2982</b>		640509 <b>FO 0029 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>MARK</b>	<b>MSM 7.5</b>			
<b>MSM 7.5</b>	640593 <b>FD 3563 V</b>	640814 <b>FA 2070</b>		2202726102 <b>FO 0029 V</b>
<b>RF 10 FROM 1995</b>	640510 <b>FD 3133</b>	640555 <b>FA 1743</b>		640509 <b>FO 0029 V</b>
<b>RF 10 NEW SERIES</b>	640045 <b>FD 3133</b>	640175 <b>FA 1743</b>		640130 <b>FO 0029 V</b>
<b>RF 10 UP TO 1994</b>	640045 <b>FD 3133</b>	640075 <b>FA 0010</b>		640130 <b>FO 0029 V</b>
<b>RF 15</b>	640057 <b>FD 3053</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<b>RF 15 FROM 1995</b>	641151 <b>FD 3389</b>	640556 <b>FA 1742</b>		640509 <b>FO 0029 V</b>
<b>RF 15 NEW SERIES</b>	640057 <b>FD 3053</b>	640111 <b>FA 1742</b>		640130 <b>FO 0029 V</b>
<b>RF 15 UP TO 1994</b>	640057 <b>FD 3053</b>	640110 <b>FA 0023</b>		640130 <b>FO 0029 V</b>
<b>RF 20 FROM 1988 UP TO 1994</b>	640057 <b>FD 3053</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<b>RF 20 FROM 1995</b>	641151 <b>FD 3389</b>	640556 <b>FA 1742</b>		640509 <b>FO 0029 V</b>
<b>RF 20 NEW SERIES</b>	640057 <b>FD 3053</b>	640111 <b>FA 1742</b>		640130 <b>FO 0029 V</b>
<b>RF 20 UP TO 1987</b>	640510 <b>FD 3133</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<b>RF 20 UP TO 1994</b>	640057 <b>FD 3053</b>	640110 <b>FA 0023</b>		640130 <b>FO 0029 V</b>
<b>RF 25 FROM 1988 UP TO 1994</b>	641152 <b>FD 3039</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<b>RF 25 FROM 1995</b>	641152 <b>FD 3039</b>	640556 <b>FA 1742</b>		640509 <b>FO 0029 V</b>
<b>RF 25 NEW SERIES</b>	640048 <b>FD 3039</b>	640111 <b>FA 1742</b>		640140 <b>FI 1288 V</b>
<b>RF 25 UP TO 1987</b>	640510 <b>FD 3133</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<b>RF 25 UP TO 1994</b>	640048 <b>FD 3039</b>	640110 <b>FA 0023</b>		640140 <b>FI 1288 V</b>
<b>RF 30 FROM 1988 UP TO 1994</b>	641152 <b>FD 3039</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<b>RF 30 FROM 1995</b>	641152 <b>FD 3039</b>	640556 <b>FA 1742</b>		640211 <b>FI 1288 V</b>
<b>RF 30 NEW SERIES</b>	640048 <b>FD 3039</b>	640111 <b>FA 1742</b>		640140 <b>FI 1288 V</b>
<b>RF 30 UP TO 1987</b>	640510 <b>FD 3133</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<b>RF 30 UP TO 1994</b>	640048 <b>FD 3039</b>	640110 <b>FA 0023</b>		640140 <b>FI 1288 V</b>
<b>RF 5 FROM 1994</b>	640514 <b>FD 3410</b>	640555 <b>FA 1743</b>		640509 <b>FO 0029 V</b>
<b>RF 5 NEW SERIES</b>	640066 <b>FD 3410</b>	640175 <b>FA 1743</b>		640130 <b>FO 0029 V</b>
<b>RF 5 UP TO 1993</b>	640045 <b>FD 3133</b>	640075 <b>FA 0010</b>		640130 <b>FO 0029 V</b>
<b>RF 50</b>	640135 <b>FD 3464</b>	640068 <b>FA 1704</b>		640150 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>MARK</b>				
<i>RF 50 FROM 1992</i>				
<i>RF 50 FROM 1992</i>	640588 <b>FD 3559</b>	640553 <b>FA 1704</b>		640608 <b>FO 0148 V</b>
<i>RF 50 UP TO 1991</i>	640561 <b>FD 3077</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>
<i>RF 60 FROM 1993</i>	640918 <b>FD 3078</b>	640553 <b>FA 1704</b>		640557 <b>FI 1045 V</b>
<i>RF 60 NEW SERIES</i>	640067 <b>FD 3078</b>	640068 <b>FA 1704</b>		640666 <b>FI 1045 V</b>
<i>RF 60 UP TO 1992</i>	640190 <b>FD 3183</b>	640068 <b>FA 1704</b>		640608 <b>FO 0148 V</b>
<i>RF 7 FROM 1994</i>	640514 <b>FD 3410</b>	640555 <b>FA 1743</b>		640509 <b>FO 0029 V</b>
<i>RF 7 NEW SERIES</i>	640066 <b>FD 3410</b>	640175 <b>FA 1743</b>		640130 <b>FO 0029 V</b>
<i>RF 7 UP TO 1993</i>	640045 <b>FD 3133</b>	640075 <b>FA 0010</b>		640130 <b>FO 0029 V</b>
<i>RF 75 FROM 1993</i>	640918 <b>FD 3078</b>	640553 <b>FA 1704</b>		640557 <b>FI 1045 V</b>
<i>RF 75 NEW SERIES</i>	640067 <b>FD 3078</b>	640068 <b>FA 1704</b>		640666 <b>FI 1045 V</b>
<i>RF 75 UP TO 1992</i>	640190 <b>FD 3183</b>	640068 <b>FA 1704</b>		640608 <b>FO 0148 V</b>
<i>RF40</i>	640135 <b>FD 3464</b>	640068 <b>FA 1704</b>		640150 <b>FO 0148 V</b>
<i>RF40 FROM 1992</i>	640588 <b>FD 3559</b>	640553 <b>FA 1704</b>		640608 <b>FO 0148 V</b>
<i>RF40 UP TO 1991</i>	640561 <b>FD 3077</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>
<i>RFC 10</i>	640045 <b>FD 3133</b>	640075 <b>FA 0010</b>		640509 <b>FO 0029 V</b>
<i>RFC 15</i>	640552 <b>FD 3373 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>RFC 20</i>	640552 <b>FD 3373 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>RFC 5</i>	640045 <b>FD 3133</b>	640075 <b>FA 0010</b>		640509 <b>FO 0029 V</b>
<i>RFC 7</i>	640045 <b>FD 3133</b>	640075 <b>FA 0010</b>		640509 <b>FO 0029 V</b>
<i>RM 11</i>	640552 <b>FD 3373 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>RM 15</i>	640552 <b>FD 3373 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>RM 18</i>	641137 <b>FD 3031 V</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<i>RM 22</i>	2200641141 <b>FD 3595 V</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<i>RM 37</i>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>
<i>RM 4</i>	640510 <b>FD 3133</b>	641115 <b>FA 0010</b>		640509 <b>FO 0029 V</b>
<i>RM 45</i>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>
<i>RM 5.5</i>	640510 <b>FD 3133</b>	641115 <b>FA 0010</b>		640509 <b>FO 0029 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>MARK</b>	<i>RM 55</i>			
<b>RM 55</b>	640594 <b>FD 3462</b>	640058 <b>FA 1106</b>		640608 <b>FO 0148 V</b>
<b>RM 7.5</b>	640510 <b>FD 3133</b>	641115 <b>FA 0010</b>		640509 <b>FO 0029 V</b>
<b>RMB 11</b>	640552 <b>FD 3373 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<b>RMB 15</b>	640552 <b>FD 3373 V</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<b>RMB 22</b>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>
<b>RMB 30</b>	640584 <b>FD 3560</b>	640550 <b>FA 1943</b>		640608 <b>FO 0148 V</b>
<b>RMD 110</b>	6221341600 <b>FD 3272</b>	6211460400 <b>FA 5932</b>		6211441200 <b>FO 0280 V</b>
<b>RMD 132</b>	6221341600 <b>FD 3272</b>	6211460400 <b>FA 5932</b>		6211441200 <b>FO 0280 V</b>
<b>RMD 160</b>	6221341600 <b>FD 3272</b>	6211460400 <b>FA 5932</b>		6211441200 <b>FO 0280 V</b>
<b>RMD 160 INVERTER</b>	6221341600 <b>FD 3272</b>	6211460400 <b>FA 5932</b>		6211441250 <b>FI 1062 V</b>
<b>RMD 55</b>	6221338300 <b>FD 3594</b>	6211459400 <b>FA 5854</b>		6211441200 <b>FO 0280 V</b>
<b>RMD 55 FROM SERIES No. 550099</b>	6221338300 <b>FD 3594</b>	6211459400 <b>FA 5854</b>		6211441250 <b>FI 1062 V</b>
<b>RMD 55 UP TO SERIES No. 550098</b>	6221338300 <b>FD 3594</b>	6211460500 <b>FA 1485 AL</b>		6211441250 <b>FI 1062 V</b>
<b>RMD 75</b>	6221338300 <b>FD 3594</b>	6211459400 <b>FA 5854</b>		6211441200 <b>FO 0280 V</b>
<b>RMD 75 FROM SERIES No. 550099</b>	6221338300 <b>FD 3594</b>	6211459400 <b>FA 5854</b>		6211441250 <b>FI 1062 V</b>
<b>RMD 75 UP TO SERIES No. 550098</b>	6221338300 <b>FD 3594</b>	6211460500 <b>FA 1485 AL</b>		6211441250 <b>FI 1062 V</b>
<b>RMD 90</b>	6221338300 <b>FD 3594</b>	6211459400 <b>FA 5854</b>		6211441200 <b>FO 0280 V</b>
<b>RMD 90 FROM SERIES No. 550099</b>	6221338300 <b>FD 3594</b>	6211459400 <b>FA 5854</b>		6211441250 <b>FI 1062 V</b>
<b>RMD 90 UP TO SERIES No. 550098</b>	6221338300 <b>FD 3594</b>	6211460500 <b>FA 1485 AL</b>		6211441250 <b>FI 1062 V</b>
<b>RP 100 WITH RECEIVER OF 170 LITERS</b>	640125 <b>FD 3065</b>	640068 <b>FA 1704</b>		640557 <b>FI 1045 V</b>
<b>RP 100 WITH RECEIVER OF 80 LITERS</b>	640067 <b>FD 3078</b>	640068 <b>FA 1704</b>		640557 <b>FI 1045 V</b>
<b>RP 125</b>	640189 <b>FD 3066</b>	640055 <b>FA 1217</b>		640151 <b>FO 0030 V</b>
<b>RP 150</b>	640196 <b>FD 3080</b>	640095 <b>FA 1468</b>		640557 <b>FI 1045 V</b>
<b>RP 180</b>	640181 <b>FD 3012</b>	640095 <b>FA 1468</b>		640557 <b>FI 1045 V</b>
<b>RP 220</b>	640181 <b>FD 3012</b>	640095 <b>FA 1468</b>		640557 <b>FI 1045 V</b>
<b>RP 60</b>	640190 <b>FD 3183</b>	640058 <b>FA 1106</b>		640150 <b>FO 0148 V</b>
<b>RP 75</b>	640190 <b>FD 3183</b>	640058 <b>FA 1106</b>		640150 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>MARK</b>	<i>RSA 100 DS</i>			
<i>RSA 100 DS</i>	640045 <b>FD 3133</b>	640075 <b>FA 0010</b>		640130 <b>FO 0029 V</b>
<i>RSA 100 DS FROM 1991</i>	641151 <b>FD 3389</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>RSA 100 DS NEW SERIES</i>	640057 <b>FD 3053</b>	640110 <b>FA 0023</b>		640130 <b>FO 0029 V</b>
<i>RSA 150 D2PS</i>	641151 <b>FD 3389</b>	640551 <b>FA 0023</b>		640509 <b>FO 0029 V</b>
<i>RSA 150 D2PS FROM 1988 UP TO 1990</i>	640560 <b>FD 3036</b>	640574 <b>FA 2116</b>		640509 <b>FO 0029 V</b>
<i>RSA 150 D2PS NEW SERIES</i>	640057 <b>FD 3053</b>	640110 <b>FA 0023</b>		640130 <b>FO 0029 V</b>
<i>RSA 150 D2PS UP TO 1990</i>	640040 <b>FD 3036</b>	640090 <b>FA 2116</b>		640130 <b>FO 0029 V</b>
<i>RSA 150 DS FROM 1988 UP TO 1990</i>	640560 <b>FD 3036</b>	640574 <b>FA 2116</b>		640509 <b>FO 0029 V</b>
<i>RSA 150 DS UP TO 1988</i>	640040 <b>FD 3036</b>	640090 <b>FA 2116</b>		640130 <b>FO 0029 V</b>
<i>RSA 200 DS</i>	640057 <b>FD 3053</b>	640110 <b>FA 0023</b>		640130 <b>FO 0029 V</b>
<i>RSA 200 DS NEW SERIES</i>	640057 <b>FD 3053</b>	640110 <b>FA 0023</b>		640130 <b>FO 0029 V</b>
<i>RSA 250 DS FROM 1998</i>	641152 <b>FD 3039</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<i>RSA 250 DS NEW TYPE</i>	640048 <b>FD 3039</b>	640110 <b>FA 0023</b>		640140 <b>FI 1288 V</b>
<i>RSA 250 DS UP TO 1987</i>	640180 <b>FD 3062</b>	640110 <b>FA 0023</b>		640140 <b>FI 1288 V</b>
<i>RSA 300 DS</i>	641152 <b>FD 3039</b>	640551 <b>FA 0023</b>		640211 <b>FI 1288 V</b>
<i>RSA 300 DS NEW TYPE</i>	640048 <b>FD 3039</b>	640110 <b>FA 0023</b>		640140 <b>FI 1288 V</b>
<i>RSA 400 DS FROM 1988</i>	641125 <b>FD 3062</b>	640553 <b>FA 1704</b>		640608 <b>FO 0148 V</b>
<i>RSA 400 DS NEW SERIES</i>	640180 <b>FD 3062</b>	640068 <b>FA 1704</b>		640150 <b>FO 0148 V</b>
<i>RSA 400 DS UP TO 1987</i>	640180 <b>FD 3062</b>	640120 <b>FA 1943</b>		640150 <b>FO 0148 V</b>
<i>RSA 500 DS</i>	640180 <b>FD 3062</b>	640110 <b>FA 0023</b>		640150 <b>FO 0148 V</b>
<i>RSA 500 DS FROM 1988</i>	641125 <b>FD 3062</b>	640553 <b>FA 1704</b>		640608 <b>FO 0148 V</b>
<i>RSA 500 DS NEW SERIES</i>	640180 <b>FD 3062</b>	640068 <b>FA 1704</b>		640150 <b>FO 0148 V</b>
<i>RSA 500 DS UP TO 1987</i>	641125 <b>FD 3062</b>	640551 <b>FA 0023</b>		640608 <b>FO 0148 V</b>
<i>RSA 600 DS</i>	640190 <b>FD 3183</b>	640120 <b>FA 1943</b>		640150 <b>FO 0148 V</b>
<i>RSA 75</i>	640045 <b>FD 3133</b>	640090 <b>FA 2116</b>		640130 <b>FO 0029 V</b>
<i>RT 10</i>	640040 <b>FD 3036</b>	640090 <b>FA 2116</b>		640130 <b>FO 0029 V</b>
<i>RT 15</i>	640040 <b>FD 3036</b>	640090 <b>FA 2116</b>		640130 <b>FO 0029 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>MARK</b>	<b>RT 20</b>			
<b>RT 20</b>	640180 <b>FD 3062</b>	640090 <b>FA 2116</b>		640140 <b>FI 1288 V</b>
<b>RT 25</b>	640180 <b>FD 3062</b>	640090 <b>FA 2116</b>		640140 <b>FI 1288 V</b>
<b>RT 30</b>	640180 <b>FD 3062</b>	640090 <b>FA 2116</b>		640140 <b>FI 1288 V</b>
<b>RT 40</b>	640180 <b>FD 3062</b>	640110 <b>FA 0023</b>		640150 <b>FO 0148 V</b>
<b>RT 50</b>	640190 <b>FD 3183</b>	640120 <b>FA 1943</b>		640150 <b>FO 0148 V</b>
<b>RT 60</b>	640190 <b>FD 3183</b>	640120 <b>FA 1943</b>		640150 <b>FO 0148 V</b>
<b>SA 10</b>	640040 <b>FD 3036</b>			
<b>SA 15</b>	640040 <b>FD 3036</b>			
<b>SA 20</b>	640180 <b>FD 3062</b>	640110 <b>FA 0023</b>		640140 <b>FI 1288 V</b>
<b>SA 25</b>	640180 <b>FD 3062</b>	640110 <b>FA 0023</b>		640140 <b>FI 1288 V</b>
<b>SD 10</b>	640040 <b>FD 3036</b>			
<b>SD 15</b>	640040 <b>FD 3036</b>			
<b>SD 20</b>	640180 <b>FD 3062</b>	640110 <b>FA 0023</b>		640140 <b>FI 1288 V</b>
<b>SD 25</b>	640180 <b>FD 3062</b>	640110 <b>FA 0023</b>		640140 <b>FI 1288 V</b>
<b>SE 100 DRY</b>	640045 <b>FD 3133</b>	640075 <b>FA 0010</b>		640130 <b>FO 0029 V</b>
<b>SE 250</b>	640048 <b>FD 3039</b>	640110 <b>FA 0023</b>		640140 <b>FI 1288 V</b>
<b>SE 300</b>	640048 <b>FD 3039</b>	640110 <b>FA 0023</b>		640140 <b>FI 1288 V</b>
<b>SE 400</b>	640180 <b>FD 3062</b>	640120 <b>FA 1943</b>		640150 <b>FO 0148 V</b>
<b>SE 500</b>	640180 <b>FD 3062</b>	640120 <b>FA 1943</b>		640150 <b>FO 0148 V</b>
<b>T 10</b>	640040 <b>FD 3036</b>	640090 <b>FA 2116</b>		640130 <b>FO 0029 V</b>
<b>T 15</b>	640040 <b>FD 3036</b>	640090 <b>FA 2116</b>		640130 <b>FO 0029 V</b>
<b>T 20</b>	640180 <b>FD 3062</b>	640110 <b>FA 0023</b>		640140 <b>FI 1288 V</b>
<b>T 25</b>	640180 <b>FD 3062</b>	640110 <b>FA 0023</b>		640140 <b>FI 1288 V</b>
<b>T 30</b>	640180 <b>FD 3062</b>	640110 <b>FA 0023</b>		640140 <b>FI 1288 V</b>
<b>T 40 WITH SCREW CF 75 ED</b>	640180 <b>FD 3062</b>	640110 <b>FA 0023</b>		640150 <b>FO 0148 V</b>
<b>T 40 WITH SCREW SF 128 D</b>	640190 <b>FD 3183</b>	640120 <b>FA 1943</b>		640150 <b>FO 0148 V</b>
<b>T 50</b>	640190 <b>FD 3183</b>	640068 <b>FA 1704</b>		640150 <b>FO 0148 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>MARK</b>				
<i>T 50 WITH SCREW SF 128 D</i>				
<i>T 50 WITH SCREW SF 128 D</i>	640190 <b>FD 3183</b>	640120 <b>FA 1943</b>		640150 <b>FO 0148 V</b>
<i>T 60</i>	640190 <b>FD 3183</b>	640068 <b>FA 1704</b>		640150 <b>FO 0148 V</b>
<i>T 60 WITH SCREW SF 128 D</i>	640190 <b>FD 3183</b>	640120 <b>FA 1943</b>		640150 <b>FO 0148 V</b>
<i>TS 10</i>	640045 <b>FD 3133</b>	640075 <b>FA 0010</b>		640130 <b>FO 0029 V</b>
<i>TS 10 NEW SERIES</i>	640045 <b>FD 3133</b>	640175 <b>FA 1743</b>		640130 <b>FO 0029 V</b>
<i>TS 15</i>	640057 <b>FD 3053</b>	640111 <b>FA 1742</b>		640130 <b>FO 0029 V</b>
<i>TS 15 NEW SERIES</i>	640057 <b>FD 3053</b>	640111 <b>FA 1742</b>		640130 <b>FO 0029 V</b>
<i>TS 20</i>	640057 <b>FD 3053</b>	640111 <b>FA 1742</b>		640130 <b>FO 0029 V</b>
<i>TS 20 NEW SERIES</i>	640057 <b>FD 3053</b>	640111 <b>FA 1742</b>		640130 <b>FO 0029 V</b>
<i>TS 5</i>	640066 <b>FD 3410</b>	640175 <b>FA 1743</b>		640130 <b>FO 0029 V</b>
<i>TS 7</i>	640066 <b>FD 3410</b>	640175 <b>FA 1743</b>		640130 <b>FO 0029 V</b>
<b>MATTEI</b>				
<i>1015 AC-ERC (25 HP)</i>	30732 <b>FD 3169</b>	30336 <b>FA 2150</b>		CR21G30319 <b>FI 1298</b>
<i>1018 AC-ERC (25 HP)</i>	30732 <b>FD 3169</b>	30336 <b>FA 2150</b>		CR21G30319 <b>FI 1298</b>
<i>1022 AC-ERC (25 HP)</i>	30732 <b>FD 3169</b>	30336 <b>FA 2150</b>		CR21G30319 <b>FI 1298</b>
<i>110 AC-ERC (20 HP)</i>	12857 <b>FD 3050</b>	30336 <b>FA 2150</b>		
<i>110 AC-ERC (20 HP) NEW TYPE</i>	30732 <b>FD 3169</b>	30336 <b>FA 2150</b>		
<i>114 AC-ERC (20 HP)</i>	12857 <b>FD 3050</b>	30336 <b>FA 2150</b>		
<i>114 AC-ERC (20 HP) NEW TYPE</i>	30732 <b>FD 3169</b>	30336 <b>FA 2150</b>		
<i>120 AC-ERC (20 HP)</i>	11131 <b>FD 3109</b>	10633 <b>FA 2117</b>		CR21A10641
<i>120 AC-ERC (20 HP) NEW TYPE</i>	30725 <b>FD 3033</b>	10633 <b>FA 2117</b>		CR21A10641
<i>130 AC-ERC (30 HP)</i>	11131 <b>FD 3109</b>	10633 <b>FA 2117</b>		
<i>130 AC-ERC (30 HP) NEW TYPE</i>	30725 <b>FD 3033</b>	10633 <b>FA 2117</b>		
<i>134 AC-ERC (30 HP)</i>	12857 <b>FD 3050</b>	30336 <b>FA 2150</b>		
<i>134 AC-ERC (30 HP) NEW TYPE</i>	30732 <b>FD 3169</b>	30336 <b>FA 2150</b>		
<i>140 AC-ERC (30 HP)</i>	11131 <b>FD 3109</b>	10633 <b>FA 2117</b>		CR21A10641
<i>140 AC-ERC (30 HP) NEW TYPE</i>	30725 <b>FD 3033</b>	10633 <b>FA 2117</b>		CR21A10641



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>MATTEI</b>				
<i>180 AC-ERC (40 HP)</i>				
<i>180 AC-ERC (40 HP)</i>	11131 <b>FD 3109</b>	10442 <b>FA 2115</b>		CR21C8123A <b>FI 1296</b>
<i>180 AC-ERC (40 HP) NEW TYPE</i>	30725 <b>FD 3033</b>	10919 <b>FA 2118</b>		CR21C8123A <b>FI 1296</b>
<i>200 AC-ERC (40 HP)</i>	11131 <b>FD 3109</b>	10442 <b>FA 2115</b>		CR21C8123A <b>FI 1296</b>
<i>200 AC-ERC (40 HP) NEW TYPE</i>	30725 <b>FD 3033</b>	10919 <b>FA 2118</b>		CR21C8123A <b>FI 1296</b>
<i>2030 AC-ERC (40 HP)</i>	30733 <b>FD 3150</b>	30566 <b>FA 2148</b>		CR21H30581 <b>FI 1272</b>
<i>2030 AC-ERC (40 HP) NEW TYPE</i>	30733 <b>FD 3150</b>	30566 <b>FA 2148</b>		CR21H30581 <b>FI 1272</b>
<i>2037 AC-ERC (40 HP)</i>	30733 <b>FD 3150</b>	30566 <b>FA 2148</b>		CR21H30581 <b>FI 1272</b>
<i>2037 AC-ERC (40 HP) NEW TYPE</i>	30733 <b>FD 3150</b>	30566 <b>FA 2148</b>		CR21H30581 <b>FI 1272</b>
<i>2045 AC-ERC (60 HP)</i>	30733 <b>FD 3150</b>	30566 <b>FA 2148</b>		CR21H30581 <b>FI 1272</b>
<i>2045 AC-ERC (60 HP) NEW TYPE</i>	30733 <b>FD 3150</b>	30566 <b>FA 2148</b>		CR21H30581 <b>FI 1272</b>
<i>2055 L</i>	30733 <b>FD 3150</b>	30566 <b>FA 2148</b>		CR21H30581 <b>FI 1272</b>
<i>215 AC-ERC (50 HP)</i>	11131 <b>FD 3109</b>	10442 <b>FA 2115</b>		CR21C8123A <b>FI 1296</b>
<i>215 AC-ERC (50 HP) NEW TYPE</i>	30725 <b>FD 3033</b>	10919 <b>FA 2118</b>		CR21C8123A <b>FI 1296</b>
<i>22 AC-ERC</i>	30725 <b>FD 3033</b>	119 <b>FA 0066</b>		
<i>22 AC-ERC NEW TYPE</i>	30725 <b>FD 3033</b>	O119 <b>FA 0066</b>		
<i>23 AC-ERC</i>	11131 <b>FD 3109</b>	119 <b>FA 0066</b>		
<i>23 AC-ERC NEW TYPE</i>	30725 <b>FD 3033</b>	O119 <b>FA 0066</b>		
<i>250 AC-ERC (60 HP)</i>	11131 <b>FD 3109</b>	10442 <b>FA 2115</b>		CR21C8123A <b>FI 1296</b>
<i>250 AC-ERC (60 HP) NEW TYPE</i>	30725 <b>FD 3033</b>	10919 <b>FA 2118</b>		CR21C8123A <b>FI 1296</b>
<i>260 AC-ERC (60 HP)</i>	11131 <b>FD 3109</b>	10919 <b>FA 2118</b>		CR21C8123A <b>FI 1296</b>
<i>260 AC-ERC (60 HP) NEW TYPE</i>	30725 <b>FD 3033</b>	10919 <b>FA 2118</b>		CR21C8123A <b>FI 1296</b>
<i>300 AC-ERC (75 HP)</i>	11131 <b>FD 3109</b>	11113 <b>FA 2124</b>		CR21D11031 <b>FI 1271</b>
<i>300 AC-ERC (75 HP) NEW TYPE</i>	30725 <b>FD 3033</b>	13011 <b>FA 2143</b>		CR21D11031 <b>FI 1271</b>
<i>33 PU 10 (7.5 HP)</i>	11131 <b>FD 3109</b>	119 <b>FA 0066</b>		O941/1
<i>33 PU 10 (7.5 HP) NEW TYPE</i>	30725 <b>FD 3033</b>	O119 <b>FA 0066</b>		O941/1
<i>33 PUA 10 (7.5 HP)</i>	11131 <b>FD 3109</b>	119 <b>FA 0066</b>		O941/1
<i>33 PUA 10 (7.5 HP) NEW TYPE</i>	30725 <b>FD 3033</b>	O119 <b>FA 0066</b>		O941/1

	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>MATTEI</b>				
<i>33 PUT 10 (7.5 HP)</i>				
<b>33 PUT 10 (7.5 HP)</b>	11131 <b>FD 3109</b>	119 <b>FA 0066</b>		O941/1
<b>33 PUT 10 (7.5 HP) NEW TYPE</b>	30725 <b>FD 3033</b>	O119 <b>FA 0066</b>		O941/1
<b>350 AC-ERC (75 HP)</b>	11131 <b>FD 3109</b>	11113 <b>FA 2124</b>		CR21D11031 <b>FI 1271</b>
<b>350 AC-ERC (75 HP) NEW TYPE</b>	30725 <b>FD 3033</b>	13011 <b>FA 2143</b>		CR21D11031 <b>FI 1271</b>
<b>38 AC-ERC (10 HP)</b>	20113 <b>FD 3125</b>	20153 <b>FA 2146</b>		CR21E20097
<b>400 AC-ERC (100 HP)</b>	11131 <b>FD 3109</b>	11113 <b>FA 2124</b>		CR21D11031 <b>FI 1271</b>
<b>400 AC-ERC (100 HP) NEW TYPE</b>	30725 <b>FD 3033</b>	13011 <b>FA 2143</b>		CR21D11031 <b>FI 1271</b>
<b>4055</b>	32486 <b>FD 3272</b>	32450 <b>FA 1252</b>		32179 <b>FI 1211 V</b>
<b>4075</b>	32486 <b>FD 3272</b>	32450 <b>FA 1252</b>		32179 <b>FI 1211 V</b>
<b>4090</b>	32486 <b>FD 3272</b>	32450 <b>FA 1252</b>		32179 <b>FI 1211 V</b>
<b>43 AC-ERC PU (10 HP)</b>	12857 <b>FD 3050</b>	10633 <b>FA 2117</b>		O941
<b>43 AC-ERC PU (10 HP) NEW TYPE</b>	30732 <b>FD 3169</b>	10633 <b>FA 2117</b>		O941
<b>44 AC-ERC</b>	20113 <b>FD 3125</b>	20153 <b>FA 2146</b>		CR21E20097
<b>450 AC-ERC (100 HP)</b>	11131 <b>FD 3109</b>	11113 <b>FA 2124</b>		CR21D11031 <b>FI 1271</b>
<b>450 AC-ERC (100 HP) NEW TYPE</b>	30725 <b>FD 3033</b>	13011 <b>FA 2143</b>		CR21D11031 <b>FI 1271</b>
<b>504 AC-ERC (5.5 HP)</b>	30725 <b>FD 3033</b>	30393 <b>FA 2149</b>		CR21F30389 <b>FI 1297</b>
<b>504 AC-ERC (5.5 HP) NEW TYPE</b>	30725 <b>FD 3033</b>	30393 <b>FA 2149</b>		CR21F30389 <b>FI 1297</b>
<b>505 AC-ERC (7.5 HP)</b>	30725 <b>FD 3033</b>	30393 <b>FA 2149</b>		CR21F30389 <b>FI 1297</b>
<b>505 AC-ERC (7.5 HP) NEW TYPE</b>	30725 <b>FD 3033</b>	30393 <b>FA 2149</b>		CR21F30389 <b>FI 1297</b>
<b>507 AC-ERC (10 HP)</b>	20113 <b>FD 3125</b>	20153 <b>FA 2146</b>		CR21E20097
<b>511 AC-ERC (15 HP)</b>	20113 <b>FD 3125</b>	20153 <b>FA 2146</b>		CR21E20097
<b>515 AC-ERC</b>	20113 <b>FD 3125</b>	20153 <b>FA 2146</b>		CR21E20097
<b>58 AC-ERC (15 HP)</b>	20113 <b>FD 3125</b>	20153 <b>FA 2146</b>		CR21E20097
<b>64 AC-ERC</b>	20113 <b>FD 3125</b>	20153 <b>FA 2146</b>		CR21E20097
<b>66 AC-ERC</b>	13815 <b>FD 3108</b>	10627 <b>FA 2116</b>		CR21A10641
<b>90 AC-ERC (25 HP)</b>	12857 <b>FD 3050</b>	30336 <b>FA 2150</b>		
<b>90 AC-ERC (25 HP) NEW TYPE</b>	30732 <b>FD 3169</b>	30336 <b>FA 2150</b>		



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>MATTEI</b>				
<i>94 AC-ERC (20 HP)</i>				
<i>94 AC-ERC (20 HP)</i>	12857 <b>FD 3050</b>	30336 <b>FA 2150</b>		
<i>94 AC-ERC (20 HP) NEW TYPE</i>	30732 <b>FD 3169</b>	30336 <b>FA 2150</b>		
<i>AC 37 HH</i>	30733 <b>FD 3150</b>	30566 <b>FA 2148</b>		CR21H30581 <b>FI 1272</b>
<i>OPTIMA 75 L/75 H</i>	32486 <b>FD 3272</b>			
<i>OPTIMA 90 L/90 H</i>	32486 <b>FD 3272</b>			
<i>SERIES 4000 AC 55</i>	20113 <b>FD 3125</b>			34794 <b>FI 1045 V</b>
<i>SERIES 4000 AC 75</i>	20113 <b>FD 3125</b>			34794 <b>FI 1045 V</b>
<i>SERIES 4000 AC 90</i>	20113 <b>FD 3125</b>			34794 <b>FI 1045 V</b>
<b>PARISE</b>				
<i>PC 10-15-20</i>	6010020100 <b>FD 3587</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PC 20-25-30 B</i>	6010020110 <b>FD 3671</b>	6010040060 <b>FA 2017</b>		6010060010 <b>FI 1268 V</b>
<i>PC 40 C</i>	6010020120 <b>FD 3102</b>	6010040060 <b>FA 2017</b>		6010060010 <b>FI 1268 V</b>
<i>PC 5.5-7.5</i>	6010020090 <b>FD 3672</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PC 50-60-75/CF 90</i>	6010020130 <b>FD 3047</b>	6010040060 <b>FA 2017</b>		6010060060 <b>FI 1045 V</b>
<i>PCZ 100 D</i>	6010020320 <b>FD 3447</b>	6010040080 <b>FA 1103 AL</b>		6010060060 <b>FI 1045 V</b>
<i>PCZ 10-15-20 A</i>	6010020150 <b>FD 3675</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PCZ 20-25-30 B</i>	6010020160 <b>FD 3673</b>	6010040060 <b>FA 2017</b>		6010060010 <b>FI 1268 V</b>
<i>PCZ 30-40-50 C</i>	6010020170 <b>FD 3676</b>	6010040070 <b>FA 5001</b>		6010060010 <b>FI 1268 V</b>
<i>PCZ 5.5-7.5 A</i>	6010020140 <b>FD 3674</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PCZ 50-60 D</i>	6010020180 <b>FD 3464</b>	6010040080 <b>FA 1103 AL</b>		6010060060 <b>FI 1045 V</b>
<i>PCZ 75 D</i>	6010020190 <b>FD 3205</b>	6010040080 <b>FA 1103 AL</b>		6010060060 <b>FI 1045 V</b>
<i>PD 100 EC-05</i>	6010020350	6010040080 <b>FA 1103 AL</b>		6010060060 <b>FI 1045 V</b>
<i>PD 15 EC-06</i>	6010020010 <b>FD 3096 V</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PD 20 EC-06</i>	6010020010 <b>FD 3096 V</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PD 25 EC-06</i>	6010020310 <b>FD 3031 V</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PD 30 EC-06</i>	6010020310 <b>FD 3031 V</b>	6010040060 <b>FA 2017</b>		6010060010 <b>FI 1268 V</b>
<i>PD 40 EC-06</i>	6010020310 <b>FD 3031 V</b>	6010040060 <b>FA 2017</b>		6010060010 <b>FI 1268 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>PARISE</b>				
<i>PD 50 EC-05</i>				
<i>PD 50 EC-05</i>	6010020310 <b>FD 3031 V</b>	6010040080 <b>FA 1103 AL</b>		6010060060 <b>FI 1045 V</b>
<i>PD 50 EC-06</i>	6010020310 <b>FD 3031 V</b>	6010040110		6010060080 <b>FO 0148 V</b>
<i>PD 60 EC-05</i>	6010020310 <b>FD 3031 V</b>	6010040080 <b>FA 1103 AL</b>		6010060060 <b>FI 1045 V</b>
<i>PD 60 EC-06</i>	6010020310 <b>FD 3031 V</b>	6010040110		6010060080 <b>FO 0148 V</b>
<i>PD 75 EC-05</i>	6010020350	6010040080 <b>FA 1103 AL</b>		6010060060 <b>FI 1045 V</b>
<i>PDL 100 EC-05</i>	6010020350	6010040080 <b>FA 1103 AL</b>		6010060060 <b>FI 1045 V</b>
<i>PHA 10</i>	6010020020 <b>FD 3034 V</b>	6010040480 <b>FA 0093</b>		6010060010 <b>FI 1268 V</b>
<i>PHA 15</i>	6010020010 <b>FD 3096 V</b>	6010040480 <b>FA 0093</b>		6010060010 <b>FI 1268 V</b>
<i>PHA 7.5</i>	6010020020 <b>FD 3034 V</b>	6010040480 <b>FA 0093</b>		6010060010 <b>FI 1268 V</b>
<i>PHJ 3</i>	6010020020 <b>FD 3034 V</b>	6010040480 <b>FA 0093</b>		6010060010 <b>FI 1268 V</b>
<i>PHJ 4</i>	6010020020 <b>FD 3034 V</b>	6010040480 <b>FA 0093</b>		6010060010 <b>FI 1268 V</b>
<i>PHJ 5.5</i>	6010020020 <b>FD 3034 V</b>	6010040480 <b>FA 0093</b>		6010060010 <b>FI 1268 V</b>
<i>PR 10</i>	6010020210 <b>FD 3281</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PR 20-25</i>	6010020210 <b>FD 3281</b>	6010040060 <b>FA 2017</b>		6010060010 <b>FI 1268 V</b>
<i>PR 5.5-7.5-10</i>	6010020210 <b>FD 3281</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PV 15</i>	6010020010 <b>FD 3096 V</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PV 20</i>	6010020010 <b>FD 3096 V</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PV 5.5-7.5-10</i>	6010020020 <b>FD 3034 V</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PVA 15</i>	6010020010 <b>FD 3096 V</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PVA 20</i>	6010020010 <b>FD 3096 V</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PVA 5.5-7.5-10</i>	6010020020 <b>FD 3034 V</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PVB 15</i>	6010020010 <b>FD 3096 V</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PVB 20</i>	6010020010 <b>FD 3096 V</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PVB 20-HT</i>	6010020310 <b>FD 3031 V</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PVB 25</i>	6010020310 <b>FD 3031 V</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PVB 30</i>	6010020310 <b>FD 3031 V</b>	6010040030 <b>FA 1959</b>		6010060010 <b>FI 1268 V</b>
<i>PVC 30</i>	6010020310 <b>FD 3031 V</b>	6010040060 <b>FA 2017</b>		6010060010 <b>FI 1268 V</b>





	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>PARISE</b>				
<i>PVC 40</i>				
<i>PVC 40</i>	6010020310 <b>FD 3031 V</b>	6010040060 <b>FA 2017</b>		6010060010 <b>FI 1268 V</b>
<i>PVC 40-HT</i>	6010020310 <b>FD 3031 V</b>	6010040060 <b>FA 2017</b>		6010060010 <b>FI 1268 V</b>
<i>PVC 50</i>	6010020310 <b>FD 3031 V</b>	6010040060 <b>FA 2017</b>		6010060010 <b>FI 1268 V</b>
<i>PVD 50</i>	6010020310 <b>FD 3031 V</b>	6010040110		6010060080 <b>FO 0148 V</b>
<i>PVD 60</i>	6010020310 <b>FD 3031 V</b>	6010040110		6010060080 <b>FO 0148 V</b>
<i>PVF 50</i>	6010020310 <b>FD 3031 V</b>	6010040110		6010060010 <b>FI 1268 V</b>
<i>PVF 60</i>	6010020310 <b>FD 3031 V</b>	6010040110		6010060010 <b>FI 1268 V</b>
<i>PX-PXA 10</i>	6010020020 <b>FD 3034 V</b>	6010040020		6010060010 <b>FI 1268 V</b>
<i>PX-PXA 15</i>	6010020010 <b>FD 3096 V</b>	6010040020		6010060010 <b>FI 1268 V</b>
<i>PX-PXA 5.5-7.5</i>	6010020010 <b>FD 3096 V</b>	6010040020		6010060010 <b>FI 1268 V</b>
<b>PNEUMOFORE</b>				
<i>T 10</i>	041883 <b>FD 3032</b>	041748 <b>FA 5505</b>		041376
<i>T 20</i>	041883 <b>FD 3032</b>	041748 <b>FA 5505</b>		041376
<i>T 30</i>	041883 <b>FD 3032</b>	041748 <b>FA 5505</b>		041376
<i>U 1</i>	40923 <b>FD 3566</b>	40907 <b>FA 1831</b>		40873 <b>FI 1288 V</b>
<i>U 12</i>	040337 <b>FD 3624</b>	040741 <b>FA 1106</b>		041210
<i>U 2</i>	40311 <b>FD 3049</b>	40428 <b>FA 1511</b>		
<i>U 3</i>	40311 <b>FD 3049</b>	40428 <b>FA 1511</b>		
<i>U 6</i>	40360 <b>FD 3565</b>	40659 <b>FA 1220</b>		
<i>U 9</i>	041129 <b>FD 3565</b>	040741 <b>FA 1106</b>		041210
<i>U 9 UP TO 1</i>	40923 <b>FD 3566</b>	40907 <b>FA 1831</b>		40873 <b>FI 1288 V</b>
<i>U 9 UP TO 12 NEW TYPE</i>	40337 <b>FD 3624</b>	41779 <b>FA 5500</b>		
<i>UF 18</i>	040337 <b>FD 3624</b>	041430 <b>FA 1217</b>		041210
<i>UF 18 B</i>	040337 <b>FD 3624</b>	041430 <b>FA 1217</b>		041508
<i>UF 26</i>	040618	041500 <b>FA 1302</b>		041508
<i>UF 26 B</i>	040618	041500 <b>FA 1302</b>		041508
<i>UP 1</i>	040923 <b>FD 3566</b>	040907 <b>FA 1831</b>		040873



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>PNEUMOFORE</b>				
<i>UP 12</i>				
<i>UP 12</i>	040337 <b>FD 3624</b>	040741 <b>FA 1106</b>		041210
<i>UP 12 E</i>	040337 <b>FD 3624</b>	041779 <b>FA 5500</b>		
<i>UP 2</i>	41046 <b>FD 3144</b>	40428 <b>FA 1511</b>		41038 <b>FI 1045 V</b>
<i>UP 2 NEW TYPE</i>	041047 <b>FD 3056</b>	041327 <b>FA 1266 AL</b>		041041
<i>UP 2 OLD TYPE</i>	041047 <b>FD 3056</b>	040428 <b>FA 1511</b>		041038 <b>FI 1045 V</b>
<i>UP 3</i>	41046 <b>FD 3144</b>	40436 <b>FA 1267</b>		
<i>UP 3 NEW TYPE</i>	041047 <b>FD 3056</b>	041327 <b>FA 1266 AL</b>		041041
<i>UP 3 OLD TYPE</i>	041047 <b>FD 3056</b>	040436 <b>FA 1267</b>		040038 <b>FI 1045 V</b>
<i>UP 6</i>	41079 <b>FD 3114</b>	40659 <b>FA 1220</b>		41160
<i>UP 6 NEW TYPE</i>	041079 <b>FD 3114</b>	041764 <b>FA 5501</b>		041160
<i>UP 6 OLD TYPE</i>	041079 <b>FD 3114</b>	040659 <b>FA 1220</b>		041160
<i>UP 9</i>	041129 <b>FD 3565</b>	040741 <b>FA 1106</b>		041210
<i>UP 9 E</i>	041129 <b>FD 3565</b>	041779 <b>FA 5500</b>		041210
<i>UR 1</i>	40923 <b>FD 3566</b>	40907 <b>FA 1831</b>		41336
<i>UR 12</i>	041986 <b>FD 3275</b>	041963 <b>FA 5854</b>		041210
<i>UR 2</i>	041047 <b>FD 3056</b>	041327 <b>FA 1266 AL</b>		041376
<i>UR 2 E</i>	041047 <b>FD 3056</b>	041327 <b>FA 1266 AL</b>		041376
<i>UR 3</i>	041047 <b>FD 3056</b>	041327 <b>FA 1266 AL</b>		041392
<i>UR 3 E</i>	041047 <b>FD 3056</b>	041327 <b>FA 1266 AL</b>		041392
<i>UR 6</i>	041971 <b>FD 3462</b>	041947 <b>FA 5502</b>		041160
<i>UR 9</i>	041971 <b>FD 3462</b>	041779 <b>FA 5500</b>		041210
<i>UV 16</i>	042002	041430 <b>FA 1217</b>		041210
<i>UV 4</i>	041971 <b>FD 3462</b>			041376
<i>UV 8</i>	042035 <b>FD 3236</b>			041210
<b>POWER SYSTEM</b>				
<i>PS 11</i>	490001 <b>FD 3059</b>	480002 <b>FA 1959</b>		470001 <b>FI 1268 V</b>
<i>PS 110 DV</i>	490005 <b>FD 3030</b>	480025 <b>FA 5931</b>		470003



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>POWER SYSTEM</b>				
<i>PS 110 DV FROM 2007</i>				
<i>PS 110 DV FROM 2007</i>	490005 <b>FD 3030</b>	480024 <b>FA 5854</b>		470003
<i>PS 15</i>	490001 <b>FD 3059</b>	480002 <b>FA 1959</b>		470001 <b>FI 1268 V</b>
<i>PS 18</i>	490002 <b>FD 3432</b>	480003 <b>FA 2017</b>		470001 <b>FI 1268 V</b>
<i>PS 20 DV</i>	490002 <b>FD 3432</b>	480003 <b>FA 2017</b>		
<i>PS 2037</i>	490018 <b>FD 3460</b>	480028 <b>FA 5501</b>		470002 <b>FI 1304 V</b>
<i>PS 22</i>	490002 <b>FD 3432</b>	480003 <b>FA 2017</b>		470001 <b>FI 1268 V</b>
<i>PS 250 DV</i>	490007 <b>FD 3268</b>	480031		470015 <b>FI 1099 V</b>
<i>PS 30</i>	490003 <b>FD 3265</b>	480005 <b>FA 1004 AL</b>		470002 <b>FI 1304 V</b>
<i>PS 3055</i>	490005 <b>FD 3030</b>	480006		470003
<i>PS 35 10 DV</i>	490004 <b>FD 3464</b>	480006		470003
<i>PS 37</i>	490003 <b>FD 3265</b>	480005 <b>FA 1004 AL</b>		470002 <b>FI 1304 V</b>
<i>PS 4</i>	490001 <b>FD 3059</b>	480002 <b>FA 1959</b>		470001 <b>FI 1268 V</b>
<i>PS 404</i>	490008 <b>FD 3034 V</b>			
<i>PS 407</i>	490009 <b>FD 3096 V</b>			
<i>PS 411</i>	490009 <b>FD 3096 V</b>			
<i>PS 5.5</i>	490001 <b>FD 3059</b>	480002 <b>FA 1959</b>		470001 <b>FI 1268 V</b>
<i>PS 7.5</i>	490001 <b>FD 3059</b>	480002 <b>FA 1959</b>		470001 <b>FI 1268 V</b>
<i>PS 70 DV</i>	490005 <b>FD 3030</b>	480023 <b>FA 5500</b>		470003
<i>PS 90 DV</i>	490005 <b>FD 3030</b>	480023 <b>FA 5500</b>		470003
<b>PVR ROTANT</b>				
<i>PVL 100</i>	301138	000902 <b>FA 1657</b>		
<i>PVL 150</i>	301138	000903 <b>FA 0243</b>		
<i>PVL 25</i>	301137	000900 <b>FA 1665</b>		
<i>PVL 35</i>	301137	000900 <b>FA 1665</b>		
<b>RENNER</b>				
<i>NK 100</i>	R12101 <b>FD 3031 V</b>	R8556 <b>FA 1797</b>		R333 <b>FI 1295 V</b>
<i>NK 100 type 25, 30, 40 HP</i>	10291 <b>FD 3031 V</b>	10290		10289
<i>NK 100/160</i>	R12101 <b>FD 3031 V</b>	R12017 <b>FA 5501</b>		R1161 <b>FI 1286 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>RENNER</b>				
<i>NK 160</i>				
<i>NK 160</i>	R12101 <b>FD 3031 V</b>			R9206 <b>FI 1290 V</b>
<i>NK 160 type 50 HP</i>	10291 <b>FD 3031 V</b>	10296		10295
<i>NK 40</i>	R12476 <b>FD 3096 V</b>	R9213 <b>FA 0093</b>		R9206 <b>FI 1290 V</b>
<i>NK 60</i>	R12476 <b>FD 3096 V</b>	R2215 <b>FA 0028</b>		R9206 <b>FI 1290 V</b>
<i>RS 11.0 (15 HP)</i>	R12476 <b>FD 3096 V</b>	R2215 <b>FA 0028</b>		R9206 <b>FI 1290 V</b>
<i>RS 11.0-15.0</i>	R12476 <b>FD 3096 V</b>	R2215 <b>FA 0028</b>		R9206 <b>FI 1290 V</b>
<i>RS 1-30.0 (40 HP)</i>	R12101 <b>FD 3031 V</b>			R333 <b>FI 1295 V</b>
<i>RS 15.0 (20 HP)</i>	R12476 <b>FD 3096 V</b>	R2215 <b>FA 0028</b>		R9206 <b>FI 1290 V</b>
<i>RS 18.5 (25 HP)</i>	R12101 <b>FD 3031 V</b>	R8556 <b>FA 1797</b>		R333 <b>FI 1295 V</b>
<i>RS 18.5-22.0-30.0</i>	R12101 <b>FD 3031 V</b>	R8556 <b>FA 1797</b>		R333 <b>FI 1295 V</b>
<i>RS 2 30.0</i>	R12101 <b>FD 3031 V</b>	R12017 <b>FA 5501</b>		R1161 <b>FI 1286 V</b>
<i>RS 22.0 (30 HP)</i>	R12101 <b>FD 3031 V</b>	R8556 <b>FA 1797</b>		R333 <b>FI 1295 V</b>
<i>RS 2-30.0 (40 HP)</i>	R12101 <b>FD 3031 V</b>	R12017 <b>FA 5501</b>		R1161 <b>FI 1286 V</b>
<i>RS 3.0 (4 HP)</i>	R12476 <b>FD 3096 V</b>	R9213 <b>FA 0093</b>		R9206 <b>FI 1290 V</b>
<i>RS 3.0-4.0-5.5-9.0</i>	R12476 <b>FD 3096 V</b>	R9213 <b>FA 0093</b>		R9206 <b>FI 1290 V</b>
<i>RS 37.0 (50 HP)</i>	R12101 <b>FD 3031 V</b>	R12017 <b>FA 5501</b>		R1161 <b>FI 1286 V</b>
<i>RS 37.0-45.0</i>	R12101 <b>FD 3031 V</b>	R12017 <b>FA 5501</b>		R1161 <b>FI 1286 V</b>
<i>RS 4.0 (5.5 HP)</i>	R12476 <b>FD 3096 V</b>	R9213 <b>FA 0093</b>		R9206 <b>FI 1290 V</b>
<i>RS 45.0 (60 HP)</i>	R12101 <b>FD 3031 V</b>	R12017 <b>FA 5501</b>		R1161 <b>FI 1286 V</b>
<i>RS 5.5 (7.5 HP)</i>	R12476 <b>FD 3096 V</b>	R9213 <b>FA 0093</b>		R9206 <b>FI 1290 V</b>
<i>RS 55.0</i>	R12101 <b>FD 3031 V</b>	R12012		R1161 <b>FI 1286 V</b>
<i>RS 55.0 (75 HP)</i>	R12101 <b>FD 3031 V</b>			R1161 <b>FI 1286 V</b>
<i>RS 9.0 (12 HP)</i>	R12476 <b>FD 3096 V</b>			R9206 <b>FI 1290 V</b>
<b>RIETSCHLE</b>				
<i>CL 25 DV</i>		730501 <b>FA 1768</b>		
<i>CL 40 DV</i>		730501 <b>FA 1768</b>		
<i>CL 40 DV VLS</i>		730501 <b>FA 1768</b>		



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>RIETSCHLE</b>				
<i>CL 60 DV</i>				
<i>CL 60 DV</i>		730501 <b>FA 1768</b>		
<i>CL 60 DV VLS</i>		730506 <b>FA 1778</b>		
<i>CLF 101</i>	730936 <b>FD 3140</b>	730500 <b>FA 1767</b>		
<i>CLF 101 FROM 2001</i>	731400 <b>FD 3617</b>	730500 <b>FA 1767</b>		
<i>CLF 141</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<i>CLF 141 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>CLF 181</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<i>CLF 181 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>CLF 251</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<i>CLF 251 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>CLF 341</i>	730936 <b>FD 3140</b>	730080 <b>FA 3070</b>		
<i>CLF 341 FROM 2001</i>	731400 <b>FD 3617</b>	730080 <b>FA 3070</b>		
<i>CLF 61</i>	730946 <b>FD 3139</b>	730500 <b>FA 1767</b>		
<i>CLF 61 FROM 2001</i>	731399 <b>FD 3619</b>	730500 <b>FA 1767</b>		
<i>CLF 81</i>	730946 <b>FD 3139</b>	730500 <b>FA 1767</b>		
<i>CLF 81 FROM 2001</i>	731399 <b>FD 3619</b>	730500 <b>FA 1767</b>		
<i>CLF41</i>	730946 <b>FD 3139</b>	730506 <b>FA 1778</b>		
<i>CLF41 FROM 2001</i>	731399 <b>FD 3619</b>	730506 <b>FA 1778</b>		
<i>CLFD 141</i>	730937 <b>FD 3115</b>	730507 <b>FA 1782</b>		
<i>CLFD 141 FROM 2001</i>	731401 <b>FD 3618</b>	730507 <b>FA 1782</b>		
<i>CLFD 181</i>	730937 <b>FD 3115</b>	730084		
<i>CLFD 181 FROM 2001</i>	731401 <b>FD 3618</b>	730084		
<i>CLFD 251</i>	730937 <b>FD 3115</b>	730095 <b>FA 2180</b>		
<i>CLFD 251 FROM 2001</i>	731401 <b>FD 3618</b>	730095 <b>FA 2180</b>		
<i>CLFE 101</i>	730936 <b>FD 3140</b>	730500 <b>FA 1767</b>		
<i>CLFE 101 FROM 2001</i>	731400 <b>FD 3617</b>	730500 <b>FA 1767</b>		
<i>CLFE 141</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		

	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>RIETSCHLE</b>				
<i>CLFE 141 FROM 2001</i>				
<i>CLFE 141 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>CLFE 181</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<i>CLFE 181 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>CLFE 251</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<i>CLFE 251 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>CLFE 341</i>	730936 <b>FD 3140</b>	730080 <b>FA 3070</b>		
<i>CLFE 341 FROM 2001</i>	731400 <b>FD 3617</b>	730080 <b>FA 3070</b>		
<i>CLFE 41</i>	730946 <b>FD 3139</b>	730506 <b>FA 1778</b>		
<i>CLFE 41 FROM 2001</i>	731399 <b>FD 3619</b>	730506 <b>FA 1778</b>		
<i>CLFE 61</i>	730946 <b>FD 3139</b>	730500 <b>FA 1767</b>		
<i>CLFE 61 FROM 2001</i>	731399 <b>FD 3619</b>	730500 <b>FA 1767</b>		
<i>CLFE 81</i>	730946 <b>FD 3139</b>	730500 <b>FA 1767</b>		
<i>CLFE 81 FROM 2001</i>	731399 <b>FD 3619</b>	730500 <b>FA 1767</b>		
<i>CLFEH 1001</i>	730936 <b>FD 3140</b>	730080 <b>FA 3070</b>		
<i>CLFEH 1001 FROM 2001</i>	731400 <b>FD 3617</b>	730080 <b>FA 3070</b>		
<i>CLFEH 141</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<i>CLFEH 141 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>CLFEH 181</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<i>CLFEH 181 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>CLFEH 251</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<i>CLFEH 251 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>CLFEH 341</i>	730936 <b>FD 3140</b>	730080 <b>FA 3070</b>		
<i>CLFEH 341 FROM 2001</i>	731400 <b>FD 3617</b>	730080 <b>FA 3070</b>		
<i>CLFEH 501</i>	730937 <b>FD 3115</b>	730080 <b>FA 3070</b>		
<i>CLFEH 501 FROM 2001</i>	731401 <b>FD 3618</b>	730080 <b>FA 3070</b>		
<i>CLFEH 631</i>	730936 <b>FD 3140</b>	730080 <b>FA 3070</b>		
<i>CLFEH 631 FROM 2001</i>	731400 <b>FD 3617</b>	730080 <b>FA 3070</b>		



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>RIETSCHLE</b>				
<i>CLFG 11 V</i>				
<i>CLFG 11 V</i>		730501 <b>FA 1768</b>		
<i>CLFG 41</i>		730506 <b>FA 1778</b>		
<i>CLFG 41 V</i>		730506 <b>FA 1778</b>		
<i>CLFG 61</i>		730507 <b>FA 1782</b>		
<i>CLFT 100</i>		730502 <b>FA 1769</b>		
<i>CLFT 100 DV</i>		730502 <b>FA 1769</b>		
<i>CLFT 101</i>		730502 <b>FA 1769</b>		
<i>CLFT 101 DV</i>		730502 <b>FA 1769</b>		
<i>CLFT 141 DV</i>		730502 <b>FA 1769</b>		
<i>CLFT 40 DV</i>		730502 <b>FA 1769</b>		
<i>CLFT 41 DV</i>		730502 <b>FA 1769</b>		
<i>CLFT 60 DV</i>		730502 <b>FA 1769</b>		
<i>CLFT 61 DV</i>		730502 <b>FA 1769</b>		
<i>CLFT 80 DV</i>		730505 <b>FA 1776</b>		
<i>CLFT 81 DV</i>		730505 <b>FA 1776</b>		
<i>DCL (F) 100 DV</i>		730505 <b>FA 1776</b>		
<i>DCL (F) 130 DV</i>		730505 <b>FA 1776</b>		
<i>DCL (F) 130 DV VLS</i>		730505 <b>FA 1776</b>		
<i>DCL (F) 200 DV</i>		730505 <b>FA 1776</b>		
<i>DCL (F) 40 DV</i>		730502 <b>FA 1769</b>		
<i>DCL (F) 60 DV</i>		730502 <b>FA 1769</b>		
<i>DCL (F) 60 DV VLS</i>		730502 <b>FA 1769</b>		
<i>DCL (F) 80 DV</i>		730502 <b>FA 1769</b>		
<i>DCL (F) 80 DV VLS</i>		730502 <b>FA 1769</b>		
<i>DCL 198 DV</i>		730505 <b>FA 1776</b>		
<i>DFT 40</i>		730506 <b>FA 1778</b>		
<i>DFT 500</i>		730080 <b>FA 3070</b>		

	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>RIETSCHLE</b>				
<i>DLT 15</i>				
<i>DLT 15</i>		317900 <b>FA 2207</b>		
<i>DLT 40</i>		317957 <b>FA 2210</b>		
<i>DTA 100</i>		731142 <b>FA 2129</b>		
<i>DTA 140</i>		731142 <b>FA 2129</b>		
<i>DTA 60</i>		731142 <b>FA 2129</b>		
<i>DTA 80</i>	1022230101	731142 <b>FA 2129</b>		
<i>DTB 180</i>		730511 <b>FA 1621</b>		
<i>DTB 250</i>		730511 <b>FA 1621</b>		
<i>KLT 15</i>		317900 <b>FA 2207</b>	317856 <b>FA 1773</b>	
<i>KLT 25</i>		317895	317856 <b>FA 1773</b>	
<i>KLT 40</i>		317856 <b>FA 1773</b>	317856 <b>FA 1773</b>	
<i>KTA 100</i>		731142 <b>FA 2129</b>		
<i>KTA 140</i>		731142 <b>FA 2129</b>		
<i>KTA 60</i>		731142 <b>FA 2129</b>		
<i>KTA 80/1</i>	1022230101	731142 <b>FA 2129</b>		
<i>KTA 80/2</i>	1022230101	731142 <b>FA 2129</b>		
<i>KTA 80/3</i>	1022230101	731142 <b>FA 2129</b>		
<i>KTA 80/4</i>		731142 <b>FA 2129</b>		
<i>KTA 80/5</i>		731142 <b>FA 2129</b>		
<i>TLV 10</i>		730502 <b>FA 1769</b>		
<i>TR 10 DV</i>		513457 <b>FA 1770</b>		
<i>TR 15 DV</i>		513457 <b>FA 1770</b>		
<i>TR 25 DV</i>		515339 <b>FA 1771</b>		
<i>TR 25/26 DV</i>		515339 <b>FA 1771</b>		
<i>TR 26 DV</i>		515339 <b>FA 1771</b>		
<i>TR 40 DV</i>		515340 <b>FA 1777</b>		
<i>TR 41 DV</i>		515340 <b>FA 1777</b>		



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>RIETSCHLE</b> <i>TR 60/61 DV (V)</i>				
<i>TR 60/61 DV (V)</i>		515411 <b>FA 2215</b>		
<i>TR 61 DV</i>		515411 <b>FA 2215</b>		
<i>TR 61 V</i>		730508 <b>FA 2214</b>		
<i>TR 80 DVV</i>		515310 <b>FA 2216</b>		
<i>TR 80/81</i>		515310 <b>FA 2216</b>		
<i>TR 81 DVV</i>		515310 <b>FA 2216</b>		
<i>VC 100</i>	731401 <b>FD 3618</b>			
<i>VC 150</i>	731401 <b>FD 3618</b>			
<i>VC 200</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<i>VC 200 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>VC 300</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<i>VC 300 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>VC 400</i>	731400 <b>FD 3617</b>	730080 <b>FA 3070</b>		
<i>VC 500</i>	731401 <b>FD 3618</b>	730080 <b>FA 3070</b>		
<i>VC 700</i>	731401 <b>FD 3618</b>	730080 <b>FA 3070</b>		
<i>VC 900</i>	731400 <b>FD 3617</b>	730080 <b>FA 3070</b>		
<i>VCA 100</i>	730936 <b>FD 3140</b>			
<i>VCA 100 FROM 2001</i>	731400 <b>FD 3617</b>			
<i>VCA 40</i>	730946 <b>FD 3139</b>			
<i>VCA 40 FROM 2001</i>	731399 <b>FD 3619</b>			
<i>VCA 60</i>	730946 <b>FD 3139</b>			
<i>VCA 60 FROM 2001</i>	731399 <b>FD 3619</b>			
<i>VCAH 100</i>	730936 <b>FD 3140</b>			
<i>VCAH 100 FROM 2001</i>	731400 <b>FD 3617</b>			
<i>VCAH 160</i>	730937 <b>FD 3115</b>			
<i>VCAH 160 FROM 2001</i>	731401 <b>FD 3618</b>			
<i>VCAH 250</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		

	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>RIETSCHLE</b>				
<i>VCAH 250 FROM 2001</i>				
<i>VCAH 250 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>VCB 20</i>	731023 <b>FD 3159</b>			
<i>VCE 100</i>	730936 <b>FD 3140</b>			
<i>VCE 100 FROM 2001</i>	731400 <b>FD 3617</b>			
<i>VCE 40</i>	730946 <b>FD 3139</b>	513258		
<i>VCE 40 FROM 2001</i>	731399 <b>FD 3619</b>	513258		
<i>VCE 60</i>	730946 <b>FD 3139</b>	513258		
<i>VCE 60 FROM 2001</i>	731399 <b>FD 3619</b>	513258		
<i>VCEH 160</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<i>VCEH 160 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>VCEH 250</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<i>VCEH 250 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>VCH 100</i>	730936 <b>FD 3140</b>			
<i>VCH 100 FROM 2001</i>	731400 <b>FD 3617</b>			
<i>VCH 140</i>	730936 <b>FD 3140</b>			
<i>VCH 140 FROM 2001</i>	731400 <b>FD 3617</b>			
<i>VCH 180</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<i>VCH 180 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>VCH 220</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<i>VCH 220 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>VCH 250</i>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<i>VCH 250 FROM 2001</i>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<i>VFT 250</i>		730511 <b>FA 1621</b>		
<i>VFT 340</i>		730080 <b>FA 3070</b>		
<i>VFT 340 FROM 1992</i>		730080 <b>FA 3070</b>		
<i>VFT 500</i>		730080 <b>FA 3070</b>		
<i>VGD 10</i>	731023 <b>FD 3159</b>	514347 <b>FA 1770</b>		

	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>RIETSCHLE</b>				
<i>VG D 15</i>				
<b>VG D 15</b>	731399 <b>FD 3619</b>			
<b>VG D 15 OLD MODEL</b>	731023 <b>FD 3159</b>			
<b>VG D 20</b>	731023 <b>FD 3159</b>	514347 <b>FA 1770</b>		
<b>VLT 15</b>		317900 <b>FA 2207</b>		
<b>VLT 40</b>		317957 <b>FA 2210</b>		
<b>VSH 1000</b>	730936 <b>FD 3140</b>	730080 <b>FA 3070</b>		
<b>VSH 1000 FROM 2001</b>	731400 <b>FD 3617</b>	730080 <b>FA 3070</b>		
<b>VSH 140</b>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<b>VSH 140 FROM 2001</b>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<b>VSH 1500</b>	730936 <b>FD 3140</b>	730080 <b>FA 3070</b>		
<b>VSH 1500 FROM 2001</b>	731400 <b>FD 3617</b>	730080 <b>FA 3070</b>		
<b>VSH 180</b>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<b>VSH 180 FROM 2001</b>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<b>VSH 250</b>	730937 <b>FD 3115</b>	730503 <b>FA 1773</b>		
<b>VSH 250 FROM 2001</b>	731401 <b>FD 3618</b>	730503 <b>FA 1773</b>		
<b>VSH 340</b>	730936 <b>FD 3140</b>	730080 <b>FA 3070</b>		
<b>VSH 340 FROM 2001</b>	731400 <b>FD 3617</b>	730080 <b>FA 3070</b>		
<b>VSH 500</b>	730937 <b>FD 3115</b>	730080 <b>FA 3070</b>		
<b>VSH 500 FROM 2001</b>	731401 <b>FD 3618</b>	730080 <b>FA 3070</b>		
<b>VSH 630</b>	730936 <b>FD 3140</b>	730080 <b>FA 3070</b>		
<b>VSH 630 FROM 2001</b>	731400 <b>FD 3617</b>	730080 <b>FA 3070</b>		
<b>VSW 1000</b>	730936 <b>FD 3140</b>	730080 <b>FA 3070</b>		
<b>VSW 1000 FROM 2001</b>	731400 <b>FD 3617</b>	730080 <b>FA 3070</b>		
<b>VSW 340</b>	730936 <b>FD 3140</b>	730080 <b>FA 3070</b>		
<b>VSW 340 FROM 2001</b>	731400 <b>FD 3617</b>	730080 <b>FA 3070</b>		
<b>VSW 500</b>	730937 <b>FD 3115</b>	730080 <b>FA 3070</b>		
<b>VSW 500 FROM 2001</b>	731401 <b>FD 3618</b>	730080 <b>FA 3070</b>		

	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>RIETSCHLE</b>				
<i>VSW 630</i>				
<i>VSW 630</i>	730936 <b>FD 3140</b>	730080 <b>FA 3070</b>		
<i>VSW 630 FROM 2001</i>	731400 <b>FD 3617</b>	730080 <b>FA 3070</b>		
<i>VTA 100</i>		731142 <b>FA 2129</b>		
<i>VTA 140</i>		731142 <b>FA 2129</b>		
<i>VTA 80</i>		731142 <b>FA 2129</b>		
<i>VTB 180</i>		730511 <b>FA 1621</b>		
<i>VTB 250</i>		730511 <b>FA 1621</b>		
<i>VTB 340</i>		730080 <b>FA 3070</b>		
<b>ROTAIR</b>				
<i>25 AR TURBOSOL</i>	157007S <b>FD 3281</b>			
<i>33 AR TURBOSOL</i>	157007S <b>FD 3281</b>			
<i>3500 LT</i>	157004S <b>FD 3075</b>			
<i>EMDV 15</i>	157100S <b>FD 3083</b>			
<i>EMDV 20</i>	157100S <b>FD 3083</b>	162280S <b>FA 1729</b>		099007S <b>FI 1288 V</b>
<i>MDVN 100</i>	157180S <b>FD 3503</b>			
<i>MDVN 130 PK</i>	157145S <b>FD 3446</b>			
<i>MDVN 16</i>	157003S <b>FD 3116</b>			
<i>MDVN 17</i>	157010S <b>FD 3059</b>			
<i>MDVN 170 PK</i>	157147S <b>FD 3447</b>			
<i>MDVN 20</i>	157010S <b>FD 3059</b>			
<i>MDVN 210</i>	157007S <b>FD 3281</b>			
<i>MDVN 24</i>	157020S <b>FD 3432</b>			
<i>MDVN 25 A</i>	157002S <b>FD 3117</b>			
<i>MDVN 250</i>	157007S <b>FD 3281</b>			
<i>MDVN 28 B</i>	157007S <b>FD 3281</b>			
<i>MDVN 30 AP NEW VERSION</i>	157148S <b>FD 3669</b>	162574S <b>FA 2026</b>		
<i>MDVN 30 AP OLD VERSION</i>	157148S <b>FD 3669</b>	162106S		



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ROTAIR</b>	<b>MDVN 32</b>			
<b>MDVN 32</b>	157020S <b>FD 3432</b>			
<b>MDVN 33 A</b>	157007S <b>FD 3281</b>			
<b>MDVN 34</b>	157060S <b>FD 3283</b>			
<b>MDVN 35/B</b>	157007S <b>FD 3281</b>			
<b>MDVN 36 AP NEW VERSION</b>	157148S <b>FD 3669</b>	162574S <b>FA 2026</b>		099007S <b>FI 1288 V</b>
<b>MDVN 36 AP OLD VERSION</b>	157148S <b>FD 3669</b>	162106S		099007S <b>FI 1288 V</b>
<b>MDVN 40</b>	157030S <b>FD 3064</b>			
<b>MDVN 40 B</b>	157090S <b>FD 3324</b>			
<b>MDVN 41 A</b>	157007S <b>FD 3281</b>			
<b>MDVN 42</b>	157020S <b>FD 3432</b>			
<b>MDVN 45 AP</b>	157144S	162576S <b>FA 2004</b>		
<b>MDVN 50</b>	157030S <b>FD 3064</b>			
<b>MDVN 50 B</b>	157090S <b>FD 3324</b>			
<b>MDVN 52 AP</b>	157144S	162576S <b>FA 2004</b>		
<b>MDVN 67</b>	157095S <b>FD 3325</b>			
<b>MDVN 70</b>	157040S <b>FD 3069</b>			
<b>MDVN 70 BT</b>	157160S <b>FD 3501</b>	162300S <b>FA 1732</b>		
<b>MDVN 75</b>	157095S <b>FD 3325</b>			
<b>MDVN 85</b>	157070S <b>FD 3005</b>			
<b>MDVS 100</b>	157180S <b>FD 3503</b>			
<b>MDVS 130 PK</b>	157145S <b>FD 3446</b>			
<b>MDVS 170 PK</b>	157147S <b>FD 3447</b>			
<b>MDVS 85</b>	157180S <b>FD 3503</b>			
<b>RVC 20</b>	157140S <b>FD 3006</b>			
<b>RVC 25</b>	157141S <b>FD 3007</b>			
<b>RVC 25 NEW</b>	157142S <b>FD 3225</b>			
<b>RVC 40</b>	157141S <b>FD 3007</b>			



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ROTAIR</b> <i>RVC 40 NEW</i>				
<i>RVC 40 NEW</i>	157142S <b>FD 3225</b>			
<i>RVC 8</i>	157140S <b>FD 3006</b>			
<i>RVS 10</i>	157005S <b>FD 3228</b>	162440S <b>FA 2742</b>	162460S <b>FA 2743</b>	099007S <b>FI 1288 V</b>
<i>RVS 100</i>	157110S <b>FD 3356</b>			
<i>RVS 15</i>	157002S <b>FD 3117</b>	162440S <b>FA 2742</b>	162460S <b>FA 2743</b>	099007S <b>FI 1288 V</b>
<i>RVS 15 NEW</i>	157007S <b>FD 3281</b>	162440S <b>FA 2742</b>		099007S <b>FI 1288 V</b>
<i>RVS 20</i>	157005S <b>FD 3228</b>			
<i>RVS 20 NEW</i>	157007S <b>FD 3281</b>			
<i>RVS 25</i>	157004S <b>FD 3075</b>	162208S <b>FA 1729</b>	162281S <b>FA 1892</b>	
<i>RVS 25 A</i>	157002S <b>FD 3117</b>			
<i>RVS 25 NEW</i>	157007S <b>FD 3281</b>			
<i>RVS 30</i>	157004S <b>FD 3075</b>			
<i>RVS 30 A</i>	157002S <b>FD 3117</b>			
<i>RVS 30 NEW</i>	157007S <b>FD 3281</b>			
<i>RVS 40</i>	157095S <b>FD 3325</b>			
<i>RVS 40 NEW</i>	157190S <b>FD 3505</b>			
<i>RVS 50</i>	157190S <b>FD 3505</b>			
<i>RVS 60</i>	157095S <b>FD 3325</b>	162300S <b>FA 1732</b>		
<i>RVS 60 NEW</i>	157160S <b>FD 3501</b>			
<i>RVS 75</i>	157095S <b>FD 3325</b>			
<i>RVS 75 NEW</i>	157130S <b>FD 3351</b>			
<i>RVS 8</i>	157005S <b>FD 3228</b>			
<i>VR 115</i>	157005S <b>FD 3228</b>			
<i>VR 150</i>	157005S <b>FD 3228</b>			
<i>VR 180</i>	157005S <b>FD 3228</b>			
<b>ROTORCOMP</b>				
<i>NK 100</i>	R12101 <b>FD 3031 V</b>	R8556 <b>FA 1797</b>		R833 <b>FI 1295 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>ROTORCOMP</b>				
<i>NK 160</i>				
<b>NK 160</b>	R12101 <b>FD 3031 V</b>	R12107 <b>FA 1805</b>		R1161 <b>FI 1286 V</b>
<b>NK 40</b>	115500 <b>FD 3047</b>	109213 <b>FA 0093</b>		109206 <b>FI 1290 V</b>
<b>NK 60</b>	R12476 <b>FD 3096 V</b>	R12107 <b>FA 1805</b>		R2979 <b>FI 0906 V</b>
<b>RC 15 KW/HP 15</b>	R12476 <b>FD 3096 V</b>	R215 <b>FA 0028</b>		PER252 <b>FO 0029 V</b>
<b>RC 30 KW/HP 30</b>	R12476 <b>FD 3096 V</b>	R8556 <b>FA 1797</b>		
<b>RC 50 KW/HP 50</b>	R12101 <b>FD 3031 V</b>	R12107 <b>FA 1805</b>		R1161 <b>FI 1286 V</b>
<b>RC 75 KW/HP 75</b>	R907 <b>FD 3616</b>			
<b>SULLAIR</b>				
<b>10B-25 ACAC</b>	250034112 <b>FD 3472</b>	042445 <b>FA 2075</b>		250025525
<b>150</b>	68520690 <b>FD 3064</b>			
<b>160</b>	68520690 <b>FD 3064</b>			
<b>160 MOBILE COMPRESSOR</b>	410333	040596 <b>FA 1004 AL</b>		046701
<b>16B8-75 WCAC</b>	250034116 <b>FD 3470</b>	408990		250025526 <b>FI 1308 V</b>
<b>175</b>	68520690 <b>FD 3064</b>	040899 <b>FA 2092</b>		
<b>185</b>	68520690 <b>FD 3064</b>	040899 <b>FA 2092</b>		
<b>425 XH</b>	409805007 <b>FD 3612</b>			
<b>65 WITH KUBOTA V2203- B ENG.</b>	68560439 <b>FD 3222</b>	2250102158 <b>FA 5903</b>	68560938 <b>FA 5101</b>	68521824 <b>FI 1306 V</b>
<b>BDS 11</b>	68561857 <b>FD 3584</b>	042445 <b>FA 2075</b>		250028032 <b>FI 1303 V</b>
<b>BDS 15</b>	68561857 <b>FD 3584</b>	042445 <b>FA 2075</b>		250028032 <b>FI 1303 V</b>
<b>BDS 18.5 FROM 03/2003</b>	02250121500 <b>FD 3032</b>	042445 <b>FA 2075</b>		250028032 <b>FI 1303 V</b>
<b>BDS 18.5 UP TO 2003</b>	250034114 <b>FD 3032</b>	042445 <b>FA 2075</b>		250028032 <b>FI 1303 V</b>
<b>BDS 22 FROM 03/2003</b>	02250121500 <b>FD 3032</b>	042445 <b>FA 2075</b>		250028032 <b>FI 1303 V</b>
<b>BDS 22 UP TO 2003</b>	250034114 <b>FD 3032</b>	042445 <b>FA 2075</b>		250028032 <b>FI 1303 V</b>
<b>BDS 30 FROM 03/2003</b>	02250121500 <b>FD 3032</b>	02250087420 <b>FA 1004 AL</b>		250028032 <b>FI 1303 V</b>
<b>BDS 30 UP TO 2003</b>	250034114 <b>FD 3032</b>	02250087420 <b>FA 1004 AL</b>		250028032 <b>FI 1303 V</b>
<b>BDS 37</b>	250034116 <b>FD 3470</b>	02250087420 <b>FA 1004 AL</b>		250025526 <b>FI 1308 V</b>
<b>BDS 45</b>	250034116 <b>FD 3470</b>	02250087420 <b>FA 1004 AL</b>		250025526 <b>FI 1308 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>SULLAIR</b>				
<i>BDS 55</i>				
<i>BDS 55</i>	250034116 <b>FD 3470</b>	02250046012 <b>FA 1252</b>		250025526 <b>FI 1308 V</b>
<i>BDS 7.5</i>	68561857 <b>FD 3584</b>	042445 <b>FA 2075</b>		250028032 <b>FI 1303 V</b>
<i>BDS 75</i>	250034116 <b>FD 3470</b>	02250046012 <b>FA 1252</b>		250025526 <b>FI 1308 V</b>
<i>E 6 (5.7.5.10 HP)</i>	250025264 <b>FD 3404</b>		2250111804	250026982 <b>FI 1303 V</b>
<i>ES 11</i>	02250106706	02250087420 <b>FA 1004 AL</b>		02250083656
<i>ES 11 24KT</i>	02250106706	02250087420 <b>FA 1004 AL</b>		02250083656
<i>ES 11 SRF</i>	02250106706	02250087420 <b>FA 1004 AL</b>		02250083656
<i>ES 11 SULLUBE</i>	02250106706	02250087420 <b>FA 1004 AL</b>		02250083656
<i>ES 6</i>	250028033 <b>FD 3404</b>	250028034 <b>FA 2087</b>		250028032 <b>FI 1303 V</b>
<i>ES 6 SRF</i>	250028033 <b>FD 3404</b>	250028034 <b>FA 2087</b>		250028032 <b>FI 1303 V</b>
<i>ES 6 SULLUBE</i>	250028033 <b>FD 3404</b>	250028034 <b>FA 2087</b>		250028032 <b>FI 1303 V</b>
<i>ES 8</i>	02250106791 <b>FD 3405</b>	02250131496 <b>FA 1003 AL</b>		250028032 <b>FI 1303 V</b>
<i>ES 8 (15. 20. 25 &amp; 30 HP)</i>	250035239 <b>FD 3405</b>	043334 <b>FA 1003 AL</b>		250026982 <b>FI 1303 V</b>
<i>ES 8 SRF</i>	02250106791 <b>FD 3405</b>	02250131496 <b>FA 1003 AL</b>		250028032 <b>FI 1303 V</b>
<i>ES 8 SULLUBE</i>	02250106791 <b>FD 3405</b>	02250131496 <b>FA 1003 AL</b>		250028032 <b>FI 1303 V</b>
<i>F100D WITH DEUTZ F6L912 ENG.</i>	00743 <b>FD 3186</b>	01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	
<i>F100D10 WITH DEUTZ F6L912 ENG.</i>	00743 <b>FD 3186</b>	01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	
<i>F100DN WITH DEUTZ F6L912 ENG.</i>	00743 <b>FD 3186</b>	01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	
<i>F100DN10 WITH DEUTZ F6L912 ENG.</i>	00743 <b>FD 3186</b>	01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	
<i>F100E</i>		01144 <b>FA 1106</b>	5729 <b>FA 1346</b>	
<i>F100E10</i>		01144 <b>FA 1106</b>	5729 <b>FA 1346</b>	
<i>F100P WITH PERKINS 6.354 ENG.</i>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	
<i>F130E</i>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<i>F130E10</i>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<i>F150D WITH DEUTZ F5L413R ENG.</i>			10003221 <b>FA 1543</b>	4061130 <b>FO 0077 V</b>
<i>F150D10 WITH DEUTZ F5L413R ENG.</i>			10003221 <b>FA 1543</b>	4061130 <b>FO 0077 V</b>
<i>F160E</i>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916





	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>SULLAIR</b>				
<i>F160E10</i>				
<b>F160E10</b>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<b>F180D WITH DEUTZ F6L413R ENG.</b>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	4061130 <b>FO 0077 V</b>
<b>F180D10 WITH DEUTZ F6L413R ENG.</b>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	4061130 <b>FO 0077 V</b>
<b>F180DN WITH DEUTZ F6L413R ENG.</b>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	4061130 <b>FO 0077 V</b>
<b>F180DN10 WITH DEUTZ F6L413R ENG.</b>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	4061130 <b>FO 0077 V</b>
<b>F180F12</b>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<b>F200E</b>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<b>F200E10</b>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<b>F21D WITH DEUTZ F1L511 ENG.</b>		5048480 <b>FA 1219</b>		6708 <b>FI 1290 V</b>
<b>F230D WITH DEUTZ F8L413V ENG.</b>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<b>F230D10 WITH DEUTZ F8L413V ENG.</b>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<b>F230D12 WITH DEUTZ F8L413V ENG.</b>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<b>F230DN WITH DEUTZ F8L413V ENG.</b>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<b>F230E</b>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<b>F230E10</b>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<b>F25D</b>	01799 <b>FD 3032</b>			
<b>F25E</b>		00568		3545 <b>FI 1288 V</b>
<b>F25E10</b>		00568		3545 <b>FI 1288 V</b>
<b>F28</b>	01799 <b>FD 3032</b>	00568		
<b>F280D WITH DEUTZ BF8L413 ENG.</b>			10003221 <b>FA 1543</b>	5081916
<b>F280D10 WITH DEUTZ BF8L413 ENG.</b>			10003221 <b>FA 1543</b>	5081916
<b>F280D12 WITH DEUTZ BF8L413 ENG.</b>			10003221 <b>FA 1543</b>	5081916
<b>F28D WITH DEUTZ F2L511D ENG.</b>	01799 <b>FD 3032</b>	00568		68527264 <b>FO 0029 V</b>
<b>F30D WITH DEUTZ F2L512 ENG.</b>		5048480 <b>FA 1219</b>		6708 <b>FI 1290 V</b>
<b>F35D WITH DEUTZ F2L912 ENG.</b>		01144 <b>FA 1106</b>	5729 <b>FA 1346</b>	3545 <b>FI 1288 V</b>
<b>F35E</b>		00568		3545 <b>FI 1288 V</b>
<b>F35E10</b>		00568		3545 <b>FI 1288 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>SULLAIR</b>				
<i>F40D WITH DEUTZ F2L511D ENG.</i>				
<i>F40D WITH DEUTZ F2L511D ENG.</i>	01799 <b>FD 3032</b>	00568		68527264 <b>FO 0029 V</b>
<i>F40E</i>		2061350 <b>FA 1220</b>	8274 <b>FA 1586</b>	3545 <b>FI 1288 V</b>
<i>F40E10</i>		2061350 <b>FA 1220</b>	8274 <b>FA 1586</b>	3545 <b>FI 1288 V</b>
<i>F50D WITH DEUTZ F3L912 ENG.</i>		01144 <b>FA 1106</b>	5729 <b>FA 1346</b>	3545 <b>FI 1288 V</b>
<i>F50E</i>		2061350 <b>FA 1220</b>	8274 <b>FA 1586</b>	3545 <b>FI 1288 V</b>
<i>F50E10</i>		2061350 <b>FA 1220</b>	8274 <b>FA 1586</b>	3545 <b>FI 1288 V</b>
<i>F50P WITH PERKINS 4.236 ENG.</i>		01144 <b>FA 1106</b>	5729 <b>FA 1346</b>	3545 <b>FI 1288 V</b>
<i>F55D WITH DEUTZ F3L912 ENG.</i>		5048480 <b>FA 1219</b>		6708 <b>FI 1290 V</b>
<i>F70E</i>		01144 <b>FA 1106</b>	5729 <b>FA 1346</b>	
<i>F70E10</i>		01144 <b>FA 1106</b>	5729 <b>FA 1346</b>	
<i>F70P WITH PERKINS 4.236 ENG.</i>		01144 <b>FA 1106</b>	5729 <b>FA 1346</b>	3545 <b>FI 1288 V</b>
<i>F85E</i>		01144 <b>FA 1106</b>	5729 <b>FA 1346</b>	
<i>F85E10</i>		01144 <b>FA 1106</b>	5729 <b>FA 1346</b>	
<i>FD25D WITH DEUTZ F2L411 ENG.</i>		00568		68527264 <b>FO 0029 V</b>
<i>L45SR</i>				486613 <b>FI 1286 V</b>
<i>LS 10 25/30 HP</i>	250034112 <b>FD 3472</b>	02250131496 <b>FA 1003 AL</b>		250025525
<i>LS 10 40 HP</i>	02250121500 <b>FD 3032</b>	02250121500		250025525
<i>LS 10 LEAK FREE</i>	02250121500 <b>FD 3032</b>	02250131496 <b>FA 1003 AL</b>		250025525
<i>LS 12</i>	250034116 <b>FD 3470</b>	040899 <b>FA 2092</b>		250025526 <b>FI 1308 V</b>
<i>LS 12 LEAK FREE</i>	02250100755 <b>FD 3644</b>	02250131498 <b>FA 1202 AL</b>		250025526 <b>FI 1308 V</b>
<i>LS 16 100 HP</i>	250034116 <b>FD 3470</b>	02250046012 <b>FA 1252</b>		250025526 <b>FI 1308 V</b>
<i>LS 16 24KT 100 HP</i>	250034116 <b>FD 3470</b>	02250045012		250025526 <b>FI 1308 V</b>
<i>LS 16 24KT 60/75 HP</i>	250034116 <b>FD 3470</b>	047542 <b>FA 1103 AL</b>		250025526 <b>FI 1308 V</b>
<i>LS 16 24KT LEAK FREE 100 HP</i>	02250100755 <b>FD 3644</b>	02250046012 <b>FA 1252</b>		250025526 <b>FI 1308 V</b>
<i>LS 16 24KT LEAK FREE 60/75 HP</i>	02250100755 <b>FD 3644</b>	250018652		250025526 <b>FI 1308 V</b>
<i>LS 16 60/75 HP</i>	250034116 <b>FD 3470</b>	047542 <b>FA 1103 AL</b>		250025526 <b>FI 1308 V</b>
<i>LS 16 E 100 HP</i>	02250061137 <b>FD 3630</b>	88290002337		250025526 <b>FI 1308 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>SULLAIR</b>				
<i>LS 16 LEAK FREE 100 HP</i>				
<i>LS 16 LEAK FREE 100 HP</i>	02250100755 <b>FD 3644</b>	02250046012 <b>FA 1252</b>		250025526 <b>FI 1308 V</b>
<i>LS 16 LEAK FREE 60/75 HP</i>	02250100755 <b>FD 3644</b>	02250131499 <b>FA 1104</b>		250025526 <b>FI 1308 V</b>
<i>LS 16 SRF 100 HP</i>	250034116 <b>FD 3470</b>	02250045012		250025526 <b>FI 1308 V</b>
<i>LS 16 SRF 60/75 HP</i>	250034116 <b>FD 3470</b>	047542 <b>FA 1103 AL</b>		250025526 <b>FI 1308 V</b>
<i>LS 16 SRF LEAK FREE 100 HP</i>	02250100755 <b>FD 3644</b>	02250046012 <b>FA 1252</b>		250025526 <b>FI 1308 V</b>
<i>LS 16 SRF LEAK FREE 60/75 HP</i>	02250100755 <b>FD 3644</b>	250018652		250025526 <b>FI 1308 V</b>
<i>LS 16-75 ACAC</i>	250034116 <b>FD 3470</b>	408990		250025526 <b>FI 1308 V</b>
<i>LS 20 100 HP</i>	02250042862	040889 <b>FA 2092</b>		250025526 <b>FI 1308 V</b>
<i>LS 20 24KT 100 HP</i>	02250061137 <b>FD 3630</b>	040899 <b>FA 2092</b>		250025526 <b>FI 1308 V</b>
<i>LS 20 E 125/150 HP</i>	02250048734 <b>FD 3539</b>	88290001469		250025526 <b>FI 1308 V</b>
<i>LS 20 S 125/150 HP</i>	02250048734 <b>FD 3539</b>	405158 <b>FA 2818</b>		250025526 <b>FI 1308 V</b>
<i>LS 20 S E 175/200 HP</i>	250034122 <b>FD 3066</b>	88290003111		250025526 <b>FI 1308 V</b>
<i>LS 20 S LEAK FREE</i>	02250048734 <b>FD 3539</b>	02250135148		250025526 <b>FI 1308 V</b>
<i>LS 20 S SULLUBE 125/150 HP</i>	02250048734 <b>FD 3539</b>	405158 <b>FA 2818</b>		250025526 <b>FI 1308 V</b>
<i>LS 20 SRF 100 HP</i>	02250061137 <b>FD 3630</b>	040899 <b>FA 2092</b>		250025526 <b>FI 1308 V</b>
<i>LS 20 SULLUBE 100 HP</i>	02250061137 <b>FD 3630</b>	040899 <b>FA 2092</b>		250025526 <b>FI 1308 V</b>
<i>S 10 (20. 30. 40 HP)</i>	2250121500 <b>FD 3032</b>	040899 <b>FA 2092</b>		
<i>S 10 LEAK FREE (20. 30 .40 HP)</i>	2250137895 <b>FD 3032</b>	040899 <b>FA 2092</b>		
<i>S 12 (60. 75 HP)</i>	250034116 <b>FD 3470</b>	040899 <b>FA 2092</b>		
<i>S 12 LEAK FREE (60. 75 HP)</i>	2250100755 <b>FD 3644</b>	270009081		
<i>S 12 LEAK FREE (60.75 HP)</i>			270009082	250025526 <b>FI 1308 V</b>
<i>S 16 (75. 100 HP)</i>	250034116 <b>FD 3470</b>	040899 <b>FA 2092</b>		
<i>S 16 LEAK FREE (75. 100 HP)</i>	2250100755 <b>FD 3644</b>	270009102		
<i>S 16 LEAK FREE (75.100 HP)</i>			270009103	250025526 <b>FI 1308 V</b>
<i>S 20 SERIES UNTIL 5987 (100. 150. 200 HP)</i>	2250048734 <b>FD 3539</b>	405158 <b>FA 2818</b>		
<i>S100E</i>		01144 <b>FA 1106</b>	5729 <b>FA 1346</b>	
<i>S100E10</i>		01144 <b>FA 1106</b>	5729 <b>FA 1346</b>	



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>SULLAIR</b>				
<i>S130E</i>				
<i>S130E</i>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<i>S130E10</i>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<i>S160E</i>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<i>S160E10</i>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<i>S200E</i>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<i>S200E10</i>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<i>S230E</i>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<i>S230E10</i>		01279 <b>FA 1217</b>	8273 <b>FA 1310</b>	5081916
<i>S25E</i>		00568		3545 <b>FI 1288 V</b>
<i>S25E10</i>		00568		3545 <b>FI 1288 V</b>
<i>S35E</i>		00568		3545 <b>FI 1288 V</b>
<i>S35E10</i>		00568		3545 <b>FI 1288 V</b>
<i>S40E</i>		2061350 <b>FA 1220</b>	8274 <b>FA 1586</b>	3545 <b>FI 1288 V</b>
<i>S40E10</i>		2061350 <b>FA 1220</b>	8274 <b>FA 1586</b>	3545 <b>FI 1288 V</b>
<i>S50E</i>		2061350 <b>FA 1220</b>	8274 <b>FA 1586</b>	3545 <b>FI 1288 V</b>
<i>S50E10</i>		2061350 <b>FA 1220</b>	8274 <b>FA 1586</b>	3545 <b>FI 1288 V</b>
<i>S70E</i>		01144 <b>FA 1106</b>	5729 <b>FA 1346</b>	
<i>S70E10</i>		01144 <b>FA 1106</b>	5729 <b>FA 1346</b>	
<i>S85E</i>		01144 <b>FA 1106</b>	5729 <b>FA 1346</b>	
<i>S85E10</i>		01144 <b>FA 1106</b>	5729 <b>FA 1346</b>	
<b>SCREW COMPRESSOR SERIES LS 10</b>	2250121500 <b>FD 3032</b>	2250044537		250025525
<b>SCREW COMPRESSOR SERIES LS 10 (25. 30 HP)</b>	250034113 <b>FD 3473</b>	040596 <b>FA 1004 AL</b>		
<b>SCREW COMPRESSOR SERIES LS 12</b>	2250100755 <b>FD 3644</b>	2250131498 <b>FA 1202 AL</b>		250025526 <b>FI 1308 V</b>
<b>SCREW COMPRESSOR SERIES LS 12 (100 HP)</b>	250034116 <b>FD 3470</b>	040899 <b>FA 2092</b>		250025524 <b>FI 1303 V</b>
<b>SCREW COMPRESSOR SERIES LS 16</b>	2250061137 <b>FD 3630</b>	2250131499 <b>FA 1104</b>	88290002338 <b>FA 1310</b>	250025526 <b>FI 1308 V</b>
<b>SCREW COMPRESSOR SERIES LS 20</b>	2250034085 <b>FD 3487</b>	2250046012 <b>FA 1252</b>	2250046013	250025526 <b>FI 1308 V</b>
<b>SCREW COMPRESSOR SERIES LS 20 S</b>	2250034122 <b>FD 3066</b>	88290003111		250025526 <b>FI 1308 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>SULLAIR</b>				
<i>SCREW COMPRESSOR SERIES LS 25 S</i>				
<i>SCREW COMPRESSOR SERIES LS 25 S</i>	2250034124 <b>FD 3490</b>	88290001466	88290001467	2250139996
<i>SCREW COMPRESSOR SERIES TS 32 S</i>	2250109319 <b>FD 3538</b>	88290004372		2250139996
<i>SK110</i>		3198 <b>FA 1229</b>		486613 <b>FI 1286 V</b>
<i>SK40E10</i>				3545 <b>FI 1288 V</b>
<i>SK40E13</i>				3545 <b>FI 1288 V</b>
<i>SK40E7</i>				3545 <b>FI 1288 V</b>
<i>SK55</i>				3545 <b>FI 1288 V</b>
<i>SK55E10</i>	03124	02981		3545 <b>FI 1288 V</b>
<i>SK55E13</i>				3545 <b>FI 1288 V</b>
<i>SK55E7</i>	03124	02981		3545 <b>FI 1288 V</b>
<i>SK70E10</i>		3198 <b>FA 1229</b>		3545 <b>FI 1288 V</b>
<i>SK70E13</i>		3198 <b>FA 1229</b>		3545 <b>FI 1288 V</b>
<i>SK70E7</i>		3198 <b>FA 1229</b>		3545 <b>FI 1288 V</b>
<i>SK90E</i>	01085			486613 <b>FI 1286 V</b>
<i>TS 20 100 HP</i>	250034122 <b>FD 3066</b>	405158 <b>FA 2818</b>		250025526 <b>FI 1308 V</b>
<i>TS 20 125/150 HP</i>	250034122 <b>FD 3066</b>	405158 <b>FA 2818</b>		250025526 <b>FI 1308 V</b>
<i>TS 20 200 HP</i>	250034122 <b>FD 3066</b>	02250135150		02250139995
<i>TS 20 250 HP</i>	250034122 <b>FD 3066</b>	02250135150		02250139995
<i>TS 32 200/250 HP</i>	250034122 <b>FD 3066</b>	250007838		02250139996
<i>TS 32 400/500/600 HP UP TO JUNE 2002</i>	02250109319 <b>FD 3538</b>	250007838		02250139996
<i>VS 16 30/40 HP</i>	02250049889 <b>FD 3538</b>	250024867 <b>FA 2109</b>		250028032 <b>FI 1303 V</b>
<i>VS 16 50 HP</i>	2250034124 <b>FD 3490</b>	250024867 <b>FA 2109</b>		250028032 <b>FI 1303 V</b>
<i>VS 20</i>	2250034124 <b>FD 3490</b>	250026148 <b>FA 2074</b>		250025525
<i>VS 25</i>	02250109319 <b>FD 3538</b>	250026683		250025525
<i>VS 32</i>	02250109319 <b>FD 3538</b>	250026120 <b>FA 2073</b>		250025525
<b>TAMROCK</b>				
<i>FI 40</i>	03267728 <b>FD 3122</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>TAMROCK</b>				
	<i>FI 60</i>			
<i>FI 60</i>	03340028 <b>FD 3408</b>	03400158 <b>FA 2922</b>		89515869 <b>FI 1300</b>
<i>FI 80</i>	03340028 <b>FD 3408</b>	03400158 <b>FA 2922</b>		89515869 <b>FI 1300</b>
<i>FL 45</i>	03340028 <b>FD 3408</b>	03400158 <b>FA 2922</b>		89515869 <b>FI 1300</b>
<i>FL 55</i>	03340028 <b>FD 3408</b>	03400158 <b>FA 2922</b>		89515869 <b>FI 1300</b>
<i>FL 75</i>	03340028 <b>FD 3408</b>	03400158 <b>FA 2922</b>		89515869 <b>FI 1300</b>
<i>FM 18</i>	03267728 <b>FD 3122</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>FM 22</i>	03267728 <b>FD 3122</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>FM 30</i>	03267728 <b>FD 3122</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>FM 37</i>	03267728 <b>FD 3122</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>FS 11 T3</i>	03582228 <b>FD 3135</b>	85644309		81649209 <b>FO 0339 V</b>
<i>FS 11 T6</i>	03498328 <b>FD 3409</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>FS 15 T6</i>	03498328 <b>FD 3409</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>FS 18 T6</i>	03498328 <b>FD 3409</b>	81166609 <b>FA 2117</b>		89559379 <b>FI 1268 V</b>
<i>FS 5</i>	03582228 <b>FD 3135</b>	85644309		81649209 <b>FO 0339 V</b>
<i>FS 7</i>	03582228 <b>FD 3135</b>	85644309		81649209 <b>FO 0339 V</b>
<i>FX 5</i>	03582228 <b>FD 3135</b>	85644309		81649209 <b>FO 0339 V</b>
<i>FX 7</i>	03582228 <b>FD 3135</b>	85644309		81649209 <b>FO 0339 V</b>
<i>M 110</i>	03340028 <b>FD 3408</b>	85067179 <b>FA 1758</b>		85062259 <b>FI 1301</b>
<i>M 132</i>	03340028 <b>FD 3408</b>	85067179 <b>FA 1758</b>		85062259 <b>FI 1301</b>
<i>M 160</i>	03340028 <b>FD 3408</b>	85067179 <b>FA 1758</b>		85062259 <b>FI 1301</b>
<i>M 75</i>	03340028 <b>FD 3408</b>	85067179 <b>FA 1758</b>		85062259 <b>FI 1301</b>
<i>M 90</i>	03340028 <b>FD 3408</b>	85067179 <b>FA 1758</b>		85062259 <b>FI 1301</b>
<i>MC</i>	87286889 <b>FD 3546</b>	85644309		81649209 <b>FO 0339 V</b>
<i>MI 130</i>	03340028 <b>FD 3408</b>	85067179 <b>FA 1758</b>		85062259 <b>FI 1301</b>
<i>MI 155</i>	03340028 <b>FD 3408</b>	85067179 <b>FA 1758</b>		85062259 <b>FI 1301</b>
<i>RM</i>	87286889 <b>FD 3546</b>	85644309		81649209 <b>FO 0339 V</b>
<i>TA</i>	87286889 <b>FD 3546</b>	89559659 <b>FA 1449</b>		81649209 <b>FO 0339 V</b>



	<i>SEPARATOR OE BSB REF.</i>	<i>AIR PRIMARY OE BSB REF.</i>	<i>AIR SAFETY OE BSB REF.</i>	<i>OIL FILTER OE BSB REF.</i>
<b>TAMROCK</b>				
<i>TERRIER</i>				
<i>TERRIER</i>	87286889 <b>FD 3546</b>	85644309		81649209 <b>FO 0339 V</b>
<b>TERMOMECCANICA</b>				
<i>SCI 6</i>	1018710049 <b>FD 3034 V</b>			1148520002
<i>SCI 7</i>	1018710049 <b>FD 3034 V</b>	1148510124		1148520002
<b>WITTIG</b>				
				43299600 <b>FI 1099 V</b>
<b>WORTHINGTON</b>				
<i>RLR 1000 AM 7</i>	6221347800 <b>FD 3096 V</b>	6211457850 <b>FA 1933</b>		6211441255 <b>FI 1062 V</b>
<i>RLR 1500 AM 6</i>	6259033600 <b>FD 3662</b>	6211457850 <b>FA 1933</b>		6211441255 <b>FI 1062 V</b>
<i>RLR 1500 AM 7</i>	6221347800 <b>FD 3096 V</b>	6211457850 <b>FA 1933</b>		6211441255 <b>FI 1062 V</b>
<i>RLR 20 E</i>	6221357850 <b>FD 3373 V</b>	6211464150 <b>FA 2050</b>		
<i>RLR 25 E</i>	6221357850 <b>FD 3373 V</b>	6211464150 <b>FA 2050</b>		
<i>RLR 30 E</i>	6221357850 <b>FD 3373 V</b>	6211464150 <b>FA 2050</b>		
<i>RLR 30 V8</i>	6221358250 <b>FD 3031 V</b>	6211464150 <b>FA 2050</b>		
<i>RLR 4000 AX 1</i>	6221326900 <b>FD 3665</b>	6211443600 <b>FA 1954</b>		6211441250 <b>FI 1062 V</b>
<i>RLR 50 AX 6</i>	6221347950 <b>FD 3665</b>	6211462150 <b>FA 5500</b>		6211441255 <b>FI 1062 V</b>
<i>RLR 550 AM 7</i>	6221347800 <b>FD 3096 V</b>	6211457850 <b>FA 1933</b>		6211441255 <b>FI 1062 V</b>
<i>RLR 750 AM 7</i>	6221347800 <b>FD 3096 V</b>	6211457850 <b>FA 1933</b>		6211441255 <b>FI 1062 V</b>
<i>ROLAIR 1000</i>				6211441200 <b>FO 0280 V</b>
<i>ROLAIR 2000</i>				6211441200 <b>FO 0280 V</b>
<i>ROLAIR 3000</i>				6211441200 <b>FO 0280 V</b>
<i>ROLAIR 40</i>	41113676			6211441200 <b>FO 0280 V</b>

